

PROJECT: Keystone Pacific Warehouse

DATE: Wednesday, February 17, 2016

REPORT BY: Rick Buhl

MANPOWER DETAIL

SUB-CONTRACTOR: Phase 1 Construction

OF WORKERS:

.

ACTIVITIES:

They finished up the water line and and storm drain pipes then began to backfill after the inspection.

INSPECTION REPORT

The 2 inch water pipe and storm drain were inspected and we were givin the ok to backfill.