

CAW[®]

**Coatings Application &
Waterproofing Co.
5125 N. 2nd Street
St. Louis, Mo. 63147**

Phone: 314-241-6370
Fax: 314-241-0871
Toll Free: 1-866-278-4440

Volume 3, Issue 5
October 2009

Commercial Façade Restoration Hurricane Ike Damages Restored

American National Insurance Office Building is located at #1 Moody Plaza Galveston Texas.

Construction was completed in 1972 on the 355' tall 21 floor pre cast concrete building. The building has been through three hurricanes.

After two inspections of the façade by two consulting firms a decision was made to have the façade repaired after Hurricane Ike.

A specification was agreed on to repair all cracks, new sealants, clean, prime and apply 2 coats of Neogard Neoflex. There was a total of over 5,000 gallons of Neogard products applied .

The lower 60' core of the structure is marble veneer. All undamaged marble was removed and stored for resetting. The balance of the marble that was required was ordered from Italy. The marble was reset for a total of 15,000 square feet. All salvageable marble units were reset on one elevation.

All damaged brick of the retaining walls and penthouse were removed and reset with matching brick which were manufactured locally



In Progress Photo Of Project

Restoration Specialists

Marble Restoration

Brick Restoration

Wall Coatings

**Wall Sealants &
Waterproofing**

**Window Glazing &
Caulking**

EIFS Repairs

Deck Coatings

Planter Restoration

**Thermoplastic Roofing
Systems**

**Modified Roofing
Systems**

**Spray Polyurethane
Foam Roofing Systems**



Typical damaged brickwork that was restored




More damaged brickwork that was restored




Walls had scaffolding set up to replace the marble.



Completed brickwork after being restored



Completed brickwork after being restored



Finished Marble after Grout was installed

