

**CMS Contracting & Plant Hire Pty Ltd**

ABN 73 143 852 411

10-12 Churchill Street, SILVERWATER NSW 2128

Ph 02 9647 1929

Email accounts@cmscontracting.com.au

www.cmscontracting.com.au

**SERVICE & MAINTENANCE REPORT****Docket # 0045**

DATE: 10-9-2023 MAKE: Kubota  
 LOCATION OF JOB: Silverwater MODEL: U25-3  
 PLANT NO: X41 SERIAL NO: 52238  
 REGO NO: \_\_\_\_\_ HOURS/KMS: 2534

WORK REQUIRED: 2500 HOUR SERVICE

WORK PERFORMED:  
Change engine oil & filter  
" fuel filter & drain water separator  
" final drive oil  
checked belts  
top up hydraulic oil  
change hydraulic return & pilot oil filter  
" air filters  
top up coolant  
grease + safety inspection

OUTSTANDING WORK REQUIRED:  
Battery needs replacement soon  
Change 6x plugs + o rings on final drives next service

CONSUMABLES: \_\_\_\_\_ HYDRAULIC OIL: 4 GREASE: 1  
 ENGINE OIL: 4.5 GEAR OIL: 2 COOLANT: 1  
 TRANS OIL: \_\_\_\_\_ DIFF OIL: \_\_\_\_\_ ENVIRO COSTS: \_\_\_\_\_

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>3.5</u>	TOTAL KILOMETERS	
-------------	----------	--------------	------------	------------------	--

PLANT SAFETY CHECK	<input checked="" type="checkbox"/>
Machine Hours	
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

**SIGN OFF**  
 Serviceperson: Trenton Van Loan  
 Licence No.: \_\_\_\_\_  
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.  
 Signature: \_\_\_\_\_

**CMS Contracting & Plant Hire Pty Ltd**

ABN 73 143 852 411

10-12 Churchill Street, SILVERWATER NSW 2128

Ph 02 9647 1929

Email accounts@cmscontracting.com.au

www.cmscontracting.com.au

**CONTRACTING****SERVICE & MAINTENANCE REPORT****Docket # 0032**

DATE: 12-6-23 MAKE: Kubota  
 LOCATION OF JOB: Silverwater MODEL: U25-3 HGA  
 PLANT NO: X41 SERIAL NO: 52238  
 REGO NO: \_\_\_\_\_ HOURS/KMS: 2380

WORK REQUIRED: 2250 HOUR SERVICE

WORK PERFORMED:  
Change engine oil & filter  
" final drive oil  
Top up hydraulic oil  
Tension fan belt  
Inspect fuel separator  
Fix quick hitch line leak  
Clean out radiator + air filters  
Grease  
Safety inspection

OUTSTANDING WORK REQUIRED: Light switch not functioning

CONSUMABLES: \_\_\_\_\_ HYDRAULIC OIL: 4 GREASE: 1  
 ENGINE OIL: 4.4 GEAR OIL: 2 COOLANT: \_\_\_\_\_  
 TRANS OIL: \_\_\_\_\_ DIFF OIL: \_\_\_\_\_ ENVIRO COSTS: \_\_\_\_\_

TRAVEL TIME		FIELD LABOUR	<u>2.5</u>	TOTAL KILOMETERS	
-------------	--	--------------	------------	------------------	--

PLANT SAFETY CHECK	✓
Machine Hours	
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

**SIGN OFF**Serviceperson: Trenton Van Loon

Licence No.: \_\_\_\_\_

I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Signature: \_\_\_\_\_