

# **RISK MANAGEMENT REPORT**

TYPE	Dump Truck - Site
MAKE	Ausa
MODEL	D600 APG
SERIAL NUMBER	64075270
ENGINE NUMBER	2FG3799



Report Number	AHS 20170615-1710
Date	15-Jun-2017
Created By	Paul Rozier
Assessor	Paul Rozier
Assist. Assessor(s)	
Completed By	Paul Rozier
Owner	Australian Hammer Supplies Pty Ltd
Assessment Purpose	Sale
State	NSW

## **TABLE OF CONTENTS**

SECTION 1 IMPORTANT INFORMATION

Contains information outlining the scope and any limitations applicable to this Risk Management Report

SECTION 2 MACHINE DETAILS
Contains standard machine specifications and details of any extras fitted

Contains standard machine specifications and details of any extras litted

SECTION 3 Contains details of the technique used to calculate risk ratings, time frame and risk treatments. Please refer to this information when reviewing and interpreting the information in section 4 & 5

**RISK ANALYSIS, RISK EVALUATION & RISK TREATMENT** 

RISK TREATMENTS REQUIRED

Contains detailed information regarding the risk treatments to be implemented including hazard, risk rating, time frame, relevant standards & legislative references

**RISK TREATMENTS IN PLACE** 

Contains detailed information regarding the risk treatments in place including hazard, risk rating,

relevant standards & legislative references

SECTION 6

IMAGES AND NOTES

Contains images & any relevant information entered by the assessor



**SECTION 4** 

**SECTION 5** 



## **SECTION 1** IMPORTANT INFORMATION

This report generated by Plant Assessor™ © Online Safety Systems on Thursday, 15 Jun 2017 5:16 PM

This Risk Management Report has been prepared for -

(insert recipient name/company name)

This document has been prepared to cover the sale or transfer of this item of plant between the Company identified on the front cover and their named recipient. This report must not be used for any subsequent sale or transfer.

This document is provided to meet duty of care obligations as set out in relevant state and territory health and safety regulations for the supply of plant and the sale and transfer of plant.

The safety hazards associated with the operating and maintaining of this item of plant have been identified as far as practical by visual inspection. This item of plant is being sold in an "as-is" condition with known and unknown safety hazards. No physical testing has been conducted (eg. Wire rope tests, stress tests, structural/non-destructive tests, noise tests, vibration tests, brake tests, insulation tests etc.) unless stated otherwise in the notes.

This document is not intended to provide information on, nor warrant the mechanical, electrical or structural condition of this item of plant. Any information on standard features have been supplied through the manufacturer and should be used as a guide only until otherwise verified.

This item of plant should be further assessed, tested and inspected or dismantled as necessary to gauge any further hazards and /or risks relating to SPECIFIC WORKPLACE USE, which are currently unknown, in accordance with relevant standards, regulations and acts.

Under common law and relevant state and territory health and safety acts, regulations and codes of practice, there is a requirement for the plant owner, employer and operator to exercise a duty of care in the safe operation and maintenance of plant. Accordingly before this item of plant is supplied to, or used at any workplace it must be inspected to ensure it is in a fully operational, safe and serviceable condition and that operators and maintenance personnel are appropriately trained in the use & maintenance of this item of plant.

For further information regarding this report contact Online Safety Systems on 1300 72 88 52

## **SECTION 2** MACHINE DETAILS

1. Manufacturers specified noise level dBA 2. Ambient noise level dBA MACHINE DETAIL 3. Noise level - Operator position (high idle) dBA 4. Noise level - Operator position (low idle) dBA - NOISE TEST RESULTS 5. Noise level LHS dBA @ m (high idle) 6. Noise level Front dBA @ m (high idle) 7. Noise level RHS dBA @ m (high idle) 8. Noise level Rear dBA @ m (high idle) **CAPACITIES** 4.1 Heaped capacity (m3) Dump angle (deg) Height (mm) 3178 **DIMENSIONS/WEIGHTS** 4462.78 Length (mm) Loading Height (mm) Turn circle diameter, outside corner (mm)





Ausa D600 APG Dump Truck - Site Serial Number Assessed By Date

64075270 Paul Rozier 15-Jun-2017

	1	T
	Unladen weight (kg)	
	Width (mm)	
DRIVES	Drive	4x4
	Engine Displacement (Ltr)	
	Engine Hours	
ENGINE	Engine Make & Model	Kubota V3300T
ENGINE	Engine Number	
	Number of Cylinders	
	Power (kW@rpm)	
PLANT CLASSIFICATIONS	Class	
PLANT CLASSIFICATIONS	Year	2017
OAFETY OTDUOTUDES	FOPS Serial No.	
SAFETY STRUCTURES	ROPS Serial No.	
SPEEDS	Number of speeds, F/R	
STEERING	Steering system	
TRANSMISSION	Maximum speed (km/h)	
TRANSMISSION	Transmission	
TVDES	Tyre Size	
TYRES	Tyres, front/rear	
WORK CAPABILITIES	Dump speed, raiser/lower (sec)	
	Gradeability (%)	60
	Payload (kg)	
EXTRAS	ROPS - Two Post	





## **SECTION 3** RISK ANALYSIS / RISK EVALUATION

RIS	SK ANALYSIS					
_ <	← CONSEQUENCE →					
ПКЕЦІНООВ ————		1. INSIGNIFICANT Dealt with by in house first aid	2. MINOR Treated by medical professionals, hospital out patients	3. MODERATE Significant non permanent injury overnight hospital stay	4. MAJOR Extensive permanent injury eg. Loss of fingers, extended hospital stay	5. CATASTROPHIC Death, permanent disabling injury eg. Loss of hand, quadriplegia
TIKETI	A. Almost certain to occur in most circumstances	MEDIUM 8	HIGH 16	HIGH 18	CRITICAL 23	CRITICAL 25
ļ	B. Likely to occur frequently	MEDIUM 7	MEDIUM 10	HIGH 17	HIGH 20	CRITICAL 24
	C. Possibly and likely to occur at sometime	LOW 3	MEDIUM 9	MEDIUM 12	HIGH 19	HIGH 22
	D. Unlikely to occur but could happen	LOW 2	LOW 5	MEDIUM 11	MEDIUM 14	HIGH 21
	E. May occur but only in rare circumstances	LOW 1	LOW 4	LOW 6	MEDIUM 13	MEDIUM 15

LUATION	CRITICAL	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below.
RISK EVA	HIGH	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below. If the appropriate risk treatments are not immediately accessible establish interim risk treatment strategies. Permanent risk treatments must be implemented within one week.
	MEDIUM	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented within one month.
	LOW	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented within three months.

EATMENT	Selecting the most appropriate risk treatment option involves balancing the costs and efforts of implementation against the benefits derived, with regard to legal, regulatory and other requirements. (source AS/NZS ISO 31000:2009)		
REAT	Eliminate	Eliminate the risk source.	
RISKT	Substitute	Provide an alternative that is capable of performing the same task which is safer.	
	Engineering	Provide or construct a physical barrier or guard.	
	Administration	Develop policies, procedures, practices and guidelines in consultation with employees to mitigate the risk.  Provide training, instruction and supervision about the risk source.	
	Personal protective	Provide personal protective equipment to protect the individual from the risk source.	





## **SECTION 4** RISK TREATMENTS REQUIRED

This section of the report pertains to hazards created by use of this item of plant which currently do not have risk treatments in place. The risk treatments recommended in this section have been developed based on relevant Australian Standards, health & safety legislation, the hierarchy of risk treatment in accordance with the guidelines set forth in AS/NZS ISO 31000 – Risk Management and various other sources. The recommended risk treatment measures must be developed, implemented and validated as effective prior to the operation, maintenance or testing of this item of plant. Treatments applied must be dated and initialled adjacent the recommendations. All operators must read and understand the entire contents of this section prior to operating this item of plant.

HAZARD(S)	Prelim. Risk	Residual Risk	Time	Due Date	Date	Initial
HAZARD(3)	Rating	Rating	Frame	Due Date	Rectified	IIIItiai

## **SECTION 5** RISK TREATMENTS IN PLACE

This section of the report pertains to risk treatments currently in place on this item of plant. This section must be read in conjunction with the safety section of the manufacturers handbook. All operators must read and understand the entire contents of this section prior to operating this item of plant. These treatments or equivalent must remain in place at all times whilst this item of plant is in operation.

	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating			
ERY	CRUSHING	HIGH 22	MEDIUM 15			
DELIVERY	tilt tray.					
	References: Work Health & Safety Act & Regulations-					
	CRUSHING	HIGH 22	MEDIUM 15			
	Risk Treatments in Place: SWMS Load Restraint Ensure that all operators follow the approved SWMS/SOP when restraining this machine for	or transport.				
	References: Work Health & Safety Act & Regulations-					
NOI	NOMINATED OPERATION ONLY	CRITICAL 24	MEDIUM 15			
OPERATION	Risk Treatments in Place: Operator Competency Only persons who are qualified, trained and experienced and/or hold the relevant certificat competent/licensed person available for operation of this item of plant then only persons w operate this item of plant.					
	References: Work Health & Safety Act & Regulations-					
	INCORRECT OPERATION	HIGH 22	MEDIUM 15			
	Risk Treatments in Place: Operation Handbook  The manufacturer's operation handbook has been supplied for this item of plant.					
	This handbook must be available at all times to all potential operators and supervisory staff. All potential operators must read and be familiar with this handbook prior to operating.					
	A complete risk assessment/Job Safety Analysis must be undertaken covering all operating processes and environments associated with this item of plant. SWMS should be produced for specific tasks associated with use of this item of plant.					
	References: Work Health & Safety Act & Regulations-					





## HAZARD(S) Prelim. Risk Rating **Residual Risk Rating INCORRECT OPERATION** HIGH 22 MEDIUM 15 Risk Treatments in Place: Pre-op Checklist Dump Truck - Site A pre-operational checklist is available for this Dump Truck - Site. All operators must complete this checklist prior to operating this Dump Truck -References: Work Health & Safety Act & Regulations-**INCORRECT OPERATION** HIGH 22 MFDIUM 15 Risk Treatments in Place: SOP Dump Truck - Site Safe Operation Procedures are available for this Dump Truck - Site. The information in the Safe Operation Procedures must be followed at all times whilst operating this Dump Truck - Site. References: Work Health & Safety Act & Regulations-



**INCORRECT OPERATION** 

HIGH 22

MEDIUM 15

Risk Treatments in Place: Control Labels

All controls including all levers, buttons, pedals, switches etc. are clearly labelled as to their purpose and method of operation. These labels must be maintained in a clean and serviceable condition at all times.

References: AS/NZS4024.1905



**FALLING, CRUSHING** 

HIGH 22

MFDIUM 15

Risk Treatments in Place: Passenger Seat Label

This item of plant is fitted with a clear hazard warning label re: Operator only, No passengers. Passengers must not be carried at anytime. This label must be clear and legible at all times whilst this item of plant is in operation.

Legislation: State Health & Safety Legislation & Regulation

References: AS1319-



**CRUSHING** 

HIGH 22

MEDIUM 15

Risk Treatments in Place: ROPS Label

The warning label stating that the ROPS must not be damaged at any time (including cuts, drill holes and welds) must be present, clean and legible at all times.

References: ISO3471



**CRUSHING** 

HIGH 22

MEDIUM 15

Risk Treatments in Place: ROPS seat belt label

The advisory label stating that a "ROPS is fitted seatbelts must be worn" must be followed at all times whilst operating this item of plant. This label must be present, clean and legible at all times.

References: AS2294, ISO3471



**ELECTROCUTION** 

HIGH 22

MEDIUM 15

Risk Treatments in Place: Electrical Approach Distances

This item of plant has a hazard warning label re: overhead electrical hazards and minimum approach distances fitted. These distances must be adhered to strictly. These labels and tables must be present, clear and legible at all times.

Spotters are required when working within 5 metres of the minimum approach distance of any live electrical apparatus.

Any encroach within the minimum approach distances must only occur if the following provisions have been met -

- 1. The machine is designed to work within the minimum approach distances
- 2. Permission has been granted by the electricity company and
- 3. Safe systems of work have been documented and approved.

References: ISO31000





Ausa D600 APG Dump Truck - Site

Serial Number Assessed By Date

64075270 Paul Rozier 15-Jun-2017

Page 6 of 15

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
COLLISION	HIGH 22	MEDIUM 15

#### Risk Treatments in Place: Phone Use label

This item of plant is fitted with an instruction label advising that mobile phones must not be used whilst operating this machine. Accordingly all operators must not use a mobile phone at any time whilst operating machine. If phone use is necessary then operator must place machine in park configuration in a safe position prior to phone use. Operators MUST adhere to this advice at all times.

This label must be clear and legible at all times whilst this item of plant is in operation.

References: AS1319-, ISO31000



POISONING, EXPLOSION, BURNS

HIGH 22

MEDIUM 15

#### Risk Treatments in Place: Tank ID Label

The tank(s) on this item of plant have clear, legible label(s) identifying their contents, and if appropriate any necessary controls re: the contents. These must be present, clear and legible at all times. (this includes radiator, hydraulic and petrol/diesel tanks)

References: Work Health & Safety Act & Regulations-



#### **OPERATIONAL MALFUNCTION, INCORRECT OPERATION**

HIGH 22

MEDIUM 15

#### Risk Treatments in Place: Drawbar Capacity Label

The item of plant has a drawbar and a hazard warning label attached adjacent the drawbar/tow hitch re: maximum towing capacity, crushing, keep clear. It must be present and fully functional and serviceable at all times.

References: ISO31000



**CRUSHING** 

HIGH 21

MEDIUM 15

#### Risk Treatments in Place: Articulated Joint Crush Label

This item of plant has clear hazard warning labels re: crush zone, keep clear, that are attached to each side of the articulated joint. These must be present, clear and legible at all times whilst this item of plant is in operation.

References: ISO20474- . AS/NZS4024.1201



**HEARING LOSS** 

HIGH 19

MEDIUM 14

## Risk Treatments in Place: Hearing Protection Label - Bystanders

The hazard warning labels re: wearing of hearing protection for bystanders attached to this item of plant refer to the level of noise produced. Permanent hearing damage will result if hearing protection is not worn. These labels must be present, clear and legible at all times whilst this item of plant is in operation.

References: AS/NZS1269, AS3781-



**HEARING LOSS** 

HIGH 19

MEDIUM 14

## Risk Treatments in Place: Hearing Protection Label - Operator

The hazard warning label(s) re: wearing of hearing protection attached to this item of plant refer to the level of noise produced. Permanent hearing damage will result if hearing protection is not worn. These labels must be present, clear and legible at all times whilst this item of plant is in operation.

References: AS/NZS1269, AS3781-



BURNS, ENTANGLEMENT, SHEARING

HIGH 19

MEDIUM 13

## Risk Treatments in Place: Engine Guard Label

The engine fan and alternator belts, pulleys and gears are guarded. These guards have clear legible hazard warning labels re do not open or remove guards while engine is running. These labels must be present, legible and easily seen at all times whilst this item of plant is in operation.

References: AS1319-, AS/NZS4024.1201





Make Ausa
Model D600 APG
Type Dump Truck - Site

Serial Number Assessed By Date 64075270 Paul Rozier 15-Jun-2017



## Risk Treatments in Place: Crush Zone General

This item of plant has hazard warning labels re: Crushing, keep all body parts clear, adjacent all crush zones. These labels must be present and fully functional and serviceable at all times.

References: AS1319-, AS/NZS4024.1201



**FIRE** 

MEDIUM 13

LOW 4

#### Risk Treatments in Place: Fire Extinguisher

This item of plant is fitted with an approved and maintained fire extinguisher. Fire extinguisher(s) must be present and fully functional at all times. They must be readily accessible to the operator. Regular inspections must also be carried out in accordance with the manufacturer's requirements and AS 1851 – 1995

References: AS/NZS1841, AS1851



**COLLISION, CRUSHING** 

MEDIUM 12

LOW 6

#### Risk Treatments in Place: Warning Device (horn)

This item of plant is fitted with a fully functional audible warning device such as a horn. This must be easily accessed by the operator, and easily identifiable by nearby pedestrians.

All operators should ensure the warning devices are functional at the start of each shift, by completing pre-start checklists. Warning devices should operate automatically where appropriate (eg reversing)

References: ISO7731, ISO9533



BURNS

MEDIUM 12

MEDIUM 12

#### Risk Treatments in Place: Open Cabin

Dust, exhaust fumes, chemical fumes, sunstroke and sunburn pose serious risk to the operator both short and long term. The appropriate controls for all of these hazards must always be available whilst this item of plant is in operation. If these controls e.g. hats, sunscreen, dust masks etc are not available then operation of this item of plant must cease until these are made available to all operators.

References: ISO31000



**COLLISION, STRIKING, CRUSHING** 

MEDIUM 12

LOW 6

## Risk Treatments in Place: Tail Swing Label

The rear of this item of plant has a hazard warning label re: general plant movement, tail swing, keep clear. It must be present and fully functional and serviceable at all times.

References: ISO20474-



COLLISION

MEDIUM 9

LOW 5

## Risk Treatments in Place: Recovery Point Label

This item of plant is fitted with a hazard warning label adjacent the recovery tow point which states "Danger – Read manufacturer's towing instructions before towing. Failure to do so could result in DEATH or SERIOUS INJURY."

This label must be clear and legible at all times whilst this item of plant is in operation.

References: ISO31000







#### Risk Treatments in Place: Park Brake

The park brake fitted to this item of plant is fully functional at all times. The park brake must be regularly inspected and tested. These inspections and tests must be documented as part of your plant safety programme.

References: AS2958



## CRUSHING, COLLISION

HIGH 22

MEDIUM 15

#### Risk Treatments in Place: Hold To Run Tipping Body Controls

The tipping body controls are the "hold to run" type.

Operators and maintenance staff MUST NEVER attempt to bypass this important safety feature. Failure to comply with this instruction may lead to serious injury or death.

References: AS1418.8



## STRIKING, ENTANGLEMENT, COLLISION, CRUSHING

HIGH 22

MEDIUM 15

## **Risk Treatments in Place: Neutral Start**

This item of plant has neutral start control in place. It must be fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS4024.1603

**CRUSHING** 

HIGH 22

MEDIUM 15

#### Risk Treatments in Place: Seat Belt

This item of plant is fitted with an operator seat belt. This seat belt must be free from damage, and permanently and sturdily attached at all times whilst this item of plant is in operation. Operators must use this seat belt at all times during operation.

References: ISO6683

**CRUSHING** 

HIGH 22

MEDIUM 15

## Risk Treatments in Place: Passenger Seat

An ergonomic passenger seat with an approved restraint is fitted to this item of plant. These must both be serviceable at all times whilst this item of plant is in operation.

References: ISO6683, AS/NZS4024.1401



CRUSHING

HIGH 22

MEDIUM 15

## Risk Treatments in Place: Earthmoving ROPS

A Roll Over Protective Structure (ROPS) to AS 2294, ISO 3471, ISO 12117.1 or 2 or SAE J1040 is fitted to this item of plant. A permanent label stating this standard must be attached to the structure at all times. It must also carry a warning label re: wearing of seat belts at all times whilst this item of plant is in operation, and accordingly seat belts must be worn at all times during operation.

References: AS2294, ISO3471



**COLLISION, CRUSHING** 

HIGH 22

MEDIUM 15

## Risk Treatments in Place: Reverse Movement Alarm

A reverse movement sensor alarm is fitted to this item of plant. It must be fully functional and serviceable at all times whilst this item of plant is in operation.

References: ISO7731, ISO9533







## Risk Treatments in Place: Emergency Stop Device

This item of plant is fitted with an emergency stop device.

The emergency stop must meet all of the following criteria whilst this item of plant is in operation:

- 1. Is operational
- 2. Is coloured red with yellow background
- 3. Is clearly labeled as to purpose and method of operation
- 4. Is easily accessible to the operator(s) at all times whilst operating this item of plant
- 5. Resetting of emergency stop does not automatically restart machine
- 6. Is located at each operator control station.

References: AS/NZS4024.1604



## ENTANGLEMENT, SHEARING, CRUSHING, BURNS, PINCHING

HIGH 22

MEDIUM 15

## Risk Treatments in Place: Safe Operator Location

This machine is designed so that the operator is isolated from all danger zones whilst at the operator position. This condition must exist at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201



### STRIKING, BURNS

HIGH 22

MEDIUM 15

#### Risk Treatments in Place: Hydraulic Hoses

This item of plant has hydraulic hoses. These hoses must be inspected each day or before each use for wear and tear. If there are visible signs of wear immediate action must be taken to control the risk arising from this wear. These inspections must be documented.

Hydraulic fluid at high pressure can penetrate the skin, never use any part of your body to check for leaks. If oil penetrates the skin seek medical advice immediately. Always use a piece of cardboard or similar to check for suspected leaks.

Hydraulic pressure can be stored and is a hazard. Before disconnection or connection of hydraulic hoses complete the following steps -

- 1. Stop engine
- 2. Keep all bystanders clear of the work area
- 3. Refer to operators manual as to methods to release pressure
- 4. Wait 5 minutes

References: AS2671, AS4024



### **COLLISION, POOR VISIBILITY**

HIGH 22

MEDIUM 15

## **Risk Treatments in Place: Machine Lights**

This item of plant is fitted with self contained lighting. All of these lights must be fully functional and serviceable whilst this item of plant is in operation in areas of reduced light. If any of these lights stop working the operation must cease immediately and the faulty light be repaired before operation can continue in the areas of reduced light.

References: ISO20474-



### **ENTANGLEMENT**

HIGH 22

MEDIUM 15

## Risk Treatments in Place: Engine Guards

The engine fan and alternator belts, pulleys and gears are guarded. These guards must be present and fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS/NZS4024.1601






HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
CRUSHING	HIGH 22	MEDIUM 15

#### Risk Treatments in Place: Articulated Joint Locking Device

This item of plant is fitted with a safety locking device to the articulated joint (either a locking arm or cylinder locking devices) and clear, legible instruction labels on both sides of the articulated joint which state that either of these devices must be engaged during any maintenance to the articulated joint. These must be present, serviceable and employed at all times whilst this item of plant is in operation.

References: AS1319-, AS/NZS4024.1201



#### Risk Treatments in Place: Hydraulic Load Holding Devices - Tippers

The load carrying cylinders to the tipping body on this item of plant fitted with automatic means (e.g. load-holding valves) to prevent uncontrolled movement of the unit in the case of loss of power or hydraulic failure. These devices must be present and fully functional at all times whilst this item of plant is in operation.

References: AS1418.8



CRUSHING

HIGH 22

MEDIUM 15

## Risk Treatments in Place: Tipping Body Prop

The tipping body on this item of plant is fitted with a mechanical safety support and instruction label. These must be fully functional and serviceable at all times. The support must be used when accessing the area under the tipping body for maintenance or any other purpose.

References: AS1418.8



COLLISION

HIGH 22

MEDIUM 15

#### **Risk Treatments in Place: Beacon**

This item of plant is fitted with a safety beacon. This beacon must meet the following criteria at all times whilst this item of plant fitted is in operation

- Is visible up to 200m in all directions (allowing for intermittent obstruction from the plant structure whilst the plant is in operation)
- Is fitted in the most appropriate location on machine to maximise visibility without risking continual damage

NOTE: more than one beacon may be fitted to meet these criteria.

References: ISO20474-

OPERATIONAL MALFUNCTION

HIGH 22

LOW 2

## Risk Treatments in Place: Plant Modification

The plant is in original condition.

References: ISO31000



CRUSHING

HIGH 21

LOW 5

#### Risk Treatments in Place: FOPS General

This item of plant is fitted with a Level I Falling Objects Protective Structure (FOPS). This structure is designed to protect the operator from small falling objects (e.g. bricks, small concrete blocks, hand tools)

Before operating this item of plant a task based risk assessment must be conducted to determine the level of FOPS required.

Level I - withstands 1,365 joules (e.g. 20kgs @ 7m drop, 70kgs @ 2m drop)

- operations such as highway maintenance, landscaping and other construction site services

Level II - withstands 11,600 joules (e.g. 200kgs @ 6m drop, 394kgs @ 3m drop) - operations such as site clearing, overhead demolition or forestry

This task risk assessment must be undertaken before each operation, in particular when the item of plant is moved to a new location, even if it is within the same site.

References: AS2294, ISO10262, ISO3449





HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
INCORRECT OPERATION	HIGH 20	MEDIUM 14

## **Risk Treatments in Place: Intuitive Controls**

The controls fitted to this item of plant are orientated so that the movement of the control is consistent with the action of the machine e.g. moving a control lever to the left results in the machine turning to the left. This design feature must be maintained at all times whilst this item of plant is in operation.

References: AS/NZS4024.1906



STRAINS

HIGH 19

LOW 5

#### Risk Treatments in Place: Controls Ergonomics

All controls including all levers, buttons, pedals, switches etc, are placed near the operator work position and are easy to reach and operate during the execution of the operator's normal duties. This applies for all persons within the 95th percentile of the normal population distribution.

References: AS/NZS4024.1901



STRIKING, BURNS

HIGH 19

LOW 5

#### Risk Treatments in Place: Hydraulic Hose Failure Shield

This item of plant is fitted with a sturdy, permanent shield(s) between the hydraulic hoses and any body parts of the operator to provide protection during a hose or component failure. This shield(s) must be present and fully functional at all times whilst this item of plant is in operation.

References: AS2671, AS4024, ISO4413



SLIPPING, INCORRECT OPERATION

HIGH 17

LOW 6

## Risk Treatments in Place: Control Levers/Pedals/Buttons

All controls including all levers, buttons, pedals, switches etc. must be kept non-slip and free from damage at all times.

References: AS/NZS4024.1901



SLIPPING

MEDIUM 12

LOW 6

## Risk Treatments in Place: Operator Work Area Access/Egress

Safe access and egress to the cabin/work area(s) must be maintained at all times whilst this item of plant is in operation. It must be non slip, free from damage, located at a height so as to not cause undue body stresses and strains with three points of contact available to personnel at all times

All personnel must -

- 1. Always face the item of plant during access and egress.
- 2. Always maintain three points of contact during access and egress.
- 3. Never carry an object(s) in his/her hand(s) during access and egress.
- Never jump off machine.

References: AS3868



SLIPPING, FALLING

MEDIUM 12

LOW 6

## Risk Treatments in Place: Access/Egress Instruction Label

An instruction label is fitted adjacent access/egress areas to advise all personnel of the following -

- 1. Always face the item of plant during access and egress.
- 2. Always maintain three points of contact during access and egress.
- 3. Ensure the steps are clean.
- 4. Never jump off machine.

This label must be clear and legible at all times whilst this item of plant is in operation.

References: ISO31000





## SLIPPING, FALLING, TRIPPING

HAZARD(S)

MEDIUM 12

Prelim. Risk Rating

**Residual Risk Rating** LOW 6

#### Risk Treatments in Place: Engine Bay Access

Safe access and egress to the engine bay/work area(s) must be maintained at all times whilst this item of plant is in operation. It must be non slip, free from damage, located at a height so as to not cause undue body stresses and strains with three points of contact available to personnel at all times.

All personnel must -

- 1. Always face the item of plant during access and egress.
- 2. Always maintain three points of contact during access and egress.
- 3. Never carry an object(s) in his/her hand(s) during access and egress.
- 4. Never jump off machine.

References: AS3868



### **ELECTRIC SHOCK, BURNS**

MFDIUM 12

I OW 6

### Risk Treatments in Place: Battery Cover

All batteries fitted to this item of plant are constrained to prevent displacement & fitted with a permanent sturdy cover which allows for ventilation. The constraint and cover must be present and fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201



#### SLIPPING, INCORRECT OPERATION

MEDIUM 9

LOW 4

#### Risk Treatments in Place: Operator Floor

All work area floors are non-slip and free from damage & debris.

Floor area must remain non-slip and free from damage & debris, including rubbish, tools and other items, at all times whilst this item of plant is in

References: AS/NZS4024.1201, ISO20474-



## **STRAINS**

MEDIUM 9

LOW 1

## Risk Treatments in Place: Operator Seat

The operator seat fitted to this item of plant must remain free from damage and tears, and be permanently and securely fitted at all times.

References: AS/NZS4024.1401, ISO20474-



## **BURNS**

MEDIUM 9

I OW 5

#### **Risk Treatments in Place: Exhaust**

The engine exhaust on this item of plant is fitted with a guard to prevent injury to any person and control the risk of initiating a fire. It must be present and fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201

MAINTENANCE

## **COLLISION, CRUSHING**

**CRITICAL 25** 

MEDIUM 15

## Risk Treatments in Place: Brakes

The brakes fitted to this item of plant must be fully functional at all times whilst this item of plant is in operation. The brakes must be regularly inspected and tested. These inspections and tests must be documented as part of your plant safety programme.

References: AS2958



#### **CURRENT OR PREVIOUS STRUCTURAL DAMAGE**

**CRITICAL 25** 

MEDIUM 15

#### Risk Treatments in Place: Structural Integrity

Regular checks for structural damage must be undertaken. Look for cracks in frames/chassis (current or repaired), bends or damage to structural components, etc.

References: ISO31000





Make Ausa D600 APG Dump Truck - Site Serial Number Assessed By Date

64075270 Paul Rozier 15-Jun-2017

	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
*	INCORRECT OPERATION	HIGH 22	MEDIUM 15

## Risk Treatments in Place: Maintenance Manual

The manufacturer's maintenance manual(s) has been supplied for this item of plant

These manual(s) must be available at all times to all users and maintenance staff of this item of plant. All users and maintenance staff must read and be familiar with these handbook(s) prior to maintaining or repairing this item of plant.

A complete risk assessment/JSEA must be undertaken covering all inspection, maintenance, servicing and transportation requirements of this piece of plant prior to use.

A full assessment of the competence of people using the book(s) must also be undertaken

References: Work Health & Safety Act & Regulations-



CRUSHING

HIGH 22

MEDIUM 15

#### Risk Treatments in Place: ROPS Damage

The Roll Over Protective Structure (ROPS) fitted to this item of plant must remain free from damage at all times whilst this item of plant is in operation.

References: AS2294, ISO3471



STRIKING, BURNS

HIGH 22

MEDIUM 15

## Risk Treatments in Place: Hydraulic Damage

The hydraulic hoses to this item of plant are free from damage and protected against damage arising from contact with the plant structure. Ensure that hoses are free from damage and that protection is in place at all times whilst this item of plant is in operation. Inspection of the hydraulic hoses and protection system should be conducted regularly and documented as part of your plant safety programme.

References: AS2671, AS4024, ISO4413



**OPERATIONAL MALFUNCTION** 

HIGH 22

LOW 2

## Risk Treatments in Place: Major Fluid Leaks

This item of plant must remain free from leaks at all times whilst in operation (this includes engine, transmission, cooling system, air, fuel, drive line, wheel hubs, steering and hydraulics). Development of a major leak will require this item of plant to be stood-down until repaired. Minor leaks detected must be repaired within 1-14 days.

References: ISO31000



**COLLISION, INSTABILITY** 

HIGH 22

MEDIUM 15

### **Risk Treatments in Place: Tyres**

The tyres and wheel components must be inspected as part of a "pre start" checklist. These inspections must be documented as part of your plant safety programme.

References: ISO31000



OPERATIONAL MALFUNCTION

HIGH 21

MEDIUM 15

#### Risk Treatments in Place: Service Records

Service and maintenance records are available for this item of plant.

These records must continue to be maintained and stored in a secure area as part of your plant safety management programme. This programme includes the undertaking of regular inspections concerning the general condition of the item of plant including (but not limited to) tyre condition, oil levels and wear and tear on critical items such as brakes and steering, etc. All OEM prescribed, scheduled and non scheduled maintenance must also be documented as part of these records and attended to within a risk management framework.

References: Work Health & Safety Act & Regulations-

## **SECTION 6 IMAGES AND NOTES**

## **IMAGES**





Make Ausa
Model D600 APG
Type Dump Truck - Site

Serial Number Assessed By Date 64075270 Paul Rozier 15-Jun-2017

Page 14 of 15

ssed By Paul Rozie

## **NOTES**

- No Notes Available -







# **RISK MANAGEMENT REPORT**

TYPE	Dump Truck - Site	Report Number	AHS 20170615-1710
MAKE	Ausa	Date	15-Jun-2017
MODEL	D600 APG	Created By	Paul Rozier
SERIAL NUMBER	64075270	Assessor	Paul Rozier
ENGINE NUMBER	2FG3799	Assist. Assessor(s)	
		Owner	Australian Hammer Supplies Pty Ltd
		Assessment Purpose	Sale
		State	NSW

# **PURCHASER ACKNOWLEDGEMENT**

I the undersigned acknowledge that I have read and understand the risk management report described above. I also acknowledge that I have recieved a copy of this risk management report. I also acknowledge that I am authorised to sign on behalf of the purchaser.

Name
Company Name
Position
Signature
Date
The manufacturer's operational & maintenance handbooks have been supplied, (circle one) YES NO (initial)
Please transfer this assessment to my Plant Assessor membership as a (circle one) HIRE / PLANT IN USE assessment.
My Plant Assessor email is



Dump Truck - Site

Make