

CMS Contracting & Plant Hire Pty Ltd
 ABN 73 143 852 411
 10-12 Churchill Street, SILVERWATER NSW 2128
 Ph 02 9647 1929
 Email accounts@cmscontracting.com.au
 www.cmscontracting.com.au



Form No. 1608

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date	4:29 PM, 10th Apr, 2024	Make	Kubota
Asset	X47	Model	U48-4
Rego Nbr		Serial Number	20167
Location of job	Silverwater	Hours/Odometer	3265
Completed by	Connor Snell	Licence Number	Hayden Rust

Work Required	250 hour service
---------------	------------------

Work Performed	Change engine oil, change engine oil and filter, replace outer air filter, replace pin bolt on arm of machine, check all fluid levels, safety inspection and grease
----------------	---

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease			
Consumables		Hydraulic Oil	Grease 1
Engine Oil	9	Gear Oil	Coolant
Trans Oil		Diff Oil	Enviro Costs

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	2	Total Kilometers	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Hayden Rust
Licence No:	Hayden Rust
Signature:	

CMS Contracting & Plant Hire Pty Ltd

ABN 73 143 852 411

10-12 Churchill Street, SILVERWATER NSW 2128

Ph 02 9647 1929

Email accounts@cmscontracting.com.au

www.cmscontracting.com.au



SERVICE & MAINTENANCE REPORT

Docket # 0046

DATE: 10 - 9 - 2023 MAKE: Kubota
 LOCATION OF JOB: Silverwater MODEL: U48-4
 PLANT NO: X47 SERIAL NO: 20167
 REGO NO: _____ HOURS/KMS: 3020

WORK REQUIRED: 3000 HOUR SERVICE

WORK PERFORMED:
Change engine oil & filter
" fuel filter & drain water separator
" hydraulic oil & 3 filters
" final drive oil
clean hydraulic breather & air precleaner
top up coolant
change air filters
check belts, tracks & track rollers
clean radiator
grease & safety inspection

OUTSTANDING WORK REQUIRED:
change hydraulic tank drain plug
next service.

CONSUMABLES: _____ HYDRAULIC OIL: 45 GREASE: 1
 ENGINE OIL: 10 GEAR OIL: 3 COOLANT: 1
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>5</u>	TOTAL KILOMETERS	
-------------	----------	--------------	----------	------------------	--

PLANT SAFETY CHECK	
Machine Hours	✓
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF
 Serviceperson: Trenton Van Loon
 Licence No.: _____
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.
 Signature: _____