


N6020N

# Propeller Logbook

Dowt  
Hamilton Sundstran  
Hartze  
McCauley  
mt-propelle  
Sensenich



INSTALLING AGENCY PLEASE NOTE  
Recording of Propeller Total Time Since New (TTSN)  
is Required Per F.A.R. 91.417, 121.380 and 135.

290 Larkin Drive • Wheeling, IL 60090-6456 • (847) 541-1133 • (800) 323-4130 • FAX (847) 541-0176 • CRS EY2R811K • EASA.145.51  
[www.aircraftpropeller.com](http://www.aircraftpropeller.com)

Propeller Model D3A34C.402

Blade Model 90DFA-10

Hub Serial No. 785922

Blade Serial No. 1 B93039

2 B93004

3 B94160

4

5

6

1. Approving Civil Aviation Aviation Authority/Country: <b>FAA/UNITED STATES</b>		2. <b>AUTHORIZED RELEASE CERTIFICATE</b> FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: <b>556977</b>	
4. Organization Name and Address: <b>AIRCRAFT PROPELLER SERVICE, LLC</b> 595 TELSER ROAD LAKE ZURICH, IL 60047		EY2R811K		5. Work Order/Contract/Invoice Number: <b>121267 / LUM-1610921</b> w/attached pages 1 thru 2 Dated: 08/17/2016	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	McCAULEY PROPELLER ASSEMBLY	D3A34C402/90DFA-10	1.00	785922	OVERHAULED

12. Remarks:  
OVERHAULED per: BOM100 R: 7 (10/19/2015), MPC24 R: 2.2.2 (12/1/2015), MPC400 R: 4 (7/26/2016), SPM100 R: 6 (10/19/2015)

COMPLIED WITH:  
AD: NONE

S/B: SEE MPC 24

S/L: SEE MPC24

OTHER: NONE

The next action required on this component is within 2,000 HOURS OR 72 MONTHS PER MPC26-04.

	SERIAL #	TSN	TSO/TSMI
ASSEMBLY:	785922	UNK	0.0
HUB:	785922	UNK	0.0
BLADE 1:	B93039	UNK	0.0
BLADE 2:	B93224	UNK	0.0
BLADE 3:	B94160	UNK	0.0

Full detail of the work specified in Block 11 is on file within this agency.



