



**INSURANCE COMPANY NAME
STANDARD REPLACEMENT COST REPORT**

ORDER #: SO011629

Coverage A Amount:	138000
Replacement Cost:	150621
Variance Percentage:	92%

GENERAL INFORMATION

INSURED Happy Homeowner 123 Main Street Happyville, FL 32725	AGENT CODE: 774 ICA Insurance Agency 123-456-7890	POLICY #: ICAH0709148 Effective Date: 08/28/2011 Order Date: 8/8/2011 Inspection Date: 8/24/2011 Inspector: Inspector H
--	--	--

GENERAL DWELLING INFORMATION

Year Built: 1974 How Confirmed? Property Appraiser Dwelling Occupancy: Occupied	Property Access: Flat Area & Easy Access Roads Dwelling Outside City Limits? No Dwellings Count w/in View: 12	Dwelling Type: Single Family # of Families in Dwelling: 1 # Units Attached: N/A # Units b/t Firewalls: N/A Center or End Unit: N/A
Water Exposure: 1650 ft. to Pond 1230 ft. to Lake	Fire Protection: (distance to property) Fire Hydrant: <500 feet Fire Department: <1 miles Responding Fire Department: Happyville Fire Department	

UNDERWRITING INFORMATION

Dwelling in need of repair: No Major cracks in exterior walls: No Roof in need of repair: No Property in poor condition: No Detached structures in need of repair: No Overhanging trees present: No In contact with roof: No	Exterior stairs in need of repair: N/A Stair railings present: N/A Dock in need of repair: N/A Dock railings present: N/A Outdoor appliances present: N/A Outdoor appliances secured: N/A Wood burning stove present: N/A In-ground oil tank present: N/A
Animals Present: No Type: N/A Type: N/A	Business on Property: No Name: N/A Type: N/A # of employees: N/A
Pool on Property: N/A Secured? N/A Hot Tub on Property: Yes Secured? Fenced	Trampoline on Property: N/A Secured? N/A

INTERVIEW		ADDITIONAL CONCERNS
Person Interviewed:	N/A	N/A
Notes:		
N/A		

This report is provided from limited observation and information that may have been obtained in whole or in part, from third parties. Innovative Inspection Service ("IIS") disclaims any responsibility for, and assumes no liability as a result of, inaccuracies and misinformation received by IIS from third party sources. IIS assumes no liability arising from the Replacement Cost Report data in this report which is provided by a third party entity. With this report, the requesting company agrees to hold IIS harmless from any liability arising from the use of this report.

REPLACEMENT COST ESTIMATION

Valuation Total Summary	Coverage A	Coverage B	Cost Data as of: May-11
Reconstruction Cost w/o Debris Removal	\$143,687		
Debris Removal	\$6,934		
Reconstruction Cost with Debris Removal	\$150,621	\$0	Total Living Area 1104 SF

Building Description

Construction Type:	Standard	Year Built	1974
Construction Style:	Ranch	Number of Stories	1

Materials

Foundation: 100% Slab		Exterior Walls:	100% Stucco on Frame
Roof Material: 100% Shingle, Asphalt		Roof Shape:	100% Gable

Wall Finish	Floor Finish	Partition Walls
Paint 89 %	Carpet, Acrylic/Nylon 73 %	Drywall 100 %
Paneling, Sheet 5 %	Tile, Ceramic 17 %	Ceiling Finish
Wallpaper, Vinyl 6 %	Vinyl 10 %	Drywall 100 %

Kitchens & Baths	Heating & Cooling
Kitchen, Builder's Grade 1 Cnt	Air Conditioning
Full Bath, Builder's Grade 2 Cnt	Central Air Conditioning, same duct 100 %
	Heating
	Heating, Electric 100 %

Exterior Features	Garages & Carports
	Attached Garage, 1 Car 1 Cnt

Attached Structures

Open Porch	100 SF
Enclosed Porch	200 SF

Detached Structures

Shed, Small	1 Cnt
Hot Tub	1 Cnt


Uncovered Patio Slab 240 SF

This report is provided from limited observation and information that may have been obtained in whole or in part, from third parties. Innovative Inspection Service ("IIS") disclaims any responsibility for, and assumes no liability as a result of, inaccuracies and misinformation received by IIS from third party sources. IIS assumes no liability arising from the Replacement Cost Report data in this report which is provided by a third party entity. With this report, the requesting company agrees to hold IIS harmless from any liability arising from the use of this report.

Valuation Total Details

Coverage A	Labor	Equipment/Misc.	Material	Total
General Conditions	0	5,006	0	5,006
Sitework	0	0	0	0
Foundations	0	0	0	0
Slab on Grade	2,871	87	4,125	7,083
Framing	12,203	0	11,156	23,359
Roofing	3,745	0	4,955	8,700
Exterior Walls	10,445	223	9,154	19,822
Partitions	4,846	0	2,152	6,998
Wall Finishes	3,449	0	2,551	6,000
Floor Finishes	1,553	0	3,089	4,642
Ceiling Finishes	1,740	12	414	2,166
Equipment	1,653	0	10,107	11,760
Conveying Systems	0	0	0	0
Plumbing Systems	5,552	0	8,731	14,283
HVAC Systems	2,857	0	3,775	6,632
Electrical Systems	3,414	0	2,925	6,339
Attached Structures	7,906	0	12,991	20,897
SUBTOTAL \$:	62,234	5,328	76,125	143,687

FLOOR PLAN



This report is provided from limited observation and information that may have been obtained in whole or in part, from third parties. Innovative Inspection Service ("IIS") disclaims any responsibility for, and assumes no liability as a result of, inaccuracies and misinformation received by IIS from third party sources. IIS assumes no liability arising from the Replacement Cost Report data in this report which is provided by a third party entity. With this report, the requesting company agrees to hold IIS harmless from any liability arising from the use of this report.

PHOTOGRAPHS



Photograph 1

Address

Notes:

N/A



Photograph 2

Front

Notes:

N/A

This report is provided from limited observation and information that may have been obtained in whole or in part, from third parties. Innovative Inspection Service ("IIS") disclaims any responsibility for, and assumes no liability as a result of, inaccuracies and misinformation received by IIS from third party sources. IIS assumes no liability arising from the Replacement Cost Report data in this report which is provided by a third party entity. With this report, the requesting company agrees to hold IIS harmless from any liability arising from the use of this report.

PHOTOGRAPHS



Photograph 3

Right

Notes:

N/A



Photograph 4

Back

Notes:

Hot tub present in photo.

This report is provided from limited observation and information that may have been obtained in whole or in part, from third parties. Innovative Inspection Service ("IIS") disclaims any responsibility for, and assumes no liability as a result of, inaccuracies and misinformation received by IIS from third party sources. IIS assumes no liability arising from the Replacement Cost Report data in this report which is provided by a third party entity. With this report, the requesting company agrees to hold IIS harmless from any liability arising from the use of this report.

PHOTOGRAPHS



Photograph 5

Back

Notes:

N/A



Photograph 6

Back

Notes:

Shed.

This report is provided from limited observation and information that may have been obtained in whole or in part, from third parties. Innovative Inspection Service ("IIS") disclaims any responsibility for, and assumes no liability as a result of, inaccuracies and misinformation received by IIS from third party sources. IIS assumes no liability arising from the Replacement Cost Report data in this report which is provided by a third party entity. With this report, the requesting company agrees to hold IIS harmless from any liability arising from the use of this report.

PHOTOGRAPHS




Photograph 7

Left

Notes:

N/A



Photograph 8

Notes:

N/A

This report is provided from limited observation and information that may have been obtained in whole or in part, from third parties. Innovative Inspection Service ("IIS") disclaims any responsibility for, and assumes no liability as a result of, inaccuracies and misinformation received by IIS from third party sources. IIS assumes no liability arising from the Replacement Cost Report data in this report which is provided by a third party entity. With this report, the requesting company agrees to hold IIS harmless from any liability arising from the use of this report.