

REPORT NO: BNR32-XXXXXX

1990 NISSAN SKYLINE GT-R NISMO (SAMPLE)

Report generated on 2020-05-14

VEHICLE DETAILS GRADE AUTOCHECK GRADING Data Source **Repaired History** The Autocheck grading scheme is based on standard **Reported Date** Japanese auction grading system. it let's you compare similar vehicles with ease. Lot number Chassis ID BNR32-XXXXXX Auction grade Repaired history Make NISSAN Model SKYLINE **Accident / Repair** X Repair & Part exchange Mileage history **Engine CC** 2600 Mileage report Good mileage 1990 Year Grade GT-R NISMO **Use history** Private/Normal N/A Inspection P/S P/W Equipment **Stolen check** No stolen status Transmission F5 Start price ¥1,780,000 **AUTOCHECK FACTS Finish price GUNMETAL** Color Auction grade **Repaired Car** Condition R SOLD with negotiation. **Status** Use history (Sōdan 相談) Good mileage & Vehicle use as a private

NOTE: This Autocheck Vehicle History Report is based only on Information supplied to Autocheck CO. and available as of 2020-05-14 09:25:45. Other information about this vehicle, including problems, may not have been reported to Autocheck CO. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next Japanese used car.

vehicle

HISTORY RECORDS (JAPAN)

Type of record	Reported event	Reported date	Source	Details	Airbag
Accident/Repair	Reported				
Malfunction	Reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

REPORTED ODOMETER HISTORY


Reported date	Kilometres	Source

Image: Sector sector

MANUFACTURE RECALL HISTORY

No records found.

CONDITION SHEET & PHOTOS



Please proceed to the next page to see English Translation of this auction sheet.

CONDITION SHEET ENGLISH TRANSLATION

Auction No.	Vehicle Use		Displacement	Grade	Grade	
	Priv	vate use	2600 cc	GTR NISMO	F	3
6027	Japan Y/M	Make/model	Model code	Door Style	Exterior	Interior
	1990/05	SKYLINE	E-BNR32 改	2D	С	С

Current Inspection (Year/month)		Transr	
	N/A		F
м	ileage in Kms		Air co
			N
original color	change color	color no:	Recyclin
GUNMETAL		KH2	N
Fu	lel	Interior color	
Pe	trol	black	
Seats	Drive type	Drive	
2	2WD	RHD	
Notice			Registrat

Transmission	sunroof	alloy wheel	power steering	power window
F5	-	-	✓	1
Air condition	Leather	ABS	TV/Navi	Airbag
N/A	-	-	-	-
Recycling deposit	Sales point			
N/A	Nismo 500 Modified Car			
	GTR Key			
	Alloy whells			
	BBS. LM Wheels			
	New Tait high edition			
Registration number				
Chassis number		1.1.1	laters.	

Nismo record book

Inspector Report

Hood has been replaced XX

Front right fender replaced XX

Front left fender replaced XX

Repair marks

- Scratch marks A, V
- Scratch mark on windscreen

Repair history on both left & right body W

Dirty Interior

Left back door part exchange history X

Length	Width	Height
454	175	132

A Scratch or crack

- **B** Large Dent
- **C** Corrosion
- S Rust
- U Dent


Χ

AU Scratch & Dent

W Repair History

Part exchange required

XX Part exchange history



CONDITION SHEET EXPLANATION

- A1 Small Scratch
- A2 Scratch
- A3 Big Scratch
- B Dent with scratch

B1 Distortion on (radiator) core support or back panel (approximately size of a thumb)

B2 Big Distortion on (radiator) core support or back panel

B1-B4 Large dents

- C1 Corrosion
- C2 Heavy Corrosion
- AU2 Dent and Scratch (Medium).
- E1 Few Dimples
- E2 Several Dimples
- E3 Many Dimples
- G Stone chip in glass
- **H** Paint faded or (Thumb size hole from rust, corrosion or rotting)
- P Paint damaged marked

- S1 Rust
- S2 Heavy Rust
- **U1** Small Dent
- U2 Dent
- **U3** Big Dent

Y1 Small Hole or Crack

- Y2 Hole or Crack
- Y3 Big Hole or Crack

X1 Small Crack on Windshield (approximately 1cm)

R Repaired Crack on Windshield

RX Repaired Crack on Windshield (needs to be replaced)

- X Needs to be replaced or crack on glass
- XX Replaced
- W1 Repair Mark/Wave (hardly detectable)
- W2 Repair Mark/Wave
- W3 Obvious Repair Mark/Wave (needs to be repainted)

AUCTION GRADE EXPLANATION

- 6 / S New car
- 5 Used but appears as new
- 4.5 Very clean with only minor pin dents & scratches
- 4 Good condition with normal wear & tear
- 3.5 Numerous condition faults / possible minor repair

3 Poor condition / noticeable dents & damage / rust / past repair

- 2 Very poor condition / water damaged
- **1** Modified (usually performance parts)

0 Repaired

R Repaired (History of being repaired, parts replaced, no quality guarantee, buy at your risk, could be big damages, frame bent possibility.)

RA Accident repaired, been in crash, parts replaced, generally small damages.

*** Ungraded (existing fault / damage)

A - D Body / interior condition (A – as new, B – very clean, C – average, D – poor)

E – The car is in bad shape. Rust, corrosion and exterior breakdowns are plenty.





** Verified Photos



1 Chassis number: a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

2 Safety grade: Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

3 Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily - not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely - not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export - not qualified for driving in Japan , the vehicle is determined to be exported

4 Use in the contaminated regions: The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

5 Radioactive contamination test: radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

AUTOCHECK.JP DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY AUTOCHECK.JP OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. AUTOCHECK.JP FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2020 Autocheck Corporation. All rights reserved.