SR8
Example:
Mounting in the reveal

Order dimension A

Order dimension C

Order dimension A1

W

W

50   50   50   50   50   50

Width B   Width B1   Width B2

Measurement LB   Measurement LB1   Measurement LB2

entire measurement GB

SR8
Example:
Mounting in front of the reveal

Measurement LA (measured on axis wind protection)

Order dimension A

Order dimension C

Order dimension A1

Measurement LA1 (measured on axis wind protection)

W

W

50   50   50   50   50   50

Width B   Width B1   Width B2

Measurement LB   Measurement LB1   Measurement LB2