



BINDER LIFT™



BECAUSE HUMANS DON'T
COME WITH HANDLES™

23 Beacon Dr. Cody, WY 82414
855-239-5438 / FX. 866-873-7357
Info@BinderLift.com
www.BinderLift.com

Warranty

Coverage

Every Binder Lift product sold via Binder Lift LLC or through a licensed distributor is covered by a 5 year manufacture warranty. All Binder Lift products have been manufactured and tested to the highest quality standards. This Manufacture Warranty covers defects in materials and workmanship of any Binder Lift product. Binder Lift will send replacement buckles in the rare event that a removable buckle is broken during normal use. If a fixed buckle is broken, or if there is a material defect due to poor workmanship, Binder Lift, at our discretion, will either repair or replace the damaged unit.

What Is Not Covered

Our warranty does not cover any problem that is caused by;

- A. Conditions, malfunctions or damage not resulting from defects in material or workmanship
- B. Conditions, malfunctions or damage from normal wear and tear, improper cleaning procedures, misuse, abuse, negligence, accident, or alteration

Submitting A Claim

To submit a claim the original customer must contact Binder Lift LLC directly to receive a warranty claim number. Upon receiving a claim number, the customer will be expected to pay for shipping to mail the damaged device to the manufacture if workmanship is required to fix the defected device. At manufacture discretion the device will be repaired and mailed back, or a new replacement device will be sent free of charge. Return shipping will be covered by Binder Lift.



www.BinderLift.com

Ph. 855-239-5438 / FX. 866-873-7357 / Email: orders@binderlift.com



Part Replacement and/or Repair Costs

In the rare event that a Binder Lift product needs repair after the warranty has expired, or is defective due to negligence, the customer may replace buckles or repair the device at discounted pricing.

<u>Part/Repair</u>	<u>Unit Price</u>
Replacement Male Buckle	\$3.00
Replacement and attachment of female buckle	\$7.00
Replacement Stitching	Varies \$5.00-30.00