

OWNER: MCGRAW INSURANCE SERVICES
ADDRESS: C/O STUART JET CENTER
STUART FL 34996
PHONE:
FAX:

OPERATOR: MCGRAW INSURANCE SERVICES
ADDRESS: C/O STUART JET CENTER
STUART FL 34996
PHONE:
FAX:

ANALYST: ANTHONY BATCHELOR
EMAIL: ABATCHELOR@CAMPSYSTEMS.COM

877-411-CAMP (2267) (OFFICE)
631-588-3200 (OFFICE)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (FAX)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY; Time Accrued/Remaining: CHECKED;

AIRCRAFT SERIAL/REGNO: 083/N361K **MODEL:** FALCON 900B **MANUFACTURER:** DASSAULT AVIATION S.A.

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	27-FEB-1990	10775.7 A/C HRS	as of 11-OCT-2017	A/C HRS	as of ___/___/___
INSERVICE DATE:	31-JUL-1990	6182 AFL	as of 11-OCT-2017	AFL	as of ___/___/___
		5177.6 APH	as of 11-OCT-2017	APH	as of ___/___/___

APU SERIAL/PART: P192/3800188-2 **MODEL:** GTCP36-150(F) **MANUFACTURER:** HONEYWELL

INSTALLED ON 13-JUN-1990		LAST ACTUALS		CURRENT ACTUAL	
10 APU HRS		5177.6 APU HRS	as of 11-OCT-2017	APU HRS	as of ___/___/___
0 APUS		0 APUS	as of 08-SEP-2017	APUS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: P97304C/3075330-2 **MODEL:** TFE731-5BR-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 17-JAN-2015		LAST ACTUALS		CURRENT ACTUAL	
9206.8 ENG. HRS	9764.1 A/C HRS	10218.4 ENG. HRS	as of 11-OCT-2017	ENG. HRS	as of ___/___/___
5416 ENC		6036 ENC	as of 11-OCT-2017	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: P97301C/3075330-2 **MODEL:** TFE731-5BR-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 22-AUG-2013		LAST ACTUALS		CURRENT ACTUAL	
9196.1 ENG. HRS	9350.9 A/C HRS	10620.9 ENG. HRS	as of 11-OCT-2017	ENG. HRS	as of ___/___/___
5426 ENC		6081 ENC	as of 11-OCT-2017	ENC	as of ___/___/___

ENGINE NO. 3 SERIAL/PART: P97305C/3075330-2 **MODEL:** TFE731-5BR-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 22-AUG-2013		LAST ACTUALS		CURRENT ACTUAL	
9222.2 ENG. HRS	9350.9 A/C HRS	10582.7 ENG. HRS	as of 11-OCT-2017	ENG. HRS	as of ___/___/___
5450 ENC		6131 ENC	as of 11-OCT-2017	ENC	as of ___/___/___



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
+ 05-08-00-200-800-01	1A INSPECTION								
	PKG 1	MOS	8	+1m	-15	20-SEP-2017	05-MAY-2018	05-JUN-2018	199 d
		HRS/MSC	400	+40		10758.2	11158.2	11198.2	382.5
	REF: See Workcard	AFL				6172			
+ 05-08-00-200-800-02	2A INSPECTION								
	PKG 2	MOS	16	+1m	-34	08-FEB-2017	05-MAY-2018	05-JUN-2018	199 d
		HRS/MSC	800	+40	-67.5	10425.7	11158.2	11198.2	382.5
	REF: See Workcard	AFL				6021			
+ 05-08-00-200-800-03	3A INSPECTION								
	PKG 3	MOS	24	+1m	-117	30-AUG-2016	05-MAY-2018	05-JUN-2018	199 d
		HRS/MSC	1200	+40	-254.7	10212.9	11158.2	11198.2	382.5
	REF: See Workcard	AFL				5929			
+ 05-08-00-200-800-04	4A INSPECTION								
	PKG 4	MOS				04-OCT-2004			
		HRS/MSC	N/A			6022.6			
	REF: See Workcard	AFL				3607			
+ 05-08-00-200-800-11	1A+ INSPECTION								
	PKG 11	MOS	8	+1m	-15	20-SEP-2017	05-MAY-2018	05-JUN-2018	199 d
		HRS/MSC				10758.2			
	REF: See Workcard	AFL				6172			
+ 05-08-00-200-800-12	2A+ INSPECTION								
	PKG 12	MOS	16	+1m	-34	08-FEB-2017	05-MAY-2018	05-JUN-2018	199 d
		HRS/MSC				10425.7			
	REF: See Workcard	AFL				6021			
+ 05-08-00-200-800-14	4A+ INSPECTION								
	PKG 14	MOS	32	+1m	-34	08-FEB-2017	05-SEP-2019	05-OCT-2019	687 d
		HRS/MSC				10425.7			
	REF: See Workcard	AFL				6021			
05-08-00-200-800-18	Z INSPECTION								
	PKG 18	MOS	24	+1m	-117	30-AUG-2016	05-MAY-2018	05-JUN-2018	199 d
		HRS/MSC				10212.9			
	REF: GENERIC NO REF	AFL				5929			
+ 05-08-00-200-800-21	1B INSPECTION								
	PKG 21	MOS				20-SEP-2017			
		HRS/MSC	1600	+40		10758.2	12358.2	12398.2	1582.5
	REF: See Workcard	AFL				6172			
+ 05-08-00-200-800-22	2B INSPECTION								
	PKG 22	MOS				23-APR-2013			
		HRS/MSC	3200	+40	-3.1	9161.3	12358.2	12398.2	1582.5
	REF: See Workcard	AFL				5420			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 05-08-00-200-800-23	3B INSPECTION PKG 23 REF: See Workcard	MOS HRS/MSC AFL	4800 +40		-313.5	14-NOV-2009 7871.7	12358.2	12398.2	1582.5
+ 05-08-00-200-800-24	4B INSPECTION PKG 24 REF: See Workcard	MOS HRS/MSC AFL	N/A			31-AUG-2000 4606 2779			
+ 05-08-00-200-800-31	1C INSPECTION PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 +2m 3750			05-MAY-2014 9515 5634	05-MAY-2020 9384	05-JUL-2020	930 d 3202
+ 05-08-00-200-800-32	2C INSPECTION PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144 +2m 7500			05-MAY-2014 9515 5634	05-MAY-2026 13134	05-JUL-2026	3121 d 6952
+ 05-08-00-200-800-33	3C INSPECTION PKG 33 REF: See Workcard	MOS HRS/MSC AFL	N/A			27-FEB-2008 4161			
+ 05-08-00-200-800-34	4C INSPECTION PKG 34 REF: See Workcard	MOS HRS/MSC AFL	N/A			05-MAY-2014 9515 5634			
+ 057120 (s)	NO. 1 300/400 HOUR INSPECTION PKG 42 REF:	MOS HRS/MSC AFL	300			21-JUN-2017 10663 6123			
+ 057120 (s)	NO. 2 300/400 HOUR INSPECTION PKG 52 REF:	MOS HRS/MSC AFL	300			16-JUN-2017 10663 6123			
+ 057120 (s)	NO. 3 300/400 HOUR INSPECTION PKG 62 REF:	MOS HRS/MSC AFL	300			21-JUN-2017 10663 6123			
ENGINE NO. 1 Model : TFE731-5BR Serial # P97304C Part # 3075330-2									
+ 057110	NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION PKG 1 REF:	MOS HRS/MSC ENC	150 +100			15-SEP-2017 10200.9 6026	(10350.9) 10908.2	10450.9	132.5



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 057120	NO. 1 ENGINE - 300 TO 400 HOUR INSPECTION PKG 2	MOS HRS/MSC	300	+100			21-JUN-2017 10105.7	(10405.7) 10963	10505.7	187.3
	REF:	ENC					5977			
057140	NO. 1 ENGINE - 500 TO 850 HOUR INSPECTION PKG 4	MOS HRS/MSC	800	+50			30-AUG-2016 9655.6	(10455.6) 11012.9	10505.6	237.2
	REF:	ENC					5603			
+ 057160	NO. 1 ENGINE - 1000 TO 1400 HOUR INSPECTION PKG 0	MOS HRS/MSC	1200	+200			08-SEP-2017 10200.9	(11400.9) 11958.2	11600.9	1182.5
	REF:	ENC					6026			
057170	NO. 1 ENGINE - 1200 TO 1650 HOUR INSPECTION PKG 5	MOS HRS/MSC	1600	+50			11-NOV-2013 8983.8	(10583.8) 11141.1	10633.8	365.4
	REF:	ENC					5317			
ENGINE NO. 2 Model : TFE731-5BR Serial # P97301C Part # 3075330-2										
+ 057110	NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION PKG 1	MOS HRS/MSC	150	+100			15-SEP-2017 10603.4	(10753.4) 10908.2	10853.4	132.5
	REF:	ENC					6071			
+ 057120	NO. 2 ENGINE - 300 TO 400 HOUR INSPECTION PKG 2	MOS HRS/MSC	300	+100			16-JUN-2017 10508.2	(10808.2) 10963	10908.2	187.3
	REF:	ENC					6022			
057140	NO. 2 ENGINE - 500 TO 850 HOUR INSPECTION PKG 4	MOS HRS/MSC	800	+50			30-AUG-2016 10058.1	(10858.1) 11012.9	10908.1	237.2
	REF:	ENC					5828			
+ 057160	NO. 2 ENGINE - 1000 TO 1400 HOUR INSPECTION PKG 0	MOS HRS/MSC	1200	+200			16-JUN-2017 10508.2	(11708.2) 11863	11908.2	1087.3
	REF:	ENC					6022			
057170	NO. 2 ENGINE - 1200 TO 1650 HOUR INSPECTION PKG 5	MOS HRS/MSC	1600	+50			07-JUN-2013 9127.1	(10727.1) 10881.9	10777.1	106.2
	REF:	ENC					5393			
ENGINE NO. 3 Model : TFE731-5BR Serial # P97305C Part # 3075330-2										
+ 057110	NO. 3 ENGINE - 150 TO 250 HOUR INSPECTION PKG 1	MOS HRS/MSC	150	+100			15-SEP-2017 10565.2	(10715.2) 10908.2	10815.2	132.5
	REF:	ENC					6121			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 057120	NO. 3 ENGINE - 300 TO 400 HOUR INSPECTION PKG 2	MOS HRS/MSC ENC	300	+100		21-JUN-2017 10470 6072	(10770) 10963	10870	187.3
057140	NO. 3 ENGINE - 500 TO 850 HOUR INSPECTION PKG 4	MOS HRS/MSC ENC	800	+50		30-AUG-2016 10019.9 5816	(10819.9) 11012.9	10869.9	237.2
+ 057160	NO. 3 ENGINE - 1000 TO 1400 HOUR INSPECTION PKG 0	MOS HRS/MSC ENC	1200	+200		16-JUN-2017 10470 6072	(11670) 11863	11870	1087.3
057170	NO. 3 ENGINE - 1200 TO 1650 HOUR INSPECTION PKG 5	MOS HRS/MSC ENC	1600	+50		22-AUG-2013 9222.2 5450	(10822.2) 11015.2	10872.2	239.5

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
CHAPTER 00 INFORMATION										
6892-161220	REVIEW MPD CHAPTER 5 REVISION 7						(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF 6892	MOS HRS/MSC - AFL								
APU Model : GTCP36-150(F) Serial # P192 Part # 3800188-2										
A009-161102	APU - REVIEW GTCP36-150(F) SIL APU-56 REV 2						(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF A009	MOS HRS/MSC - APUS								
A009-170607	APU - REVIEW GTCP36-150(F) MM REV 7							10-OCT-2017 5177.6		
REQUIREMENT CHANGE FORMS	REF: RCF A009	MOS HRS/MSC - APUS								
ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P97304C Part # 3075330-2										
E006-170921	NO. 1 ENGINE - REVIEW SB TFE331-72-3263 REV 16						(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF E006	MOS HRS/MSC - ENC								
	NEW REQUIREMENT ADDED ON 12-OCT-2017 (EFFECTIVE: 21-SEP-2017). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.									
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P97301C Part # 3075330-2										
E006-170921	NO. 2 ENGINE - REVIEW SB TFE331-72-3263 REV 16						(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF E006	MOS HRS/MSC - ENC								
	NEW REQUIREMENT ADDED ON 12-OCT-2017 (EFFECTIVE: 21-SEP-2017). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.									
ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P97305C Part # 3075330-2										
E006-170921	NO. 3 ENGINE - REVIEW SB TFE331-72-3263 REV 16						(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF E006	MOS HRS/MSC - ENC								
	NEW REQUIREMENT ADDED ON 12-OCT-2017 (EFFECTIVE: 21-SEP-2017). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.									
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS										
05-50-00-100-801-01	CLEANING AFTER ELECTROLYTE SPILLAGE							27-FEB-1990		
24.270	REF: AMM 05-50-00-100-801	MOS HRS/MSC A/R AFL APH					0 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
05-50-00-200-801-01	CHECK AFTER A TOWING INCIDENT									
09.010		MOS					27-FEB-1990			
	REF: AMM 05-50-00-200-801	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
05-50-00-200-802-01	CHECK AFTER HAILSTORM									
51.110		MOS					27-FEB-1990			
	REF: AMM 05-50-00-200-802	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
05-50-00-200-803-01	CHECK AFTER A LIGHTNING STRIKE									
51.100		MOS					27-FEB-1990			
	REF: AMM 05-50-00-200-803	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
05-50-00-200-804-01	CHECK AFTER A REJECTED TAKE-OFF OR EMERGENCY BRAKING									
32.880		MOS					27-FEB-1990			
	REF: AMM 05-50-00-200-804	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
05-50-00-200-805-01	CHECK AFTER FLYING UNDER EXCESSIVE LOAD FACTOR OR THROUGH EXCESSIVE TURBULENCE									
51.120		MOS					27-FEB-1990			
	REF: AMM 05-50-00-200-805	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
05-50-00-200-806-01	CHECK AFTER AIRCRAFT TILTING BACKWARDS DURING MAINTENANCE OR POWER BACK OPERATION									
		MOS					27-FEB-1990			
	REF: AMM 05-50-00-200-806	HRS/MSC	A/R				0			
		AFL					0			
05-50-00-200-809-01	INSPECTION OF AFTER SLAT EXTENSION IN OVERSPEED CONDITION									
57.305		MOS					27-FEB-1990			
	REF: AMM 05-50-00-200-809	HRS/MSC	A/R				0			
		AFL					0			
05-50-00-200-810-01	INSPECTION AFTER FLAP EXTENSION IN OVERSPEED CONDITION									
57.310		MOS					27-FEB-1990			
	REF: AMM 05-50-00-200-810	HRS/MSC	A/R				0			
		AFL					0			
05-50-00-200-812-01	INSPECTION AFTER LANDING GEAR EXTENSION IN OVERSPEED CONDITION									
		MOS					27-FEB-1990			
	REF: AMM 05-50-00-200-812	HRS/MSC	A/R				0			
		AFL					0			
05-50-00-200-813-01	CHECK AFTER WHEEL IMPACT WITH AN OBSTACLE AT TAKE OFF OR LANDING									
		MOS					27-FEB-1990			
	REF: AMM 05-50-00-200-813	HRS/MSC	A/R				0			
		AFL					0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
05-50-00-620-801-01	SPECIFIC MAINTENANCE FOR A/C OPERATING IN CORROSIVE AMBIENT CONDITIONS - INSPECTION AND ANTI-CORROSION TREATMENT AT SHORT TIME INTERVALS	MOS					27-FEB-1990			
	REF: AMM 05-50-00-620-801	HRS/MSC	A/R				0			
		AFL					0			
05-50-00-620-801-02	SPECIFIC MAINTENANCE FOR A/C OPERATING IN CORROSIVE AMBIENT CONDITIONS - INSPECTION AND ANTI-CORROSION TREATMENT AT MEDIUM TIME INTERVALS	MOS					27-FEB-1990			
	REF: AMM 05-50-00-620-801	HRS/MSC	A/R				0			
		AFL					0			
05-50-00-620-803-01	PERFORM SPECIFIC MAINTENANCE FOR A/C OPERATING IN COLD WEATHER	MOS					27-FEB-1990			
05.020	REF: AMM 05-50-00-620-803	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
05-50-00-620-804-01	PERFORM PROCEDURES FOR AIRCRAFT PROLONGED OPERATION AT LOW TEMPERATURES	MOS					27-FEB-1990			
51.130	REF: AMM 05-50-00-620-804	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
05-50-00-700-801-01	CHECK AND DECONTAMINATION OF THE AIR CONDITIONING SYSTEM AFTER POLLUTION	MOS					27-FEB-1990			
	REF: AMM 05-50-00-700-801	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
05-50-00-700-803-01	CHECK AFTER FIRE EXTINGUISHER PERCUSSION	MOS					27-FEB-1990			
20.050	REF: See Workcard	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
05-50-00-700-806-01	CHECK AFTER LANDING ON A TAR-MACADAM RUNWAY IN VERY HOT WEATHER	MOS					27-FEB-1990			
	REF: AMM 05-50-00-700-806	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
05-50-00-700-807-01	CHECK AFTER LANDING ON A DRY AND DIRTY RUNWAY	MOS					27-FEB-1990			
32.850	REF: AMM 05-50-00-700-807	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
05-50-00-700-808-01	CHECK AFTER HARD / OVERWEIGHT LANDING	MOS					27-FEB-1990			
32.840	REF: AMM 05-50-00-700-808	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
05-50-00-700-810-01	CHECK AFTER A FLIGHT THROUGH SAND	MOS					27-FEB-1990			
	REF: AMM 05-50-00-700-810	HRS/MSC	A/R				0			
		AFL					0			
05-50-00-700-822-01	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES	MOS					27-FEB-1990			
	REF: AMM 05-50-00-700-822	HRS/MSC	A/R				0			
		AFL					0			
05-50-00-730-801-01	CHECK FILTER CLOGGING AFTER INCIDENT ON THE HYDRAULIC SYSTEM	MOS					27-FEB-1990			
29.290	REF: AMM 05-50-00-730-801	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
05-50-00-730-801-02	CHECK PUMP FAILURE AFTER INCIDENT ON THE HYDRAULIC SYSTEM	MOS					27-FEB-1990			
29.300	REF: AMM 05-50-00-730-801	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
05-50-00-730-802-01	CHECK OF THE BRAKING SYSTEM AT ACCELERATION/STOP AFTER TROUBLESHOOTING	MOS					27-FEB-1990			
	REF: AMM 05-50-00-730-802	HRS/MSC	A/R				0			
		AFL					0			
05-50-00-910-801-01 (s)	FLIGHT CHECK AIRCRAFT						PKG			
51.070	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 05-50-00-910-801	HRS/MSC					9515			
		AFL	3750				5634			
+ 05-60-00-200-801-01	PERFORM BASIC INSPECTION - BASIC INSPECTION	DAYS		+40			21-JUN-2017			
05.010	REF: AMM 05-60-00-200-801	HRS/MSC	200	+40	-50.1		10663	10812.9	10852.9	37.2 (+40)
		AFL					6123			
05-60-00-200-801-03	PERFORM BASIC INSPECTION - SERVICING OPERATIONS	DAYS		+40			21-JUN-2017			
05.010	REF: AMM 05-60-00-200-801	HRS/MSC	200	+40	-50.1		10663	10812.9	10852.9	37.2 (+40)
		AFL					6123			
ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P97304C Part # 3075330-2										
E006-170919	NO. 1 ENGINE - REVIEW TFE731-5BR LMM TR 72-232									
		MOS					(EBT)			
		HRS/MSC	-							
REQUIREMENT CHANGE FORMS	REF: RCF E006	ENC								
NEW REQUIREMENT ADDED ON 16-OCT-2017 (EFFECTIVE: 19-SEP-2017). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.										
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P97301C Part # 3075330-2										

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
E006-170919	NO. 2 ENGINE - REVIEW	TFE731-5BR LMM TR 72-232					(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF E006	MOS HRS/MSC - ENC								
NEW REQUIREMENT ADDED ON 16-OCT-2017 (EFFECTIVE: 19-SEP-2017). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.										
ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P97305C Part # 3075330-2										
E006-170919	NO. 3 ENGINE - REVIEW	TFE731-5BR LMM TR 72-232					(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF E006	MOS HRS/MSC - ENC								
NEW REQUIREMENT ADDED ON 16-OCT-2017 (EFFECTIVE: 19-SEP-2017). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.										
CHAPTER 09 TOWING AND TAXING										
09-10-00-910-810-01	DEBOGGING THE AIRCRAFT									
		MOS HRS/MSC A/R						27-FEB-1990	0	
	REF: AMM 09-10-00-910-810	AFL APH						0	0	0
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV										
10-10-00-200-801-01	CHECK AFTER PARKING OF THE AIRCRAFT IN HIGH WIND CONDITION									
		MOS HRS/MSC A/R						27-FEB-1990	0	
	REF: AMM 10-10-00-200-801	AFL APH						0	0	0
10-10-00-550-801-01	STORAGE OF THE AIRCRAFT FOR A MAXIMUM DURATION OF TWO MONTHS									
20.090		MOS HRS/MSC O/C						27-FEB-1990	0	
	REF: AMM 10-10-00-550-801	AFL APH						0	0	0
10-10-00-550-801-02	STORAGE OF THE AIRCRAFT FOR A MAXIMUM DURATION OF TWO MONTHS TO TWELVE MONTHS									
20.090		MOS HRS/MSC O/C						27-FEB-1990	0	
	REF: AMM 10-10-00-550-801	AFL APH						0	0	0
10-10-00-550-801-04	PERFORM PERIODIC CHECKS EVERY MONTH DURING THE STORAGE PERIOD									
20.090		MOS HRS/MSC O/C						27-FEB-1990	0	
	REF: AMM 10-10-00-550-801	AFL APH						0	0	0
10-10-00-550-801-05	PERFORM PERIODIC CHECKS EVERY TWO MONTHS DURING THE STORAGE PERIOD									
20.090		MOS HRS/MSC O/C						27-FEB-1990	0	
	REF: AMM 10-10-00-550-801	AFL APH						0	0	0

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
10-10-00-550-801-06	PERFORM PERIODIC CHECKS EVERY SIX MONTHS DURING THE STORAGE PERIOD									
20.090	REF: AMM 10-10-00-550-801	MOS HRS/MSC AFL APH	O/C				27-FEB-1990 0 0 0			
10-10-00-550-801-07	REMOVAL FROM STORAGE AFTER TWO MONTHS									
20.090	REF: AMM 10-10-00-550-801	MOS HRS/MSC AFL APH	O/C				27-FEB-1990 0 0 0			
10-10-00-550-801-08	REMOVAL FROM STORAGE AFTER MORE THAN TWO MONTHS									
20.090	REF: AMM 10-10-00-550-801	MOS HRS/MSC AFL APH	O/C				27-FEB-1990 0 0 0			
10-20-00-910-802-01	PERFORM MOORING THE AIRCRAFT IN CASE OF SNOWFALL									
10.010	REF: AMM 10-20-00-910-802	MOS HRS/MSC AFL APH	A/R				27-FEB-1990 0 0 0			
CHAPTER 11		PLACARDS AND MARKINGS								
11-00-00-210-801-01 (s)	INSPECTION OF THE INTERIOR AND EXTERIOR PLACARDS						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
	REF: See Workcard		3750							
CHAPTER 20		STANDARD PRACTICES - AIRFRAME								
20-00-00-910-801-01	GENERAL MAINTENANCE INSTRUCTIONS - GENERAL MAINTENANCE AND SAFETY PRECAUTIONS									
20.000	REF: AMM 20-00-00-910-801	MOS HRS/MSC AFL	A/R				05-MAY-2014 9515 5634			
20-00-00-910-803-01	GENERAL MAINTENANCE INSTRUCTIONS - USE OF THE AIRCRAFT MAINTENANCE PROCEDURES									
20.010	REF: AMM 20-00-00-910-803	MOS HRS/MSC AFL APH	A/R				27-FEB-1990 0 0 0			
20-00-00-910-805-01	GENERAL MAINTENANCE INSTRUCTIONS - MAINTENANCE INSTRUCTION SPECIFIC TO A/C 001									
20.030	REF: AMM 20-00-00-910-805	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
20-00-00-910-806-01	GENERAL MAINTENANCE INSTRUCTIONS - MAINTENANCE INSTRUCTION SPECIFIC TO A/C 002									
20.040	REF: AMM 20-00-00-910-806	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-30-00-330-801-01	PERFORM TEMPORARY REPAIR AFTER MINOR DAMAGE TO A COMPOSITE MATERIAL COMPONENT									
51.090	REF: AMM 20-30-00-330-801	MOS HRS/MSC AFL APH	A/R				27-FEB-1990 0 0 0			
20-31-00-140-801-01	PERFORM RINSING THE AIRCRAFT EXTERIOR									
20.060	REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
20-31-00-910-801-01	PERFORM ON-GROUND DE-ICING AND ANTI-ICING TREATMENT									
20.070	REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
20-33-00-300-804-01	REPAIR (TEMPORARY) OF A HYDRAULIC OR WATER PIPE USING RYNGLOK FITTINGS									
	REF: AMM 20-33-00-300-804	MOS HRS/MSC AFL APH	A/R				27-FEB-1990 0 0 0			
20-60-00-370-813-01	PERFORM APPLICATION OF THE PAINT SCHEME ON COMPOSITE COMPONENTS									
20.080	REF: See Workcard	MOS HRS/MSC AFL	A/R				27-FEB-1990 0 0			
CHAPTER 21 AIR CONDITIONING										
21-20-01-350-801-01	RESTORATION (OVERHAUL) LH FLOW LIMITER									
21.020	2742A020100	MOS					05-MAY-2014			
OVERHAUL	061	HRS/MSC	4500	+3%			9515	14015	14150	3239.3 (+135)
	REF: AMM 21-20-01-350-801	AFL					5634			
21-20-01-350-801-02	RESTORATION (OVERHAUL) RH FLOW LIMITER									
21.020	2742A020100	MOS					05-MAY-2014			
OVERHAUL	173	HRS/MSC	4500	+3%			9515	14015	14150	3239.3 (+135)
	REF: AMM 21-20-01-350-801	AFL					5634			
21-20-01-900-801-01	LH FLOW LIMITER									
21.020	2742A020100	MOS					05-MAY-2014			
	061	HRS/MSC	O/C				9515			
	REF: AMM 21-20-01-900-801	AFL					5634			
21-20-01-900-801-02	RH FLOW LIMITER									
21.020	2742A020100	MOS				TSO:2	05-MAY-2014			
	173	HRS/MSC	O/C			TSO:0	9515			
	REF: AMM 21-20-01-900-801	AFL				TSO:0	5634			
+ 21-28-00-710-801-01 (s)	OPERATIONAL TEST EFIS VENTILATION SYSTEM						PKG			
21.175	PKG 21	MOS					20-SEP-2017			
	REF: AMM 21-28-00-710-801	HRS/MSC	1600	+40			10758.2			
		AFL					6172			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 21-30-00-790-802-01 (s)	PERFORM IN-FLIGHT CHECK OF THE CABIN SEALING PKG 21	MOS					PKG 20-SEP-2017 10758.2 6172			
21.180	REF: AMM 21-30-00-790-802	HRS/MSC AFL	1600	+40						
21-30-01-900-801-01	AUTOMATIC PRESSURIZATION CONTROLLER 22250J030800	MOS					27-FEB-1990 0 0			
21.280	REF: AMM 21-30-01-900-801	HRS/MSC AFL	O/C		TSN:0					
+ 21-30-09-720-801-01	FUNCTIONAL TEST ALTITUDE/DELTA P TRIPLE INDICATOR ALTITUDE ALERT 3311AJ44	MOS					11-JAN-2010 7635.9			
21.290	REF: AMM 21-30-09-720-801	HRS/MSC AFL	4000	+3%				11635.9	11755.9	860.2 (+120)
21-31-00-720-801-01 (s)	FUNCTIONAL TEST OF THE NOSE CONE PRESSURIZATION SYSTEM - PNEUMATIC ACTUATOR (506HP) PKG 21	MOS					PKG 20-SEP-2017 10758.2 6172			
	REF: AMM 21-31-00-720-801	HRS/MSC AFL	1600	+40						
21-31-00-720-801-02 (s)	FUNCTIONAL TEST OF THE NOSE CONE PRESSURIZATION SYSTEM - PRESSURE RELIEF VALVE (507HP) PKG 21	MOS					PKG 20-SEP-2017 10758.2 6172			
	REF: AMM 21-31-00-720-801	HRS/MSC AFL	1600	+40						
+ 21-31-01-720-801-01 (s)	FUNCTIONAL TEST OF THE NOSE CONE THERMOSTAT OVERHEAT INDICATING SYSTEM PKG 21	MOS					PKG 20-SEP-2017 10758.2 6172			
21.150	REF: AMM 21-31-01-720-801	HRS/MSC AFL	1600	+40						
21-31-09-350-801-01	RESTORATION NOSE CONE VENTILATION FAN (REPLACEMENT OF BEARINGS) EVT608A	MOS					23-DEC-2015 10135 5897		12535	1759.3
	REF: AMM 21-31-09-350-801	HRS/MSC AFL	2400							
21-31-09-350-802-01	RESTORATION NOSE CONE VENTILATION FAN (REPLACEMENT OF BEARINGS AND CHECK OF BRUSHES) EVT608A	MOS								
	REF: AMM 21-31-09-350-802	HRS/MSC AFL	N/A							
+ 21-31-09-710-801-01 (s)	OPERATIONAL TEST OF THE NOSE CONE VENTILATION FAN PKG 3	MOS					PKG 30-AUG-2016 10212.9 5929			
21.160	REF: AMM 21-31-09-710-801	HRS/MSC AFL	24 1200	+1m +40						
21-31-09-900-801-01	NOSE CONE VENTILATION FAN EVT608A	MOS					23-DEC-2015 10135 5897			
21.160	REF: AMM 21-31-09-900-801	HRS/MSC AFL	O/C		TSO:0 TSO:0 TSO:0					
21-31-25-220-801-01	CHECK/REPLACEMENT NOSE CONE VENTILATION FAN BRUSHES EVT608A	MOS					23-DEC-2015 10135 5897		11375	599.3
	REF: AMM 21-31-25-220-801	HRS/MSC AFL	1240							

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 21-32-00-710-801-01 (s)	OPERATIONAL TEST OF THE CABIN PRESSURIZATION SYSTEM						PKG			
21.200	PKG 21 REF: AMM 21-32-00-710-801	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
+ 21-32-00-710-802-01 (s)	OPERATIONAL TEST OF THE PRESSURIZATION SYSTEM EMERGENCY SUPPLY						PKG			
21.190	PKG 21 REF: AMM 21-32-00-710-802	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
21-32-00-790-801-01 (s)	LEAK CHECK OF THE AROUND THE LH STATIC PRESSURE PROBES						PKG			
	PKG 16,18,203 REF: AMM 21-32-00-790-801	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
21-32-00-790-801-02 (s)	LEAK CHECK OF THE AROUND THE RH STATIC PRESSURE PROBES						PKG			
	PKG 16,18,203 REF: AMM 21-32-00-790-801	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
21-32-00-790-801-03	LEAK CHECK AROUND LH STAND-BY STATIC PRESSURE PROBE						PKG			
	PKG 16 REF: AMM 21-32-00-790-801	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
21-32-00-790-801-04	LEAK CHECK AROUND RH STAND-BY STATIC PRESSURE PROBE						PKG			
	PKG 16 REF: AMM 21-32-00-790-801	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
21-32-06-200-801-01	CLEANING ELECTROPNEUMATIC VALVE SEAT									
21.260	2097D020700 256 REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640	+3%			06-NOV-2014 9738 5733	11378	11427.2	602.3 (+49.2)
21-32-06-200-801-02	CLEANING PNEUMATIC VALVE SEAT									
21.270	2099E010700 211 REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640	+3%			06-NOV-2014 9738 5733	11378	11427.2	602.3 (+49.2)
+ 21-32-06-200-801-03	CHECK ELECTROPNEUMATIC VALVE OVERPRESSURE TIGHTNESS									
21.260	2097D020700 256 REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640				05-MAY-2014 9515 5634	11155		379.3
+ 21-32-06-200-801-03A	CHECK ELECTROPNEUMATIC VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)									
21.260 MANDATORY 5-40	2097D020700 256 REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640				05-MAY-2014 9515 5634	11155		379.3
+ 21-32-06-200-801-04	CHECK PNEUMATIC VALVE OVERPRESSURE TIGHTNESS									
21.270	2099E010700 211 REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640				05-MAY-2014 9515 5634	11155		379.3

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 21-32-17-720-801-01 (s)	FUNCTIONAL TEST OF THE OF THE NO. 1 BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE						PKG			
21.350	PKG 31 REF: AMM 21-32-17-720-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
+ 21-32-17-720-801-02 (s)	FUNCTIONAL TEST OF THE OF THE NO. 2 BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE						PKG			
21.360	PKG 31 REF: AMM 21-32-17-720-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
+ 21-32-33-710-801-01 (s)	OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT ISOLATION ELECTRIC VALVE (INDICATING)						PKG			
21.120	PKG 1,5 REF: AMM 21-32-33-710-801	MOS HRS/MSC AFL	8 400	+1m +40			20-SEP-2017 10758.2 6172			
+ 21-32-37-200-801-01 (s)	INSPECTION OF THE BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVES						PKG			
21.370	PKG 21 REF: AMM 21-32-37-200-801	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
+ 21-32-37-720-801-01	FUNCTIONAL TEST NO. 1 BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVE									
21.370	2827A01 377 REF: AMM 21-32-37-720-801	MOS HRS/MSC AFL	4000	+3%			11-JAN-2010 7635.9	11635.9	11755.9	860.2 (+120)
+ 21-32-37-720-801-02	FUNCTIONAL TEST NO. 2 BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVE									
21.380	2827A01 369 REF: AMM 21-32-37-720-801	MOS HRS/MSC AFL	4000	+3%			11-JAN-2010 7635.9	11635.9	11755.9	860.2 (+120)
21-32-37-900-801-01	NO. 1 BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVE									
21.370	2827A01 377 REF: AMM 21-32-37-900-801	MOS HRS/MSC AFL	O/C				11-JAN-2010 7635.9			
21-32-37-900-801-02	NO. 2 BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVE									
21.380	2827A01 369 REF: AMM 21-32-37-900-801	MOS HRS/MSC AFL	O/C				11-JAN-2010 7635.9			
+ 21-32-41-200-801-01 (s)	INSPECTION OF THE OF THE ANTI-NICOTINE FILTER CARTRIDGE						PKG			
21.250	PKG 31 REF: AMM 21-32-41-200-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
+ 21-52-00-710-801-01 (s)	OPERATIONAL TEST OF THE WATER REINJECTION SYSTEM						PKG			
21.440	PKG 22 REF: AMM 21-52-00-710-801	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
21-52-05-350-801-01	RESTORATION TURBOCOOLER (OVERHAUL)									
21.410 OVERHAUL	3269B0202 00390 REF: AMM 21-52-05-350-801	MOS HRS/MSC AFL	3000	+3%			24-JUN-2011 8305.4 4964	11305.4	11395.4	529.7 (+90)

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-52-05-610-801-01	TOP UP OF THE TURBOCOOLER OIL	MOS HRS/MSC O/C AFL					25-SEP-2005 6221.6 3737			
	REF: AMM 21-52-05-610-801									
21-52-05-610-801-02 (s)	DRAINING AND REFILLING OF THE TURBOCOOLER OIL	MOS	16	+1m			08-FEB-2017 10425.7 6021			
	PKG 2,5,201	HRS/MSC AFL	800	+40						
	REF: AMM 21-52-05-610-801									
21-52-05-900-801-01	TURBOCOOLER	MOS					24-JUN-2011 8305.4 4964			
21.410	3269B0202 00390	HRS/MSC AFL	H/T		TSO:1 TSO:0 TSO:0					
	REF: AMM 21-52-05-900-801									
+ 21-52-09-210-802-01 (s)	GENERAL VISUAL INSPECTION ECU HEAT EXCHANGER GRID	MOS	8	+1m			20-SEP-2017 10758.2 6172			
	PKG 11	HRS/MSC AFL								
	REF: AMM 21-52-09-210-802									
21-52-17-900-801-01	HIGH PRESSURE WATER SEPARATOR	MOS					27-FEB-1990 0 0			
21.420	8903D03 130	HRS/MSC AFL	O/C		TSN:0					
	REF: AMM 21-52-17-900-801									
21-52-18-100-801-01 (s)	CLEAN OF THE HIGH PRESSURE WATER SEPARATOR FILTER	MOS	24	+1m			30-AUG-2016 10212.9 5929			
	PKG 3	HRS/MSC AFL	1200	+40						
	REF: AMM 21-52-18-100-801									
21-52-19-200-801-01 (s)	INSPECTION/CHECK OF THE LOW PRESSURE WATER SEPARATOR OF THE LP WATER SEPARATOR COMPONENTS	MOS	8	+1m			20-SEP-2017 10758.2 6172			
	PKG 11	HRS/MSC AFL								
	REF: AMM 21-52-19-200-801									
21-52-21-350-801-01	RESTORATION EXCHANGER TURBO TURBOFAN (OVERHAUL)	MOS					30-AUG-2016 10212.9 5929	8929		2747
21.400	TVT107-28H4 307	HRS/MSC AFL	3000							
	REF: AMM 21-52-21-350-801									
21-52-21-900-801-01	EXCHANGER TURBO TURBOFAN	MOS					30-AUG-2016 10212.9 5929			
21.400	TVT107-28H4 307	HRS/MSC AFL	H/T		TSO:2 TSO:0 TSO:0					
	REF: AMM 21-52-21-900-801									
+ 21-71-01-350-801-01	RESTORATION NO. 1 OZONE CONVERTER (FUNCTIONAL TEST AND CLEANING)	MOS	5000	+3%			05-MAY-2014 9515 5634	14515	14665	3739.3 (+150)
	20425-1 6128	HRS/MSC AFL								
	REF: AMM 21-71-01-350-801									
+ 21-71-01-350-801-02	RESTORATION NO. 2 OZONE CONVERTER (FUNCTIONAL TEST AND CLEANING)	MOS	5000	+3%			05-MAY-2014 9515 5634	14515	14665	3739.3 (+150)
	20425-1 6164	HRS/MSC AFL								
	REF: AMM 21-71-01-350-801									

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-90-01-900-801-01	AFT AVIONICS RACK COOLING VALVE PN NOT INSTALLED REF: GENERIC CMM	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0 0			
212121	LH COLD AIR CHECK VALVE CYLB50713-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
212131	RH COLD AIR CHECK VALVE CYLB50713-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
212141	AERATOR PRESSURE REGULATING VALVE B17DA1002 T506 REF:	MOS HRS/MSC AFL	O/C				02-MAY-2008 6968.3 4165			
212151	AERATOR CHECK VALVE CYLB50712 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
212161	PASSENGER COMPARTMENT COLD AIR CHECK VALVE CYLB51162 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
212171	CREW COLD AIR CHECK VALVE CYLB51162 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
212181	PILOT AERATOR 2368 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
212191	COPILOT AERATOR 2368 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
212251	PASSENGER COMPARTMENT AIR CONDITIONING CHECK VALVE CYLB51111 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
212261	CREW AIR CONDITIONING CHECK VALVE CYLB51111 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
212271	BAGGAGE COMPARTMENT ELECTRIC CHECK VALVE CYLB50414	MOS					27-FEB-1990			
21.080	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
212281	FRONT PRECONDITIONING FLOOD DUCT PN	MOS					27-FEB-1990			
21.090	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
212291	REAR PRECONDITIONING FLOOD DUCT PN	MOS					27-FEB-1990			
21.090	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
212321	NOSE CONE ISOLATION RESTRICTOR VALVE BYLB51003	MOS					27-FEB-1990			
21.100	196 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
212341	COCKPIT/CABIN SYSTEM INTERCONNECTION FLAP ASSEMBLY BYLB51603	MOS					27-FEB-1990			
21.110	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
212361	BAGGAGE COMPARTMENT ISOLATION ELECTRIC VALVE 3188-000	MOS					27-FEB-1990			
21.120	97 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
212381	BAGGAGE COMPARTMENT SUPPLY ELECTRIC VALVE B97-26-551	MOS					27-FEB-1990			
21.130	20183 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
212401	COCKPIT CONDITIONING ELECTRIC VALVE BYLB51003	MOS					27-FEB-1990			
21.140	206 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
212421	CABIN CONDITIONING ELECTRIC VALVE BYLB51003	MOS					27-FEB-1990			
21.140	196 REF: AMM 21-20-00-900-801	HRS/MSC AFL	O/C	TSN:0			0 0			
212441	NOSE CONE THERMOSTAT 784-756-1	MOS					27-FEB-1990			
21.150	207 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
213101	NO. 1 ENGINE PRESSURE SUPPLY CHECK VALVE 2506AC01	MOS					27-FEB-1990			
21.230	1115 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
213121	NO. 2 ENGINE PRESSURE SUPPLY CHECK VALVE 2506AC01	MOS					27-FEB-1990			
21.230	1129 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
213127	APU SUPPLY PRESSURE CHECK VALVE 2506AC01	MOS					27-FEB-1990			
21.230	1093 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
213131	PRESSURIZATION JET PUMP FGFB722602A2	MOS					27-FEB-1990			
21.240	69 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
213141	ANTI-NICOTINE FILTER 234A0101	MOS					27-FEB-1990			
21.250	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
213261	ALTITUDE/DELTA P TRIPLE INDICATOR 3311AJ44	MOS					11-JAN-2010			
21.290	212 REF:	HRS/MSC AFL	O/C	TSO:0 TSO:0			7635.9			
213281	EMERGENCY PRESSURIZATION PANEL 911A0301	MOS					27-FEB-1990			
21.300	209 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
213301	NOSE CONE PNEUMATIC ACTUATOR 7021-000	MOS					27-FEB-1990			
21.310	372 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
213321	PNEUMATIC ACTUATOR CONTROLLED VALVE PN	MOS					27-FEB-1990			
21.320	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
213331	NOSE CONE PRESSURE RELIEF VALVE 6025-300	MOS					20-JUN-2000			
21.330	193 REF:	HRS/MSC AFL	O/C				4516.5			
213351	NOSE CONE ISOLATION VALVE B97M19-203-1	MOS					27-FEB-1990			
21.335	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
213501	NO. 1 BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE 985C63-21	MOS					05-MAY-2014			
21.350	200 REF:	HRS/MSC AFL	O/C	TSR:3 TSN:9515 TSR:0			9515 5634			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
213531	NO. 2 BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE									
21.360	985C63-21 202 REF:	MOS HRS/MSC AFL	O/C	TSR:3 TSN:9515 TSR:0			05-MAY-2014 9515 5634			
215101	PRIMARY HEAT EXCHANGER									
21.390	11-831149-1 74 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0			26-SEP-2006 6419.2			
215181	NO. 1 HIGH PRESSURE/LOW PRESSURE TURBINE BRAKE CHECK VALVE									
21.405	2506AC01 1191 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
215191	NO. 2 HIGH PRESSURE/LOW PRESSURE TURBINE BRAKE CHECK VALVE									
21.405	2506AC01 1190 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
215271	LOW PRESSURE WATER SEPARATOR									
21.430	PN-UNKNOWN SN-UNKNOWN REF: AMM 21-52-19-200-801	MOS HRS/MSC AFL	O/C	TSR:4 TSR:0 TSR:0			30-AUG-2016 10212.9 5929			
215301	TURBINE ANTI-ICING AMPLIFIER									
21.450	784-688-1 0112 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			09-NOV-2011 8483.5 5057			
215311	TURBINE ANTI-ICING TUBING SENSOR									
21.450	784-646 1072 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-SEP-2017 10758.2 6172			
215321	TURBINE ANTI-ICING ELECTRIC VALVE									
21.450	784723-3 793 REF: AMM 21-52-33-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:327 TSR:0			20-SEP-2017 10758.2 6172			
215331	BLOWER BY-PASS ELECTRIC VALVE									
21.460	BYLB51035-1 196 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
215341	ECU OVERHEATING SENSOR									
21.460	RP129-00 761 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
215A04	WATER TRAP LP COALESCER									
	B31WA3010-053 01158 REF:	MOS HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			08-FEB-2017 10425.7 6021			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
216101	CONDITIONING BOX									
21.470	5897-65-80-13 666 REF:	MOS HRS/MSC AFL	O/C				10-MAR-2009 7314 4377			
216111	COCKPIT THERMO RESISTOR									
21.470	HYLZ50514-32 568 REF:	MOS HRS/MSC AFL	O/C				07-JAN-2008 6903.5			
216121	CABIN THERMO RESISTOR									
21.470	HYLZ50414-31 1145J REF:	MOS HRS/MSC AFL	O/C			10/28/2004	28-OCT-2003 5640.1 3409			
216131	COCKPIT TEMPERATURE REGULATION DUAL ELECTRIC VALVE									
21.480	BYLB51034-003 95 REF:	MOS HRS/MSC AFL	O/C			TSR:0 TSR:0 TSR:0	18-DEC-2015 10130 5895			
216141	CABIN TEMPERATURE REGULATION DUAL ELECTRIC VALVE									
21.480	BYLB51226-002 185 REF:	MOS HRS/MSC AFL	O/C			TSO:28 TSO:0 TSO:0	19-APR-2013 9161.3 5420			
216151	COCKPIT SHEATH SENSOR									
21.490	AYLF50425 935 REF:	MOS HRS/MSC AFL	O/C			TSN:0	27-FEB-1990 0 0			
216161	CABIN SHEATH SENSOR									
21.490	AYLF50425 2446 REF:	MOS HRS/MSC AFL	O/C				17-JAN-2007 6495.9			
216171	COCKPIT THERMOSTAT									
21.500	150T346 547 REF:	MOS HRS/MSC AFL	O/C			TSN:0	27-FEB-1990 0 0			
216191	CABIN THERMOSTAT									
21.500	150T346 546 REF:	MOS HRS/MSC AFL	O/C			TSN:0	27-FEB-1990 0 0			
CHAPTER 22 AUTO FLIGHT										
+ 22-10-00-710-801-01 (s) OPERATIONAL TEST OF THE AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS) PKG										
22.030	PKG 2,16	MOS	16	+1m			08-FEB-2017			
RVSM	REF: AMM 22-10-00-710-801	HRS/MSC AFL	800	+40			10425.7 6021			
+ 22-10-07-700-801-01 (s) CHECK OF THE AILERON AUTOPILOT SERVOMOTOR CABLES AND PULLEYS PKG										
22.085	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 22-10-07-700-801	HRS/MSC AFL	3750				9515 5634			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 22-10-07-700-801-02 (s)	CHECK OF THE ELEVATOR AUTOPILOT SERVOMOTOR CABLES AND PULLEYS						PKG			
22.085	PKG 31 REF: AMM 22-10-07-700-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
22-13-01-900-801-01	YAW DAMPER ACTUATOR									
22.050	7002800-914 85080145 REF: AMM 22-13-01-900-801	MOS HRS/MSC AFL	O/C				18-NOV-2013 9449.6 5588			
221021	AUTOPILOT CONTROL									
22.010	7003975-805 88070738 REF:	MOS HRS/MSC AFL	O/C		TSR:7 TSR:0 TSR:0		30-AUG-2016 10212.9 5929			
221031	PILOT AUTOPILOT COMPUTER									
22.020	7003974-719 95094257 REF:	MOS HRS/MSC AFL	O/C				22-JAN-2014 9489.3 5616			
221041	COPILOT AUTOPILOT COMPUTER									
22.020	7003974-719 88071321 REF:	MOS HRS/MSC AFL	O/C				20-NOV-2003 5669.2 3426			
221101	AILERON AUTOPILOT SERVO MOTOR									
22.040	7002260-621 89022517 REF:	MOS HRS/MSC AFL	O/C				18-SEP-2002 5317.6 3220			
221121	ELEVATOR AUTOPILOT SERVO MOTOR									
22.060	7002260-621 89012506 REF:	MOS HRS/MSC AFL	O/C				18-SEP-2002 5317.6 3220			
221201	NO. 1 AUTOPILOT AILERON CABLE									
22.070	59054 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
221211	NO. 2 AUTOPILOT AILERON CABLE									
22.070	59054 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
221231	NO. 1 AUTOPILOT ELEVATOR CABLE									
22.080	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
221241	NO. 2 AUTOPILOT ELEVATOR CABLE									
22.080	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
221301	PILOT ADVISORY DISPLAY									
22.090	7003652-631 94032242 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			03-DEC-2016 10334.5 5986			
221311	COPILOT ADVISORY DISPLAY									
22.090	7003652-631 89031101 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
CHAPTER 23 COMMUNICATIONS										
23-12-13-900-801-01	HF ANTENNA									
23.050	FGFB312001 SO82/287 REF: AMM 23-12-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
+ 23-60-00-760-801-01 (s)	VISUAL INSPECTION AND ELECTRICAL BONDING CHECK OF THE STATIC DISCHARGERS						PKG			
23.090	PKG 21 REF: AMM 23-60-00-760-801	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
230A05	NOISE FUEL PUMP #1 FILTER									
	7700216-507 029 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
230A06	NOISE FUEL PUMP #2 FILTER									
	7700216-507 034 REF:	MOS HRS/MSC AFL	O/C							
230A07	NOISE FUEL PUMP #3 FILTER									
	7700216-507 036 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
231101	NO. 1 VHF CONTROL									
23.020	822-1120-005 20985 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-AUG-1999 4139.6 2477			
231111	NO. 2 VHF CONTROL									
23.030	822-1120-005 15426 REF:	MOS HRS/MSC AFL	O/C				11-MAY-2017 10553.3 6091			
231116	NO. 3 VHF CONTROL									
23.035	G5868 131 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
231121	NO. 1 VHF TRANSCEIVER									
23.020	822-1114-001 27729 REF:	MOS HRS/MSC AFL	O/C				13-AUG-1999 4139 2477			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
231131	NO. 2 VHF TRANSCEIVER									
23.030	822-1114-001 26238 REF:	MOS HRS/MSC AFL	O/C				13-AUG-1999 4139 2477			
231136	NO. 3 VHF TRANSCEIVER									
23.035	622-6153-001 26120 REF:	MOS HRS/MSC AFL	O/C				08-SEP-2000 4613 2784			
231141	NO. 1 VHF ANTENNA									
23.020	S65-8280-19 389 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
231151	NO. 2 VHF ANTENNA									
23.030	S65-8280-10 702 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
231156	NO. 3 VHF ANTENNA									
23.035	S65-8280-10 892 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
231201	NO. 1 HF COUPLER AMPLIFIER									
23.040	064-1017-02 15366 REF:	MOS HRS/MSC AFL	O/C	TSR:7 TSR:0 TSR:0			22-JUN-2017 10663 6123			
231206	NO. 2 HF COUPLER AMPLIFIER									
23.045	064-1017-02 13468 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			21-JUN-2017 10663 6123			
231211	NO. 1 HF TRANSCEIVER									
23.040	064-1015-01 28811 REF:	MOS HRS/MSC AFL	O/C				20-MAY-2005 6159.4			
231216	NO. 2 HF TRANSCEIVER									
23.045	064-1015-01 26832 REF:	MOS HRS/MSC AFL	O/C				20-MAY-2005 6159.4			
231221	NO. 1 HF CONTROL									
23.040	064-1016-03 11412 REF:	MOS HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			22-JUN-2017 10663 6123			
231226	NO. 2 HF CONTROL									
23.045	064-1016-03 5961 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5996 TSR:0 TSN:3593 TSR:0			12-OCT-2004 6022.6 3607			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
231241	HF ANTENNA TUNING VARIABLE CAPACITOR									
23.055	071-1270-01 1819 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			18-MAY-2005 6159.4 3694			
231A01	HF #1 AMPLIFIER									
	071-0019-00 X3623 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			05-JUN-2001 4881 2958			
231A06	HF #2 AMPLIFIER									
	071-0019-00 3767 REF:	MOS HRS/MSC AFL	O/C				20-MAY-2005 6159.4 3694			
231A29	COMM UNIT,SATELITE									
	153-017311-01 805 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-JUN-2001 4881 2958			
231A30	HPA/LNA AMPLIFIER									
	153-017310-01 800 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-JUN-2001 4881 2958			
231A31	COMM SATELITE ANTENNA									
	121-017537-01 540 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-JUN-2001 4881 2958			
231B02	COCKPIT SATELLITE TELEPHONE HANDSET									
	P12192-002 1219214265 REF:	MOS HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			05-MAY-2014 9515 5634			
231B03	SATELLITE TELEPHONE HANDSET (VIP SEAT)									
	P12192-002 1219237633 REF:	MOS HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			05-MAY-2014 9515 5634			
231B04	SATELLITE TELEPHONE HANDSET (AFT CABIN)									
	P12192-002 1285732460 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-SEP-2012 8931 5293			
232001	SELCAL RECEIVER									
23.100	2800-0012-105 000882 REF:	MOS HRS/MSC AFL	O/C				14-SEP-2007 6769.6			
232101	COMMUNICATION ANNUNCIATOR PANEL									
23.110	872TS06Y SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
233101	PILOT AUDIO CONTROL M1045FBAAHJB7 8902110 REF:	MOS HRS/MSC AFL	O/C				14-NOV-2006 6434.9			
233121	COPILOT AUDIO CONTROL M1045FBAAHJB7 890149 REF:	MOS HRS/MSC AFL	O/C				14-NOV-2006 6434.9			
233151	PUBLIC ADDRESS AMPLIFIER M2050C 9004274 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
233201	PILOT LOUD SPEAKER 5FUA SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				02-MAY-2008 6968.3 4165			
233211	COPILOT LOUD SPEAKER 5FUA SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				02-MAY-2008 6968.3 4165			
233A06	CASSETTE VIDEO PLAYER SLV-P30HF 0803921-9 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
233A07	CASSETTE VIDEO #2 PLAYER SLV-P30HF 080389G REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
233A08	COMPACT DISC PLAYER CDX-A2001 10739 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
233A09	COMPACT DISC #2 PLAYER CDX-A2001 11153 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
233A11	PREAMP,COMP DISC PLAYER M1080A 890107 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
233A13	VIDEO CABIN REAR MONITOR FD151CV-LP 1510289005-RS REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-NOV-2016 10318.4 5973			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
233A14	PREAMP,COMP DISC PLAYR #2 M1080A 9001038 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
233A16	VIDEO CABIN FWD MONITOR FD151CV-LP 1510289005-RS REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-FEB-2017 10425.7 6021			
233A19	PREAMP,VIDEO SYSTEM M1080A 8910323 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
233A20	PREAMP,VIDEO SYSTEM #2 M1080A 9001037 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
233A21	VIDEO SYSTEM INVERTER 2A1000-1G SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				24-JUL-1992 834.6			
233A29	AIRSHOW 500 441-1333-100 500T0211 REF:	MOS HRS/MSC AFL	O/C				03-DEC-2016 10334.5 5986			
234A01	FLITEFONE ANTENNA 015-11203-001 449-2522 REF:	MOS HRS/MSC AFL	O/C				02-MAY-2008 6968.3 4165			
234A03	FLITEFONE COCKPIT CONTROL 400-0123-210 5567 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-JUL-1990 37			
234A08	FLITEFONE TRANSCEIVER P12023 1203311025 REF:	MOS HRS/MSC AFL	O/C				02-MAY-2008 6968.3 4165			
234A11	FLITEFONE CABN #1 CONTROL 725729-815WH MX48218 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-2002 5317.6 3220			
234A12	FLITEFONE CABN #2 CONTROL 400-018100-01 252 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-AUG-1996 2691 1526			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
234A13	FLITEFONE CABN #3 CONTROL 725729-815WH MX48155 REF:	MOS HRS/MSC AFL	O/C				18-SEP-2002 5317.6 3220			
236A08	ATG 4000 TRANSCEIVER P13989 P1398912069 REF:	MOS HRS/MSC AFL	O/C			TSR:0 TSR:0 TSR:0	14-SEP-2016 10230 5939			
CHAPTER 24 ELECTRICAL POWER										
24-20-05-710-801-01 (s)	OPERATIONAL TEST OF THE GROUND FAULT (GFI) INTERRUPTER PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 20-SEP-2017 10758.2 6172			
24-30-00-710-801-01 (s)	OPERATIONAL TEST OF THE NO. 1 ENGINE VOLTAGE MONITORING CIRCUITS PKG 21 REF: AMM 24-30-00-710-801	MOS HRS/MSC AFL	1600	+40			PKG 20-SEP-2017 10758.2 6172			
24-30-00-710-801-02 (s)	OPERATIONAL TEST OF THE NO. 2 ENGINE VOLTAGE MONITORING CIRCUITS PKG 21 REF: AMM 24-30-00-710-801	MOS HRS/MSC AFL	1600	+40			PKG 20-SEP-2017 10758.2 6172			
24-30-00-710-801-03 (s)	OPERATIONAL TEST OF THE NO. 3 ENGINE VOLTAGE MONITORING CIRCUITS PKG 21 REF: AMM 24-30-00-710-801	MOS HRS/MSC AFL	1600	+40			PKG 20-SEP-2017 10758.2 6172			
24-30-00-710-801-04 (s)	OPERATIONAL TEST OF THE APU VOLTAGE MONITORING CIRCUITS PKG 21 REF: AMM 24-30-00-710-801	MOS HRS/MSC AFL	1600	+40			PKG 20-SEP-2017 10758.2 6172			
+ 24-30-00-710-802-01 (s)	OPERATIONAL TEST OF THE APU SHUTDOWN SAFETIES WITH "MASTER" APU CONTROL PKG 21 REF: AMM 24-30-00-710-802	MOS HRS/MSC AFL	1600	+40			PKG 20-SEP-2017 10758.2 6172			
24-30-08-210-801-01S	PERIODIC INSPECTION EMERGENCY POWER SUPPLY PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
24-30-08-900-801-01	EMERGENCY POWER SUPPLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C			TSN:0 TSN:0 TSN:0 TSN:0	27-FEB-1990 0 0 0 0			



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-31-09-900-801-01	APU GENERATOR CONTROL UNIT									
24.120	D22-501 5033-59 REF: AMM 24-31-09-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			27-MAY-2015 9899.4 5803			
24-31-09-900-801-02	NO. 1 GENERATOR CONTROL UNIT									
24.110	D22-501 8115-30 REF: AMM 24-31-09-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			01-OCT-2004 6022.6 3607			
24-31-09-900-801-03	NO. 2 GENERATOR CONTROL UNIT									
24.120	D22-501-1 80186-09 REF: AMM 24-31-09-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			09-JUL-2004 5945.6 3572			
24-31-09-900-801-04	NO. 3 GENERATOR CONTROL UNIT									
24.110	D22-501 8115-30 REF: AMM 24-31-09-900-801	MOS HRS/MSC AFL	O/C				15-MAY-2015 9887.3 5799			
24-31-13-350-801-01	RESTORATION NO. 1 STARTER/GENERATOR (OVERHAUL)									
24.080 OVERHAUL	8060-160 2524 REF: AMM 24-31-13-350-801	MOS HRS/MSC AFL	1240	+3%			15-MAY-2015 9887.3 5799	11127.3	11164.5	351.6 (+37.2)
24-31-13-350-801-02	RESTORATION NO. 2 STARTER/GENERATOR (OVERHAUL)									
24.090 OVERHAUL	8060-150 2230 REF: AMM 24-31-13-350-801	MOS HRS/MSC AFL	900	+3%			30-AUG-2016 10212.9 5929	11112.9	11139.9	337.2 (+27)
24-31-13-350-801-03	RESTORATION NO. 3 STARTER/GENERATOR (OVERHAUL)									
24.080 OVERHAUL	8060-150 2348 REF: AMM 24-31-13-350-801	MOS HRS/MSC AFL	900	+3%			30-AUG-2016 10212.9 5929	11112.9	11139.9	337.2 (+27)
24-31-13-350-801-04	RESTORATION APU STARTER/GENERATOR (OVERHAUL)									
24.100 OVERHAUL	8060-160 2739 REF: AMM 24-31-13-350-801	MOS HRS/MSC AFL APH	1240	+3%			27-JAN-2012 4002.8	5242.8	5280	65.2 (+37.2)
24-31-13-900-803-01	NO. 1 STARTER/GENERATOR									
24.080	8060-160 2524 REF: AMM 24-31-13-900-803	MOS HRS/MSC AFL	O/C	TSO:21 TSO:0 TSO:0			15-MAY-2015 9887.3 5799			
24-31-13-900-803-02	NO. 3 STARTER/GENERATOR									
24.080	8060-150 2348 REF: AMM 24-31-13-900-803	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			30-AUG-2016 10212.9 5929			
24-31-13-900-804-01	NO. 2 STARTER/GENERATOR									
24.090	8060-150 2230 REF: AMM 24-31-13-900-804	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			30-AUG-2016 10212.9 5929			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-31-17-220-803-01	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 1 STARTER-GENERATOR (L1PA) 8060-160 2524 REF: See Workcard	MOS HRS/MSC AFL	600	+30			30-AUG-2016 10212.9 5929	10812.9	10842.9	37.2 (+30)
24-31-17-220-803-02	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 2 STARTER-GENERATOR (M1PA) 8060-150 2230 REF: See Workcard	MOS HRS/MSC AFL	450	+30	-1		21-JUN-2017 10663 6123	11112.9	11142.9	337.2 (+30)
24-31-17-220-803-03	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 3 STARTER-GENERATOR (R1PA) 8060-150 2348 REF: See Workcard	MOS HRS/MSC AFL	450	+30	-1		21-JUN-2017 10663 6123	11112.9	11142.9	337.2 (+30)
24-32-01-350-801-01	RESTORATION NO. 1 MAIN BATTERY (OVERHAUL) (NICKEL-CADMIUM BATTERY ONLY) 24.030 RG380E/40B 40742469 REF: AMM 24-32-01-350-801	MOS HRS/MSC AFL	N/A							
24-32-01-350-801-02	RESTORATION NO. 2 MAIN BATTERY (OVERHAUL) (NICKEL-CADMIUM BATTERY ONLY) 24.035 RG380E/40B 40742468 REF: AMM 24-32-01-350-801	MOS HRS/MSC AFL	N/A							
24-32-01-700-801-01	REGULAR CHECK NO. 1 MAIN BATTERY (NICKEL-CADMIUM BATTERY ONLY) 24.030 RG380E/40B 40742469 REF: AMM 24-32-01-700-801	MOS HRS/MSC AFL	N/A							
24-32-01-700-801-02	REGULAR CHECK NO. 2 MAIN BATTERY (NICKEL-CADMIUM BATTERY ONLY) 24.035 RG380E/40B 40742468 REF: AMM 24-32-01-700-801	MOS HRS/MSC AFL	N/A							
24-32-01-700-802-01	REGULAR CHECK NO. 1 MAIN BATTERY (LEAD / ACID BATTERY ONLY) 24.030 RG380E/40B 40742469 REF: AMM 24-32-01-700-802	MOS HRS/MSC AFL	6	+1m			08-SEP-2017 10758.2 6172	08-MAR-2018	08-APR-2018	141 d (+31)
24-32-01-700-802-02	REGULAR CHECK NO. 2 MAIN BATTERY (LEAD / ACID BATTERY ONLY) 24.035 RG380E/40B 40742468 REF: AMM 24-32-01-700-802	MOS HRS/MSC AFL	6	+1m			08-SEP-2017 10758.2 6172	08-MAR-2018	08-APR-2018	141 d (+31)
24-32-01-900-801-01	NO. 1 MAIN BATTERY 24.030 RG380E/40B 40742469 REF: AMM 24-32-01-900-801	MOS HRS/MSC AFL	H/T				26-SEP-2015 10045.1 5863			
24-32-01-900-801-02	NO. 2 MAIN BATTERY 24.035 RG380E/40B 40742468 REF: AMM 24-32-01-900-801	MOS HRS/MSC AFL	H/T				26-SEP-2015 10045.1 5863			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-32-01-960-801-01	DISCARD NO. 1 MAIN BATTERY (LEAD / ACID BATTERY ONLY) RG380E/40B 40742469 REF: AMM 24-32-01-960-801	MOS HRS/MSC AFL	60 5000				26-SEP-2015 10045.1 5863	26-SEP-2020 15045.1		1074 d 4269.4
LIFE LIMIT										
24-32-01-960-801-02	DISCARD NO. 2 MAIN BATTERY (LEAD / ACID BATTERY ONLY) RG380E/40B 40742468 REF: AMM 24-32-01-960-801	MOS HRS/MSC AFL	60 5000				26-SEP-2015 10045.1 5863	26-SEP-2020 15045.1		1074 d 4269.4
LIFE LIMIT										
24-32-09-610-801-01	SERVICING STAND-BY HORIZON BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY) 100-0540-02 0702288 REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	N/A							
24.210										
24-32-09-610-801-02	SERVICING NO. 1 IRS STAND-BY BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY) 804747 1176 REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	16	+1m			02-FEB-2017	02-JUN-2018	02-JUL-2018	227 d (+30)
24.220										
24-32-09-610-801-03	SERVICING NO. 2 IRS STAND-BY BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY) 135687 4348 REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	16	+1m			01-FEB-2017	01-JUN-2018	01-JUL-2018	226 d (+30)
24.220										
24-32-09-610-801-04	SERVICING NO. 3 IRS STAND-BY BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY) 135687 2018 REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	16	+1m			02-FEB-2017	02-JUN-2018	02-JUL-2018	227 d (+30)
24.230										
24-32-09-610-801-05	SERVICING VHF 3 STAND-BY BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY) 100-0540-02 1018816 REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	N/A							
24.250										
24-32-09-610-801-06	SERVICING EMERGENCY STAND-BY BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY) 100-0540-02 0811191 REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	N/A							
24.240										
24-32-09-610-801-07	SERVICING NO. 3 FMS STAND-BY BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY) PN SN-UNKNOWN REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
24.260										
24-32-09-710-802-01	OPERATIONAL TEST STAND-BY HORIZON BATTERY (SECURAPLANE XL245 TYPE BATTERY ONLY) 100-0540-02 0702288 REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	12	+3%			08-SEP-2017 10758.2 6172	08-SEP-2018	18-SEP-2018	325 d (+10)
24.210										
24-32-09-710-802-02	OPERATIONAL TEST NO. 1 IRS STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY ONLY) 804747 1176 REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	N/A							
24.220										

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-32-09-710-802-03	OPERATIONAL TEST NO. 2 IRS STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY ONLY)									
24.220	135687 4348 REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	N/A							
24-32-09-710-802-04	OPERATIONAL TEST NO. 3 IRS STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY ONLY)									
24.230	135687 2018 REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	N/A							
24-32-09-710-802-05	OPERATIONAL TEST VHF 3 STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY ONLY)									
24.250	100-0540-02 1018816 REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	12	+3%			08-SEP-2017 10758.2 6172	08-SEP-2018	18-SEP-2018	325 d (+10)
24-32-09-710-802-06	OPERATIONAL TEST EMERGENCY STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY ONLY)									
24.240	100-0540-02 0811191 REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	12	+3%			11-NOV-2016 10318.4 5973	11-NOV-2017	21-NOV-2017	24 d (+10)
24-32-09-720-801-01	CAPACITY TESTING OF THE STAND-BY BATTERIES - STAND-BY HORIZON BATTERY (4FG)									
	100-0540-02 0702288 REF: AMM 24-32-09-720-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
24-32-09-720-801-02	CAPACITY TESTING OF THE STAND-BY BATTERIES - IRS1 BATTERY (L12FP)									
	804747 1176 REF: AMM 24-32-09-720-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
24-32-09-720-801-03	CAPACITY TESTING OF THE STAND-BY BATTERIES - IRS2 BATTERY (R12FP)									
	135687 4348 REF: AMM 24-32-09-720-801	MOS HRS/MSC AFL	O/C							
24-32-09-720-801-04	CAPACITY TESTING OF THE STAND-BY BATTERIES - IRS3 BATTERY (32FP)									
	135687 2018 REF: AMM 24-32-09-720-801	MOS HRS/MSC AFL	O/C							
24-32-09-720-801-05	CAPACITY TESTING OF THE STAND-BY BATTERIES - VHF3 BATTERY (28RC)									
	100-0540-02 1018816 REF: AMM 24-32-09-720-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
24-32-09-720-801-06	CAPACITY TEST BATTERY									
	100-0540-02 0811191 REF: See Workcard	MOS HRS/MSC AFL	N/A				03-NOV-2011			
24-32-09-720-801-07	CAPACITY TESTING OF THE STAND-BY BATTERIES - FMS3 BATTERY (42RJ)									
	PN SN-UNKNOWN REF: AMM 24-32-09-720-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-32-09-900-801-01	STAND-BY HORIZON BATTERY									
24.210	100-0540-02 0702288 REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			07-AUG-2015 9983.6 5839			
24-32-09-900-801-02	NO. 1 IRS STAND-BY BATTERY									
24.220	804747 1176 REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL	O/C	TSN:33 TSN:910.7 TSN:387			03-FEB-2017 10425.7 6021			
24-32-09-900-801-03	NO. 2 IRS STAND-BY BATTERY									
24.220	135687 4348 REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL	O/C				03-FEB-2017 10425.7 6021			
24-32-09-900-801-04	NO. 3 IRS STAND-BY BATTERY									
24.230	135687 2018 REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL	O/C				03-FEB-2017 10425.7 6021			
24-32-09-900-801-05	VHF 3 STAND-BY BATTERY									
24.250	100-0540-02 1018816 REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
24-32-09-900-801-06	EMERGENCY STAND-BY BATTERY									
24.240	100-0540-02 0811191 REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL	O/C	TSN:98 TSR:2 TSR:0 TSR:0			11-NOV-2016 10318.4 5973			
24-32-09-900-801-07	NO. 3 FMS STAND-BY BATTERY									
24.260	PN SN-UNKNOWN REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0 0			
24-32-09-960-802-01	DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - STAND-BY HORIZON BATTERY (4FG)									
24.210	100-0540-02 0702288 REF: AMM 24-32-09-960-802	MOS HRS/MSC AFL	48				07-AUG-2015	07-AUG-2019		658 d
LIFE LIMIT										
24-32-09-960-802-02	DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 1 BATTERY (L12FP)									
24.220	804747 1176 REF: AMM 24-32-09-960-802	MOS HRS/MSC AFL	N/A							
24-32-09-960-802-03	DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 2 BATTERY (R12FP)									
24.220	135687 4348 REF: AMM 24-32-09-960-802	MOS HRS/MSC AFL	N/A							
24-32-09-960-802-04	DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 3 BATTERY (32FP)									
24.230	135687 2018 REF: AMM 24-32-09-960-802	MOS HRS/MSC AFL	N/A							

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-32-09-960-802-05	DISCARD VHF 3 STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY ONLY)									
24.250	100-0540-02	MOS	48				30-AUG-2016	30-AUG-2020		1047 d
LIFE LIMIT	1018816	HRS/MSC								
	REF: AMM 24-32-09-960-802	AFL								
24-32-09-960-802-06	DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - EMERGENCY BATTERY (123F)									
24.240	100-0540-02	MOS	48				12-SEP-2016	12-SEP-2020		1060 d
LIFE LIMIT	0811191	HRS/MSC								
	REF: AMM 24-32-09-960-802	AFL								
24-33-01-900-801-01	APU STARTER/GENERATOR									
24.100	8060-160	MOS					27-JAN-2012			
	2739	HRS/MSC	O/C							
	REF: AMM 24-33-01-900-801	AFL								
		APH	0				4002.8			
24-33-05-220-803-01	CHECK OF THE APU STARTER GENERATOR BRUSHES - APU STARTER-GENERATOR (21PA)									
	8060-160	MOS					30-AUG-2016			
	2739	HRS/MSC					10212.9			
	REF: See Workcard	AFL					5929			
		APH	600				4887.8	5487.8		310.2
+ 24-40-00-720-801-01 (s)	FUNCTIONAL TEST OF THE GROUND POWER RECEPTACLE OF THE GROUND POWER RECEPTACLE OVERVOLTAGE PROTECTION PCB						PKG			
24.170	PKG 21	MOS					20-SEP-2017			
		HRS/MSC	1600	+40			10758.2			
	REF: AMM 24-40-00-720-801	AFL					6172			
24-41-00-720-801-01	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - GENERAL TEST OF THE FUNCTION									
		MOS					27-FEB-1990			
		HRS/MSC	O/C				0			
	REF: AMM 24-41-00-720-801	AFL					0			
24-41-00-720-801-02	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - TEST OF THE SAFETY DEVICES									
		MOS					27-FEB-1990			
		HRS/MSC	O/C				0			
	REF: AMM 24-41-00-720-801	AFL					0			
24-61-01-900-801-01	MAIN ELECTRICAL BOX									
24.165	67YG01Y03	MOS				TSO:0	29-AUG-1990			
	142	HRS/MSC	O/C			TSO:0	82			
	REF: AMM 24-61-01-900-801	AFL				TSO:0	40			
+ 24-63-13-710-801-01 (s)	OPERATIONAL TEST DOME LIGHT PCB						PKG			
24.200	PKG 21	MOS					20-SEP-2017			
		HRS/MSC	1600	+40			10758.2			
	REF: AMM 24-63-13-710-801	AFL					6172			
24-90-01-900-801-01	GROUND FAULT (GFI) INTERRUPTER									
	PN	MOS				TSN:0	27-FEB-1990			
	SN-UNKNOWN	HRS/MSC	O/C			TSN:0	0			
	REF: GENERIC NO REF	AFL				TSN:0	0			
		APH				TSN:0	0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
242A21	USB CHARGING OUTLETS - GENERAL VISUAL INSPECTION PER ICA DOC #1022474	MOS	288					01-APR-2020 M		896 d
	REF:	HRS/MSC AFL	15000					9384 M		3202
243191	NO. 1 BATTERY TEMPERATURE PROBE									
24.040	P600-14B SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
243201	NO. 2 BATTERY TEMPERATURE PROBE									
24.040	P600-14B SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
243211	BATTERY TEMPERATURE INDICATOR									
24.050	BT1600-3A 5373	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
243221	BATTERY BLOWER									
24.060	VA0906XXA 10775	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
243251	NO. 1 BATTERY REVERSE CURRENT RELAY									
24.070	PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
243261	NO. 2 BATTERY REVERSE CURRENT RELAY									
24.070	PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
243501	NO. 1 GENERATOR REVERSE CURRENT RELAY									
24.130	PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
243511	NO. 2 GENERATOR REVERSE CURRENT RELAY									
24.140	PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
243521	NO. 3 GENERATOR REVERSE CURRENT RELAY									
24.130	PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
243531	APU GENERATOR REVERSE CURRENT RELAY									
24.140	PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
243601	LH DC AMMETER									
24.150	2396-323-0 731 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
243611	RH DC AMMETER									
24.150	2396-323-0 732 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
243621	LH DC VOLTMETER									
24.160	2396-118-0 1071 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
243631	RH DC VOLTMETER									
24.160	2396-118-0 1085 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
243701	UPPER ELECTRICAL PANEL									
24.165	401TS06Y01VB 183 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
244101	GROUND POWER RECEPTACLE									
24.170	280C 15121 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
CHAPTER 25 EQUIPMENT/FURNISHINGS										
25-00-01-200-801-01 (s)	INSPECTION OF THE ONBOARD KIT						PKG			
25.065	PKG 12 REF: AMM 25-00-01-200-801	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
25-00-05-200-801-01 (s)	INSPECTION OF THE CREW AND PASSENGER SEAT HARNESSSES AND SAFETY BELTS						PKG			
25.010	PKG 31 REF: AMM 25-00-05-200-801	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
25-10-10-960-801-01S	REPLACEMENT OF THE WINDOW DEFOG FAN/HEATER BEARINGS AND BRUSHES									
	REF: GENERIC CMM	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
25-11-01-900-801-01	LH SEAT PILOT									
25.020	132-051-100 88 REF: AMM 25-11-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
25-11-01-900-801-02	RH SEAT PILOT									
25.020	132-050-100 88 REF: AMM 25-11-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-11-05-200-801-01A	VISUAL INSPECTION OF PASSENGER SEAT BELT BUCKLES (MANDATORY 5-40)									
25.030		MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
	REF: AMM 25-11-05-200-801									
25-11-13-640-801-01 (s)	GREASING OF THE OF THE LH SEAT ACTUATOR ROD END-FITTINGS						PKG			
25.020	PKG 21	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
	REF: AMM 25-11-13-640-801									
25-11-13-640-801-02 (s)	GREASING OF THE OF THE RH SEAT ACTUATOR ROD END-FITTINGS						PKG			
25.020	PKG 21	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
	REF: AMM 25-11-13-640-801									
25-11-19-960-801-01 (s)	REPLACEMENT OF THE OF THE LH PILOT SEAT LOCKING PIN SPRINGS						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m			11-MAY-2017 10553.3 6091			
	REF: AMM 25-11-19-960-801									
25-11-19-960-801-02 (s)	REPLACEMENT OF THE OF THE RH PILOT SEAT LOCKING PIN SPRINGS						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m			11-MAY-2017 10553.3 6091			
	REF: AMM 25-11-19-960-801									
25-11-25-200-801-01 (s)	INSPECTION OF THE LH PILOT SEAT ROLLER PINS						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
	REF: AMM 25-11-25-200-801									
25-11-25-200-801-02 (s)	INSPECTION OF THE RH PILOT SEAT ROLLER PINS						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
	REF: AMM 25-11-25-200-801									
25-12-00-210-801-01 (s)	INSPECTION OF THE THIRD CREW MEMBER SEAT						PKG			
	PKG 2,5,201	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
	REF: See Workcard									
25-20-00-210-801-01 (s)	INSPECTION OF THE MAIN ENTRY DOOR (MED) AND LAVATORY ASSIST HANDLE						PKG			
	PKG 31	MOS HRS/MSC AFL APH	72	+2m			27-FEB-1990 0 0 0			
	REF: See Workcard									
25-20-00-220-801-01 (s)	INSPECTION OF THE TRASH CONTAINER AND LID SEAL (INCLUDING FIRE CONTAINMENT AND SELF EXTINGUISHING CHARACTERISTICS)						PKG			
	PKG 2	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
	REF: See Workcard									
25-20-00-220-802-01 (s)	INSPECTION OF THE INTERIOR LATCHES						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
	REF: See Workcard									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-20-00-220-802-02 (s)	INSPECT/OPERATIONAL TEST OF THE POP OUT WORK SURFACE PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 27-FEB-1990 0 0			
	REF: SMM 25-90-25		3750							
25-20-00-220-802-05 (s)	OPERATIONAL TEST OF THE TAMBOUR DOOR MICROSWITCH PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 05-MAY-2014 9515 5634			
	REF: SMM 25-90-13		3750							
25-21-00-220-801-01 (s)	INSPECTION OF THE SINGLE PASSENGER SEATS PKG 2,7	MOS HRS/MSC AFL	16	+1m			PKG 08-FEB-2017 10425.7 6021			
	REF: See Workcard		800	+40						
25-21-00-220-801-02 (s)	INSPECTION OF THE DIVAN(S) PKG 2	MOS HRS/MSC AFL	16	+1m			PKG 08-FEB-2017 10425.7 6021			
	REF: SMM 25-90-05		800	+40						
25-22-01-210-801-01 (s)	DETAILED INSPECTION OF CONSOLE TABLES IN LOCATIONS OTHER THAN EMERGENCY EXIT PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 27-FEB-1990 0 0			
	REF: See Workcard		3750							
25-22-01-210-801-02 (s)	DETAILED INSPECTION OF CONSOLE TABLE IN FRONT OF THE EMERGENCY EXIT ONLY PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 26-SEP-2015 10045.1 5863			
	REF: See Workcard		3750							
25-22-05-220-802-01 (s)	INSPECTION OF THE DINING TABLE PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 27-FEB-1990 0 0			
	REF: See Workcard		3750							
25-23-61-210-801-01 (s)	INSPECTION OF THE TRACKING MAGAZINE RACK PKG 2,6	MOS HRS/MSC AFL	16	+1m			PKG 08-FEB-2017 10425.7 6021			
	REF: See Workcard		800	+40						
25-30-33-900-801-01	CONVECTION OVEN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C				27-FEB-1990 0 0 0 0			
					TSN:0 TSN:0 TSN:0 TSN:0					
25-33-09-210-801-01	INSPECTION OF COFFEE MAKER/ESPRESSO MACHINE REF: See Workcard	MOS HRS/MSC AFL APH	A/R				27-FEB-1990 0 0 0			
25-33-17-210-801-01 (s)	INSPECTION OF THE MICROWAVE OVEN PKG 7,21	MOS HRS/MSC AFL	1600	+40			PKG 20-SEP-2017 10758.2 6172			
	REF: See Workcard									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-33-17-710-801-01	OPERATIONAL TEST OF THE MICROWAVE OVEN DOOR ELECTRICAL POWER CUT-OFF FUNCTION 1539-13M-OH 98-3-23537 REF: AMM 25-33-17-710-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
+ 25-60-00-200-801-01 (s)	INSPECTION OF THE SAFETY EQUIPMENT PKG 12,16 25.060 REF: See Workcard	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
25-60-01-710-801-01S	OPERATIONAL TEST OF THE NO. 1 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT BLOWER AND BATTERY REF: GENERIC CMM	DAYS HRS/MSC AFL	N/A				05-NOV-2012 8991 5327			
25-60-01-710-801-02S	OPERATIONAL TEST OF THE NO. 2 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT BLOWER AND BATTERY REF: GENERIC CMM	DAYS HRS/MSC AFL	N/A				05-NOV-2012 8991 5327			
25-60-01-900-801-01	NO. 1 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				05-NOV-2012 8991 5327			
25-60-01-900-801-02	NO. 2 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				05-NOV-2012 8991 5327			
25-61-00-200-881-01	INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207) MANDATORY REF: GENERIC NO REF	MOS HRS/MSC AFL	12				08-SEP-2017 10758.2 6172	08-SEP-2018		325 d
25-61-00-710-801-01	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - CHECK OF THE ELT UNIT CONTROLS 25.070 REF: AMM 25-61-00-710-801	MOS HRS/MSC AFL	O/C				22-APR-2013 9161.3 5420			
25-61-00-710-801-02	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - CHECK OF ELT COCKPIT CONTROLS PKG 17 REF: AMM 25-61-00-710-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
25-61-00-710-801-03	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - SELF-TEST OF ELT REF: AMM 25-61-00-710-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
25-61-00-710-801-04	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - OPERATIONAL TEST OF ELT REF: AMM 25-61-00-710-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-61-01-710-801-01	OPERATIONAL TEST OF THE EMERGENCY LOCATOR (ELT) TRANSMITTER G-SWITCH	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
	REF: AMM 25-61-01-710-801									
25-61-01-900-803-01	EMERGENCY LOCATOR (ELT) TRANSMITTER	MOS HRS/MSC AFL	O/C				26-SEP-2006 6419.2			
25.070	453-5000-(999) 03509									
	REF: AMM 25-61-01-900-803									
25-61-13-960-801-01	DISCARD EMERGENCY LOCATOR (ELT) TRANSMITTER BATTERY PACK	MOS HRS/MSC AFL	DUE				22-APR-2013 9161.3 5420	31-MAR-2018 M		164 d
25.070	453-5000-(999) 03509									
	REF: AMM 25-61-13-960-801									
25-62-01-720-801-01	FUNCTIONAL TEST VOICE DATA RECORDER UNDERWATER LOCATOR BEACON	MOS HRS/MSC AFL		25			28-JAN-2016 10160.5 5907	28-FEB-2018		133 d
31.070	DK120/90 AT45962									
	REF: AMM 25-62-01-720-801									
25-62-01-720-801-02	FUNCTIONAL TEST FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON	MOS HRS/MSC AFL		25			20-SEP-2017 10758.2	20-OCT-2019		732 d
31.100	DK120 SD24177									
	REF: AMM 25-62-01-720-801									
25-62-05-960-801-01	DISCARD VOICE DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY	MOS HRS/MSC AFL	DUE				28-JAN-2016 10160.5 5907	01-OCT-2023 M		2174 d
31.070	DK120/90 AT45962									
	REF: AMM 25-62-05-960-801									
25-62-05-960-801-02	DISCARD FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY	MOS HRS/MSC AFL	DUE				08-SEP-2017 10758.2 6172	31-JAN-2020 M		835 d
31.100	DK120 SD24177									
	REF: AMM 25-62-05-960-801									
25-63-00-350-801-01	OVERHAUL NO. 1 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT	MOS HRS/MSC AFL	N/A				27-FEB-1990 0 0			
	REF: AMM 25-63-00-350-801									
25-63-00-350-801-02	OVERHAUL NO. 2 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT	MOS HRS/MSC AFL	N/A				27-FEB-1990 0 0			
	REF: AMM 25-63-00-350-801									
25-63-00-710-801-01	OPERATIONAL TEST OF THE EMERGENCY VISION ASSURANCE SYSTEM (EVAS) - PILOT EVAS UNIT (L9510MP)	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
	PN NOT INSTALLED									
	REF: AMM 25-63-00-710-801									
25-63-00-710-801-02	OPERATIONAL TEST OF THE EMERGENCY VISION ASSURANCE SYSTEM (EVAS) - COPILOT EVAS UNIT (R9510MP)	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
	PN NOT INSTALLED									
	REF: AMM 25-63-00-710-801									



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-63-01-960-801-01	DISCARD NO. 1 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT BATTERY	MOS HRS/MSC N/A AFL					27-FEB-1990 0 0			
	REF: AMM 25-63-01-960-801									
25-63-01-960-801-02	DISCARD NO. 2 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT BATTERY	MOS HRS/MSC N/A AFL					27-FEB-1990 0 0			
	REF: AMM 25-63-01-960-801									
25-64-13-200-801-01	INSPECTION NO. 1 LIFE RAFT 913FAUL-630-1-351 9UL-00275	MOS HRS/MSC AFL	36	+3%			08-NOV-2016	08-NOV-2019	10-DEC-2019	751 d (+32)
	REF: AMM 25-64-13-200-801									
25-64-13-200-801-02	INSPECTION NO. 2 LIFE RAFT 913FAUL-230-1-351 9UL-00276	MOS HRS/MSC AFL	36	+3%			08-NOV-2016	08-NOV-2019	10-DEC-2019	751 d (+32)
	REF: AMM 25-64-13-200-801									
25-64-13-200-801-03	INSPECTION NO. 3 LIFE RAFT PN NOT INSTALLED	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
	REF: AMM 25-64-13-200-801									
25-64-13-200-801-04	INSPECTION NO. 4 LIFE RAFT PN NOT INSTALLED	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
	REF: AMM 25-64-13-200-801									
+ 25-64-13-350-801-01	OVERHAUL NO. 1 LIFE RAFT 913FAUL-630-1-351 9UL-00275	MOS HRS/MSC AFL	O/C							
25.130	REF: AMM 25-64-13-350-801									
+ 25-64-13-350-801-02	OVERHAUL NO. 2 LIFE RAFT 913FAUL-230-1-351 9UL-00276	MOS HRS/MSC AFL	O/C							
25.130	REF: AMM 25-64-13-350-801									
25-64-13-350-801-03	OVERHAUL NO. 3 LIFE RAFT PN NOT INSTALLED	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
25.135	REF: AMM 25-64-13-350-801									
25-64-13-350-801-04	OVERHAUL NO. 4 LIFE RAFT PN NOT INSTALLED	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
25.135	REF: AMM 25-64-13-350-801									
+ 25-64-13-790-801-01S	INSPECTION/HYDROSTATIC TEST NO. 1 LIFE RAFT 913FAUL-630-1-351 9UL-00275	MOS HRS/MSC AFL	60	+3%			08-NOV-2016	08-NOV-2021	01-JAN-2022	1482 d (+54)
	REF: GENERIC NO REF									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 25-64-13-790-801-02S	INSPECTION/HYDROSTATIC TEST NO. 2 LIFE RAFT 913FAUL-230-1-351 9UL-00276 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			08-NOV-2016	08-NOV-2021	01-JAN-2022	1482 d (+54)
+ 25-64-13-790-801-03S	INSPECTION/HYDROSTATIC TEST NO. 3 LIFE RAFT PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
+ 25-64-13-790-801-04S	INSPECTION/HYDROSTATIC TEST NO. 4 LIFE RAFT PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
25-64-13-900-801-01	NO. 1 LIFE RAFT 913FAUL-630-1-351 9UL-00275 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSO:0 TSO:0 TSO:0		08-NOV-2016			
25-64-13-900-801-02	NO. 2 LIFE RAFT 913FAUL-230-1-351 9UL-00276 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSO:0 TSO:0 TSO:0		08-NOV-2016			
25-64-13-900-801-03	NO. 3 LIFE RAFT PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
25-64-13-900-801-04	NO. 4 LIFE RAFT PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
+ 25-64-17-200-802-01	INSPECTION LH PILOT LIFE VEST P01074-101C 170117000010 REF:	MOS HRS/MSC AFL	O/C				15-JUN-2017			
+ 25-64-17-200-802-02	INSPECTION RH PILOT LIFE VEST 63600-105 L3541707 REF:	MOS HRS/MSC AFL	O/C				31-OCT-2016			
+ 25-64-17-200-802-03	INSPECTION THIRD CREW MEMBER LIFE VEST 63600-105 L3541702 REF:	MOS HRS/MSC AFL	O/C				31-OCT-2016			
+ 25-64-17-200-803-01	INSPECTION NO. 1 PASSENGER LIFE VEST 63600-105 L3542449 REF:	MOS HRS/MSC AFL	O/C				31-OCT-2016			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 25-64-17-200-803-02	INSPECTION NO. 2 PASSENGER LIFE VEST 63600-105 L3541705 REF:	MOS HRS/MSC AFL	O/C				31-OCT-2016			
25.090										
+ 25-64-17-200-803-03	INSPECTION NO. 3 PASSENGER LIFE VEST P0723E105P 065074 REF:	MOS HRS/MSC AFL	O/C				09-JUN-2016			
25.095										
+ 25-64-17-200-803-04	INSPECTION NO. 4 PASSENGER LIFE VEST 63600-105 L3541706 REF:	MOS HRS/MSC AFL	O/C				31-OCT-2016			
25.095										
+ 25-64-17-200-803-05	INSPECTION NO. 5 PASSENGER LIFE VEST 63600-105 L3541700 REF:	MOS HRS/MSC AFL	O/C				31-OCT-2016			
25.100										
+ 25-64-17-200-803-06	INSPECTION NO. 6 PASSENGER LIFE VEST 63600-105 L3541704 REF:	MOS HRS/MSC AFL	O/C				31-OCT-2016			
25.100										
+ 25-64-17-200-803-07	INSPECTION NO. 7 PASSENGER LIFE VEST 63600-105 L3541701 REF:	MOS HRS/MSC AFL	O/C				31-OCT-2016			
25.105										
+ 25-64-17-200-803-08	INSPECTION NO. 8 PASSENGER LIFE VEST 63600-105 L3541709 REF:	MOS HRS/MSC AFL	O/C				31-OCT-2016			
25.105										
+ 25-64-17-200-803-09	INSPECTION NO. 9 PASSENGER LIFE VEST 63600-105 L3541703 REF:	MOS HRS/MSC AFL	O/C				31-OCT-2016			
25.110										
+ 25-64-17-200-803-10	INSPECTION NO. 10 PASSENGER LIFE VEST 63600-105 L3541708 REF:	MOS HRS/MSC AFL	O/C				31-OCT-2016			
25.110										
25-64-17-200-803-11	INSPECTION NO. 11 PASSENGER LIFE VEST PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C							
25.120										
25-64-17-200-803-12	INSPECTION NO. 12 PASSENGER LIFE VEST PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C							
25.120										

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-64-17-200-803-13	INSPECTION NO. 13 PASSENGER LIFE VEST									
25.125	PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C							
25-64-17-200-803-14	INSPECTION NO. 14 PASSENGER LIFE VEST									
25.125	PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C							
25-64-17-200-803-15	INSPECTION NO. 15 PASSENGER LIFE VEST									
25.140	PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C							
25-64-17-200-803-16	INSPECTION NO. 16 PASSENGER LIFE VEST									
25.140	REF:	MOS HRS/MSC AFL	O/C							
25-64-17-200-803-17	INSPECTION NO. 17 PASSENGER LIFE VEST									
25.150	PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C							
25-64-17-350-802-01	RESTORATION LH PILOT LIFE VEST (OVERHAUL OR DISCARD)									
	P01074-101C 170117000010 REF: AMM 25-64-17-350-802	MOS HRS/MSC AFL	60	+3%			15-JUN-2017 10663 6123	15-JUN-2022	08-AUG-2022	1701 d (+54)
25-64-17-350-802-02	RESTORATION RH PILOT LIFE VEST (OVERHAUL OR DISCARD)									
	63600-105 L3541707 REF: AMM 25-64-17-350-802	MOS HRS/MSC AFL	60	+3%			01-NOV-2016	01-NOV-2026	25-DEC-2026	3301 d (+54)
25-64-17-350-802-03	RESTORATION THIRD CREW MEMBER LIFE VEST (OVERHAUL OR DISCARD)									
	63600-105 L3541702 REF: AMM 25-64-17-350-802	MOS HRS/MSC AFL	60	+3%			03-NOV-2016	03-NOV-2021	27-DEC-2021	1477 d (+54)
25-64-17-350-803-01	RESTORATION NO. 1 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)									
	63600-105 L3542449 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	60	+3%			03-NOV-2016	03-NOV-2021	27-DEC-2021	1477 d (+54)
25-64-17-350-803-02	RESTORATION NO. 2 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)									
	63600-105 L3541705 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	60	+3%			03-NOV-2016	01-NOV-2026	25-DEC-2026	3301 d (+54)
25-64-17-350-803-03	RESTORATION NO. 3 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)									
	P0723E105P 065074 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	60	+3%			05-MAY-2014 9515 5634	05-MAY-2019	29-JUN-2019	564 d (+55)

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-64-17-350-803-04	RESTORATION NO. 4 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) 63600-105 L3541706 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	60	+3%			03-NOV-2016	03-NOV-2021	27-DEC-2021	1477 d (+54)
OVERHAUL										
25-64-17-350-803-05	RESTORATION NO. 5 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) 63600-105 L3541700 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	60				03-NOV-2016	03-NOV-2021		1477 d
OVERHAUL										
25-64-17-350-803-06	RESTORATION NO. 6 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) 63600-105 L3541704 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	60				03-NOV-2016	03-NOV-2021		1477 d
OVERHAUL										
25-64-17-350-803-07	RESTORATION NO. 7 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) 63600-105 L3541701 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	60				03-NOV-2016	03-NOV-2021		1477 d
OVERHAUL										
25-64-17-350-803-08	RESTORATION NO. 8 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) 63600-105 L3541709 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	60				03-NOV-2016	03-NOV-2021		1477 d
OVERHAUL										
25-64-17-350-803-09	RESTORATION NO. 9 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) 63600-105 L3541703 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	60				03-FEB-2017 10425.7 6021	03-FEB-2022		1569 d
OVERHAUL										
25-64-17-350-803-10	RESTORATION NO. 10 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) 63600-105 L3541708 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	60				03-NOV-2016	03-NOV-2021		1477 d
OVERHAUL										
25-64-17-350-803-11	RESTORATION NO. 11 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) PN NOT INSTALLED REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C							
25-64-17-350-803-12	RESTORATION NO. 12 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) PN NOT INSTALLED REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C							
25-64-17-350-803-13	RESTORATION NO. 13 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) PN NOT INSTALLED REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C							
25-64-17-350-803-14	RESTORATION NO. 14 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) PN NOT INSTALLED REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C							

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-64-17-350-803-15	RESTORATION NO. 15 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) PN NOT INSTALLED REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C							
25-64-17-350-803-16	RESTORATION NO. 16 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) PN NOT INSTALLED REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C							
25-64-17-350-803-17	RESTORATION NO. 17 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) PN NOT INSTALLED REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C							
25-64-17-350-804-01S	RESTORATION NO. 1 INFANT LIFE VEST PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
25-64-17-900-802-01 25.080	PILOT LIFE VEST P01074-101C 170117000010 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:6 TSN:0 TSN:0			15-JUN-2017 10663 6123			
25-64-17-900-802-02 25.080	COPILOT LIFE VEST 63600-105 L3541707 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-FEB-2017 10425.7 6021			
25-64-17-900-802-03 25.085	THIRD CREW MEMBER LIFE VEST 63600-105 L3541702 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-FEB-2017 10425.7 6021			
25-64-17-900-803-01 25.090	NO. 1 PASSENGER LIFE VEST 63600-105 L3542449 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-FEB-2017 10425.7 6021			
25-64-17-900-803-02 25.090	NO. 2 PASSENGER LIFE VEST 63600-105 L3541705 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-FEB-2017 10425.7 6021			
25-64-17-900-803-03 25.095	NO. 3 PASSENGER LIFE VEST P0723E105P 065074 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			
25-64-17-900-803-04 25.095	NO. 4 PASSENGER LIFE VEST 63600-105 L3541706 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-FEB-2017 10425.7 6021			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-64-17-900-803-05	NO. 5 PASSENGER LIFE VEST									
25.100	63600-105 L3541700 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-FEB-2017 10425.7 6021			
25-64-17-900-803-06	NO. 6 PASSENGER LIFE VEST									
25.100	63600-105 L3541704 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-FEB-2017 10425.7 6021			
25-64-17-900-803-07	NO. 7 PASSENGER LIFE VEST									
25.105	63600-105 L3541701 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-FEB-2017 10425.7 6021			
25-64-17-900-803-08	NO. 8 PASSENGER LIFE VEST									
25.105	63600-105 L3541709 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-FEB-2017 10425.7 6021			
25-64-17-900-803-09	NO. 9 PASSENGER LIFE VEST									
25.110	63600-105 L3541703 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-FEB-2017 10425.7 6021			
25-64-17-900-803-10	NO. 10 PASSENGER LIFE VEST									
25.110	63600-105 L3541708 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-FEB-2017 10425.7 6021			
25-64-17-900-803-11	NO. 11 PASSENGER LIFE VEST									
25.120	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-AUG-2012 8869.6 5260			
25-64-17-900-803-12	NO. 12 PASSENGER LIFE VEST									
25.120	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-AUG-2012 8869.6 5260			
25-64-17-900-803-13	NO. 13 PASSENGER LIFE VEST									
25.125	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-AUG-2012 8869.6 5260			
25-64-17-900-803-14	NO. 14 PASSENGER LIFE VEST									
25.125	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-AUG-2012 8869.6 5260			
25-64-17-900-803-15	NO. 15 PASSENGER LIFE VEST									
25.140	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-AUG-2012 8869.6 5260			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-64-17-900-803-16	NO. 16 PASSENGER LIFE VEST									
25.140	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-AUG-2012 8869.6 5260			
25-64-17-900-803-17	NO. 17 PASSENGER LIFE VEST									
25.150	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-AUG-2012 8869.6 5260			
25-64-17-900-804-01	NO. 1 INFANT LIFE VEST									
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0 0			
25-90-01-900-801-03	THIRD CREW MEMBER SEAT									
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0 0			
25-90-03-200-801-02S (s)	INSPECTION OF THE DUAL PASSENGER SEATS									
	PKG 2 REF: SMM 25-90-03	MOS HRS/MSC AFL	16 800	+1m +40			PKG 26-SEP-2015 10045.1 5863			
25-90-19-900-801-01	MICROWAVE OVEN									
	1539-13M-OH 98-3-23537 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-MAY-2007 6641.5			
25-90-43-350-801-01S	RESTORATION PILOT FLASHLIGHT (DEEP CYCLE) (MAGLITE ONLY)									
	PN SN-UNKNOWN REF: SMM 25-90-43	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
25-90-43-350-801-02S	RESTORATION COPILOT FLASHLIGHT (DEEP CYCLE) (MAGLITE ONLY)									
	PN SN-UNKNOWN REF: SMM 25-90-43	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
25-90-45-350-801-01S	RESTORATION PILOT FLASHLIGHT BATTERIES (MAGLITE ONLY)									
	PN SN-UNKNOWN REF: SMM 25-90-45	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
25-90-45-350-801-02S	RESTORATION COPILOT FLASHLIGHT BATTERIES (MAGLITE ONLY)									
	PN SN-UNKNOWN REF: SMM 25-90-45	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-90-53-220-801-01S	DETAILED INSPECTION OF THE PILOT FLASHLIGHT (AIR LITE ONLY)	MOS					27-FEB-1990			
	REF: SMM 25-90-53	HRS/MSC AFL	N/A				0 0			
25-90-53-220-801-02S	DETAILED INSPECTION OF THE COPILOT FLASHLIGHT (AIR LITE ONLY)	MOS					27-FEB-1990			
	REF: SMM 25-90-53	HRS/MSC AFL	N/A				0 0			
251141	PILOT SEAT BELT	MOS					27-FEB-1990			
25.030	1101167-09 SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
251151	COPILOT SEAT BELT	MOS					27-FEB-1990			
25.030	1101168-18 SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
251161	PILOT HARNESS	MOS					27-FEB-1990			
25.040	2825A3X03 SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
251171	COPILOT HARNESS	MOS					27-FEB-1990			
25.040	2825A3X03 SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
253A01	COFFEE MAKER	MOS					12-MAR-2004			
	50413-100 196 REF:	HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			5790.8 3503			
256061	EMERGENCY LOCATOR TRANSMITTER ANTENNA	MOS					04-APR-2003			
25.170	110-337 2110500 REF: AMM 25-61-21-900-801	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			5450.5 3289			
256391	LAVATORY BLOWER	MOS					27-FEB-1990			
25.160	EVT205D SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
256A54	FIRST AID KIT	MOS					13-JUL-2015			
	AIRCARE AMK027857 REF:	HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			9949.4 5827			
+ 256B35	CARDIAC DEFIBRILLATOR	MOS								
	AED-FR2 0101022630 REF:	HRS/MSC AFL	O/C							

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
259A01	CONTROL S/S DISPLAY UNIT IND-3750-01 0014 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
259A02	COMM UNIT,POWER SEC SYS BP-500-03 0020 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
259A03	PORTABLE S/S TRANSCEIVER RAD-01 8F160444 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
259A04	SECURITY SYSTEM ANTENNA CD-571 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
259A11	SOLAR PANEL,SECURITY SYS SP-02 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
259A12	ALARM SEC SYS INDICATOR IND-05 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
259A13	TEST UNIT,MICROWAVE S/S CMP-T SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
33-50-05-350-801-02	RESTORATION COPILOT FLASHLIGHT (DEEP CYCLE) (DME ONLY) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL APH	O/C				27-FEB-1990 0 0 0			
33-50-05-960-801-01	RESTORATION PILOT FLASHLIGHT (BATTERY REPLACEMENT) (DME ONLY) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				27-FEB-1990 0 0			
CHAPTER 26 FIRE PROTECTION										
+ 26-10-00-720-801-01	FUNCTIONAL TEST NO. 1 FIRE DETECTOR (PNEUMATIC) 3601-70-900/400-13 112400 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	7500/E/C				30-AUG-2016 10212.9 5929	17712.9		6937.2
+ 26-10-00-720-801-02	FUNCTIONAL TEST NO. 2 FIRE DETECTOR (PNEUMATIC) 36018290040015 73839 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	7500/E/C				13-JUL-2013 9281.9 5494	16781.9		6006.2

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 26-10-00-720-801-03	FUNCTIONAL TEST NO. 3 FIRE DETECTOR (PNEUMATIC)									
26.030	36017090040013 71467 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	7500/E/C				14-JAN-2014 9479.8 5608	16979.8		6204.1
+ 26-10-00-720-801-04	FUNCTIONAL TEST APU FIRE DETECTOR (PNEUMATIC)									
26.040	36018190040009 75851 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL APH	C/C 5000				26-SEP-2006 2428	7428		2250.4
+ 26-10-00-720-801-05	FUNCTIONAL TEST LH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR (PNEUMATIC)									
26.050	300119800270-3 61270 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	72	+3%			26-MAY-2012 8750.4	26-MAY-2018	30-JUL-2018	220 d (+65)
+ 26-10-00-720-801-06	FUNCTIONAL TEST RH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR (PNEUMATIC)									
26.050	300119800270-3 60560 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	72	+3%			26-MAY-2012 8750.4	26-MAY-2018	30-JUL-2018	220 d (+65)
26-10-17-720-801-01	FUNCTIONAL TEST OF THE LH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR (PIN POINT TYPE)									
26.050	REF: AMM 26-10-17-720-801	MOS HRS/MSC AFL	N/A				27-FEB-1990 0 0			
26-10-17-720-801-02	FUNCTIONAL TEST OF THE RH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR (PIN POINT TYPE)									
26.050	REF: AMM 26-10-17-720-801	MOS HRS/MSC AFL	N/A				27-FEB-1990 0 0			
26-10-17-900-801-01	LH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR									
26.050	300119800270-3 61270 REF: AMM 26-10-17-900-801	MOS HRS/MSC AFL	O/C			TSN:4606	17-AUG-2000 4606 2779			
26-10-17-900-801-02	RH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR									
26.050	300119800270-3 60560 REF: AMM 26-10-17-900-801	MOS HRS/MSC AFL	O/C			TSN:6419.2	03-OCT-2006 6419.2			
26-10-19-900-801-01	NO. 1 FIRE DETECTOR									
26.020	3601-70-900/400-13 112400 REF: AMM 26-10-19-900-801	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	30-AUG-2016 10212.9 5929			
26-10-19-900-801-02	NO. 2 FIRE DETECTOR									
26.020	36018290040015 73839 REF: AMM 26-10-19-900-801	MOS HRS/MSC AFL	O/C			TSN:0	27-FEB-1990 0 0			
26-10-19-900-801-03	NO. 3 FIRE DETECTOR									
26.030	36017090040013 71467 REF: AMM 26-10-19-900-801	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	20-JUL-1990 27 14			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-10-19-900-801-04	APU FIRE DETECTOR									
26.040	36018190040009 75851 REF: AMM 26-10-19-900-801	MOS HRS/MSC AFL	O/C	TSN:4618			23-AUG-2000 4606 2779			
26-20-00-760-801-01	INSULATION TEST PERCUSSION CIRCUITS									
26.080	REF: AMM 26-20-00-760-801	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
26-20-00-760-801-02	INSULATION TEST PERCUSSION CIRCUITS									
26.090	REF: AMM 26-20-00-760-801	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
26-20-00-760-801-03	INSULATION TEST PERCUSSION CIRCUITS									
26.100	REF: AMM 26-20-00-760-801	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
26-20-00-760-801-04	INSULATION TEST PERCUSSION CIRCUITS									
26.110	REF: AMM 26-20-00-760-801	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
26-20-00-760-801-05	INSULATION TEST PERCUSSION CIRCUITS									
26.120	REF: AMM 26-20-00-760-801	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
26-20-01-760-801-01 (s)	CHECK OF THE CORRECT OPERATION OF NO. 1 ENGINE FIRE EXTINGUISHER						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
	REF: AMM 26-20-01-760-801		3750							
26-20-01-760-801-02 (s)	CHECK OF THE CORRECT OPERATION OF NO. 1 ENGINE FIRE EXTINGUISHER						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
	REF: AMM 26-20-01-760-801		3750							
26-20-01-760-801-03 (s)	CHECK OF THE CORRECT OPERATION OF NO. 2 ENGINE FIRE EXTINGUISHER						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
	REF: AMM 26-20-01-760-801		3750							
26-20-01-760-801-04 (s)	CHECK OF THE CORRECT OPERATION OF NO. 2 ENGINE FIRE EXTINGUISHER						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
	REF: AMM 26-20-01-760-801		3750							
26-20-01-760-801-05 (s)	CHECK OF THE CORRECT OPERATION OF NO. 3 ENGINE FIRE EXTINGUISHER						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
	REF: AMM 26-20-01-760-801		3750							

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-20-01-760-801-06 (s)	CHECK OF THE CORRECT OPERATION OF NO. 3 ENGINE FIRE EXTINGUISHER PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 05-MAY-2014 9515 5634			
	REF: AMM 26-20-01-760-801		3750							
+ 26-20-01-760-801-07 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER "FIRE APU" CONTROL SWITCH/LIGHT PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 05-MAY-2014 9515 5634			
26.180	REF: AMM 26-20-01-760-801		3750							
+ 26-20-01-760-801-08 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER "FIRE BAG COMP" CONTROL SWITCH/LIGHT PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 05-MAY-2014 9515 5634			
26.180	REF: AMM 26-20-01-760-801		3750							
+ 26-20-09-220-801-01	WEIGHING APU, BAGGAGE COMPARTMENT EXTINGUISHER 861630	MOS HRS/MSC AFL	12	+1m			30-MAR-2017	30-MAR-2018	30-APR-2018	163 d (+31)
26.120	54752 REF: AMM 26-20-09-220-801									
+ 26-20-09-220-801-02	WEIGHING NO. 1 ENGINE FIRST-SHOOT, NO. 2 ENGINE SECOND-SHOOT FIRE EXTINGUISHER 861630	MOS HRS/MSC AFL	12	+1m			09-MAY-2017	09-MAY-2018	09-JUN-2018	203 d (+31)
26.080	56866 REF: AMM 26-20-09-220-801									
+ 26-20-09-220-801-03	WEIGHING NO. 2 ENGINE FIRST-SHOOT, NO. 1 ENGINE SECOND-SHOOT FIRE EXTINGUISHER 861630	MOS HRS/MSC AFL	12	+1m			03-MAY-2017	03-MAY-2018	03-JUN-2018	197 d (+31)
26.100	22635 REF: AMM 26-20-09-220-801									
+ 26-20-09-220-801-04	WEIGHING NO. 3 ENGINE FIRST-SHOOT, NO. 2 ENGINE SECOND-SHOOT FIRE EXTINGUISHER 861630	MOS HRS/MSC AFL	12	+1m			05-JUN-2017	05-JUN-2018	05-JUL-2018	230 d (+30)
26.110	55877 REF: AMM 26-20-09-220-801									
+ 26-20-09-220-801-05	WEIGHING NO. 2 ENGINE FIRST-SHOOT, NO. 3 ENGINE SECOND-SHOOT FIRE EXTINGUISHER 861630	MOS HRS/MSC AFL	12	+1m			02-JUN-2017	02-JUN-2018	02-JUL-2018	227 d (+30)
26.090	57255 REF: AMM 26-20-09-220-801									
+ 26-20-09-350-801-01	RESTORATION APU, BAGGAGE COMPARTMENT EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) 861630	MOS HRS/MSC AFL	60				30-MAR-2017	30-MAR-2022		1624 d
26.120	54752 REF: AMM 26-20-09-350-801									
MANDATORY										
+ 26-20-09-350-801-02	RESTORATION NO. 1 ENGINE FIRST-SHOOT, NO. 2 ENGINE SECOND-SHOOT FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) 861630	MOS HRS/MSC AFL	60				09-MAY-2017	09-MAY-2022		1664 d
26.080	56866 REF: AMM 26-20-09-350-801									
MANDATORY										

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 26-20-09-350-801-03	RESTORATION NO. 2 ENGINE FIRST-SHOOT, NO. 1 ENGINE SECOND-SHOOT FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION)									
26.100	861630	MOS	60				03-MAY-2017	03-MAY-2022		1658 d
MANDATORY	22635 REF: AMM 26-20-09-350-801	HRS/MSC AFL								
+ 26-20-09-350-801-04	RESTORATION NO. 3 ENGINE FIRST-SHOOT, NO. 2 ENGINE SECOND-SHOOT FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION)									
26.110	861630	MOS	60				05-JUN-2017	05-JUN-2022		1691 d
MANDATORY	55877 REF: AMM 26-20-09-350-801	HRS/MSC AFL								
+ 26-20-09-350-801-05	RESTORATION NO. 2 ENGINE FIRST-SHOOT, NO. 3 ENGINE SECOND-SHOOT FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION)									
26.090	861630	MOS	60				02-JUN-2017	02-JUN-2022		1688 d
MANDATORY	57255 REF: AMM 26-20-09-350-801	HRS/MSC AFL								
26-20-09-900-801-01	APU, BAGGAGE COMPARTMENT EXTINGUISHER									
26.120	861630	MOS		TSN:292 TSO:3			15-JUN-2017			
	54752	HRS/MSC	H/T	TSO:0			10663			
	REF: AMM 26-20-09-900-801	AFL		TSO:0			6123			
26-20-09-900-801-02	NO. 1 ENGINE FIRST-SHOOT, NO. 2 ENGINE SECOND-SHOOT FIRE EXTINGUISHER									
26.080	861630	MOS		TSN:230 TSO:0			15-JUN-2017			
	56866	HRS/MSC	H/T	TSO:0			10663			
	REF: AMM 26-20-09-900-801	AFL		TSO:0			6123			
26-20-09-900-801-03	NO. 2 ENGINE FIRST-SHOOT, NO. 1 ENGINE SECOND-SHOOT FIRE EXTINGUISHER									
26.100	861630	MOS		TSN:379 TSO:1			15-JUN-2017			
	22635	HRS/MSC	H/T	TSO:0			10663			
	REF: AMM 26-20-09-900-801	AFL		TSO:0			6123			
26-20-09-900-801-04	NO. 3 ENGINE FIRST-SHOOT, NO. 2 ENGINE SECOND-SHOOT FIRE EXTINGUISHER									
26.110	861630	MOS		TSN:255 TSO:0			15-JUN-2017			
	55877	HRS/MSC	H/T	TSO:0			10663			
	REF: AMM 26-20-09-900-801	AFL		TSO:0			6123			
26-20-09-900-801-05	NO. 2 ENGINE FIRST-SHOOT, NO. 3 ENGINE SECOND-SHOOT FIRE EXTINGUISHER									
26.090	861630	MOS		TSN:224 TSO:0			15-JUN-2017			
	57255	HRS/MSC	H/T	TSO:0			10663			
	REF: AMM 26-20-09-900-801	AFL		TSO:0			6123			
26-20-11-700-801-01 (s)	CHECKING OF THE APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER FOR CLOGGING						PKG			
	PKG 31	MOS	72	+2m			05-MAY-2014			
		HRS/MSC					9515			
	REF: AMM 26-20-11-700-801	AFL	3750				5634			
26-20-11-700-801-02 (s)	CHECKING OF THE NO. 1 ENGINE FIRST-SHOOT, NO. 2 ENGINE SECOND-SHOOT FIRE EXTINGUISHER LINES FOR CLOGGING						PKG			
	PKG 31	MOS	72	+2m			05-MAY-2014			
		HRS/MSC					9515			
	REF: AMM 26-20-11-700-801	AFL	3750				5634			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-20-11-700-801-03 (s)	CHECKING OF THE NO. 2 ENGINE FIRST-SHOOT, NO. 1 ENGINE SECOND-SHOOT FIRE EXTINGUISHER LINES FOR CLOGGING PKG 31 REF: AMM 26-20-11-700-801	MOS HRS/MSC AFL	72 +2m 3750				PKG 05-MAY-2014 9515 5634			
26-20-11-700-801-04 (s)	CHECKING OF THE NO. 3 ENGINE FIRST-SHOOT, NO. 2 ENGINE SECOND-SHOOT FIRE EXTINGUISHER LINES FOR CLOGGING PKG 31 REF: AMM 26-20-11-700-801	MOS HRS/MSC AFL	72 +2m 3750				PKG 05-MAY-2014 9515 5634			
26-20-11-700-801-05 (s)	CHECKING OF THE NO. 2 ENGINE FIRST-SHOOT, NO. 3 ENGINE SECOND-SHOOT FIRE EXTINGUISHER LINES FOR CLOGGING PKG 31 REF: AMM 26-20-11-700-801	MOS HRS/MSC AFL	72 +2m 3750				PKG 05-MAY-2014 9515 5634			
26-20-12-900-801-01 26.200	NO. 1 ENGINE SHUTTLE VALVE 861585 4577 REF: AMM 26-20-12-900-801	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0		02/16/2006	16-FEB-2005 6095.7 3647			
26-20-12-900-801-02 26.200	NO. 3 ENGINE SHUTTLE VALVE 861585 4578 REF: AMM 26-20-12-900-801	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			16-FEB-2005 6095.7 3647			
26-20-12-900-801-03 26.210	NO. 2 ENGINE LH SHUTTLE VALVE 861585 361 REF: AMM 26-20-12-900-801	MOS HRS/MSC AFL	H/T	TSN:0			27-FEB-1990 0 0			
26-20-12-900-801-04 26.210	NO. 2 ENGINE RH SHUTTLE VALVE 861585 4579 REF: AMM 26-20-12-900-801	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			16-FEB-2005 6095.7 3647			
26-20-12-960-801-01 SCRAP	DISCARD NO. 1 ENGINE SHUTTLE VALVE 861585 4577 REF: AMM 26-20-12-960-801	MOS HRS/MSC AFL	A/R	TSI:0 TSI:0 TSI:0			16-FEB-2005 6095.7 3647			
26-20-12-960-801-02 SCRAP	DISCARD NO. 3 ENGINE SHUTTLE VALVE 861585 4578 REF: AMM 26-20-12-960-801	MOS HRS/MSC AFL	A/R	TSI:0 TSI:0 TSI:0			16-FEB-2005 6095.7 3647			
26-20-12-960-801-03 SCRAP	DISCARD NO. 2 ENGINE LH SHUTTLE VALVE 861585 361 REF: AMM 26-20-12-960-801	MOS HRS/MSC AFL	A/R	TSI:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-20-12-960-801-04	DISCARD NO. 2 ENGINE RH SHUTTLE VALVE 861585 4579 REF: AMM 26-20-12-960-801	MOS HRS/MSC AFL	A/R	TSI:0 TSI:0 TSI:0			16-FEB-2005 6095.7 3647			
SCRAP										
26-20-13-900-801-01	NO. 1 ENGINE FIRST SHOOT FIRE EXTINGUISHER PERCUSSION (L3WB) CARTRIDGE 861385 NSN REF: AMM 26-20-13-900-801	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
26-20-13-900-801-02	NO. 3 ENGINE FIRST SHOOT FIRE EXTINGUISHER PERCUSSION (R3WB) CARTRIDGE 861375 NSN REF: AMM 26-20-13-900-801	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
26-20-13-900-801-03	NO. 2 ENGINE SECOND SHOOT LH FIRE EXTINGUISHER PERCUSSION (L4WB) CARTRIDGE 861375 NSN REF: AMM 26-20-13-900-801	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
26-20-13-900-801-04	NO. 2 ENGINE SECOND SHOOT RH FIRE EXTINGUISHER PERCUSSION (R4WB) CARTRIDGE 861385 NSN REF: AMM 26-20-13-900-801	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
26-20-13-900-801-05	NO. 1 ENGINE SECOND SHOOT FIRE EXTINGUISHER PERCUSSION (L5WB) CARTRIDGE 861385 NSN REF: AMM 26-20-13-900-801	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
26-20-13-900-801-06	NO. 3 ENGINE SECOND SHOOT FIRE EXTINGUISHER PERCUSSION (R5WB) CARTRIDGE 861375 NSN REF: AMM 26-20-13-900-801	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
26-20-13-900-801-07	NO. 2 ENGINE FIRST SHOOT LH FIRE EXTINGUISHER PERCUSSION (L6WB) CARTRIDGE 861375 NSN REF: AMM 26-20-13-900-801	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
26-20-13-900-801-08	NO. 2 ENGINE FIRST SHOOT RH FIRE EXTINGUISHER PERCUSSION (R6WB) CARTRIDGE 861385 NSN REF: AMM 26-20-13-900-801	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
26-20-13-900-801-09	APU FIRE EXTINGUISHER PERCUSSION (27WB) CARTRIDGE 861375 NSN REF: AMM 26-20-13-900-801	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
26-20-13-900-801-10	BAGGAGE COMPARTMENT FIRE EXTINGUISHER PERCUSSION (9WB) CARTRIDGE 861385 NSN REF: AMM 26-20-13-900-801	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-20-13-960-801-01	DISCARD NO. 1 ENGINE FIRST SHOOT FIRE EXTINGUISHER PERCUSSION (L3WB) CARTRIDGE (SERVICE LIFE)									
26.080	861385	MOS	60				25-AUG-2016	25-AUG-2021		1407 d
SCRAP	NSN REF: AMM 26-20-13-960-801	HRS/MSC AFL								
26-20-13-960-801-01M	DISCARD NO. 1 ENGINE FIRST SHOOT FIRE EXTINGUISHER PERCUSSION (L3WB) CARTRIDGE (LIFE LIMIT)									
26.080	861385	MOS	84				22-MAR-2016	22-MAR-2023		1981 d
LIFE LIMIT	NSN REF: AMM 26-20-13-960-801	HRS/MSC AFL								
26-20-13-960-801-02	DISCARD NO. 3 ENGINE FIRST SHOOT FIRE EXTINGUISHER PERCUSSION (R3WB) CARTRIDGE (SERVICE LIFE)									
26.110	861375	MOS	60				25-AUG-2016	25-AUG-2021		1407 d
SCRAP	NSN REF: AMM 26-20-13-960-801	HRS/MSC AFL								
26-20-13-960-801-02M	DISCARD NO. 3 ENGINE FIRST SHOOT FIRE EXTINGUISHER PERCUSSION (R3WB) CARTRIDGE (LIFE LIMIT)									
26.110	861375	MOS	84				22-MAR-2016	22-MAR-2023		1981 d
LIFE LIMIT	NSN REF: AMM 26-20-13-960-801	HRS/MSC AFL								
26-20-13-960-801-03	DISCARD NO. 2 ENGINE SECOND SHOOT LH FIRE EXTINGUISHER PERCUSSION (L4WB) CARTRIDGE (SERVICE LIFE)									
26.080	861375	MOS	60				25-AUG-2016	25-AUG-2021		1407 d
SCRAP	NSN REF: AMM 26-20-13-960-801	HRS/MSC AFL								
26-20-13-960-801-03M	DISCARD NO. 2 ENGINE SECOND SHOOT LH FIRE EXTINGUISHER PERCUSSION (L4WB) CARTRIDGE (LIFE LIMIT)									
26.080	861375	MOS	84				22-MAR-2016	22-MAR-2023		1981 d
LIFE LIMIT	NSN REF: AMM 26-20-13-960-801	HRS/MSC AFL								
26-20-13-960-801-04	DISCARD NO. 2 ENGINE SECOND SHOOT RH FIRE EXTINGUISHER PERCUSSION (R4WB) CARTRIDGE (SERVICE LIFE)									
26.110	861385	MOS	60				25-AUG-2016	25-AUG-2021		1407 d
SCRAP	NSN REF: AMM 26-20-13-960-801	HRS/MSC AFL								
26-20-13-960-801-04M	DISCARD NO. 2 ENGINE SECOND SHOOT RH FIRE EXTINGUISHER PERCUSSION (R4WB) CARTRIDGE (LIFE LIMIT)									
26.110	861385	MOS	84				22-MAR-2016	22-MAR-2023		1981 d
LIFE LIMIT	NSN REF: AMM 26-20-13-960-801	HRS/MSC AFL								
26-20-13-960-801-05	DISCARD NO. 1 ENGINE SECOND SHOOT FIRE EXTINGUISHER PERCUSSION (L5WB) CARTRIDGE (SERVICE LIFE)									
26.100	861385	MOS	60				25-AUG-2016	25-AUG-2021		1407 d
SCRAP	NSN REF: AMM 26-20-13-960-801	HRS/MSC AFL								
26-20-13-960-801-05M	DISCARD NO. 1 ENGINE SECOND SHOOT FIRE EXTINGUISHER PERCUSSION (L5WB) CARTRIDGE (LIFE LIMIT)									
26.100	861385	MOS	84				22-MAR-2016	22-MAR-2023		1981 d
LIFE LIMIT	NSN REF: AMM 26-20-13-960-801	HRS/MSC AFL								
26-20-13-960-801-06	DISCARD NO. 3 ENGINE SECOND SHOOT FIRE EXTINGUISHER PERCUSSION (R5WB) CARTRIDGE (SERVICE LIFE)									
26.090	861375	MOS	60				25-AUG-2016	25-AUG-2021		1407 d
SCRAP	NSN REF: AMM 26-20-13-960-801	HRS/MSC AFL								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-20-13-960-801-06M	DISCARD NO. 3 ENGINE SECOND SHOOT FIRE EXTINGUISHER PERCUSSION (R5WB) CARTRIDGE (LIFE LIMIT)									
26.090	861375 NSN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	84				22-MAR-2016	22-MAR-2023		1981 d
LIFE LIMIT										
26-20-13-960-801-07	DISCARD NO. 2 ENGINE FIRST SHOOT LH FIRE EXTINGUISHER PERCUSSION (L6WB) CARTRIDGE (SERVICE LIFE)									
26.100	861375 NSN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	60				25-AUG-2016	25-AUG-2021		1407 d
SCRAP										
26-20-13-960-801-07M	DISCARD NO. 2 ENGINE FIRST SHOOT LH FIRE EXTINGUISHER PERCUSSION (L6WB) CARTRIDGE (LIFE LIMIT)									
26.100	861375 NSN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	84				22-MAR-2016	22-MAR-2023		1981 d
LIFE LIMIT										
26-20-13-960-801-08	DISCARD NO. 2 ENGINE FIRST SHOOT RH FIRE EXTINGUISHER PERCUSSION (R6WB) CARTRIDGE (SERVICE LIFE)									
26.090	861385 NSN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	60				25-AUG-2016	25-AUG-2021		1407 d
SCRAP										
26-20-13-960-801-08M	DISCARD NO. 2 ENGINE FIRST SHOOT RH FIRE EXTINGUISHER PERCUSSION (R6WB) CARTRIDGE (LIFE LIMIT)									
26.090	861385 NSN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	84				22-MAR-2016	22-MAR-2023		1981 d
LIFE LIMIT										
26-20-13-960-801-09	DISCARD APU FIRE EXTINGUISHER PERCUSSION (27WB) CARTRIDGE (SERVICE LIFE)									
26.120	861375 NSN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	60				25-AUG-2016	25-AUG-2021		1407 d
SCRAP										
26-20-13-960-801-09M	DISCARD APU FIRE EXTINGUISHER PERCUSSION (27WB) CARTRIDGE (LIFE LIMIT)									
26.120	861375 NSN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	84				22-MAR-2016	22-MAR-2023		1981 d
LIFE LIMIT										
26-20-13-960-801-10	DISCARD BAGGAGE COMPARTMENT FIRE EXTINGUISHER PERCUSSION (9WB) CARTRIDGE (SERVICE LIFE)									
26.120	861385 NSN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	60				25-AUG-2016	25-AUG-2021		1407 d
SCRAP										
26-20-13-960-801-10M	DISCARD BAGGAGE COMPARTMENT FIRE EXTINGUISHER PERCUSSION (9WB) CARTRIDGE (LIFE LIMIT)									
26.120	861385 NSN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	84				22-MAR-2016	22-MAR-2023		1981 d
LIFE LIMIT										
+ 26-20-15-720-801-01	WEIGHING COCKPIT PORTABLE HALON FIRE EXTINGUISHER									
26.130	C352TS B-00097568 REF: AMM 26-20-15-720-801	MOS HRS/MSC AFL	12	+3%			20-SEP-2017	20-SEP-2018	30-SEP-2018	337 d (+10)
+ 26-20-15-720-801-02	WEIGHING FORWARD CABIN PORTABLE HALON FIRE EXTINGUISHER									
26.140	C352TS B-00096347 REF: AMM 26-20-15-720-801	MOS HRS/MSC AFL	12	+3%			20-SEP-2017	20-SEP-2018	30-SEP-2018	337 d (+10)



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 26-20-15-720-801-03	WEIGHING AFT CABIN PORTABLE HALON FIRE EXTINGUISHER									
26.150	C3528TS Y-548303 REF: AMM 26-20-15-720-801	MOS HRS/MSC AFL	12	+3%			20-SEP-2017	20-SEP-2018	30-SEP-2018	337 d (+10)
+ 26-20-15-790-801-01	HYDROSTATIC TEST COCKPIT PORTABLE HALON FIRE EXTINGUISHER									
26.130	C352TS B-00097568 REF: AMM 26-20-15-790-801	MOS HRS/MSC AFL	144				30-AUG-2016	30-AUG-2028		3969 d
+ 26-20-15-790-801-02	HYDROSTATIC TEST FORWARD CABIN PORTABLE HALON FIRE EXTINGUISHER									
26.140	C352TS B-00096347 REF: AMM 26-20-15-790-801	MOS HRS/MSC AFL	144				30-AUG-2016	30-AUG-2028		3969 d
+ 26-20-15-790-801-03	HYDROSTATIC TEST AFT CABIN PORTABLE HALON FIRE EXTINGUISHER									
26.150	C3528TS Y-548303 REF: AMM 26-20-15-790-801	MOS HRS/MSC AFL	144				01-DEC-2013	01-DEC-2025		2966 d
26-20-15-790-801-04S	HYDROSTATIC TEST BAGGAGE COMPARTMENT PORTABLE EXTINGUISHER									
	PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
26-20-19-720-801-01	WEIGHING DISPOSABLE FIRE EXTINGUISHER									
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A							
26-90-01-900-801-01	DISPOSABLE FIRE EXTINGUISHER									
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C				TSN:0 TSN:0 TSN:0 TSN:0	27-FEB-1990 0 0 0		
260101	FIRE EXTINGUISHING PANEL									
26.010	90350-1 116 REF:	MOS HRS/MSC AFL	O/C				TSN:0	27-FEB-1990 0 0		
260111	FIRE WARNING HORN									
	204ZS01Y05 122 REF:	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0	20-JUL-1990 27 14		
261251	BAGGAGE COMPARTMENT SMOKE DETECTOR									
26.060	30-231-14 18734 REF:	MOS HRS/MSC AFL	O/C					12-DEC-2008 7241.5		
261301	NO. 1 AND NO. 3 ENGINE MONITOR BOX									
26.070	6342-01 353 REF:	MOS HRS/MSC AFL	O/C				TSN:0	27-FEB-1990 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
261311	NO. 2 ENGINE AND APU FIRE MONITOR BOX									
26.070	6342-01 354 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
262601	COCKPIT PORTABLE HALON FIRE EXTINGUISHER									
26.130	C352TS B-00097568 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
262651	FORWARD CABIN PORTABLE HALON FIRE EXTINGUISHER									
26.140	C352TS B-00096347 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
262701	AFT CABIN PORTABLE HALON FIRE EXTINGUISHER									
26.150	C3528TS Y-548303 REF:	MOS HRS/MSC AFL	O/C	TSN:20 TSN:468.6 TSN:205			06-AUG-2015 9983.6 5839			
262751	BAGGAGE COMPARTMENT PORTABLE EXTINGUISHER									
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/A							
CHAPTER 27 FLIGHT CONTROLS										
+ 27-00-00-220-801-01A INTEGRITY CHECK AND VISUAL INSPECTION FOR CORROSION AND EXTERNAL LEAKS ON FLIGHT CONTROL HYDRAULIC COMPONENTS (MANDATORY 5-40)										
27.010		MOS HRS/MSC AFL	4000				26-MAY-2012 8750.4	12606		1830.3
MANDATORY 5-40	REF: AMM 27-00-00-220-801				-144.4					
27-00-00-640-801-01 (s)	PRESSURE GREASE OF THE LH AILERON SERVO-ACTUATOR BEARINGS						PKG			
27.065	PKG 32 REF: AMM 27-00-00-640-801	MOS HRS/MSC AFL	144	+2m			05-MAY-2014 9515 5634			
27-00-00-640-801-02 (s)	PRESSURE GREASE OF THE RH AILERON SERVO-ACTUATOR BEARINGS						PKG			
27.065	PKG 32 REF: AMM 27-00-00-640-801	MOS HRS/MSC AFL	144	+2m			05-MAY-2014 9515 5634			
27-00-00-640-801-03 (s)	PRESSURE GREASING OF THE RUDDER SERVO-ACTUATOR BEARINGS						PKG			
27.125	PKG 32 REF: AMM 27-00-00-640-801	MOS HRS/MSC AFL	144	+2m			05-MAY-2014 9515 5634			
27-00-00-640-801-04 (s)	PRESSURE GREASING OF THE ELEVATOR SERVO-ACTUATOR BEARING						PKG			
27.200	PKG 32 REF: AMM 27-00-00-640-801	MOS HRS/MSC AFL	144	+2m			05-MAY-2014 9515 5634			
27-00-00-640-803-01 (s)	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS IN PRESSURIZED AREA						PKG			
27.020	PKG 32 REF: AMM 27-00-00-640-803	MOS HRS/MSC AFL	144	+2m			05-MAY-2014 9515 5634			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-00-00-640-804-01 (s)	PRESSURE GREASING / LUBRICATION OF THE FLIGHT CONTROL BEARINGS AND HINGE PINS OUTSIDE PRESSURIZED AREA						PKG			
27.015	PKG 32	MOS	144	+2m			05-MAY-2014			
	REF: AMM 27-00-00-640-804	HRS/MSC AFL	7500				9515 5634			
+ 27-00-00-640-806-01 (s)	VISUAL INSPECTION AND GREASING OF THE OF THE RUDDER PRESSURE SEALED BOX						PKG			
27.155	PKG 32	MOS	144	+2m			05-MAY-2014			
	REF: AMM 27-00-00-640-806	HRS/MSC AFL	7500				9515 5634			
+ 27-00-00-640-806-02 (s)	VISUAL INSPECTION AND GREASING OF THE ELEVATOR PRESSURE SEALED BOX						PKG			
27.252	PKG 32	MOS	144	+2m			05-MAY-2014			
	REF: AMM 27-00-00-640-806	HRS/MSC AFL	7500				9515 5634			
27-00-00-710-801-01 (s)	OPERATIONAL TEST OF THE FLIGHT CONTROL - NO. 1 HYDRAULIC SYSTEM						PKG			
	PKG 21	MOS	1600	+40			20-SEP-2017			
	REF: AMM 27-00-00-710-801	HRS/MSC AFL					10758.2 6172			
27-00-00-710-801-02 (s)	OPERATIONAL TEST OF THE FLIGHT CONTROL - NO. 2 HYDRAULIC SYSTEM						PKG			
	PKG 21	MOS	1600	+40			20-SEP-2017			
	REF: AMM 27-00-00-710-801	HRS/MSC AFL					10758.2 6172			
27-00-00-710-802-01 (s)	OPERATIONAL TEST OF THE AILERON TRIM SYSTEM						PKG			
	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 27-00-00-710-802	HRS/MSC AFL	3750				9515 5634			
27-00-00-710-802-02 (s)	OPERATIONAL TEST OF THE EMERGENCY AILERON TRIM SYSTEM						PKG			
	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 27-00-00-710-802	HRS/MSC AFL	3750				9515 5634			
+ 27-00-00-710-802-03 (s)	OPERATIONAL TEST RUDDER TRIM						PKG			
27.075	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 27-00-00-710-802	HRS/MSC AFL	3750				9515 5634			
+ 27-00-00-720-803-01 (s)	FUNCTIONAL TEST OF THE LH AILERON NEUTRAL RETURN UNIT (AAFU CONNECTION AND VISUAL INSPECTION)						PKG			
27.095	PKG 32	MOS	144	+2m			05-MAY-2014			
	REF: AMM 27-00-00-720-803	HRS/MSC AFL	7500				9515 5634			
+ 27-00-00-720-803-01A	FUNCTIONAL CHECK LH AILERON NEUTRAL RETURN UNIT (AAFU CONNECTION AND VISUAL INSPECTION) (MANDATORY 5-40)									
27.095	105045-06	MOS					05-MAY-2014			
MANDATORY 5-40	3255	HRS/MSC	10000				9515	19515		8739.3
	REF: AMM 27-00-00-720-803	AFL					5634			
+ 27-00-00-720-803-02 (s)	FUNCTIONAL TEST OF THE RH AILERON NEUTRAL RETURN UNIT (AAFU CONNECTION AND VISUAL INSPECTION)						PKG			
27.095	PKG 32	MOS	144	+2m			05-MAY-2014			
	REF: AMM 27-00-00-720-803	HRS/MSC AFL	7500				9515 5634			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 27-00-00-720-803-02A	FUNCTIONAL CHECK RH AILERON NEUTRAL RETURN UNIT CONNECTION AND VISUAL INSPECTION) (MANDATORU 5-40)									
27.095	105045-06	MOS					05-MAY-2014			
MANDATORY 5-40	3292	HRS/MSC	10000				9515	19515		8739.3
	REF: AMM 27-00-00-720-803	AFL					5634			
+ 27-00-00-720-803-03 (s)	FUNCTIONAL TEST OF THE PITCH AUXILIARY ARTIFICIAL FEEL (AAFU) UNIT (AAFU CONNECTION AND VISUAL INSPECTION)						PKG			
27.230	PKG 32	MOS	144	+2m			05-MAY-2014			
	REF: AMM 27-00-00-720-803	HRS/MSC	7500				9515			
		AFL					5634			
+ 27-00-00-720-803-03A	FUNCTIONAL TEST PITCH AUXILIARY ARTIFICIAL FEEL (AAFU) UNIT (AAFU CONNECTION AND VISUAL INSPECTION) (MANDATORY 5-40)									
27.230	105045-13	MOS					05-MAY-2014			
MANDATORY 5-40	3484	HRS/MSC	10000				9515	17212.6		6436.9
	REF: AMM 27-00-00-720-803	AFL					5634			
+ 27-00-00-720-803-04 (s)	FUNCTIONAL TEST OF THE YAW AUXILIARY ARTIFICIAL (AAFU) FEEL UNIT (AAFU CONNECTION AND VISUAL INSPECTION)						PKG			
27.165	PKG 32	MOS	144	+2m			05-MAY-2014			
	REF: AMM 27-00-00-720-803	HRS/MSC	7500				9515			
		AFL					5634			
+ 27-00-00-720-803-04A	FUNCTIONAL CHECK YAW AUXILIARY ARTIFICIAL (AAFU) FEEL UNIT (AAFU CONNECTION AND VISUAL INSPECTION) (MANDATORY 5-40)									
27.165	105070-04	MOS					05-MAY-2014			
MANDATORY 5-40	811	HRS/MSC	10000				9515	19515		8739.3
	REF: AMM 27-00-00-720-803	AFL					5634			
27-00-00-720-807-01	DETAILED CHECK OF THE AILERON FLIGHT CONTROL FORCE PATTERNS									
	REF: AMM 27-00-00-720-807	MOS					27-FEB-1990			
		HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
27-00-00-720-807-02	DETAILED CHECK OF THE RUDDER FLIGHT CONTROL FORCE PATTERNS									
	REF: AMM 27-00-00-720-807	MOS					27-FEB-1990			
		HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
27-00-00-720-807-03	DETAILED CHECK OF THE ELEVATOR FLIGHT CONTROL FORCE PATTERNS									
	REF: AMM 27-00-00-720-807	MOS					27-FEB-1990			
		HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
27-00-00-790-804-01 (s)	CHECK OF THE LH AILERON SERVO-ACTUATOR INTERNAL LEAKS						PKG			
27.065	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 27-00-00-790-804	HRS/MSC	3750				9515			
		AFL					5634			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-00-00-790-804-02 (s)	CHECK OF THE RH AILERON SERVO-ACTUATOR INTERNAL LEAKS						PKG			
27.065	PKG 31 REF: AMM 27-00-00-790-804	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
27-00-00-790-804-03 (s)	CHECK OF THE RUDDER SERVO-ACTUATOR INTERNAL LEAKS						PKG			
27.125	PKG 31 REF: AMM 27-00-00-790-804	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
27-00-00-790-804-04 (s)	CHECK OF THE ELEVATOR SERVO-ACTUATOR INTERNAL LEAKS						PKG			
27.200	PKG 31 REF: AMM 27-00-00-790-804	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
27-12-01-900-801-01	LH AILERON SERVO-ACTUATOR									
27.065	103117-05 532 REF: AMM 27-12-01-900-801	MOS HRS/MSC AFL	O/C		TSR:2 TSN:9515 TSR:0		05-MAY-2014 9515 5634			
27-12-01-900-801-02	RH AILERON SERVO-ACTUATOR									
27.065	103117-06 631 REF: AMM 27-12-01-900-801	MOS HRS/MSC AFL	O/C		TSR:2 TSN:9515 TSR:0		05-MAY-2014 9515 5634			
27-13-01-640-806-01 (s)	LUBRICATION OF THE ROLL CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA						PKG			
	PKG 31 REF: AMM 27-13-01-640-806	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
27-13-01-640-808-01 (s)	GREASING OF THE ROLL CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA						PKG			
27.050	PKG 16,18,203 REF: AMM 27-13-01-640-808	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
27-13-03-220-801-01 (s)	REMOVAL/INSTALLATION OF THE LH FR15 ROLL BELLCRANKS FOR INSPECTION AND REPLACEMENT OF BALL BEARINGS						PKG			
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
27-13-03-220-801-02 (s)	REMOVAL/INSTALLATION OF THE RH FR15 ROLL BELLCRANKS FOR INSPECTION AND REPLACEMENT OF BALL BEARINGS						PKG			
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
+ 27-13-05-640-801-01 (s)	VISUAL INSPECTION AND GREASING OF THE OF THE LH ROLL CONTROL SEALED BOX						PKG			
27.097	PKG 32 REF: AMM 27-13-05-640-801	MOS HRS/MSC AFL	144 7500	+2m			05-MAY-2014 9515 5634			
+ 27-13-05-640-801-02 (s)	VISUAL INSPECTION AND GREASING OF THE RH ROLL CONTROL SEALED BOX						PKG			
27.097	PKG 32 REF: AMM 27-13-05-640-801	MOS HRS/MSC AFL	144 7500	+2m			05-MAY-2014 9515 5634			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 27-14-01-350-801-01	RESTORATION ROLL TRIM ACTUATOR (FUNCTIONAL TEST)									
27.080	021057-32 7989 REF: AMM 27-14-01-350-801	MOS HRS/MSC AFL	144	+3%			27-FEB-2014	27-FEB-2026	06-JUL-2026	3054 d (+129)
27-14-01-900-801-01	ROLL TRIM ACTUATOR									
27.080	021057-32 7989 REF: AMM 27-14-01-900-801	MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			
+ 27-14-03-350-801-01	RESTORATION AILERON (ROLL) EMERGENCY TRIM ACTUATOR (FUNCTIONAL TEST)									
27.070	021127 310 REF: AMM 27-14-03-350-801	MOS HRS/MSC AFL	144	+3%			25-FEB-2014	25-FEB-2026	04-JUL-2026	3052 d (+129)
+ 27-14-05-720-801-01 (s)	FUNCTIONAL TEST OF THE AILERON TRIM BOX CONTROL SAFETY RELAYS						PKG			
27.085	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			05-MAY-2014 9515 5634			
+ 27-14-05-720-801-01A	FUNCTIONAL TEST AILERON TRIM BOX CONTROL SAFETY RELAYS (MANDATORY REF 5-40-10)									
27.085 MANDATORY 5-40	F10A641812A1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	20000				05-MAY-2014 9515 5634	29515		18739.3
27-15-01-640-801-01 (s)	PRESSURE GREASING OF THE OF THE ROLL ARTHUR VARIABLE BELLCRANK BEARINGS						PKG			
27.060	PKG 32 REF: AMM 27-15-01-640-801	MOS HRS/MSC AFL	144	+2m			05-MAY-2014 9515 5634			
+ 27-15-01-720-801-01 (s)	FUNCTIONAL TEST OF THE OF THE ROLL ARTHUR VARIABLE BELLCRANK						PKG			
27.060	PKG 31 REF: AMM 27-15-01-720-801	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
27-15-01-900-801-01	ROLL ARTHUR VARIABLE BELLCRANK									
27.060	106043-28 1964 REF: AMM 27-15-01-900-801	MOS HRS/MSC AFL	O/C			TSR:4 TSR:0 TSR:0	05-MAY-2014 9515 5634			
27-15-03-960-801-01	REPLACEMENT OF THE SEALS ON THE SWIVEL COUPLING OF THE ROLL ARTHUR VARIABLE BELLCRANK									
27-15-05-350-801-01	RESTORATION ROLL MAIN ARTIFICIAL (AFU) FEEL UNIT (FUNCTIONAL TEST / SERVICING)									
27.090	105124 85 REF: AMM 27-15-05-350-801	MOS HRS/MSC AFL	144	+3%			25-FEB-2014	25-FEB-2026	04-JUL-2026	3052 d (+129)
27-15-05-900-801-01	ROLL MAIN ARTIFICIAL (AFU) FEEL UNIT									
27.090	105124 85 REF: AMM 27-15-05-900-801	MOS HRS/MSC AFL	O/C			TSR:3 TSN:9515 TSR:0 TSR:0	05-MAY-2014 9515 5634			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-15-07-640-801-01 (s)	PRESSURE GREASING OF THE OF THE LH AILERON NEUTRAL RETURN UNIT BEARING						PKG			
27.095	PKG 32 REF: AMM 27-15-07-640-801	MOS HRS/MSC AFL	144 7500	+2m			05-MAY-2014 9515 5634			
27-15-07-640-801-02 (s)	PRESSURE GREASING OF THE OF THE RH AILERON NEUTRAL RETURN UNIT BEARING						PKG			
27.095	PKG 32 REF: AMM 27-15-07-640-801	MOS HRS/MSC AFL	144 7500	+2m			05-MAY-2014 9515 5634			
+ 27-22-01-350-801-01	RESTORATION RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST)									
27.125	103103-18 1151 REF: AMM 27-22-01-350-801	MOS HRS/MSC AFL	4000				11-JAN-2010 7635.9	11635.9		860.2
+ 27-22-01-350-801-01A	RESTORATION RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST) (MANDATORY REF 5-40-10)									
27.125 MANDATORY 5-40	103103-18 1151 REF: AMM 27-22-01-350-801	MOS HRS/MSC AFL	4000				11-JAN-2010 7635.9	11635.9		860.2
27-22-01-900-801-01	RUDDER SERVO-ACTUATOR									
27.125	103103-18 1151 REF: AMM 27-22-01-900-801	MOS HRS/MSC AFL	O/C				11-JAN-2010 7635.9			
27-23-01-640-806-01 (s)	LUBRICATION OF THE YAW CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA						PKG			
27.115	PKG 31 REF: AMM 27-23-01-640-806	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
27-23-01-640-807-01 (s)	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHING IN PRESSURIZED AREA						PKG			
27.110	PKG 31 REF: AMM 27-23-01-640-807	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
27-23-01-640-808-01 (s)	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA						PKG			
27.105	PKG 16,18,203 REF: AMM 27-23-01-640-808	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
+ 27-24-01-350-801-01	RESTORATION YAW TRIM ACTUATOR (FUNCTIONAL TEST)									
27.145	021057-28 7942 REF: AMM 27-24-01-350-801	MOS HRS/MSC AFL	144	+3%			03-FEB-2017 10425.7 6021	03-FEB-2029	12-JUN-2029	4126 d (+129)
27-24-01-900-801-01	YAW TRIM ACTUATOR									
27.145	021057-28 7942 REF: AMM 27-24-01-900-801	MOS HRS/MSC AFL	O/C			TSR:144 TSR:4321.3 TSR:2368	02-FEB-2017 10425.7 6021			
27-24-01-900-801-02	YAW MAIN ARTIFICIAL (AFU) FEEL UNIT									
27.160	105125 76 REF: AMM 27-24-01-900-801	MOS HRS/MSC AFL	O/C			TSR:0 TSR:0 TSR:0	07-FEB-2017 10425.7 6021			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 27-24-05-720-802-01 (s)	FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS						PKG			
27.150	PKG 32	MOS	144	+2m			05-MAY-2014			
	REF: AMM 27-24-05-720-802	HRS/MSC					9515			
		AFL	7500				5634			
+ 27-24-05-720-802-01A	FUNCTIONAL TEST YAW TRIM RELAY BOX SAFETY RELAYS (MANDATORY REF 5-40-10)									
27.150	FGFB600271010A2	MOS					05-MAY-2014			
MANDATORY 5-40	SN-UNKNOWN	HRS/MSC	20000				9515	29515		18739.3
	REF: AMM 27-24-05-720-802	AFL					5634			
27-25-05-350-801-01	RESTORATION YAW MAIN ARTIFICIAL (AFU) FEEL UNIT (FUNCTIONAL TEST / SERVICING)									
	105125	MOS	144	+3%			02-FEB-2017	02-FEB-2029	11-JUN-2029	4125 d (+129)
	76	HRS/MSC					10425.7			
	REF: AMM 27-25-05-350-801	AFL					6021			
27-25-07-350-801-01	RESTORATION YAW AUXILIARY ARTIFICIAL (AAFU) FEEL UNIT (FUNCTIONAL TEST / SERVICING)									
	105070-04	MOS	144	+3%			02-FEB-2017	02-FEB-2029	11-JUN-2029	4125 d (+129)
	811	HRS/MSC					10425.7			
	REF: AMM 27-25-07-350-801	AFL					6021			
27-31-01-640-801-01 (s)	GREASING OF THE OF THE PILOT CONTROL COLUMN						PKG			
27.025	PKG 32	MOS	144	+2m			05-MAY-2014			
	REF: AMM 27-31-01-640-801	HRS/MSC					9515			
		AFL	7500				5634			
27-31-01-640-801-02 (s)	GREASING OF THE OF THE COPILOT CONTROL COLUMN						PKG			
27.030	PKG 32	MOS	144	+2m			05-MAY-2014			
	REF: AMM 27-31-01-640-801	HRS/MSC					9515			
		AFL	7500				5634			
27-32-01-350-801-01	RESTORATION ELEVATOR SERVO-ACTUATOR (FUNCTIONAL TEST)									
	103129	MOS					26-SEP-2015			
	332	HRS/MSC	10000	+3%			10045.1	20045.1	20345.1	9269.4 (+300)
	REF: AMM 27-32-01-350-801	AFL					5863			
+ 27-32-01-350-801-01A	RESTORATION ELEVATOR SERVO-ACTUATOR (FUNCTIONAL TEST) (MANDATORY REF 5-40-10)									
27.200	103129	MOS					26-SEP-2015			
MANDATORY 5-40	332	HRS/MSC	14000				10045.1	24045.1		13269.4
	REF: AMM 27-32-01-350-801	AFL					5863			
27-32-01-900-801-01	ELEVATOR SERVO-ACTUATOR									
27.200	103129	MOS					26-SEP-2015			
	332	HRS/MSC	O/C				10045.1			
	REF: AMM 27-32-01-900-801	AFL					5863			
27-33-01-640-806-01 (s)	LUBRICATION OF THE PITCH CONTROL LINKAGE HING PINS OUTSIDE PRESSURIZED AREA						PKG			
27.185	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 27-33-01-640-806	HRS/MSC					9515			
		AFL	3750				5634			
27-33-01-640-807-01 (s)	GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA						PKG			
27.180	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 27-33-01-640-807	HRS/MSC					9515			
		AFL	3750				5634			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-33-01-640-808-01 (s)	GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA						PKG			
27.175	PKG 16,18,203 REF: AMM 27-33-01-640-808	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
+ 27-35-00-720-801-01 (s)	FUNCTIONAL TEST OF THE OF PITCH ARTHUR CONTROL SYSTEM						PKG			
27.193	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
27-35-01-640-801-01 (s)	PRESSURE GREASING OF THE OF THE PITCH ARTHUR VARIABLE BELLCRANK BEARING						PKG			
27.195	PKG 32 REF: AMM 27-35-01-640-801	MOS HRS/MSC AFL	144	+2m			05-MAY-2014 9515 5634			
27-35-01-900-801-01	PITCH ARTHUR VARIABLE BELLCRANK									
27.195	106126-01 89 REF: AMM 27-35-01-900-801	MOS HRS/MSC AFL	O/C				12-AUG-2015 9987.6 5842			
27-35-05-350-801-01	RESTORATION PITCH MAIN ARTIFICIAL FEEL (AFU) UNIT (FUNCTIONAL TEST / SERVICING)									
	105122-02 101 REF: AMM 27-35-05-350-801	MOS HRS/MSC AFL	144	+3%			27-FEB-2014	27-FEB-2026	06-JUL-2026	3054 d (+129)
27-35-07-350-801-01	RESTORATION PITCH AUXILIARY ARTIFICIAL FEEL (AAFU) UNIT (DISCARD OF BUSHING 105040002)									
27.230 MANDATORY 5-40	105045-13 3484 REF: AMM 27-35-07-350-801	MOS HRS/MSC AFL	O/C			TSI:2302.4 TSI:1319	05-MAY-2014 9515 5634			
27-35-07-350-801-01A	RESTORATION PITCH AUXILIARY ARTIFICIAL FEEL (AAFU) UNIT (DISCARD OF BUSHING 105040002) (MANDATORY 5-40)									
MANDATORY 5-40	105045-13 3484 REF: AMM 27-35-07-350-801	MOS HRS/MSC AFL	O/C							
27-35-07-640-801-01 (s)	PRESSURE GREASING OF THE OF THE PITCH AUXILIARY ARTIFICIAL FEEL (AAFU) UNIT BEARING						PKG			
27.230	PKG 32 REF: AMM 27-35-07-640-801	MOS HRS/MSC AFL	144	+2m		TSI:2302.4 TSI:1319	05-MAY-2014 9515 5634			
27-35-07-900-801-01	PITCH AUXILIARY ARTIFICIAL FEEL (AAFU) UNIT									
27.230	105045-13 3484 REF: AMM 27-35-07-900-801	MOS HRS/MSC AFL	O/C			TSR:2 TSO:2302.4 TSR:0 TSO:1319 TSR:0	05-MAY-2014 9515 5634			
+ 27-40-00-720-801-01 (s)	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER CONTROL AND INDICATING SYSTEM						PKG			
27.245	PKG 21 REF: AMM 27-40-00-720-801	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
+ 27-40-01-210-802-01	VISUAL INSPECTION HORIZONTAL STABILIZER ELECTRIC ACTUATOR									
27.255	021121-11 178 REF: AMM 27-40-01-210-802	MOS HRS/MSC AFL	72	+3%			07-SEP-2013 9353.3 5528	07-SEP-2019	11-NOV-2019	689 d (+65) 3096 (+112.5)

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-40-01-350-801-01	RESTORATION HORIZONTAL STABILIZER ELECTRIC ACTUATOR (FULL DISASSEMBLY, INSPECTION AND NDT)									
27.255	021121-11 178 REF: AMM 27-40-01-350-801	MOS HRS/MSC AFL	144 7500	+3% +3%			17-SEP-2013 9380.4 5539	17-SEP-2025 13039	26-JAN-2026 13264	2891 d (+131) 6857 (+225)
27-40-01-640-802-01 (s)	GREASING OF THE HORIZONTAL STABILIZER ELECTRIC ACTUATOR HINGES AND JACK SCREW						PKG			
27.255	PKG 2,5,201 REF: AMM 27-40-01-640-802	MOS HRS/MSC AFL	16 800	+1m +40			08-FEB-2017 10425.7 6021			
27-40-01-720-801-01 (s)	MEASUREMENT OF THE HORIZONTAL STABILIZER ACTUATOR NORMAL ELECTRIC MOTOR SLIP						PKG			
27.250	PKG 21 REF: AMM 27-40-01-720-801	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
27-40-01-900-801-01	HORIZONTAL STABILIZER ELECTRIC ACTUATOR									
27.255	021121-11 178 REF: AMM 27-40-01-900-801	MOS HRS/MSC AFL	O/C				07-SEP-2013 9353.3 5528			
27-40-03-100-802-01	CHECK / CLEANING OF THE HORIZONTAL STABILIZER ACTUATOR NORMAL ELECTRIC MOTOR ELECTROMAGNETIC BRAKE									
27.260	REF: AMM 27-40-03-100-802	MOS HRS/MSC AFL	O/C				22-JUL-1998 3669 2134			
27-40-03-760-801-01	MEASUREMENT OF THE OF THE HORIZONTAL STABILIZER ACTUATOR NORMAL ELECTRIC MOTOR DROP-OUT CURRENT OF THE ELECTROMAGNETIC BRAKE									
27.260	REF: AMM 27-40-03-760-801	MOS HRS/MSC AFL	O/C				18-SEP-2002 5317.6 3220			
27-40-03-900-801-01	HORIZONTAL STABILIZER ACTUATOR NORMAL ELECTRIC MOTOR									
27.260	0210972700(1234-2) 488 REF: AMM 27-40-03-900-801	MOS HRS/MSC AFL	O/C				22-JUL-1998 3669 2134			
27-40-05-900-801-01	HORIZONTAL STABILIZER POSITION REPEATER BOX									
27.262	016092-02 45 REF: AMM 27-40-05-900-801	MOS HRS/MSC AFL	O/C				23-APR-2013 9161.3 5420			
+ 27-40-15-710-801-01 (s)	OPERATIONAL TEST OF THE HORIZONTAL STABILIZER STANDBY CONTROL BOX						PKG			
27.270	PKG 32 REF: AMM 27-40-15-710-801	MOS HRS/MSC AFL	144 7500	+2m			05-MAY-2014 9515 5634			
+ 27-40-15-710-801-01A	OPERATIONAL TEST HORIZONTAL STABILIZER STANDBY CONTROL BOX (MANDATORY 5-40)									
27.270 MANDATORY 5-40	FGFB641810A2 SN-UNKNOWN REF: AMM 27-40-15-710-801	MOS HRS/MSC AFL	16000				05-MAY-2014 9515 5634	25515		14739.3
+ 27-40-17-720-801-01 (s)	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX						PKG			
27.265	PKG 23 REF: AMM 27-40-17-720-801	MOS HRS/MSC AFL	4800	+40			14-NOV-2009 7871.7			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 27-40-17-720-801-01A	FUNCTIONAL TEST HORIZONTAL STABILIZER RELAY BOX (MANDATORY 5-40)									
27.265	PN	MOS					14-NOV-2009			
MANDATORY 5-40	SN-UNKNOWN	HRS/MSC	5000				7871.7	12871.7		2096
	REF: AMM 27-40-17-720-801	AFL								
27-50-00-640-801-01 (s)	GREASING/LUBRICATION OF FLAP MECHANISMS						PKG			
27.515	PKG 1,16	MOS	8	+1m			20-SEP-2017			
	REF: AMM 27-50-00-640-801	HRS/MSC	400	+40			10758.2			
		AFL					6172			
+ 27-50-00-720-801-01 (s)	FUNCTIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM						PKG			
27.290	PKG 21	MOS					20-SEP-2017			
	REF: AMM 27-50-00-720-801	HRS/MSC	1600	+40			10758.2			
		AFL					6172			
+ 27-50-00-720-802-01 (s)	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM						PKG			
27.285	PKG 21	MOS					20-SEP-2017			
	REF: AMM 27-50-00-720-802	HRS/MSC	1600	+40			10758.2			
		AFL					6172			
+ 27-50-00-720-802-01A	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM (MANDATORY 5-40)									
27.285		MOS					20-SEP-2017			
MANDATORY 5-40	REF: AMM 27-50-00-720-802	HRS/MSC	1800				10758.2	12558.2		1782.5
		AFL					6172			
27-50-00-720-803-01 (s)	CHECK OF THE GEAR BACKLASH OF FLAP LINKAGE						PKG			
	PKG 21	MOS					20-SEP-2017			
	REF: AMM 27-50-00-720-803	HRS/MSC	1600	+40			10758.2			
		AFL					6172			
27-52-01-900-801-01	FLAP POWER DRIVE UNIT									
27.300	021138-05	MOS				TSR:0	04-APR-2003			
	253	HRS/MSC	O/C			TSR:0	5450.5			
	REF: AMM 27-52-01-900-801	AFL				TSR:0	3289			
+ 27-52-13-200-801-01 (s)	CHECK / GREASING OF LH WING FLAP CONTROL ROD SPLINES						PKG			
27.295	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 27-52-13-200-801	HRS/MSC	3750				9515			
		AFL					5634			
27-52-13-200-801-02 (s)	CHECK / GREASING OF RH WING FLAP CONTROL ROD SPLINES						PKG			
	PKG 31	MOS	72				05-MAY-2014			
	REF: AMM 27-52-13-200-801	HRS/MSC	3750				9515			
		AFL					5634			
27-53-01-220-801-01 (s)	CLEANING/CHECK OF THE OF THE LH OUTBOARD FLAP SCREW JACK ACTUATING SCREW						PKG			
	PKG 1,5	MOS	8	+1m			20-SEP-2017			
	REF: AMM 27-53-01-220-801	HRS/MSC	400	+40			10758.2			
		AFL					6172			
27-53-01-220-801-02 (s)	CLEANING/CHECK OF THE OF THE LH INBOARD FLAP LATERAL SCREW JACK ACTUATING SCREW						PKG			
	PKG 1,5	MOS	8	+1m			20-SEP-2017			
	REF: AMM 27-53-01-220-801	HRS/MSC	400	+40			10758.2			
		AFL					6172			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-220-801-03 (s)	CLEANING/CHECK OF THE OF THE LH INBOARD FLAP CENTER SCREW JACK ACTUATING SCREW PKG 1,5 REF: AMM 27-53-01-220-801	MOS HRS/MSC AFL	8 400	+1m +40			PKG 20-SEP-2017 10758.2 6172			
27-53-01-220-801-04 (s)	CLEANING/CHECK OF THE OF THE RH INBOARD FLAP CENTER SCREW JACK ACTUATING SCREW PKG 1,5 REF: AMM 27-53-01-220-801	MOS HRS/MSC AFL	8 400	+1m +40			PKG 20-SEP-2017 10758.2 6172			
27-53-01-220-801-05 (s)	CLEANING/CHECK OF THE OF THE RH INBOARD FLAP LATERAL SCREW JACK ACTUATING SCREW PKG 1,5 REF: AMM 27-53-01-220-801	MOS HRS/MSC AFL	8 400	+1m +40			PKG 20-SEP-2017 10758.2 6172			
27-53-01-220-801-06 (s)	CLEANING/CHECK OF THE OF THE RH OUTBOARD FLAP SCREW JACK ACTUATING SCREW PKG 1,5 REF: AMM 27-53-01-220-801	MOS HRS/MSC AFL	8 400	+1m +40			PKG 20-SEP-2017 10758.2 6172			
27-53-01-350-801-01 27.315	RESTORATION LH OUTBOARD FLAP SCREW JACK (OVERHAUL) 021137-15 1799 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
27-53-01-350-801-01A MANDATORY 5-40	RESTORATION LH OUTBOARD FLAP SCREW JACK (OVERHAUL) (MANDATORY 5-40) 021137-15 1799 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
27-53-01-350-801-02 27.320	RESTORATION LH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL) 021137-13 1802 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
27-53-01-350-801-02A MANDATORY 5-40	RESTORATION LH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL) (MANDATORY 5-40) 021137-13 1802 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
27-53-01-350-801-03 27.325	RESTORATION LH INBOARD FLAP CENTER SCREW JACK (OVERHAUL) 021137-13 1287 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	O/C							
27-53-01-350-801-03A MANDATORY 5-40	RESTORATION LH INBOARD FLAP CENTER SCREW JACK (OVERHAUL) (MANDATORY 5-40) 021137-13 1287 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	O/C							
27-53-01-350-801-04 27.330	RESTORATION RH INBOARD FLAP CENTER SCREW JACK (OVERHAUL) 021137-13 1640 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	O/C							

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-350-801-04A	RESTORATION RH INBOARD FLAP CENTER SCREW JACK (OVERHAUL) (MANDATORY 5-40)									
	021137-13	MOS								
	1640	HRS/MSC	O/C							
MANDATORY 5-40	REF: AMM 27-53-01-350-801	AFL								
27-53-01-350-801-05	RESTORATION RH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL)									
	021137-13	MOS								
27.335	2504	HRS/MSC	O/C							
	REF: AMM 27-53-01-350-801	AFL								
27-53-01-350-801-05A	RESTORATION RH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL) (MANDATORY 5-40)							27-FEB-1990		
	021137-13	MOS								
	2504	HRS/MSC	O/C					0		
MANDATORY 5-40	REF: AMM 27-53-01-350-801	AFL						0		
27-53-01-350-801-06	RESTORATION RH OUTBOARD FLAP SCREW JACK (OVERHAUL)							27-FEB-1990		
	021137-14	MOS								
27.340	1798	HRS/MSC	O/C					0		
	REF: AMM 27-53-01-350-801	AFL						0		
27-53-01-350-801-06A	RESTORATION RH OUTBOARD FLAP SCREW JACK (OVERHAUL) (MANDATORY 5-40)							27-FEB-1990		
	021137-14	MOS								
	1798	HRS/MSC	O/C					0		
MANDATORY 5-40	REF: AMM 27-53-01-350-801	AFL						0		
27-53-01-350-802-01	UPGRADE LH OUTBOARD FLAP SCREW JACK (AVIAC ONLY)							27-FEB-1990		
	021137-15	MOS								
	1799	HRS/MSC	N/A					0		
	REF: AMM 27-53-01-350-802	AFL						0		
		APH						0		
27-53-01-350-802-01A	UPGRADE LH OUTBOARD FLAP SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)							27-FEB-1990		
	021137-15	MOS								
	1799	HRS/MSC	N/A					0		
MANDATORY 5-40	REF: AMM 27-53-01-350-802	AFL						0		
		APH						0		
27-53-01-350-802-02	UPGRADE LH INBOARD FLAP LATERAL SCREW JACK (AVIAC ONLY)							27-FEB-1990		
	021137-13	MOS								
	1802	HRS/MSC	N/A					0		
	REF: AMM 27-53-01-350-802	AFL						0		
		APH						0		
27-53-01-350-802-02A	UPGRADE LH INBOARD FLAP LATERAL SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)							27-FEB-1990		
	021137-13	MOS								
	1802	HRS/MSC	N/A					0		
MANDATORY 5-40	REF: AMM 27-53-01-350-802	AFL						0		
		APH						0		
27-53-01-350-802-03	UPGRADE LH INBOARD FLAP CENTER SCREW JACK (AVIAC ONLY)							27-FEB-1990		
	021137-13	MOS								
	1287	HRS/MSC	N/A					0		
	REF: AMM 27-53-01-350-802	AFL						0		
		APH						0		

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-350-802-03A	UPGRADE LH INBOARD FLAP CENTER SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)									
	021137-13	MOS					27-FEB-1990			
	1287	HRS/MSC	N/A				0			
MANDATORY 5-40	REF: AMM 27-53-01-350-802	AFL					0			
		APH					0			
27-53-01-350-802-04	UPGRADE RH INBOARD FLAP CENTER SCREW JACK (AVIAC ONLY)									
	021137-13	MOS								
	1640	HRS/MSC	N/A							
	REF: AMM 27-53-01-350-802	AFL								
		APH								
27-53-01-350-802-04A	UPGRADE RH INBOARD FLAP CENTER SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)									
	021137-13	MOS					27-FEB-1990			
	1640	HRS/MSC	N/A				0			
MANDATORY 5-40	REF: AMM 27-53-01-350-802	AFL					0			
		APH					0			
27-53-01-350-802-05	UPGRADE RH INBOARD FLAP LATERAL SCREW JACK (AVIAC ONLY)									
	021137-13	MOS								
	2504	HRS/MSC	N/A							
	REF: AMM 27-53-01-350-802	AFL								
		APH								
27-53-01-350-802-05A	UPGRADE RH INBOARD FLAP LATERAL SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)									
	021137-13	MOS					27-FEB-1990			
	2504	HRS/MSC	N/A				0			
MANDATORY 5-40	REF: AMM 27-53-01-350-802	AFL					0			
		APH					0			
27-53-01-350-802-06	UPGRADE RH OUTBOARD FLAP SCREW JACK (AVIAC ONLY)									
	021137-14	MOS					27-FEB-1990			
	1798	HRS/MSC	N/A				0			
	REF: AMM 27-53-01-350-802	AFL					0			
		APH					0			
27-53-01-350-802-06A	UPGRADE RH OUTBOARD FLAP SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)									
	021137-14	MOS					27-FEB-1990			
	1798	HRS/MSC	N/A				0			
MANDATORY 5-40	REF: AMM 27-53-01-350-802	AFL					0			
		APH					0			
27-53-01-640-802-01 (s)	GREASING OF THE LH OUTBOARD FLAP SCREW JACK						PKG			
	PKG 2,5,201	MOS	16				08-FEB-2017			
		HRS/MSC	800				10425.7			
	REF: See Workcard	AFL					6021			
27-53-01-640-802-02 (s)	GREASING OF THE LH INBOARD FLAP LATERAL SCREW JACK						PKG			
	PKG 2,5,201	MOS	16				08-FEB-2017			
		HRS/MSC	800				10425.7			
	REF: See Workcard	AFL					6021			
27-53-01-640-802-03 (s)	GREASING OF THE LH INBOARD FLAP CENTER SCREW JACK						PKG			
	PKG 2,5,201	MOS	16				08-FEB-2017			
		HRS/MSC	800				10425.7			
	REF: See Workcard	AFL					6021			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-640-802-04 (s)	GREASING OF THE RH INBOARD FLAP CENTER SCREW JACK PKG 2,5,201 REF: See Workcard	MOS HRS/MSC AFL	16 800				PKG 08-FEB-2017 10425.7 6021			
27-53-01-640-802-05 (s)	GREASING OF THE RH INBOARD FLAP LATERAL SCREW JACK PKG 2,5,201 REF: See Workcard	MOS HRS/MSC AFL	16 800				PKG 08-FEB-2017 10425.7 6021			
27-53-01-640-802-06 (s)	GREASING OF THE RH OUTBOARD FLAP SCREW JACK PKG 2,5,201 REF: See Workcard	MOS HRS/MSC AFL	16 800				PKG 08-FEB-2017 10425.7 6021			
27-53-01-720-803-01	CHECK LH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) 021137-15 1799 REF: AMM 27-53-01-720-803	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
27-53-01-720-803-01A	CHECK LH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40) 021137-15 1799 MANDATORY 5-40 REF: AMM 27-53-01-720-803	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
27-53-01-720-803-02	CHECK LH INBOARD FLAP LATERAL SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) 021137-13 1802 REF: AMM 27-53-01-720-803	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
27-53-01-720-803-02A	CHECK LH INBOARD FLAP LATERAL SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40) 021137-13 1802 MANDATORY 5-40 REF: AMM 27-53-01-720-803	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
27-53-01-720-803-03	CHECK LH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) 021137-13 1287 REF: AMM 27-53-01-720-803	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
27-53-01-720-803-03A	CHECK LH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40) 021137-13 1287 MANDATORY 5-40 REF: AMM 27-53-01-720-803	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
27-53-01-720-803-04	CHECK RH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY 021137-13 1640 REF: AMM 27-53-01-720-803	MOS HRS/MSC AFL APH	N/A							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-720-803-04A	CHECK RH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40)									
	021137-13	MOS					27-FEB-1990			
	1640	HRS/MSC	N/A				0			
MANDATORY 5-40	REF: AMM 27-53-01-720-803	AFL					0			
		APH					0			
27-53-01-720-803-05	CHECK RH INBOARD FLAP LATERAL SCREW JACK SCREW/NUT PLAY (AVIAC ONLY)									
	021137-13	MOS								
	2504	HRS/MSC	N/A							
	REF: AMM 27-53-01-720-803	AFL								
		APH								
27-53-01-720-803-05A	CHECK RH INBOARD FLAP LATERAL SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40)									
	021137-13	MOS					27-FEB-1990			
	2504	HRS/MSC	N/A				0			
MANDATORY 5-40	REF: AMM 27-53-01-720-803	AFL					0			
		APH					0			
27-53-01-720-803-06	CHECK RH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY (AVIAC ONLY)									
	021137-14	MOS					27-FEB-1990			
	1798	HRS/MSC	N/A				0			
	REF: AMM 27-53-01-720-803	AFL					0			
		APH					0			
27-53-01-720-803-06A	CHECK RH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40)									
	021137-14	MOS					27-FEB-1990			
	1798	HRS/MSC	N/A				0			
MANDATORY 5-40	REF: AMM 27-53-01-720-803	AFL					0			
		APH					0			
27-53-01-720-804-01 (s)	CHECK OF THE OF THE LH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY (DED ONLY)						PKG			
	PKG 21	MOS					20-SEP-2017			
		HRS/MSC	1600	+40			10758.2			
	REF: AMM 27-53-01-720-804	AFL					6172			
27-53-01-720-804-02 (s)	CHECK OF THE OF THE LH INBOARD FLAP LATERAL SCREW JACK SCREW/NUT PLAY (DED ONLY)						PKG			
	PKG 21	MOS					20-SEP-2017			
		HRS/MSC	1600	+40			10758.2			
	REF: AMM 27-53-01-720-804	AFL					6172			
27-53-01-720-804-03 (s)	CHECK OF THE OF THE LH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY (DED ONLY)						PKG			
	PKG 21	MOS					20-SEP-2017			
		HRS/MSC	1600	+40			10758.2			
	REF: AMM 27-53-01-720-804	AFL					6172			
27-53-01-720-804-04 (s)	CHECK OF THE OF THE RH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY (DED ONLY)						PKG			
	PKG 21	MOS					20-SEP-2017			
		HRS/MSC	1600	+40			10758.2			
	REF: AMM 27-53-01-720-804	AFL					6172			
27-53-01-720-804-05 (s)	CHECK OF THE OF THE RH INBOARD FLAP LATERAL SCREW JACK SCREW/NUT PLAY (DED ONLY)						PKG			
	PKG 21	MOS					20-SEP-2017			
		HRS/MSC	1600	+40			10758.2			
	REF: AMM 27-53-01-720-804	AFL					6172			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-720-804-06 (s)	CHECK OF THE OF THE RH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY (DED ONLY) PKG 21	MOS					PKG			
	REF: AMM 27-53-01-720-804	HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
27-53-01-900-803-01	LH OUTBOARD FLAP SCREW JACK 021137-15	MOS					27-FEB-1990			
27.315	1799	HRS/MSC AFL	O/C		TSN:0		0 0			
	REF: AMM 27-53-01-900-803									
27-53-01-900-803-02	LH INBOARD FLAP LATERAL SCREW JACK 021137-13	MOS					27-FEB-1990			
27.320	1802	HRS/MSC AFL	O/C		TSN:0		0 0			
	REF: AMM 27-53-01-900-803									
27-53-01-900-803-03	LH INBOARD FLAP CENTER SCREW JACK 021137-13	MOS					16-SEP-2004			
27.325	1287	HRS/MSC AFL	O/C		TSN:4994 TSR:0 TSN:2977 TSR:0		6022.6 3607			
	REF: AMM 27-53-01-900-803									
27-53-01-900-803-04	RH INBOARD FLAP CENTER SCREW JACK 021137-13	MOS					13-JAN-2015			
27.330	1640	HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		9764.1 5742			
	REF: AMM 27-53-01-900-803									
27-53-01-900-803-05	RH INBOARD FLAP LATERAL SCREW JACK 021137-13	MOS					05-MAY-2014			
27.335	2504	HRS/MSC AFL	O/C		TSR:4 TSR:0 TSR:0		9515 5634			
	REF: AMM 27-53-01-900-803									
27-53-01-900-803-06	RH OUTBOARD FLAP SCREW JACK 021137-14	MOS					27-FEB-1990			
27.340	1798	HRS/MSC AFL	O/C		TSN:0		0 0			
	REF: AMM 27-53-01-900-803									
27-53-01-960-801-01	DISCARD LH OUTBOARD FLAP SCREW JACK 021137-15	MOS					27-FEB-1990			
	1799	HRS/MSC AFL	O/C		TSI:0		0 0			
	REF: AMM 27-53-01-960-801									
27-53-01-960-801-02	DISCARD LH INBOARD FLAP LATERAL SCREW JACK 021137-13	MOS					27-FEB-1990			
27.320	1802	HRS/MSC AFL	O/C		TSI:0		0 0			
	REF: AMM 27-53-01-960-801									
27-53-01-960-801-03	DISCARD LH INBOARD FLAP CENTER SCREW JACK 021137-13	MOS					16-SEP-2004			
27.325	1287	HRS/MSC AFL	O/C		TSI:4994 TSI:2977		6022.6 3607			
	REF: AMM 27-53-01-960-801									
27-53-01-960-801-04	DISCARD RH INBOARD FLAP CENTER SCREW JACK 021137-13	MOS								
27.330	1640	HRS/MSC AFL	O/C							
	REF: AMM 27-53-01-960-801									

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-960-801-05	DISCARD RH INBOARD FLAP LATERAL SCREW JACK									
27.335	021137-13 2504 REF: AMM 27-53-01-960-801	MOS HRS/MSC AFL	O/C							
27-53-01-960-801-06	DISCARD RH OUTBOARD FLAP SCREW JACK									
	021137-14 1798 REF: AMM 27-53-01-960-801	MOS HRS/MSC AFL	O/C	TSI:0			27-FEB-1990 0 0			
+ 27-60-00-710-803-01 (s)	OPERATIONAL TEST OF THE AIRBRAKES IN NORMAL MODE AND AUTOMATIC RETRACTION MODES						PKG			
27.365	PKG 21 REF: AMM 27-60-00-710-803	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
27-61-01-720-801-01 (s)	FUNCTIONAL TEST OF THE LH INBOARD AIRBRAKE POSITION MICROSWITCH						PKG			
	PKG 22 REF: AMM 27-61-01-720-801	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
27-61-01-720-801-02 (s)	FUNCTIONAL TEST OF THE LH CENTER AIRBRAKE POSITION MICROSWITCH						PKG			
	PKG 22 REF: AMM 27-61-01-720-801	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
27-61-01-720-801-03 (s)	FUNCTIONAL TEST OF THE LH OUTBOARD AIRBRAKE POSITION MICROSWITCH						PKG			
	PKG 22 REF: AMM 27-61-01-720-801	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
27-61-01-720-801-04 (s)	FUNCTIONAL TEST OF THE RH INBOARD AIRBRAKE POSITION MICROSWITCH						PKG			
	PKG 22 REF: AMM 27-61-01-720-801	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
27-61-01-720-801-05 (s)	FUNCTIONAL TEST OF THE RH CENTER AIRBRAKE POSITION MICROSWITCH						PKG			
	PKG 22 REF: AMM 27-61-01-720-801	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
27-61-01-720-801-06 (s)	FUNCTIONAL TEST OF THE RH OUTBOARD AIRBRAKE POSITION MICROSWITCH						PKG			
	PKG 22 REF: AMM 27-61-01-720-801	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
27-61-01-900-801-01	LH INBOARD AIRBRAKE POSITION MICROSWITCH MICROSWITCH									
27.390	602EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
27-61-01-900-801-02	LH CENTER AIRBRAKE POSITION MICROSWITCH									
27.390	602EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-61-01-900-801-03	LH OUTBOARD AIRBRAKE POSITION MICROSWITCH									
27.390	602EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
27-61-01-900-801-04	RH INBOARD AIRBRAKE POSITION MICROSWITCH									
27.395	602EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
27-61-01-900-801-05	RH CENTER AIRBRAKE POSITION MICROSWITCH									
27.395	602EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
27-61-01-900-801-06	RH OUTBOARD AIRBRAKE POSITION MICROSWITCH									
27.395	602EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
27-62-01-640-801-01 (s)	GREASING OF THE OF THE LH OUTBOARD AIRBRAKE ACTUATOR									
27.360	PKG 12,15,202 REF: AMM 27-62-01-640-801	MOS HRS/MSC AFL	16	+1m			PKG 08-FEB-2017 10425.7 6021			
27-62-01-640-801-02 (s)	GREASING OF THE OF THE LH MIDDLE AIRBRAKE ACTUATOR									
	PKG 12,15,202 REF: AMM 27-62-01-640-801	MOS HRS/MSC AFL	16				PKG 08-FEB-2017 10425.7 6021			
27-62-01-640-801-03 (s)	GREASING OF THE OF THE LH INBOARD AIRBRAKE ACTUATOR									
	PKG 12,15,202 REF: AMM 27-62-01-640-801	MOS HRS/MSC AFL	16				PKG 08-FEB-2017 10425.7 6021			
27-62-01-640-801-04 (s)	GREASING OF THE OF THE RH INBOARD AIRBRAKE ACTUATOR									
	PKG 12,15,202 REF: AMM 27-62-01-640-801	MOS HRS/MSC AFL	16				PKG 08-FEB-2017 10425.7 6021			
27-62-01-640-801-05 (s)	GREASING OF THE OF THE RH MIDDLE AIRBRAKE ACTUATOR									
	PKG 12,15,202 REF: AMM 27-62-01-640-801	MOS HRS/MSC AFL	16				PKG 08-FEB-2017 10425.7 6021			
27-62-01-640-801-06 (s)	GREASING OF THE OF THE RH OUTBOARD AIRBRAKE ACTUATOR									
	PKG 12,15,202 REF: AMM 27-62-01-640-801	MOS HRS/MSC AFL	16				PKG 08-FEB-2017 10425.7 6021			
27-62-01-900-801-01	LH OUTBOARD AIRBRAKE ACTUATOR									
27.380	106091-04 2617 REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	TSN:5317.6			27-SEP-2002 5317.6			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-62-01-900-801-02	LH MIDDLE AIRBRAKE ACTUATOR 106091-05 2621 REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	TSN:5317.6			27-SEP-2002 5317.6			
27-62-01-900-801-03	LH INBOARD AIRBRAKE ACTUATOR 106091-06 2637 REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	TSN:5317.6			27-SEP-2002 5317.6			
27-62-01-900-801-04	RH INBOARD AIRBRAKE ACTUATOR 106091-06 2538 REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C				27-SEP-2002 5317.6			
27-62-01-900-801-05	RH MIDDLE AIRBRAKE ACTUATOR 106091-05 2622 REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C				27-SEP-2002 5317.6			
27-62-01-900-801-06	RH OUTBOARD AIRBRAKE ACTUATOR 106091-04 2631 REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C				27-SEP-2002 5317.6			
27-80-00-640-801-01 (s)	GREASING/LUBRICATION OF THE SLAT MECHANISMS PKG 12,16 REF: See Workcard	MOS HRS/MSC AFL	16	+1m			PKG 08-FEB-2017 10425.7 6021			
+ 27-80-00-710-806-01 (s)	OPERATIONAL TEST OF THE GROUND / FLIGHT RELAYS AND ANGLE-OF-ATTACK SENSOR CONTACTS PKG 21 REF: AMM 27-80-00-710-806	MOS HRS/MSC AFL	1600	+40			PKG 20-SEP-2017 10758.2 6172			
27-80-05-900-801-01	LH INBOARD SLAT ACTUATOR 106107-12 2519 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C				27-SEP-2002 5317.6			
27-80-05-900-801-02	RH INBOARD SLAT ACTUATOR 106107-12 2520 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C				27-SEP-2002 5317.6			
27-80-05-900-801-03	LH OUTBOARD SLAT INBOARD ACTUATOR 106107-15 2527 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C				27-SEP-2002 5317.6			
27-80-05-900-801-04	RH OUTBOARD SLAT INBOARD ACTUATOR 106107-15 2509 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C				27-SEP-2002 5317.6			



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-80-05-900-801-05	LH OUTBOARD SLAT STANDBY ACTUATOR									
27.440	106107-17 2512 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C	TSN:5317.6			27-SEP-2002 5317.6			
27-80-05-900-801-06	RH OUTBOARD SLAT STANDBY ACTUATOR									
27.440	106107-17 2513 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C	TSN:5317.6			27-SEP-2002 5317.6			
27-80-05-900-801-07	LH OUTBOARD SLAT OUTBOARD ACTUATOR									
27.430	106107-13 2524 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C	TSN:5317.6			27-SEP-2002 5317.6			
27-80-05-900-801-08	RH OUTBOARD SLAT OUTBOARD ACTUATOR									
27.435	106107-13 2525 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C	TSN:5317.6			27-SEP-2002 5317.6			
+ 27-80-17-720-802-01 (s)	FUNCTIONAL TEST OF THE LH INBOARD SLAT EXTENDED MICROSWITCH						PKG			
27.465	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
+ 27-80-17-720-802-02 (s)	FUNCTIONAL TEST OF THE LH INBOARD SLAT RETRACTED MICROSWITCH						PKG			
27.460	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
+ 27-80-17-720-802-03 (s)	FUNCTIONAL TEST OF THE LH OUTBOARD SLAT RETRACTED MICROSWITCH						PKG			
27.470	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
+ 27-80-17-720-802-04 (s)	FUNCTIONAL TEST OF THE LH OUTBOARD SLAT EXTENDED MICROSWITCH						PKG			
27.475	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
+ 27-80-17-720-802-05 (s)	FUNCTIONAL TEST OF THE RH INBOARD SLAT EXTENDED MICROSWITCH						PKG			
27.465	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
+ 27-80-17-720-802-06 (s)	FUNCTIONAL TEST OF THE RH INBOARD SLAT RETRACTED MICROSWITCH						PKG			
27.460	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
+ 27-80-17-720-802-07 (s)	FUNCTIONAL TEST OF THE RH OUTBOARD SLAT RETRACTED MICROSWITCH						PKG			
27.470	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 27-80-17-720-802-08 (s)	FUNCTIONAL TEST OF THE RH OUTBOARD SLAT EXTENDED MICROSWITCH						PKG			
27.475	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
+ 27-80-17-720-802-09 (s)	FUNCTIONAL TEST OF THE FLAP POSITION MICROSWITCH						PKG			
27.477	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
27-80-17-900-801-01	LH INBOARD SLAT EXTENDED MICROSWITCH							27-FEB-1990		
27.465	602EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		0 0			
27-80-17-900-801-02	LH INBOARD SLAT RETRACTED MICROSWITCH							27-FEB-1990		
27.460	402EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		0 0			
27-80-17-900-801-03	LH OUTBOARD SLAT RETRACTED MICROSWITCH							27-FEB-1990		
27.470	402EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		0 0			
27-80-17-900-801-04	LH OUTBOARD SLAT EXTENDED MICROSWITCH							27-FEB-1990		
27.475	602EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		0 0			
27-80-17-900-801-05	RH INBOARD SLAT EXTENDED MICROSWITCH							27-FEB-1990		
27.465	602EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		0 0			
27-80-17-900-801-06	RH INBOARD SLAT RETRACTED MICROSWITCH							27-FEB-1990		
27.460	402EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		0 0			
27-80-17-900-801-07	RH OUTBOARD SLAT RETRACTED MICROSWITCH							27-FEB-1990		
27.470	402EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		0 0			
27-80-17-900-801-08	RH OUTBOARD SLAT EXTENDED MICROSWITCH							27-FEB-1990		
27.475	602EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		0 0			
27-80-17-900-803-01	FLAP POSITION MICROSWITCH							27-FEB-1990		
27.477	402EN1-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 27-80-23-720-801-01	FUNCTIONAL TEST INBOARD SLAT VALVE BOX									
27.425	108117-06 237 REF: AMM 27-80-23-720-801	MOS HRS/MSC AFL	144	+3%			05-MAR-2014	05-MAR-2026	14-JUL-2026	3060 d (+131)
+ 27-80-23-720-802-01	FUNCTIONAL TEST OUTBOARD SLAT VALVE BOX									
27.425	108117-05 165 REF: AMM 27-80-23-720-802	MOS HRS/MSC AFL	144	+3%			05-MAR-2014	05-MAR-2026	14-JUL-2026	3060 d (+131)
270101	PILOT CONTROL COLUMN									
27.025	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
270106	PILOT WHEEL									
27.025	FGFB215250850 091 REF:	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
270121	COPILOT CONTROL COLUMN									
27.030	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
270126	COPILOT WHEEL									
27.030	FGFB215500850 091 REF:	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
270201	TRIM/AIRBRAKE CONTROL									
27.035	013015-14 1273 REF:	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
270221	TRIPLE TRIM INDICATOR									
27.035	4863-557-80-13 216 REF: AMM 21-30-09-900-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
270241	SLATS/FLAPS CONTROL									
27.040	013016-21 675 REF:	MOS HRS/MSC AFL	O/C				02-SEP-2016 10217.5 5933			
271191	AILERON (ROLL) EMERGENCY TRIM ACTUATOR									
27.070	021127 310 REF: AMM 27-14-03-900-801	MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			
271251	AILERON TRIM BOX									
27.085	F10A641812A1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
271351	LH AILERON NEUTRAL RETURN UNIT 105045-06 3255 REF:	MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			
271381	RH AILERON NEUTRAL RETURN UNIT 105045-06 3292 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
271401	LH ROLL CONTROL SEALED BOX FGFB271111A1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
271421	RH ROLL CONTROL SEALED BOX FGFB271211A1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
271601	RUDDER PRESSURE SEALED BOX PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
271621	ELEVATOR PRESSURE SEALED BOX PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
272071	PILOT RUDDER BAR PEDAL ASSEMBLY 0CV299-03 161 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
272081	COPILOT RUDDER BAR PEDAL ASSEMBLY 0CV299-04 178 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
272091	PILOT PEDALS ADJUSTMENT ROD BOX 4505-1 300 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
272096	COPILOT PEDALS ADJUSTMENT ROD BOX 4505-1 301 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
272163	YAW TRIM RELAY BOX FGFB600271010A2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
272251	YAW AUXILIARY ARTIFICIAL (AAFU) FEEL UNIT									
27.165	105070-04 811 REF: AMM 27-25-07-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			02-FEB-2017 10425.7 6021			
273161	ARTHUR Q-UNIT PITCH SERVO VALVE									
27.215	108019-13 1714 REF:	MOS HRS/MSC AFL	O/C				01-AUG-1994 1776.5			
273171	PITCH ARTHUR BOX									
27.220	062175-03 111 REF:	MOS HRS/MSC AFL	O/C	TSR:13 TSR:199			04-OCT-2005 6221.6			
273201	PITCH MAIN ARTIFICIAL FEEL (AFU) UNIT									
27.225	105122-02 101 REF: AMM 27-35-05-900-801	MOS HRS/MSC AFL	O/C	TSR:3 TSR:0 TSR:0			05-MAY-2014 9515 5634			
274161	HORIZONTAL STABILIZER STANDBY ELECTRIC MOTOR									
27.260	993 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
274201	HORIZONTAL STABILIZER RELAY BOX									
27.265	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
274251	HORIZONTAL STABILIZER STANDBY CONTROL BOX									
27.270	FGFB641810A2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
275121	LH FLAP DUAL BEVEL GEAR									
27.305	021068-06 1109 REF:	MOS HRS/MSC AFL	O/C	TSN:0		08/14/2001	14-AUG-2000 4606 2779			
275141	RH FLAP DUAL BEVEL GEAR									
27.305	021068-06 851 REF:	MOS HRS/MSC AFL	O/C				31-AUG-2000 4606.6			
275161	LH FLAP BEVEL GEAR									
27.310	021063-01 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
275181	RH FLAP BEVEL GEAR									
27.310	021063-01 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
275351	LH FLAP POSITION TRANSMITTER									
27.350	1-4414-2 441 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
275361	RH FLAP POSITION TRANSMITTER									
27.350	2-4414-2 256 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
275371	FLAP ASYMMETRY DETECTOR									
27.355	J2201-2-10MEB SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
275401	CONFIGURATION PANEL									
27.355	205TS04Y01 488 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
276101	INBOARD/OUTBOARD AIRBRAKE SELECTOR VALVE									
27.370	65670-1 1174A REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
276141	MIDDLE AIRBRAKE SELECTOR VALVE									
27.370	65670-1 1170A REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
276181	AIRBRAKE HOLD VALVE									
27.375	D25AB1702 76 REF:	MOS HRS/MSC AFL	O/C			01/22/2002	22-JAN-2001 4704 2854			
276191	AIRBRAKE HOLD VALVE GAUGE									
27.375	18040100 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
276401	LH OUTBOARD AIRBRAKE RESTRICTOR									
27.402	C24370-202 B2851 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
276411	LH MIDDLE AIRBRAKE RESISTOR									
27.402	C24370-402 B2880 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
276421	LH INBOARD AIRBRAKE RESISTOR									
27.402	C24370-302 B2686 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
276431	RH INBOARD AIRBRAKE RESTRICTOR									
27.403	C24370-302 B2693 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
276441	RH MIDDLE AIRBRAKE RESTRICTOR									
27.403	C24370-402 B2881 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
276451	RH OUTBOARD AIRBRAKE RESTRICTOR									
27.403	C24370-202 B2852 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
278101	OUTBOARD SLAT AUTOMATIC DISTRIBUTOR									
27.415	108103-04 555 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
278111	OUTBOARD SLAT NORMAL SOLENOID SELECTOR/MANIFOLD VALVE									
27.415	108033-16 2015 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
278121	OUTBOARD SLAT STANDBY ELECTRIC DISTRIBUTOR									
27.420	65670-1 1168A REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
278131	INBOARD SLAT ELECTRIC DISTRIBUTOR									
27.420	65670-1 1158A REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
278151	INBOARD SLAT VALVE BOX									
27.425	108117-06 237 REF:	MOS HRS/MSC AFL	O/C	TSR:2 TSR:0 TSR:0			05-MAY-2014 9515 5634			
278171	OUTBOARD SLAT VALVE BOX									
27.425	108117-05 165 REF:	MOS HRS/MSC AFL	O/C	TSR:2 TSR:0 TSR:0			05-MAY-2014 9515 5634			
278401	LH INBOARD SLAT ACTUATOR EXTENSION RESTRICTOR									
27.445	C24346-102 B1279 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
278411	RH INBOARD SLAT ACTUATOR EXTENSION RESTRICTOR									
27.445	C24346-102 B1280 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
278421	LH OUTBOARD SLAT ACTUATOR EXTENSION RESTRICTOR VALVE C24370-102	MOS					27-FEB-1990			
27.450	B2814 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
278431	RH OUTBOARD SLAT ACTUATOR EXTENSION RESTRICTOR VALVE C24370-102	MOS					27-FEB-1990			
27.450	B2815 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
278441	LH ACTUATOR STANDBY RESTRICTOR VALVE FCFA1875150D	MOS					27-FEB-1990			
27.455	160 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
278451	RH ACTUATOR STANDBY RESTRICTOR VALVE FCFA1875150D	MOS					27-FEB-1990			
27.455	161 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
278461	SLATS ACTUATOR RETRACTION RESTRICTOR VALVE C24346-302	MOS					27-FEB-1990			
27.455	B1323 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
CHAPTER 28 FUEL										
28-00-00-280-801-01 (s)	TEST FUEL CONTAMINATION DETECTION						PKG			
28.560	PKG 1,15 REF: AMM 28-00-00-280-801	MOS HRS/MSC AFL	8 400	+1m +40			20-SEP-2017 10758.2 6172			
28-00-00-910-804-01	PERFORM MEASURES TO BE TAKEN AFTER MAINTENANCE OPERATIONS IN THE FUEL TANK						27-FEB-1990			
28.570	REF: AMM 28-00-00-910-804	MOS HRS/MSC AFL APH	A/R				0 0 0			
+ 28-10-00-280-801-01 (s)	SPECIAL DETAILED INSPECTION OF THE FUEL TANK FLAPPER VALVES						PKG			
28.030	PKG 31 REF: AMM 28-10-00-280-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
28-21-01-900-801-01	NO. 1 BOOSTER PUMP P99C31-604	MOS					24-NOV-2010			
28.370	141 REF: AMM 28-21-01-900-801	HRS/MSC AFL	O/C				8089.7 4843			
28-21-01-900-801-02	NO. 2 BOOSTER PUMP P99C31-604	MOS					10-NOV-2006			
28.380	567 REF: AMM 28-21-01-900-801	HRS/MSC AFL	O/C				6434.9			
28-21-01-900-801-03	NO. 3 BOOSTER PUMP P99C31-601	MOS					10-DEC-2011			
28.370	494 REF: AMM 28-21-01-900-801	HRS/MSC AFL	O/C				8516.7 5074			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-21-01-900-801-04	NO. 2 BOOSTER STAND-BY PUMP									
28.380	226-650-3 522 REF: AMM 28-21-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
28-21-05-900-801-01	NO. 1 BP MANIFOLD									
28.280	L88A31-662 20122 REF: AMM 28-21-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
28-21-05-900-801-02	NO. 2 BP MANIFOLD									
28.290	L88A31-663 20112 REF: AMM 28-21-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
28-21-05-900-801-03	NO. 3 BP MANIFOLD									
28.300	L88A31-664 20130 REF: AMM 28-21-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
+ 28-21-11-710-801-01 (s)	OPERATIONAL TEST OF THE LOW PRESSURE 1-2 CROSSFEED ELECTRIC VALVE						PKG			
28.350	PKG 2,7 REF: AMM 28-21-11-710-801	MOS HRS/MSC AFL	16 800	+1m +40			08-FEB-2017 10425.7 6021			
+ 28-21-11-710-801-02 (s)	OPERATIONAL TEST OF THE LOW PRESSURE 2-3 CROSSFEED ELECTRIC VALVE						PKG			
28.350	PKG 2,7 REF: AMM 28-21-11-710-801	MOS HRS/MSC AFL	16 800	+1m +40			08-FEB-2017 10425.7 6021			
+ 28-21-13-710-801-01 (s)	OPERATIONAL TEST OF THE NO. 1 ENGINE FUEL SHUTOFF VALVE						PKG			
76.100	PKG 31 REF: AMM 28-21-13-710-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
+ 28-21-13-710-801-01A	OPERATIONAL TEST NO. 1 ENGINE FUEL SHUTOFF VALVE (MANDATORY 5-40)									
76.100 MANDATORY 5-40	L88A31662 SN-UNKNOWN REF: AMM 28-21-13-710-801	MOS HRS/MSC AFL	11600				05-MAY-2014 9515 5634	21115		10339.3
+ 28-21-13-710-801-02 (s)	OPERATIONAL TEST OF THE NO. 2 ENGINE FUEL SHUTOFF VALVE						PKG			
76.110	PKG 31 REF: AMM 28-21-13-710-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
+ 28-21-13-710-801-02A	OPERATIONAL TEST NO. 2 ENGINE FUEL SHUTOFF VALVE (MANDATORY 5-40)									
76.110 MANDATORY 5-40	L88A31663 SN-UNKNOWN REF: AMM 28-21-13-710-801	MOS HRS/MSC AFL	11600				05-MAY-2014 9515 5634	21115		10339.3
+ 28-21-13-710-801-03 (s)	OPERATIONAL TEST OF THE NO. 3 ENGINE FUEL SHUTOFF VALVE						PKG			
76.120	PKG 31 REF: AMM 28-21-13-710-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 28-21-13-710-801-03A	OPERATIONAL TEST NO. 3 ENGINE FUEL SHUTOFF VALVE (MANDATORY 5-40)									
76.120	L88A31664 SN-UNKNOWN REF: AMM 28-21-13-710-801	MOS HRS/MSC AFL	11600				05-MAY-2014 9515 5634	21115		10339.3
28-21-13-790-801-01	LEAK TEST OF THE OF THE NO. 1 ENGINE FUEL SHUTOFF VALVE									
76.100	REF: AMM 28-21-13-790-801	MOS HRS/MSC AFL	E/C				30-SEP-2013 9385 5543			
28-21-13-790-801-02	LEAK TEST OF THE OF THE NO. 2 ENGINE FUEL SHUTOFF VALVE									
76.110	REF: AMM 28-21-13-790-801	MOS HRS/MSC AFL	E/C				13-JUL-2013 9281.9 5494			
28-21-13-790-801-03	LEAK TEST OF THE OF THE NO. 3 ENGINE FUEL SHUTOFF VALVE									
76.120	REF: AMM 28-21-13-790-801	MOS HRS/MSC AFL	E/C				14-JAN-2014 9479.8 5608			
+ 28-21-14-720-801-01	FUNCTIONAL TEST NO. 1 BP MANIFOLD THERMAL EXPANSION									
28.280	L88A31-662 20122 REF: AMM 28-21-14-720-801	MOS HRS/MSC AFL	10000	+3%			26-SEP-2015 10045.1 5863	20045.1	20345.1	9269.4 (+300)
+ 28-21-14-720-801-02	FUNCTIONAL TEST NO. 2 BP MANIFOLD THERMAL EXPANSION									
28.290	L88A31-663 20112 REF: AMM 28-21-14-720-801	MOS HRS/MSC AFL	10000	+3%			26-SEP-2015 10045.1 5863	20045.1	20345.1	9269.4 (+300)
+ 28-21-14-720-801-03	FUNCTIONAL TEST NO. 3 BP MANIFOLD THERMAL EXPANSION									
28.300	L88A31-664 20130 REF: AMM 28-21-14-720-801	MOS HRS/MSC AFL	10000	+3%			26-SEP-2015 10045.1 5863	20045.1	20345.1	9269.4 (+300)
+ 28-21-25-710-801-01 (s)	OPERATIONAL TEST OF THE CROSSFEED UNITS									
28.160	PKG 2,7 REF: AMM 28-21-25-710-801	MOS HRS/MSC AFL	16 800	+1m +40			08-FEB-2017 10425.7 6021			
28-21-25-900-801-01	LH CROSSFEED UNIT									
28.270	L88A31-665-1 20172 REF: AMM 28-21-25-900-801	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
28-21-25-900-801-02	RH CROSSFEED UNIT									
28.270	L88A31-665-1 20142 REF: AMM 28-21-25-900-801	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
+ 28-21-29-100-801-01 (s)	CLEANING OF THE LH CROSSFEED UNIT FILTER									
28.270	PKG 1,5,201 REF: AMM 28-21-29-100-801	MOS HRS/MSC AFL	8 400	+1m +40			20-SEP-2017 10758.2 6172			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 28-21-29-100-801-02 (s)	CLEANING OF THE RH CROSSFEED UNIT FILTER						PKG			
28.270	PKG 1,5,201 REF: AMM 28-21-29-100-801	MOS HRS/MSC AFL	8 400	+1m +40			20-SEP-2017 10758.2 6172			
+ 28-21-29-100-801-03 (s)	CLEANING OF THE NO. 2 ENGINE PUMPS BLOCK FILTER						PKG			
28.330	PKG 1,5,201 REF: AMM 28-21-29-100-801	MOS HRS/MSC AFL	8 400	+1m +40			20-SEP-2017 10758.2 6172			
28-22-00-610-801-01	SERVICING OF THE TRANSFER SOLENOID VALVE STAND-BY MANUAL CONTROL						PKG			
28.250	PKG 16 REF: AMM 28-22-00-610-801	MOS HRS/MSC AFL	N/A				27-FEB-1990 0 0			
28-22-01-710-801-01	OPERATIONAL TEST OF THE XTK2 TRANSFER SOLENOID VALVE						PKG			
28.260	PKG 16 REF: AMM 28-22-01-710-801	MOS HRS/MSC AFL	N/A				27-FEB-1990 0 0			
28-22-01-900-801-01	TANK INTERCONNECTION VALVE									
28.150	L87B63-653 20041 REF: AMM 28-22-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
28-30-00-680-802-05	PERFORM FUEL TANK SUMP DRAINING									
	REF: AMM 28-30-00-680-804	MOS HRS/MSC AFL	2	+5d			08-SEP-2017 10758.2 6172	08-NOV-2017	13-NOV-2017 21 d	(+5)
28-30-00-680-802-06	LEAK CHECK OF THE DRY BAY									
	REF: AMM 28-30-00-680-802	MOS HRS/MSC AFL	O/C				05-JAN-2015 9764.1 5742			
+ 28-30-00-680-803-01	DRAINING OF THE GRAVITY DEFUELING LINE									
28.340	REF: AMM 28-30-00-680-803	MOS HRS/MSC AFL	2	+5d			08-SEP-2017 10758.2 6172	08-NOV-2017	13-NOV-2017 21 d	(+5)
+ 28-41-00-720-801-01 (s)	FUNCTIONAL TEST FUEL QUANTITY INDICATION SYSTEM						PKG			
28.385	PKG 22 REF: AMM 28-41-00-720-801	MOS HRS/MSC AFL	3200	+40			23-APR-2013 9161.3 5420			
28-41-05-900-801-01	LH WING CENTER FUSELAGE TANK GAUGE									
28.430	766-189-4 1159 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-AUG-2016 10212.9 5929			
28-41-05-900-801-02	RH WING CENTER FUSELAGE TANK GAUGE									
28.430	766-189-4 306 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-41-05-900-801-03	LH FUSELAGE FEEDER TANK GAUGE 766-190-1 251 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
28-41-05-900-801-04	CENTER FUSELAGE FEEDER TANK GAUGE 766-195-2 214 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
28-41-05-900-801-05	RH FUSELAGE FEEDER TANK GAUGE 766-190-2 855 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C				13-MAY-2010 7752.4 4651			
28-41-05-900-801-06	FRONT FUSELAGE TANK REAR GAUGE 766-193-3 218 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
28-41-05-900-801-07	FRONT FUSELAGE TANK FRONT GAUGE 766-192-4 215 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
28-41-05-900-801-08	REAR FUSLAGE TANK GAUGE 766-608-1 212 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
28-41-09-900-801-01	LH WING INBOARD TANK GAUGE 792-366-1 698 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
28-41-09-900-801-02	RH WING INBOARD TANK GAUGE 792-366-1 699 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
28-41-09-900-801-03	LH WING CENTER TANK GAUGE 792-367-2 778 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
28-41-09-900-801-04	RH WING CENTER TANK GAUGE 792-367-2 779 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
28-41-09-900-801-05	LH WING OUTBOARD TANK GAUGE 792-368-2 764 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-41-09-900-801-06	RH WING OUTBOARD TANK GAUGE									
28.410	792-368-2 765 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
+ 28-43-01-720-801-01 (s)	FUNCTIONAL TEST OF THE FUEL TEMPERATURE SENSOR						PKG			
28.490	PKG 31 REF: AMM 28-43-01-720-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
28-50-05-700-801-01	INTEGRITY CHECK OF HIGH-LEVEL SENSORS									
28.590	REF: AMM 28-50-05-700-801	MOS HRS/MSC AFL	O/C				26-MAY-2012 8750.4			
28-50-05-900-801-01	LH HIGH LEVEL SENSOR									
28.470	722105-3 1157 REF: AMM 28-50-05-900-801	MOS HRS/MSC AFL	O/C				30-APR-2011 8225 4913			
28-50-05-900-801-02	RH HIGH LEVEL SENSOR									
28.470	722105-3 1122 REF: AMM 28-50-05-900-801	MOS HRS/MSC AFL	O/C				30-APR-2011 8225 4913			
+ 28-70-01-780-801-01 (s)	CHECK OF THE FUEL PRESSURE GAGE CORRECT CALIBRATION						PKG			
28.240	PKG 31 REF: AMM 28-70-01-780-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
28-70-05-900-801-01	PRESSURE REDUCING VALVE									
28.170	B14DE2080 214 REF: AMM 28-70-05-900-801	MOS HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			23-APR-2013 9161.3 5420			
28-70-09-350-801-01	RESTORATION (FILTER CLEANING AND CALIBRATION CHECK) LH VALVE BOX									
	REF: AMM 28-70-09-350-801	MOS HRS/MSC AFL	5000	+3%			23-APR-2009 7355.7	12355.7	12505.7	1580 (+150)
28-70-09-350-801-02	RESTORATION (FILTER CLEANING AND CALIBRATION CHECK) RH VALVE BOX									
	REF: AMM 28-70-09-350-801	MOS HRS/MSC AFL	5000	+3%			11-MAR-2009 7319.4	12319.4	12469.4	1543.7 (+150)
28-70-09-900-801-01	LH VALVE BOX									
28.210	B04BA1005 2452 REF: AMM 28-70-09-900-801	MOS HRS/MSC AFL	O/C				23-APR-2009 7355.7			
28-70-09-900-801-02	RH VALVE BOX									
28.210	B04BA1005 2451 REF: AMM 28-70-09-900-801	MOS HRS/MSC AFL	O/C				11-MAR-2009 7319.4 4382			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-70-13-350-801-01	RESTORATION LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (AIR FLOW AND PRESSURE DROP TEST/LEAK TEST) B06GA1051 2110 REF: AMM 28-70-13-350-801	MOS HRS/MSC AFL	10000				(EBT)	16612.7		5837
28-70-13-350-801-02	RESTORATION RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (AIR FLOW AND PRESSURE DROP TEST/LEAK TEST) B06GA1051 2984 REF: AMM 28-70-13-350-801	MOS HRS/MSC AFL	10000				(EBT)	16846.4		6070.7
28-70-13-720-802-01	FUNCTIONAL TEST LH WING TANK NEGATIVE PRESSURE RELIEF VALVE B06GA1051 2110 REF: AMM 28-70-13-720-802	MOS HRS/MSC AFL	5000				02-MAY-2007 6612.7	11612.7		837
28-70-13-720-802-02	FUNCTIONAL TEST RH WING TANK NEGATIVE PRESSURE RELIEF VALVE B06GA1051 2984 REF: AMM 28-70-13-720-802	MOS HRS/MSC AFL	5000				24-NOV-2007 6846.4	11846.4		1070.7
28-70-13-900-801-01	LH WING TANK NEGATIVE PRESSURE RELIEF VALVE B06GA1051 2110 REF: AMM 28-70-13-900-801	MOS HRS/MSC AFL	O/C				02-MAY-2007 6612.7			
28-70-13-900-801-02	RH WING TANK NEGATIVE PRESSURE RELIEF VALVE B06GA1051 2984 REF: AMM 28-70-13-900-801	MOS HRS/MSC AFL	O/C				24-NOV-2007 6846.4			
28-70-17-130-801-01 (s)	CLEANING OF THE OF THE NO. 1 ENGINE FUEL TANK PRESSURIZATION SYSTEM FILTER ELEMENT PKG 21 REF: AMM 28-70-17-130-801	MOS HRS/MSC AFL	1600	+40			PKG 20-SEP-2017 10758.2 6172			
28-70-17-130-801-02 (s)	CLEANING OF THE OF THE NO. 2 ENGINE FUEL TANK PRESSURIZATION SYSTEM FILTER ELEMENT PKG 21 REF: AMM 28-70-17-130-801	MOS HRS/MSC AFL	1600	+40			PKG 20-SEP-2017 10758.2 6172			
28-70-21-900-801-01	LH WING VENT VALVE B97F38-653 E50843 REF: AMM 28-70-21-900-801	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	13-SEP-2013 9367.9 5534			
28-70-21-900-801-02	RH WING VENT VALVE B97F38-653 20378 REF: AMM 28-70-21-900-801	MOS HRS/MSC AFL	O/C				08-MAY-2009 7377.5 4424			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-70-37-230-801-01	SPECIAL DETAILED INSPECTION	OF FRAME	12	PRESSURIZATION LINE						
28.580	REF: AMM 28-70-37-230-801	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
281101	PRESSURE FUELING COUPLING									
28.040	K97-63-206 20367 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
281131	LH WING BLEED VALVE									
28.060	142D12-11 867 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
281141	RH WING BLEED VALVE									
28.060	142D12-11 868 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
281151	FRONT FUEL TANK BLEED VALVE									
28.060	142G12-32 990 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
281161	CENTER FUEL TANK FRONT BLEED VALVE									
28.070	142G12-33 1274 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
281171	CENTER FUEL TANK CENTER BLEED VALVE									
28.070	142G12-32 D08589 REF:	MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			
281176	CENTER FUEL TANK LATERAL BLEED VALVE									
28.070	142G12-32 H17338 REF:	MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			
281181	CENTER FUEL TANK REAR BLEED VALVE									
28.080	142G12-32 H17336 REF:	MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			
281191	REAR FUEL TANK FRONT BLEED VALVE									
28.080	142G12-32 H17339 REF:	MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			
281201	REAR FUEL TANK REAR BLEED VALVE									
28.080	142G12-32 H15598 REF:	MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
281211	FILLING BLOCK									
28.090	K99-31-007 20083 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
281221	FRONT FUEL TANK FILLING ELECTRIC CHECK VALVE									
28.100	L96Z31-201 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
281231	CENTER FUEL TANK FILLING ELECTRIC VALVE									
28.100	L96Z31-201 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
281241	REAR FUEL TANK FILLING ELECTRIC VALVE									
28.100	L96Z31-201 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
281251	FRONT FUEL TANK FILLING RESTRICTOR VALVE									
28.110	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
281261	CENTER FUEL TANK FILLING RESTRICTOR VALVE									
28.110	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
281271	REAR FUEL TANK FILLING RESTRICTOR VALVE									
28.110	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
281281	REAR FUEL TANK FILLING CHECK VALVE									
28.120	L85D38-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
281311	LH WING FUELING ELECTRIC VALVE									
28.140	L94Z31-201 20441 REF:	MOS HRS/MSC AFL	O/C				07-SEP-2013 9353.3 5528			
281321	RH WING FUELING ELECTRIC VALVE									
28.140	L94Z31-201 21001 REF:	MOS HRS/MSC AFL	O/C				07-SEP-2013 9353.3 5528			
281331	FRONT/REAR FUEL TANK FUELING ELECTRIC VALVE									
28.140	L94Z31-201 21001 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
281351	LP3-1 ELECTRIC INTERCONNECTION VALVE									
28.150	L92B07-205 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
282151	NO. 1 ENGINE PRESSURE BLEED CHECK VALVE									
28.180	L96Z19-003 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
282161	NO. 2 ENGINE PRESSURE BLEED CHECK VALVE									
28.180	L96Z19-003 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
282201	NO. 1 ENGINE FUEL TANK PRESSURIZATION SYSTEM FILTER ELEMENT									
28.190	P6742 SN-UNKNOWN REF: AMM 28-70-17-130-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
282221	NO. 2 ENGINE FUEL TANK PRESSURIZATION SYSTEM FILTER ELEMENT									
28.190	P6742 SN-UNKNOWN REF: AMM 28-70-17-130-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
282451	FUEL PRESSURE GAGE									
28.240	MPMC50701-01 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
282501	PARTIAL FUEL SELECTOR									
28.550	796-740 193 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0		08/19/2004	19-AUG-2003 5580.7 3361			
283121	XTK2 TRANSFER SOLENOID VALVE									
28.260	B97-38-662 NOT INST. REF:	MOS HRS/MSC AFL	O/C				20-JUL-1990 27 14			
284251	NO. 2 ENGINE PUMPS BLOCK									
28.330	L88A31-206 20081 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
284321	LOW PRESSURE 1-2 CROSSFEED ELECTRIC VALVE									
28.350	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
284351	LOW PRESSURE 2-3 CROSSFEED ELECTRIC VALVE									
28.350	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
285101	LH FUEL QUANTITY AMPLIFIER									
28.390	736-327-1 333 REF:	MOS HRS/MSC AFL	O/C				23-JUL-1998 3669 2134			
285121	RH FUEL QUANTITY AMPLIFIER									
28.390	736-327-1 233 REF:	MOS HRS/MSC AFL	O/C	TSN:225			06-SEP-1991 549 293			
285141	CENTER FUEL QUANTITY AMPLIFIER									
28.390	736-328-2 212 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
285261	LH FUEL QUANTITY INDICATOR									
28.420	748-326-2 316 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
285271	RH FUEL QUANTITY INDICATOR									
28.420	748-326-2 208 REF:	MOS HRS/MSC AFL	O/C				20-JUL-1990 27.2 14			
285281	CENTER FUEL QUANTITY INDICATOR									
28.420	748-326-2 208 REF:	MOS HRS/MSC AFL	O/C	TSN:15			20-JUL-1990 27 14			
285401	LOW LEVEL THERMISTOR RELAY BOX									
28.480	722-087-2 369 REF:	MOS HRS/MSC AFL	O/C				12-APR-2010 7706.6 4620			
285421	1000 LBS LEVEL DETECTION BOX									
28.480	722-087-2 383 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
285451	FUEL TEMPERATURE SENSOR									
28.490	1122505 SN-UNKNOWN REF: AMM 28-43-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
285461	FUEL TEMPERATURE INDICATOR									
28.490	5318-201-80-10 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
285471	REAR TANK LEVEL RELAY BOX									
28.500	722-233-1 201 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
285501	NO. 1 ENGINE LOW PRESSURE PRESSURE SWITCH									
28.510	8G1256-1 570 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
285511	NO. 2 ENGINE LOW PRESSURE SWITCH									
28.510	8G1256-1 574 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
285521	NO. 3 ENGINE LOW PRESSURE SWITCH									
28.510	8G1256-1 575 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
285531	HIGH LEVEL RELAY BOX									
28.520	722087-3 1110 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-SEP-2016 10230 5939			
285701	FUELING PANEL									
28.540	19-54-6 114 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			07-FEB-2017 10425.7 6021			
285A01	TOTAL FUEL USED INDICATOR									
	9-138-01 JW475 REF:	MOS HRS/MSC AFL	O/C				23-AUG-1996 2695.7			
CHAPTER 29		HYDRAULIC POWER								
29-10-00-720-801-01 (s)	FUNCTIONAL TEST OF THE NO. 1 MAIN HYDRAULIC SYSTEM						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
	REF: AMM 29-10-00-720-801		3750							
29-10-00-720-801-02 (s)	FUNCTIONAL TEST OF THE NO. 2 MAIN HYDRAULIC SYSTEM						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
	REF: AMM 29-10-00-720-801		3750							
29-11-01-350-801-01	RESTORATION NO. 1 HYDRAULIC PUMP (OVERHAUL)									
29.050 OVERHAUL	42045-01 JX47 REF: AMM 29-11-01-350-801	MOS HRS/MSC AFL	3240	+3%			11-JAN-2011 8115.9	11355.9	11453.1	580.2 (+97.2)
29-11-01-350-801-02	RESTORATION NO. 2 HYDRAULIC PUMP (OVERHAUL)									
29.050 OVERHAUL	42045-01 ME27 REF: AMM 29-11-01-350-801	MOS HRS/MSC AFL	3240	+3%			04-JAN-2010 7630.5	10870.5	10967.7	94.8 (+97.2)
29-11-01-350-801-03	RESTORATION NO. 3 HYDRAULIC PUMP (OVERHAUL)									
29.050 OVERHAUL	4204501 AH-18025 REF: AMM 29-11-01-350-801	MOS HRS/MSC AFL	3240	+3%			19-JUL-2013 9287.7 5499	12527.7	12624.9	1752 (+97.2)

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-11-01-900-801-01	NO. 1 HYDRAULIC PUMP 42045-01 JX47 REF: AMM 29-11-01-900-801	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			11-JAN-2011 8115.9			
29-11-01-900-801-02	NO. 2 HYDRAULIC PUMP 42045-01 ME27 REF: AMM 29-11-01-900-801	MOS HRS/MSC AFL	H/T				04-JAN-2010 7630.5			
29-11-01-900-801-03	NO. 3 HYDRAULIC PUMP 4204501 AH-18025 REF: AMM 29-11-01-900-801	MOS HRS/MSC AFL	H/T				19-JUL-2013 9287.7 5499			
29-11-21-230-801-01	SPECIAL DETAILED INSPECTION NO. 1 HYDRAULIC PUMP PRESSURE RELIEF VALVE INTERNAL PART OF THE BODY A24518-001A FM02370 REF: AMM 29-11-21-230-801	MOS HRS/MSC AFL	O/C				21-AUG-2000 4606 2779			
29-11-21-230-801-02	SPECIAL DETAILED INSPECTION NO. 2 HYDRAULIC PUMP PRESSURE RELIEF VALVE INTERNAL PART OF THE BODY A24518-001A FM02366 REF: AMM 29-11-21-230-801	MOS HRS/MSC AFL	O/C				21-AUG-2000 4606 2779			
29-11-21-230-801-03	SPECIAL DETAILED INSPECTION NO. 3 HYDRAULIC PUMP PRESSURE RELIEF VALVE OF THE INTERNAL PART OF THE BODY A24518-001A FM02368 REF: AMM 29-11-21-230-801	MOS HRS/MSC AFL	O/C				21-AUG-2000 4606 2779			
29-11-21-900-801-01	NO. 1 HYDRAULIC PUMP PRESSURE RELIEF VALVE A24518-001A FM02370 REF: AMM 29-11-21-900-801	MOS HRS/MSC AFL	O/C				21-AUG-2000 4606 2779			
29-11-21-900-801-02	NO. 2 HYDRAULIC PUMP PRESSURE RELIEF VALVE A24518-001A FM02366 REF: AMM 29-11-21-900-801	MOS HRS/MSC AFL	O/C				21-AUG-2000 4606 2779			
29-11-21-900-801-03	NO. 3 HYDRAULIC PUMP PRESSURE RELIEF VALVE A24518-001A FM02368 REF: AMM 29-11-21-900-801	MOS HRS/MSC AFL	O/C				21-AUG-2000 4606 2779			
29-11-25-900-801-01	NO. 1 HYDRAULIC PUMP PRESSURE SWITCH 15H0089PH 0692-0711 REF: AMM 29-11-25-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-SEP-2017 10758.2 6172			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-11-25-900-801-02	NO. 2 HYDRAULIC PUMP PRESSURE SWITCH 95G229 2708 REF: AMM 29-11-25-900-801	MOS HRS/MSC AFL	O/C				07-JUN-2010 7798.6			
29-11-25-900-801-03	NO. 3 HYDRAULIC PUMP PRESSURE SWITCH 90G229 401 REF: AMM 29-11-25-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
29-11-25-960-801-01	DISCARD NO. 1 HYDRAULIC PUMP PRESSURE SWITCH 15H0089PH 0692-0711 REF: AMM 29-11-25-960-801	MOS HRS/MSC AFL	O/C				20-SEP-2017 10758.2 6172			
29-11-25-960-801-02	DISCARD NO. 2 HYDRAULIC PUMP PRESSURE SWITCH 95G229 2708 REF: AMM 29-11-25-960-801	MOS HRS/MSC AFL	O/C							
29-11-25-960-801-03	DISCARD NO. 3 HYDRAULIC PUMP PRESSURE SWITCH 90G229 401 REF: AMM 29-11-25-960-801	MOS HRS/MSC AFL	O/C	TSI:0			27-FEB-1990 0 0			
29-13-09-900-801-01	NO. 1 SYSTEM HYDRAULIC FILTER AD3258-10Y12 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-JAN-2008 6903.5			
29-13-09-900-801-02	NO. 2 SYSTEM HYDRAULIC FILTER AC3255R8Y60 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				05-APR-2009 7344.5 4398			
29-13-09-960-801-01 (s)	REPLACEMENT OF THE OF STANDBY PUMP FILTER PKG 31 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	72 3750	+2m			PKG 05-MAY-2014 9515 5634			
29-13-09-960-801-02 (s)	REPLACEMENT OF THE OF HYDRAULIC PUMP 1 RETURN FILTER PKG 31 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	72 3750	+2m			PKG 05-MAY-2014 9515 5634			
29-13-09-960-801-03 (s)	REPLACEMENT OF THE OF HYDRAULIC PUMP 2 RETURN FILTER PKG 31 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	72 3750				PKG 05-MAY-2014 9515 5634			
29-13-09-960-801-04 (s)	REPLACEMENT OF THE OF HYDRAULIC PUMP 3 RETURN FILTER PKG 31 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	72 3750				PKG 05-MAY-2014 9515 5634			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-13-09-960-801-05 (s)	REPLACEMENT OF THE OF SYSTEM 1 GENERAL RETURN FILTER PKG 31	MOS HRS/MSC AFL	72				PKG 05-MAY-2014 9515 5634			
	REF: AMM 29-13-09-960-801		3750							
29-13-09-960-801-06 (s)	REPLACEMENT OF THE OF SYSTEM 2 GENERAL RETURN FILTER PKG 31	MOS HRS/MSC AFL	72				PKG 05-MAY-2014 9515 5634			
	REF: AMM 29-13-09-960-801		3750							
29-13-09-960-801-07 (s)	REPLACEMENT OF THE OF HYDRAULIC PUMP 1 DELIVERY FILTER PKG 31	MOS HRS/MSC AFL	72				PKG 05-MAY-2014 9515 5634			
	REF: AMM 29-13-09-960-801		3750							
29-13-09-960-801-08 (s)	REPLACEMENT OF HYDRAULIC PUMP 2 DELIVERY FILTER PKG 31	MOS HRS/MSC AFL	72				PKG 05-MAY-2014 9515 5634			
	REF: AMM 29-13-09-960-801		3750							
29-13-09-960-801-09 (s)	REPLACEMENT OF HYDRAULIC PUMP 3 DELIVERY FILTER PKG 31	MOS HRS/MSC AFL	72				PKG 05-MAY-2014 9515 5634			
	REF: AMM 29-13-09-960-801		3750							
29-14-01-680-801-01 (s)	DRAIN OF THE NO. 1 SYSTEM HYDRAULIC RESERVOIR PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 05-MAY-2014 9515 5634			
29.030	REF: AMM 29-14-01-680-801		3750							
29-14-01-680-801-02 (s)	DRAIN OF THE NO. 2 SYSTEM HYDRAULIC RESERVOIR PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 05-MAY-2014 9515 5634			
29.030	REF: AMM 29-14-01-680-801		3750							
29-14-01-900-801-01	NO. 1 SYSTEM HYDRAULIC RESERVOIR 029029-06	MOS HRS/MSC AFL	O/C			TSN:0	27-FEB-1990 0 0			
29.030	REF: AMM 29-14-01-900-801									
29-14-01-900-801-02	NO. 2 SYSTEM HYDRAULIC RESERVOIR 029029-05	MOS HRS/MSC AFL	O/C			TSN:0	27-FEB-1990 0 0			
29.030	REF: AMM 29-14-01-900-801									
29-14-11-900-801-01	NO. 1 SYSTEM HYDRAULIC ACCUMULATOR 60833-2	MOS HRS/MSC AFL	O/C			TSN:0	27-FEB-1990 0 0			
29.060	REF: AMM 29-14-11-900-801									
29-14-11-900-801-02	NO. 2 SYSTEM HYDRAULIC ACCUMULATOR 60833-2	MOS HRS/MSC AFL	O/C			TSN:0	27-FEB-1990 0 0			
29.060	REF: AMM 29-14-11-900-801									

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-20-01-900-801-01	STANDBY ELECTRIC PUMP ASSEMBLY									
29.240	42032 AH57505 REF: AMM 29-20-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
+ 29-20-03-220-801-01	CHECK STANDBY ELECTRIC PUMP ASSEMBLY MOTOR BRUSHES									
29.240	42032 AH57505 REF: AMM 29-20-03-220-801	MOS HRS/MSC AFL	5000	+3%			13-JUL-2015 9949.4 5827	14949.4	15099.4	4173.7 (+150)
+ 29-20-03-720-801-01	FUNCTIONAL TEST STANDBY ELECTRIC PUMP ASSEMBLY MOTOR									
29.240	42032 AH57505 REF: AMM 29-20-03-720-801	MOS HRS/MSC AFL	5000	+3%			13-JUL-2015 9949.4 5827	14949.4	15099.4	4173.7 (+150)
29-20-07-900-801-01	NO. 1 SYSTEM STANDBY PUMP PRESSURE SWITCH									
29.200	90G196-2 835 REF: AMM 29-20-07-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
29-20-07-900-801-02	NO. 2 SYSTEM STANDBY PUMP PRESSURE SWITCH									
29.200	15H0092PH 0509 REF: AMM 29-20-07-900-801	MOS HRS/MSC AFL	O/C	TSN:8 TSN:0 TSN:0			16-JAN-2015 9764.1 5742			
29-20-07-960-801-01	DISCARD NO. 1 SYSTEM STANDBY PUMP PRESSURE SWITCH									
29.200	90G196-2 835 REF: AMM 29-20-07-960-801	MOS HRS/MSC AFL	O/C				07-JUN-2010 7798.6			
29-20-07-960-801-02	DISCARD NO. 2 SYSTEM STANDBY PUMP PRESSURE SWITCH									
29.200	15H0092PH 0509 REF: AMM 29-20-07-960-801	MOS HRS/MSC AFL	O/C				16-JAN-2015 9764.1 5742			
291091	NO. 1 SYSTEM HYDRAULIC RESERVOIR DE-AERATOR VALVE									
29.040	034001 313 REF:	MOS HRS/MSC AFL	O/C				17-DEC-2008 7247.6			
291141	NO. 2 SYSTEM HYDRAULIC RESERVOIR DE-AERATOR VALVE									
29.040	034001 324 REF:	MOS HRS/MSC AFL	O/C				17-DEC-2008 7247.6			
291311	NO. 1 HYDRAULIC PUMP DISCHARGE FILTER									
29.080	AD3255-8Y60 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				07-JAN-2008 6903.5			
291321	NO. 2 HYDRAULIC PUMP DISCHARGE FILTER									
29.080	AD3255-8Y60 0271 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
291331	NO. 3 HYDRAULIC PUMP DISCHARGE FILTER AD3255-8Y60	MOS					27-FEB-1990			
29.080	0287 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
291341	NO. 1 SYSTEM HYDRAULIC HOLD VALVE 70073	MOS					27-FEB-1990			
29.090	165 REF: AMM 29-14-09-900-802	HRS/MSC AFL	O/C	TSN:0			0 0			
291346	NO. 1 HYDRAULIC SYSTEM PRESSURE GAUGE 18040100	MOS					27-FEB-1990			
29.095	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
291351	NO. 2 SYSTEM HYDRAULIC HOLD VALVE 70073	MOS					27-FEB-1990			
29.090	186 REF: AMM 29-14-09-900-802	HRS/MSC AFL	O/C	TSN:0			0 0			
291356	NO. 2 HYDRAULIC SYSTEM PRESSURE GAUGE 18040100	MOS					27-FEB-1990			
29.095	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
291361	NO. 1 PUMP REGULATION RETURN FILTER ADB296-5Y3	MOS					07-JAN-2008			
29.100	SN-UNKNOWN REF:	HRS/MSC AFL	O/C				6903.5			
291381	NO. 2 PUMP REGULATION RETURN FILTER ADB296-5Y3	MOS					27-FEB-1990			
29.100	0253 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
291401	NO. 3 PUMP REGULATION RETURN FILTER ADB296-5Y3	MOS					27-FEB-1990			
29.100	0261 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
291461	NO. 1 SUCTION SYSTEM HYDRAULIC GROUND CONNECTION B3005-S4-12D	MOS					27-FEB-1990			
29.120	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
291471	NO. 2 SUCTION SYSTEM HYDRAULIC GROUND CONNECTION B3005-S4-12D	MOS					27-FEB-1990			
29.120	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
291481	NO. 1 DISCHARGE SYSTEM HYDRAULIC GROUND CONNECTION TB3005-S4-8D	MOS					27-FEB-1990			
29.130	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
291491	NO. 2 DISCHARGE SYSTEM HYDRAULIC GROUND CONNECTION									
29.130	TB3005-S4-8D SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291501	NO. 1 DISCHARGE PUMP QUICK DISCHARGE VALVE									
29.140	405-20403-13200 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291511	NO. 2 DISCHARGE PUMP QUICK DISCHARGE VALVE									
29.140	405-20403-13200 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291521	NO. 3 DISCHARGE PUMP QUICK DISCHARGE VALVE									
29.140	405-20403-13200 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291531	NO. 1 SUCTION PUMP QUICK DISCHARGE VALVE									
29.150	405-20402-13300 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291541	NO. 2 SUCTION PUMP QUICK DISCHARGE VALVE									
29.150	405-20402-13300 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291551	NO. 3 SUCTION PUMP QUICK DISCHARGE VALVE									
29.150	405-20402-13300 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291561	NO. 1 RETURN REGULATION PUMP CHECK VALVE									
29.160	A24515-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291571	NO. 2 AFT RETURN REGULATION PUMP CHECK VALVE									
29.160	A24515-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291581	NO. 3 RETURN REGULATION PUMP CHECK VALVE									
29.160	A24515-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291591	NO. 1 FILTER/PUMP PROTECTION CHECK VALVE									
29.170	A24517 FM2012 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
291601	NO. 2 PUMP PROTECTION CHECK VALVE									
29.180	A24517 FM2193 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291611	NO. 2 FILTER PROTECTION CHECK VALVE									
29.170	A24517 FM2194 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291621	NO. 3 PUMP PROTECTION CHECK VALVE									
29.180	A24517 FM2195 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291631	NO. 2 SYSTEM EXTERIOR POWER SUPPLY CHECK VALVE									
29.185	A24517 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291701	NO. 1 LEVEL/PRESSURE DUAL INDICATOR									
29.210	5502-380-80-10 296 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291711	NO. 2 LEVEL/PRESSURE DUAL INDICATOR									
29.210	5502-380-80-10 309 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291721	NO. 1 SYSTEM PRESSURE TRANSMITTER									
29.220	8107-132-00-10 282 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291731	NO. 2 SYSTEM PRESSURE TRANSMITTER									
29.220	8107-132-00-10 286 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291751	NO. 1 SYSTEM HYDRAULIC QUANTITY GAUGE									
29.230	18040100 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
291761	NO. 2 SYSTEM HYDRAULIC QUANTITY GAUGE									
29.230	18040100 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
292151	ELECTRIC PUMP SELECTOR									
29.260	B94A13-205 20128 REF: AMM 29-20-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
292171	ELECTRIC PUMP DISCHARGE FILTER									
29.260	AD3255-8Y63 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
292201	NO. 1 SYSTEM ELECTRIC PUMP PROTECTION CHECK VALVE									
29.270	A24516 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
292211	NO. 2 SYSTEM ELECTRIC PUMP PROTECTION CHECK VALVE									
29.270	A24516 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
292301	HYDRAULIC CONTROL PANEL									
29.280	380TS06Y02 176 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0		04/08/2006	08-APR-2005 6136.4 3671			
CHAPTER 30 ICE AND RAIN PROTECTION										
30-00-00-960-801-01 (s)	REPLACEMENT OF THE ANTI-ICING SYSTEM WIGGINS COUPLING SEALS						PKG			
30.040	PKG 32 REF: AMM 30-00-00-960-801	MOS HRS/MSC AFL	144	+2m			05-MAY-2014 9515 5634			
30-11-00-350-801-01	RESTORATION LH INBOARD SLAT TELESCOPIC DUCT (OVERHAUL)									
30.060	5036-400 111 REF: AMM 30-11-00-350-801	MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			
30-11-00-350-801-02	RESTORATION RH INBOARD SLAT TELESCOPIC DUCT (OVERHAUL)									
30.060	5035-700 366 REF: AMM 30-11-00-350-801	MOS HRS/MSC AFL	O/C				26-MAY-2012 8750.4 5198			
30-11-00-350-801-03	RESTORATION LH OUTBOARD SLAT TELESCOPIC DUCT (OVERHAUL)									
30.050	5035-600 272 REF: AMM 30-11-00-350-801	MOS HRS/MSC AFL	O/C				26-MAY-2012 8750.4 5198			
30-11-00-350-801-04	RESTORATION RH OUTBOARD SLAT TELESCOPIC DUCT (OVERHAUL)									
30.050	5035-700 230 REF: AMM 30-11-00-350-801	MOS HRS/MSC AFL	O/C				26-MAY-2012 8750.4 5198			
+ 30-11-00-720-801-01	FUNCTIONAL TEST LH INBOARD SLAT TELESCOPIC DUCT / SWIVELING TORQUE MEASUREMENT									
30.060	5036-400 111 REF: AMM 30-11-00-720-801	MOS HRS/MSC AFL	2480	+3%			05-MAY-2014 9515 5634	11995 7634	12069.4 7694	1219.3 (+74.4) 1452 (+60)
+ 30-11-00-720-801-02	FUNCTIONAL TEST RH INBOARD SLAT TELESCOPIC DUCT / SWIVELING TORQUE MEASUREMENT									
30.060	5035-700 366 REF: AMM 30-11-00-720-801	MOS HRS/MSC AFL	2480	+3%			26-MAY-2012 8750.4 5198	11230.4 7198	11304.8 7258	454.7 (+74.4) 1016 (+60)

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 30-11-00-720-801-03	FUNCTIONAL TEST LH OUTBOARD SLAT TELESCOPIC DUCT / SWIVELING TORQUE MEASUREMENT									
30.050	5035-600 272 REF: AMM 30-11-00-720-801	MOS HRS/MSC AFL	2480 +3% 2000 +3%				26-MAY-2012 8750.4 5198	11230.4 7198	11304.8 7258	454.7 (+74.4) 1016 (+60)
+ 30-11-00-720-801-04	FUNCTIONAL TEST RH OUTBOARD SLAT TELESCOPIC DUCT / SWIVELING TORQUE MEASUREMENT									
30.050	5035-700 230 REF: AMM 30-11-00-720-801	MOS HRS/MSC AFL	2480 +3% 2000 +3%				26-MAY-2012 8750.4 5198	11230.4 7198	11304.8 7258	454.7 (+74.4) 1016 (+60)
30-11-00-900-801-01	LH INBOARD SLAT TELESCOPIC DUCT									
30.060	5036-400 111 REF: AMM 30-11-00-900-801	MOS HRS/MSC AFL	O/C	TSO:36 TSO:0 TSO:0			05-MAY-2014 9515 5634			
30-11-00-900-801-02	RH INBOARD SLAT TELESCOPIC DUCT									
30.060	5035-700 366 REF: AMM 30-11-00-900-801	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			26-MAY-2012 8750.4 5198			
30-11-00-900-801-03	LH OUTBOARD SLAT TELESCOPIC DUCT									
30.050	5035-600 272 REF: AMM 30-11-00-900-801	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			26-MAY-2012 8750.4 5198			
30-11-00-900-801-04	RH OUTBOARD SLAT TELESCOPIC DUCT									
30.050	5035-700 230 REF: AMM 30-11-00-900-801	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			26-MAY-2012 8750.4 5198			
30-11-01-200-801-01	INSPECTION OF THE LH INBOARD SLAT TELESCOPIC TUBE									
30.060		MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			
30-11-01-200-801-02	INSPECTION OF THE RH INBOARD SLAT TELESCOPIC TUBE									
30.060		MOS HRS/MSC AFL	O/C				26-MAY-2012 8750.4 5198			
+ 30-11-17-200-801-01 (s)	INSPECTION OF THE WING ANTI-ICING SYSTEM COUPLINGS LOCATED IN THE REAR COMPARTMENT									
30.020	PKG 16,18,203 REF: AMM 30-11-17-200-801	MOS HRS/MSC AFL	24 +1m				PKG 30-AUG-2016 10212.9 5929			
+ 30-11-17-200-803-01 (s)	INSPECTION OF THE WING ANTI-ICING SYSTEM GENERAL CONNECTOR COUPLINGS									
30.150	PKG 31 REF: AMM 30-11-17-200-803	MOS HRS/MSC AFL	72 +2m 3750				PKG 05-MAY-2014 9515 5634			
30-20-00-710-801-01 (s)	OPERATIONAL TEST OF THE NO. 1 ENGINE AIR INTAKE ANTI-ICING SYSTEM									
	PKG 21 REF: AMM 30-20-00-710-801	MOS HRS/MSC AFL	1600 +40				PKG 20-SEP-2017 10758.2 6172			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 30-20-00-710-801-02 (s)	OPERATIONAL TEST OF THE NO. 2 ENGINE AIR INTAKE ANTI-ICING SYSTEM PKG 21	MOS					PKG 20-SEP-2017 10758.2 6172			
30.100	REF: AMM 30-20-00-710-801	HRS/MSC AFL	1600	+40						
30-20-00-710-801-03 (s)	OPERATIONAL TEST OF THE NO. 3 ENGINE AIR INTAKE ANTI-ICING SYSTEM PKG 21	MOS					PKG 20-SEP-2017 10758.2 6172			
	REF: AMM 30-20-00-710-801	HRS/MSC AFL	1600	+40						
+ 30-20-01-700-801-01	FUNCTIONAL/SEALING TEST NO. 1 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE 1818-00-1A 0132	MOS					05-MAY-2014 9515 5634	14515	14665	3739.3 (+150)
30.110	REF: AMM 30-20-01-700-801	HRS/MSC AFL	5000	+3%						
+ 30-20-01-700-801-02	FUNCTIONAL/SEALING TEST NO. 2 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE 1818-00-1A 0113	MOS					02-SEP-2016 10217.5 5933	15217.5	15367.5	4441.8 (+150)
30.120	REF: AMM 30-20-01-700-801	HRS/MSC AFL	5000	+3%						
+ 30-20-01-700-801-03	FUNCTIONAL/SEALING TEST NO. 3 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE 1818-00-1A 0237	MOS					05-MAY-2014 9515 5634	14515	14665	3739.3 (+150)
30.130	REF: AMM 30-20-01-700-801	HRS/MSC AFL	5000	+3%						
30-30-00-710-801-01 (s)	OPERATIONAL TEST OF THE AIR DATA PROBE ANTI-ICING SYSTEM PKG 21	MOS					PKG 20-SEP-2017 10758.2 6172			
	REF: AMM 30-30-00-710-801	HRS/MSC AFL	1600	+40						
+ 30-41-00-710-801-01 (s)	OPERATIONAL TEST OF THE WINDSHIELD DE-ICING SYSTEM PKG 23	MOS					PKG 14-NOV-2009 7871.7			
30.230	REF: AMM 30-41-00-710-801	HRS/MSC AFL	4800	+40						
+ 30-43-09-220-801-01	CHECK PILOT WINDSHIELD WIPER MOTOR BRUSHES 4267568 11395	MOS					27-FEB-1990 0 0	15000	15450	4224.3 (+450)
30.260	REF: AMM 30-43-09-220-801	HRS/MSC AFL	15000	+3%						
+ 30-43-09-220-801-02	CHECK COPILOT WINDSHIELD WIPER MOTOR BRUSHES 4267575 13055	MOS					27-JUL-1990 27.2	15027.2	15477.2	4251.5 (+450)
30.260	REF: AMM 30-43-09-220-801	HRS/MSC AFL	15000	+3%						
30-90-00-710-801-01	OPERATIONAL TEST OF THE BRAKE HEATING SYSTEM	MOS					27-FEB-1990 0 0			
30.045	REF: AMM 30-90-00-710-801	HRS/MSC AFL	N/A							
301301	WING ANTI-ICING VALVE BYLB51035-1	MOS					27-FEB-1990 0 0			
30.070	REF:	HRS/MSC AFL	O/C	TSN:0						

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
301351	LH WING ANTI-ICING PRESSURE SWITCH 8G1199-2	MOS					27-FEB-1990			
30.080	707 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
301381	RH WING ANTI-ICING PRESSURE SWITCH 8G1199-2	MOS					27-FEB-1990			
30.080	708 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
301401	BLEED AIR HIGH PRESSURE MONITOR EL126-00	MOS					12-JAN-2005			
30.080	333 REF:	HRS/MSC AFL	O/C	TSN:0 TSR:0 TSN:1279 TSR:0			6068.6 3631			
302101	NO. 1 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE 1818-00-1A	MOS					05-MAY-2014			
30.110	0132 REF:	HRS/MSC AFL	O/C	TSO:21 TSO:0 TSO:0			9515 5634			
302121	NO. 2 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE 1818-00-1A	MOS					02-SEP-2016			
30.120	0113 REF:	HRS/MSC AFL	O/C	TSO:2 TSO:0 TSO:0			10217.5 5933			
302141	NO. 3 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE 1818-00-1A	MOS					05-MAY-2014			
30.130	0237 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			9515 5634			
302261	NO. 2 ENGINE DUCT ANTI-ICING VALVE BYBL51908	MOS					22-MAY-2015			
30.160	548 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			9898.1 5801			
302301	NO. 1 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH 8G1199-2	MOS					27-FEB-1990			
30.170	827 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
302321	NO. 1 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH 8G1340-1	MOS					27-FEB-1990			
30.170	374 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
302341	NO. 2 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH 8G1199-2	MOS					27-FEB-1990			
30.180	809 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
302361	NO. 2 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH 8G1340-1	MOS					27-FEB-1990			
30.180	357 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
302381	NO. 2 ENGINE DUCT ANTI-ICING PRESSURE SWITCH 8G1199-2	MOS					27-FEB-1990			
30.190	806 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
302401	NO. 3 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH 8G1199-2	MOS					27-FEB-1990			
30.200	784 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
302421	NO. 3 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH 8G1340-1	MOS					27-FEB-1990			
30.200	347 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
303101	LH PITOT/STATIC HEAT MONITORING BOX 24-255	MOS					27-FEB-1990			
30.220	192 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
303131	RH PITOT/STATIC HEAT MONITORING BOX 24-255	MOS					27-FEB-1990			
30.220	193 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
303161	STANDBY PITOT HEAT MONITORING BOX 24-256	MOS					27-FEB-1990			
30.220	107 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
304101	PILOT WINDSHIELD HEATING REGULATOR HYLZ50426-1	MOS					27-FEB-1990			
30.240	774D REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
304121	COPILOT WINDSHIELD HEATING REGULATOR HYLZ50426-001	MOS					04-OCT-2004			
30.240	910D REF:	HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			6022.6 3607			
304141	LH SIDE WINDOW HEATING REGULATOR HYLZ50422	MOS					27-FEB-1990			
30.250	966D REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
304161	RH SIDE WINDOW HEATING REGULATOR HYLZ50422	MOS					27-FEB-1990			
30.250	969D REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
304301	PILOT WINDSHIELD WIPER MOTOR 4267568	MOS					27-FEB-1990			
30.260	11395 REF: AMM 30-43-09-220-801	HRS/MSC AFL	O/C	TSN:0			0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
304331	COPILOT WINDSHIELD WIPER MOTOR									
30.260	4267575 13055 REF: AMM 30-43-09-220-801	MOS HRS/MSC AFL	O/C				20-JUL-1990 27 14			
304361	PILOT WINDSHIELD WIPER ARM									
30.270	4218246 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
304371	COPILOT WINDSHIELD WIPER ARM									
30.270	4218209 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
CHAPTER 31 INDICATING/RECORDING SYSTEMS										
31-21-05-960-801-01	REPLACE PILOT CHRONOMETER BATTERIES									
31.080	811B-FTR-24HR 95576 REF: AMM 31-21-05-960-801	MOS HRS/MSC AFL	25				10-NOV-2016 10318.4 5973	10-DEC-2018		418 d
LIFE LIMIT										
31-21-05-960-801-02	REPLACE COPILOT CHRONOMETER BATTERIES									
31.080	811BFTR24HR 25576 REF: AMM 31-21-05-960-801	MOS HRS/MSC AFL	25				10-NOV-2016 10318.4 5973	10-DEC-2018		418 d
SCRAP										
31-31-00-710-802-01 (s)	OPERATIONAL TEST OF THE OF THE FLIGHT DATA (FDR) RECORDER									
31.100	PKG 12,17 REF: AMM 31-31-00-710-802	MOS HRS/MSC AFL	16	+1m			PKG 08-FEB-2017 10425.7 6021			
31-31-00-720-802-01	FUNCTIONAL TEST FLIGHT DATA (FDR) RECORDER 57-PARAMETERS									
31.100	S800-2000-01 01462 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C							
31-31-00-720-803-01	FUNCTIONAL TEST OF THE FLIGHT DATA (FDR) RECORDER 32-PARAMETERS									
31.100	REF: AMM 31-31-00-720-803	MOS HRS/MSC AFL	O/C							
31-31-00-970-801-01	DOWNLOAD OF THE OF THE FLIGHT DATA (FDR) RECORDER									
31.100	REF: AMM 31-31-00-970-801	MOS HRS/MSC AFL APH	A/R							
31-31-09-710-801-01	OPERATIONAL TEST COCKPIT VOICE RECORDER (CVR) ACCELERATION CONTACT									
	6UO-114 56490 REF: AMM 31-31-09-710-801	MOS HRS/MSC AFL	N/A				16-APR-2007			
31-31-09-710-801-02	OPERATIONAL TEST FLIGHT DATA RECORDER (FDR) ACCELERATION CONTACT									
	PN SN-UNKNOWN REF: AMM 31-31-09-710-801	MOS HRS/MSC AFL	N/A				31-JUL-1990 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
31-31-09-900-801-01	COCKPIT VOICE RECORDER (CVR) ACCELERATION CONTACT									
31.110	6UO-114 56490 REF: AMM 31-31-09-900-801	MOS HRS/MSC AFL	O/C				16-APR-2007 6601			
31-31-09-900-801-02	FLIGHT DATA RECORDER (FDR) ACCELERATION CONTACT									
31.110	PN SN-UNKNOWN REF: AMM 31-31-09-900-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
31-31-31-900-801-01	FLIGHT DATA (FDR) RECORDER									
31.100	S800-2000-01 01462 REF: AMM 31-31-31-900-801	MOS HRS/MSC AFL	O/C				16-APR-2007 6601			
+ 31-31-50-710-801-01 (s)	OPERATIONAL TEST OF THE OF THE VOICE DATA RECORDER									
31.070	PKG 12,17 REF: AMM 31-31-50-710-801	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
31-31-50-970-801-01	DOWNLOAD OF THE OF THE VOICE DATA RECORDER									
		MOS HRS/MSC AFL	A/R				27-FEB-1990 0 0			
31-32-00-970-801-01	DOWNLOAD QUICK ACCESS (QAR) RECORDER DATA									
31.140	PN NOT INSTALLED REF: AMM 31-32-00-970-801	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
31-32-01-900-801-01	QUICK ACCESS (QAR) RECORDER									
31.140	PN NOT INSTALLED REF: AMM 31-32-01-900-801	MOS HRS/MSC AFL APH	O/C			TSN:0 TSN:0 TSN:0 TSN:0	27-FEB-1990 0 0 0			
31-32-05-960-801-01	REPLACEMENT QUICK ACCESS (QAR) RECORDER BATTERY									
31.140	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
+ 31-52-00-710-801-01 (s)	OPERATIONAL TEST OF THE WARNING PANEL EMERGENCY POWER SUPPLY									
31.010	PKG 2,7 REF: AMM 31-52-00-710-801	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
+ 31-54-00-720-803-01 (s)	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES ALARM TEST									
31.030	PKG 1 REF: AMM 31-54-00-720-803	MOS HRS/MSC AFL	8	+1m			20-SEP-2017 10758.2 6172			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 31-54-00-720-803-02 (s)	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES INDICATION LOGIC						PKG			
31.030	PKG 21 REF: AMM 31-54-00-720-803	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
+ 31-55-00-720-801-01 (s)	FUNCTIONAL TEST OF THE LANDING SAFETIES						PKG			
31.040	PKG 21 REF: AMM 31-55-00-720-801	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
310101	WARNING PANEL									
31.010	90300-4 182 REF:	MOS HRS/MSC AFL	O/C				05-APR-2010 7697.3 4616			
312001	PILOT CHRONOMETER									
31.080	811B-FTR-24HR 95576 REF: AMM 31-21-05-960-801	MOS HRS/MSC AFL	O/C				20-JUL-1990 27.2			
312006	COPILOT CHRONOMETER									
31.080	811BFTR24HR 25576 REF: AMM 31-21-05-960-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		20-JUL-1990 27 14			
313001	FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON									
31.100	DK120 SD24177 REF: AMM 25-62-00-900-801	MOS HRS/MSC AFL	O/C				08-SEP-2017 10758.2 6172			
313006	VOICE DATA RECORDER UNDERWATER LOCATOR BEACON									
31.070	DK120/90 AT45962 REF: AMM 25-62-00-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-JAN-2016 10160.5 5907			
314A03	(E)GPWS COMPUTER									
	965-0976-040-218-218 23659 REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		05-DEC-2016 10334.5 5986			
314A04	(E)GPWS INVERTER									
	1A50-1B-1 NOT INSTALL REF:	MOS HRS/MSC AFL	O/C				18-SEP-2002 5317.6 3220			
315101	AUDIO WARNING UNIT									
31.050	240ZS01Y05 122 REF:	MOS HRS/MSC AFL	O/C				20-JUL-1990 27.2			
315251	VOICE DATA RECORDER									
31.070	93-A100-83 57502 REF:	MOS HRS/MSC AFL	O/C		TSO:12 TSO:0 TSO:0		03-FEB-2017 10425.7 6021			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
315256	VOICE DATA RECORDER CONTROL									
31.120	93-A151-20 71516 REF:	MOS HRS/MSC AFL	O/C				17-JUN-2017 10663 6123			
315261	VOICE DATA RECORDER REMOTE MICROPHONE									
31.130	93-A055-40 51438 REF:	MOS HRS/MSC AFL	O/C				29-AUG-1999 4148			
315A04	INERTIA CVR SWITCH									
	6U0-114/2.75 93714 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2013 9403.4 5553			
CHAPTER 32 LANDING GEAR										
+ 32-00-00-700-801-01	CHECK OF THE NOSE LANDING GEAR (NLG) UPLOCK BOX									
32.130		MOS HRS/MSC AFL	O/C				01-JUL-2012 8826.6 5235			
REF:	AMM 32-00-00-700-801									
+ 32-00-00-700-801-02	CHECK OF THE LH MAIN LANDING GEAR (MLG) UPLOCK BOX									
32.050		MOS HRS/MSC AFL	O/C				26-MAY-2012 8750.4			
REF:	AMM 32-00-00-700-801									
+ 32-00-00-700-801-03 (s)	CHECK OF THE RH MAIN LANDING GEAR (MLG) UPLOCK BOX						PKG			
32.050	PKG 12	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
REF:	AMM 32-00-00-700-801									
32-00-00-780-802-01 (s)	CHECK OF THE CHARGING PRESSURE OF THE LH MLG SHOCK ABSORBER						PKG			
	PKG 21	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
REF:	AMM 32-00-00-780-802									
32-00-00-780-802-02 (s)	CHECK OF THE CHARGING PRESSURE OF THE RH MLG SHOCK ABSORBER						PKG			
	PKG 21	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
REF:	AMM 32-00-00-780-802									
32-00-00-780-802-03 (s)	CHECK OF THE CHARGING PRESSURE OF THE NLG SHOCK ABSORBER						PKG			
	PKG 21	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
REF:	AMM 32-00-00-780-802									
32-10-00-640-801-01 (s)	LUBRICATION LEFT OF THE LH MAIN LANDING GEARS (MLG) AND DOORS						PKG			
32.010	PKG 1	MOS HRS/MSC AFL	8	+1m			20-SEP-2017 10758.2 6172			
REF:	AMM 32-10-00-640-801									
32-10-00-640-801-02 (s)	LUBRICATION RIGHT OF THE RH MAIN LANDING GEARS (MLG) AND DOORS						PKG			
32.010	PKG 1	MOS HRS/MSC AFL	8	+1m			20-SEP-2017 10758.2 6172			
REF:	AMM 32-10-00-640-801									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 32-11-00-220-801-01	DETAILED INSPECTION LH MAIN LANDING GEAR (MLG) LEG AND CHECK FOR CORROSION									
32.020	D22801100-11-/-13-14 U87 REF: AMM 32-11-00-220-801	MOS HRS/MSC AFL	72	+8m			27-MAR-2014	27-MAR-2020	27-NOV-2020	891 d (+245)
+ 32-11-00-220-801-02	DETAILED INSPECTION RH MAIN LANDING GEAR (MLG) LEG AND CHECK FOR CORROSION									
32.030	D22802100-11-/-13-14 U88 REF: AMM 32-11-00-220-801	MOS HRS/MSC AFL	72	+8m			27-MAR-2014	27-MAR-2020	27-NOV-2020	891 d (+245)
32-11-00-350-801-01	RESTORATION LH MAIN LANDING GEAR (MLG) LEG (OVERHAUL)									
OVERHAUL	D22801100-11-/-13-14 U87 REF: AMM 32-11-00-350-801	MOS HRS/MSC AFL	144	+3%			05-MAY-2014 9515 5634	05-MAY-2026	14-SEP-2026	3121 d (+132) 5452
32-11-00-350-801-02	RESTORATION RH MAIN LANDING GEAR (MLG) LEG (OVERHAUL)									
OVERHAUL	D22802100-11-/-13-14 U88 REF: AMM 32-11-00-350-801	MOS HRS/MSC AFL	144	+3%			05-MAY-2014 9515 5634	05-MAY-2026	14-SEP-2026	3121 d (+132) 5452
32-11-00-900-801-01	LH MAIN LANDING GEAR (MLG) LEG									
32.020	D22801100-11-/-13-14 U87 REF: AMM 32-11-00-900-801	MOS HRS/MSC AFL	H/T				TSO:2 TSN:9515 TSO:0 TSN:5634 TSO:0	05-MAY-2014 9515 5634		
32-11-00-900-801-02	RH MAIN LANDING GEAR (MLG) LEG									
32.030	D22802100-11-/-13-14 U88 REF: AMM 32-11-00-900-801	MOS HRS/MSC AFL	H/T				TSO:2 TSN:9515 TSO:0 TSN:5634 TSO:0	05-MAY-2014 9515 5634		
32-11-00-960-801-01	REPLACEMENT LH MAIN LANDING GEAR (MLG) LEG (DISCARD LIFE LIMITED PARTS)									
32.020	D22801100-11-/-13-14 U87 REF: AMM 32-11-00-960-801	MOS HRS/MSC AFL	20000				TSI:9515 TSI:5634	05-MAY-2014 9515 5634	20000	13818
32-11-00-960-801-01A	REPLACEMENT LH MAIN LANDING GEAR (MLG) LEG (DISCARD LIFE LIMITED PARTS) (MANDATORY 5-40)									
LIFE LIMIT	D22801100-11-/-13-14 U87 REF: AMM 32-11-00-960-801	MOS HRS/MSC AFL	20000				TSI:9515 TSI:5634	05-MAY-2014 9515 5634	20000	13818
32-11-00-960-801-02	REPLACEMENT RH MAIN LANDING GEAR (MLG) LEG (DISCARD LIFE LIMITED PARTS)									
32.030	D22802100-11-/-13-14 U88 REF: AMM 32-11-00-960-801	MOS HRS/MSC AFL	20000				TSI:9515 TSI:5634	05-MAY-2014 9515 5634	20000	13818
32-11-00-960-801-02A	REPLACEMENT RH MAIN LANDING GEAR (MLG) LEG (DISCARD LIFE LIMITED PARTS) (MANDATORY 5-40)									
LIFE LIMIT	D22802100-11-/-13-14 U88 REF: AMM 32-11-00-960-801	MOS HRS/MSC AFL	20000				TSI:9515 TSI:5634	05-MAY-2014 9515 5634	20000	13818
32-11-05-900-801-01	LH MAIN LANDING GEAR (MLG) SHOCK ABSORBER									
32.020	D22805100 SN-UNKNOWN REF: AMM 32-11-05-900-801	MOS HRS/MSC AFL	O/C				TSN:291 TSO:140 TSN:9515 TSO:4197.4 TSN:5634 TSO:2414	05-MAY-2014 9515 5634		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-11-05-900-801-02	RH MAIN LANDING GEAR (MLG) SHOCK ABSORBER D22806100 SN-UNKNOWN REF: AMM 32-11-05-900-801	MOS HRS/MSC AFL	O/C	TSN:291 TSO:140 TSN:9515 TSO:4197.4 TSN:5634 TSO:2414			05-MAY-2014 9515 5634			
32-11-21-900-801-01	LH MAIN LANDING GEAR (MLG) BRACE ACTUATOR D22791002 U96 REF: AMM 32-11-21-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
32-11-21-900-801-02	RH MAIN LANDING GEAR (MLG) BRACE ACTUATOR D22792002 U98 REF: AMM 32-11-21-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
32-12-17-900-801-01	LH MAIN LANDING GEAR (MLG) UPLOCK BOX C24244007-3 H1061 REF: AMM 32-12-17-900-801	MOS HRS/MSC AFL	O/C				26-MAY-2012 8750.4 5198			
32-12-17-900-801-02	RH MAIN LANDING GEAR (MLG) UPLOCK BOX C24245007-1 U294 REF: AMM 32-12-17-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
32-12-25-900-801-01	LH MAIN LANDING GEAR (MLG) DOOR ACTUATOR VN1031-1 180 REF: AMM 32-12-25-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
32-12-25-900-801-02	RH MAIN LANDING GEAR (MLG) DOOR ACTUATOR VN1031-1 63 REF: AMM 32-12-25-900-801	MOS HRS/MSC AFL	O/C				04-OCT-1996 2742.8			
32-20-00-640-801-01 (s)	LUBRICATION NOSE LANDING GEAR OF THE NOSE LANDING GEAR (NLG) AND DOORS PKG 1 REF: AMM 32-20-00-640-801	MOS HRS/MSC AFL	8 400	+1m +40			PKG 20-SEP-2017 10758.2 6172			
+ 32-21-00-220-801-01	DETAILED INSPECTION NOSE LANDING GEAR (NLG) LEG AND CHECK FOR CORROSION D22811200-16-X-18-19-/-/-22 U90 REF: AMM 32-21-00-220-801	MOS HRS/MSC AFL	72	+8m			27-MAR-2014	27-MAR-2020	27-NOV-2020	891 d (+245)
32-21-00-350-801-01	RESTORATION NOSE LANDING GEAR (NLG) LEG (OVERHAUL) D22811200-16-X-18-19-/-/-22 U90 REF: AMM 32-21-00-350-801	MOS HRS/MSC AFL	144 6000	+3%			05-MAY-2014 9515 5634	05-MAY-2026	14-SEP-2026	3121 d (+132) 5452
32-21-00-900-801-01	NOSE LANDING GEAR (NLG) LEG D22811200-16-X-18-19-/-/-22 U90 REF: AMM 32-21-00-900-801	MOS HRS/MSC AFL	H/T	TSO:2 TSN:9515 TSO:0 TSN:5634 TSO:0			05-MAY-2014 9515 5634			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-21-00-960-801-01	REPLACEMENT NOSE LANDING GEAR (NLG) LEG (DISCARD LIFE LIMITED PARTS)									
32.110	D22811200-16-X-18-19-/-/22	MOS					05-MAY-2014			
LIFE LIMIT	U90	HRS/MSC		TSI:9515			9515			
	REF: AMM 32-21-00-960-801	AFL	20000	TSI:5634			5634	20000		13818
32-21-00-960-801-01A	REPLACEMENT NOSE LANDING GEAR (NLG) LEG (DISCARD LIFE LIMITED PARTS) (MANDATORY 5-40)									
	D22811200-16-X-18-19-/-/22	MOS					05-MAY-2014			
LIFE LIMIT	U90	HRS/MSC		TSI:9515			9515			
	REF: AMM 32-21-00-960-801	AFL	20000	TSI:5634			5634	20000		13818
32-21-01-780-802-01	CHECK OF THE CHARGING PRESSURE OF THE NOSE LANDING GEAR (NLG) SHOCK ABSORBER BY APPLYING A ROTATIONAL TORQUE									
		MOS					26-MAY-2012			
		HRS/MSC	O/C				8750.4			
	REF: AMM 32-21-01-780-802	AFL								
32-21-09-900-801-01 (s)	REMOVAL/INSTALLATION AND INSPECTION OF THE LH NOSE LANDING GEAR DRAG BRACE BALL-JOINT BEARING						PKG			
32.135	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: See Workcard	HRS/MSC					9515			
		AFL	3750				5634			
+ 32-21-09-900-801-02 (s)	REMOVAL / INSTALLATION AND INSPECTION OF THE RH NOSE LANDING GEAR DRAG BRACE BALL-JOINT BEARING						PKG			
	PKG 31	MOS	72				27-FEB-1990			
	REF: See Workcard	HRS/MSC					0			
		AFL	3750				0			
+ 32-21-09-900-801-03 (s)	REMOVAL / INSTALLATION AND INSPECTION OF THE LH NOSE LANDING GEAR LEG BALL-JOINT BEARING						PKG			
	PKG 31	MOS	72				27-FEB-1990			
	REF: AMM 32-21-09-900-801	HRS/MSC					0			
		AFL	3750				0			
+ 32-21-09-900-801-04 (s)	REMOVAL / INSTALLATION AND INSPECTION OF THE RH NOSE LANDING GEAR LEG BALL-JOINT BEARING						PKG			
	PKG 31	MOS	72				27-FEB-1990			
	REF: AMM 32-21-09-900-801	HRS/MSC					0			
		AFL	3750				0			
32-22-01-350-801-01	RESTORATION NOSE LANDING GEAR TELESCOPIC TUBE YOKE ASSEMBLY (OVERHAUL)									
32.120	GA62269	MOS	144	+3%			05-MAY-2014	05-MAY-2026	14-SEP-2026	3121 d (+132)
	449MNR	HRS/MSC					9515			
	REF: AMM 32-22-01-350-801	AFL	6000				5634	11634		5452
32-22-01-900-801-01	NOSE NOSE LANDING GEAR (NLG) DRAG BRACE									
32.120	D22796001-1	MOS					27-FEB-1990			
	U94	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 32-22-01-900-801	AFL					0			
32-22-17-900-801-01	NOSE LANDING GEAR (NLG) UPLOCK BOX									
32.130	C24245006-3	MOS					07-APR-2009			
	U582	HRS/MSC	O/C				7345			
	REF: AMM 32-22-17-900-801	AFL					4401			
+ 32-30-00-720-801-01 (s)	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS NORMAL OPERATION						PKG			
32.160	PKG 21	MOS					20-SEP-2017			
	REF: AMM 32-30-00-720-801	HRS/MSC	1600	+40			10758.2			
		AFL					6172			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-30-00-720-801-02 (s)	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS HYDRAULIC EMERGENCY OPERATION PKG 21	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
	REF: AMM 32-30-00-720-801									
32-30-00-720-801-03 (s)	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS MECHANICAL EMERGENCY OPERATION PKG 21	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
	REF: AMM 32-30-00-720-801									
32-30-13-900-801-01	LANDING GEAR NORMAL / EMERGENCY SELECTOR VALVE B94B09-202-1 20128	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
	REF: AMM 32-30-13-900-801									
+ 32-31-00-700-801-01 (s)	CHECK OF THE LANDING GEAR RETRACTION INHIBITION ON THE GROUND PKG 21	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
	REF: AMM 32-31-00-700-801									
32-32-00-640-801-01 (s)	LUBRICATION OF THE OF THE NOSE LANDING GEAR (NLG) CONTROL PKG 12,16	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
	REF: AMM 32-32-00-640-801									
32-32-00-640-801-02 (s)	CHECK OF THE OF THE NOSE LANDING GEAR (NLG) CONTROL ACTUATION FORCE PKG 12,16	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
	REF: AMM 32-32-00-640-801									
32-32-00-640-801-03 (s)	LUBRICATION OF THE MAIN LANDING GEAR (MLG) CONTROLS PKG 12,16	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
	REF: AMM 32-32-00-640-801									
32-32-00-640-801-04 (s)	CHECK OF THE MAIN LANDING GEAR (MLG) CONTROL ACTUATION FORCE PKG 12,16	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
	REF: AMM 32-32-00-640-801									
32-32-00-700-801-01	CHECK AFTER LANDING GEAR EMERGENCY EXTENSION PKG 21	MOS HRS/MSC AFL APH	A/R				27-FEB-1990 0 0 0			
	REF: AMM 32-32-00-700-801									
32-32-17-640-801-01 (s)	LUBRICATION OF THE OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL PKG 12,16	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
	REF: AMM 32-32-17-640-801									

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-32-17-640-801-02 (s)	CHECK OF THE OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL ACTUATION LOADS						PKG			
	PKG 12,16	MOS	16				08-FEB-2017			
	REF: AMM 32-32-17-640-801	HRS/MSC AFL					10425.7 6021			
32-32-17-900-801-01	LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE									
	PN	MOS		TSN:0			27-FEB-1990			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 32-32-17-900-801	AFL		TSN:0			0			
32-40-00-780-801-01 (s)	CHECK OF THE NORMAL BRAKING SYSTEM BRAKING PRESSURES						PKG			
	PKG 22	MOS					23-APR-2013			
	REF: AMM 32-40-00-780-801	HRS/MSC AFL	3200	+40			9161.3 5420			
32-40-00-780-801-02 (s)	CHECK OF EMERGENCY BRAKING SYSTEM BRAKING PRESSURES						PKG			
	PKG 22	MOS					23-APR-2013			
	REF: AMM 32-40-00-780-801	HRS/MSC AFL	3200	+40			9161.3 5420			
32-40-00-780-801-03 (s)	CHECK OF THE PARK BRAKE SYSTEM BRAKING PRESSURES						PKG			
	PKG 22	MOS					23-APR-2013			
	REF: AMM 32-40-00-780-801	HRS/MSC AFL	3200	+40			9161.3 5420			
32-41-00-710-802-01	OPERATIONAL TEST OF THE LH MLG OUTBOARD BLOCKED WHEEL DETECTION									
		MOS					27-FEB-1990			
	REF: AMM 32-41-00-710-802	HRS/MSC AFL	O/C				0 0			
32-41-00-710-802-02	OPERATIONAL TEST OF THE LH MLG INBOARD BLOCKED WHEEL DETECTION									
		MOS					27-FEB-1990			
	REF: AMM 32-41-00-710-802	HRS/MSC AFL	O/C				0 0			
32-41-00-710-802-03	OPERATIONAL TEST OF THE RH MLG OUTBOARD BLOCKED WHEEL DETECTION									
		MOS					27-FEB-1990			
	REF: AMM 32-41-00-710-802	HRS/MSC AFL	O/C				0 0			
32-41-00-710-802-04	OPERATIONAL TEST OF THE RH MLG INBOARD BLOCKED WHEEL DETECTION									
		MOS					27-FEB-1990			
	REF: AMM 32-41-00-710-802	HRS/MSC AFL	O/C				0 0			
32-41-07-610-801-01 (s)	SERVICING OF THE PEDAL INTERCONNECTION FLEXIBLE CONTROLS						PKG			
	PKG 31	MOS	72	+2m			05-MAY-2014			
32.415	REF: AMM 32-41-07-610-801	HRS/MSC AFL	3750				9515 5634			
32-41-07-610-801-02 (s)	MEASUREMENT OF THE PEDAL INTERCONNECTION FLEXIBLE CONTROLS SLIDING FORCES						PKG			
	PKG 16,18,203	MOS	24	+1m			30-AUG-2016			
32.415	REF: AMM 32-41-07-610-801	HRS/MSC AFL					10212.9 5929			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-41-37-960-801-01 (s)	REPLACEMENT OF THE LH BRAKING SYSTEM FILTER ELEMENT PKG 21	MOS					PKG			
32.590	REF: AMM 32-41-37-960-801	HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
32-41-37-960-801-02 (s)	REPLACEMENT OF THE RH BRAKING SYSTEM FILTER ELEMENT PKG 21	MOS					PKG			
32.590	REF: AMM 32-41-37-960-801	HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
32-41-37-960-801-03 (s)	REPLACEMENT PARKING BRAKE SELECTOR VALVE UPSTREAM FILTER ELEMENT PN PKG 21 SN-UNKNOWN	MOS					PKG			
	REF: AMM 32-41-37-960-801	HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
32-41-37-960-801-04 (s)	REPLACEMENT PARKING BRAKE SELECTOR VALVE DOWNSTREAM FILTER ELEMENT PN PKG 21 SN-UNKNOWN	MOS					PKG			
	REF: AMM 32-41-37-960-801	HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
32-41-45-900-801-01	ANTI-SKID CONTROL UNIT C20188102 U021	MOS						27-FEB-1990		
32.610	REF: AMM 32-41-45-900-801	HRS/MSC AFL	O/C		TSN:0		0 0			
32-41-49-900-802-01	LH NOSE LANDING GEAR (NLG) WHEEL TACHOMETER - GENERATOR C20260000-1 1999	MOS						08-MAR-2013		
32.620	REF: AMM 32-41-49-900-802	HRS/MSC AFL	O/C				9127.6 5401			
32-41-49-900-802-02	RH NOSE LANDING GEAR (NLG) WHEEL TACHOMETER - GENERATOR C20260000-1 621	MOS						18-AUG-2009		
32.620	REF: AMM 32-41-49-900-802	HRS/MSC AFL	O/C				7499 4492			
32-41-49-900-803-01	LH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL TACHOMETER - GENERATOR C20260000-1 3655	MOS						10-FEB-2017		
32.630	REF: AMM 32-41-49-900-803	HRS/MSC AFL	O/C				10425.7 6021			
32-41-49-900-803-02	LH INBOARD MAIN LANDING GEAR (MLG) WHEEL TACHOMETER - GENERATOR C20260000-1 2584	MOS						10-FEB-2017		
32.630	REF: AMM 32-41-49-900-803	HRS/MSC AFL	O/C				10425.7 6021			
32-41-49-900-803-03	RH INBOARD MAIN LANDING GEAR (MLG) WHEEL TACHOMETER - GENERATOR C20260000-1 726	MOS						18-JUL-2006		
32.640	REF: AMM 32-41-49-900-803	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		6403.3 3826			
32-41-49-900-803-04	RH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL TACHOMETER - GENERATOR 00-200-1021 3656	MOS						27-FEB-1990		
32.640	REF: AMM 32-41-49-900-803	HRS/MSC AFL	O/C		TSN:0		0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-41-57-900-801-01	LH MAIN LANDING GEAR (MLG) BRAKE SERVO VALVE C20103300 193 REF: AMM 32-41-57-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
32-41-57-900-801-02	RH MAIN LANDING GEAR (MLG) BRAKE SERVO VALVE C20103300 200 REF: AMM 32-41-57-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
32-42-00-610-801-01 (s)	SERVICING OF THE OF THE PARK BRAKE CONTROL CABLE PKG 12 REF: AMM 32-42-00-610-801	MOS HRS/MSC AFL	16	+1m			PKG 08-FEB-2017 10425.7 6021			
32-42-01-900-801-01	PARKING BRAKE SELECTOR VALVE 70012-1 181 REF: AMM 32-42-01-900-801	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			28-SEP-2005 6221.6 3737			
+ 32-42-05-720-801-01 (s)	FUNCTIONAL TEST PARKING BRAKE ACCUMULATOR CAPACITY 60833-2 PKG 14,17 519 REF: AMM 32-42-05-720-801	MOS HRS/MSC AFL	32	+1m			PKG 08-FEB-2017 10425.7 6021			
32-42-05-780-801-01 (s)	CHECK OF THE PARK BRAKE ACCUMULATOR PRESSURE PKG 1 REF: AMM 32-42-05-780-801	MOS HRS/MSC AFL	8	400			PKG 20-SEP-2017 10758.2 6172			
32-42-05-900-801-01	PARKING BRAKE ACCUMULATOR 60833-2 519 REF: AMM 32-42-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
32-44-00-220-801-01	DETAILED INSPECTION OF THE MLG AND NLG WHEEL TIRES REF: AMM 32-44-00-220-801	MOS HRS/MSC AFL	2	+5d			08-SEP-2017 10758.2 6172	08-NOV-2017	13-NOV-2017	21 d (+5)
32-44-00-250-801-01	SPECIAL DETAILED INSPECTION LH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL SUBASSEMBLIES C20180410MIC 02286 REF: AMM 32-44-00-250-801	MOS HRS/MSC AFL	400	+3%			23-MAR-2017 10460.1 6047	6447	6459	265 (+12)
32-44-00-250-801-02	SPECIAL DETAILED INSPECTION LH INBOARD MAIN LANDING GEAR (MLG) WHEEL SUBASSEMBLIES C20180400 F1249/F1137 REF: AMM 32-44-00-250-801	MOS HRS/MSC AFL	400	+3%			20-SEP-2017 10758.2 6172	6572	6584	390 (+12)
32-44-00-250-801-03	SPECIAL DETAILED INSPECTION RH INBOARD MAIN LANDING GEAR (MLG) WHEEL SUBASSEMBLIES C20180410 02366 REF: AMM 32-44-00-250-801	MOS HRS/MSC AFL	400	+3%			20-SEP-2017 10758.2 6172	6572	6584	390 (+12)



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-44-00-250-801-04	SPECIAL DETAILED INSPECTION RH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL SUBASSEMBLIES									
32.480	C20180400 02523 REF: AMM 32-44-00-250-801	MOS HRS/MSC AFL	400	+3%			10-OCT-2017 10775.7 6182	6582	6594	400 (+12)
32-44-00-250-801-05	SPECIAL DETAILED INSPECTION LH NOSE LANDING GEAR (NLG) WHEEL SUBASSEMBLIES									
32.490	C20182100 00910 REF: AMM 32-44-00-250-801	MOS HRS/MSC AFL	500	+3%			04-JUL-2017 10683.8 6134	6634	6649	452 (+15)
32-44-00-250-801-06	SPECIAL DETAILED INSPECTION RH NOSE LANDING GEAR (NLG) WHEEL SUBASSEMBLIES									
32.500	C20182100 00900 REF: AMM 32-44-00-250-801	MOS HRS/MSC AFL	500	+3%			04-JUL-2017 10683.8 6134	6634	6649	452 (+15)
32-44-00-780-801-01	PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES									
	REF: AMM 32-44-00-780-801	MOS HRS/MSC AFL	2	+5d			20-SEP-2017 10758.2 6172	20-NOV-2017	25-NOV-2017	33 d (+5)
32-44-01-900-801-01	LH NOSE LANDING GEAR (NLG) WHEEL									
32.490	C20182100 00910 REF: AMM 32-44-01-900-801	MOS HRS/MSC AFL	O/C			TSO:2 TSO:74.4 TSO:38	20-SEP-2017 10758.2 6172			
32-44-01-900-801-02	RH NOSE LANDING GEAR (NLG) WHEEL									
32.500	C20182100 00900 REF: AMM 32-44-01-900-801	MOS HRS/MSC AFL	O/C			TSO:0 TSO:0 TSO:0	04-JUL-2017 10683.8 6134			
32-44-05-900-801-01	LH NOSE LANDING GEAR (NLG) TIRE									
32.490	M13301IND02 6037S229 REF: AMM 32-44-05-900-801	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	04-JUL-2017 10683.8 6134			
32-44-05-900-801-02	RH NOSE LANDING GEAR (NLG) TIRE									
32.500	M13301IND02 5197S159 REF: AMM 32-44-05-900-801	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	04-JUL-2017 10683.8 6134			
32-44-09-900-801-01	LH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL									
32.450	C20180410MIC 02286 REF: AMM 32-44-09-900-801	MOS HRS/MSC AFL	O/C			TSO:31 TSR:0 TSO:809.7 TSR:0 TSO:358 TSR:0	23-MAR-2017 10460.1 6047			
32-44-09-900-801-02	LH INBOARD MAIN LANDING GEAR (MLG) WHEEL									
32.460	C20180400 F1249/F1137 REF: AMM 32-44-09-900-801	MOS HRS/MSC AFL	O/C			TSO:0 TSO:0 TSO:0	20-SEP-2017 10758.2 6172			
32-44-09-900-801-03	RH INBOARD MAIN LANDING GEAR (MLG) WHEEL									
32.470	C20180410 02366 REF: AMM 32-44-09-900-801	MOS HRS/MSC AFL	O/C			TSO:0 TSO:0 TSO:0	20-SEP-2017 10758.2 6172			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-44-09-900-801-04	RH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL									
32.480	C20180400 02523 REF: AMM 32-44-09-900-801	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-OCT-2017 10775.7 6182			
32-44-13-900-801-01	LH OUTBOARD MAIN LANDING GEAR (MLG) TIRE									
32.450	M06201IND04 6238S112 REF: AMM 32-44-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2017 10460.1 6047			
32-44-13-900-801-02	LH INBOARD MAIN LANDING GEAR (MLG) TIRE									
32.460	M06201IND04 6329S124 REF: AMM 32-44-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-SEP-2017 10758.2 6172			
32-44-13-900-801-03	RH INBOARD MAIN LANDING GEAR (MLG) TIRE									
32.470	M06201IND04 6332S224 REF: AMM 32-44-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-SEP-2017 10758.2 6172			
32-44-13-900-801-04	RH OUTBOARD MAIN LANDING GEAR (MLG) TIRE									
32.480	M06201IND04 7127S139 REF: AMM 32-44-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-OCT-2017 10775.7 6182			
32-44-17-350-801-01	RESTORATION LH OUTBOARD MAIN LANDING GEAR (MLG) BRAKE (OVERHAUL)									
32.510 OVERHAUL	C20111800-7 U756 REF: AMM 32-44-17-350-801	MOS HRS/MSC AFL	A/R				30-JUN-2012 8822.7 5232			
32-44-17-350-801-02	RESTORATION LH INBOARD MAIN LANDING GEAR (MLG) BRAKE (OVERHAUL)									
32.510 OVERHAUL	C20181100-7 U827 REF: AMM 32-44-17-350-801	MOS HRS/MSC AFL	A/R				30-JUN-2012 8822.7 5232			
32-44-17-350-801-03	RESTORATION RH INBOARD MAIN LANDING GEAR (MLG) BRAKE (OVERHAUL)									
32.520 OVERHAUL	C20181100-7 U597 REF: AMM 32-44-17-350-801	MOS HRS/MSC AFL	A/R				04-AUG-2007 6714.6 4028			
32-44-17-350-801-04	RESTORATION RH OUTBOARD MAIN LANDING GEAR (MLG) BRAKE (OVERHAUL)									
32.520 OVERHAUL	C20181100-7 U518 REF: AMM 32-44-17-350-801	MOS HRS/MSC AFL	A/R				08-MAR-2013 9127.6 5401			
32-44-17-900-801-01	LH OUTBOARD MAIN LANDING GEAR (MLG) BRAKE									
32.510 OVERHAUL	C20111800-7 U756 REF: AMM 32-44-17-900-801	MOS HRS/MSC AFL	A/R	TSR:0 TSR:0 TSR:0			16-JAN-2015 9764.1 5742			
32-44-17-900-801-02	LH INBOARD MAIN LANDING GEAR (MLG) BRAKE									
32.510 OVERHAUL	C20181100-7 U827 REF: AMM 32-44-17-900-801	MOS HRS/MSC AFL	A/R	TSR:0 TSR:0 TSR:0			16-JAN-2015 9764.1 5742			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-44-17-900-801-03	RH INBOARD MAIN LANDING GEAR (MLG) BRAKE C20181100-7 U597 REF: AMM 32-44-17-900-801	MOS HRS/MSC AFL	A/R				07-SEP-2013 9353.3 5528			
32-44-17-900-801-04	RH OUTBOARD MAIN LANDING GEAR (MLG) BRAKE C20181100-7 U518 REF: AMM 32-44-17-900-801	MOS HRS/MSC AFL	A/R	TSO:0 TSO:0			08-MAR-2013 9127.6 5401			
32-44-18-960-801-01	REPLACEMENT LH OUTBOARD MAIN LANDING GEAR (MLG) BRAKE SEAL C20111800-7 U756 REF: AMM 32-44-18-960-801	MOS HRS/MSC AFL	C/C				30-JUN-2012 8822.7 5232			
32-44-18-960-801-02	REPLACEMENT LH INBOARD MAIN LANDING GEAR (MLG) BRAKE SEAL C20181100-7 U827 REF: AMM 32-44-18-960-801	MOS HRS/MSC AFL	C/C				30-JUN-2012 8822.7 5232			
32-44-18-960-801-03	REPLACEMENT RH INBOARD MAIN LANDING GEAR (MLG) BRAKE SEAL C20181100-7 U597 REF: AMM 32-44-18-960-801	MOS HRS/MSC AFL	C/C							
32-44-18-960-801-04	REPLACEMENT RH OUTBOARD MAIN LANDING GEAR (MLG) BRAKE SEAL C20181100-7 U518 REF: AMM 32-44-18-960-801	MOS HRS/MSC AFL	C/C				08-MAR-2013 9127.6 5401			
32-50-13-900-801-01	STEERING SERVOVALVE A25455004 00869 REF: AMM 32-50-13-900-801	MOS HRS/MSC AFL	O/C	TSR:4 TSR:0 TSR:0			08-FEB-2016 10165.3 5909			
32-50-17-960-801-01 (s)	REPLACEMENT OF THE STEERING SYSTEM FILTERING ELEMENT PKG 22 REF: AMM 32-50-17-960-801	MOS HRS/MSC AFL	3200	+40			PKG 23-APR-2013 9161.3 5420			
32-50-25-900-801-01	STEERING CONTROL HANDWHEEL UNIT 287837-1 U752 REF: AMM 32-50-25-900-801	MOS HRS/MSC AFL	O/C				10-NOV-2006 6434.9			
32-61-45-760-801-01 (s)	CHECK LH MAIN LANDING GEAR (MLG) MAIN DOOR ACTUATOR PROXIMITY SWITCH 248022750 PKG 21 SN-UNKNOWN REF: AMM 32-61-45-760-801	MOS HRS/MSC AFL	1600	+40			PKG 20-SEP-2017 10758.2 6172			
32-61-45-760-801-02 (s)	CHECK RH MAIN LANDING GEAR (MLG) MAIN DOOR ACTUATOR PROXIMITY SWITCH 248022750 PKG 21 SN-UNKNOWN REF: AMM 32-61-45-760-801	MOS HRS/MSC AFL	1600	+40			PKG 20-SEP-2017 10758.2 6172			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-61-45-900-801-01	LH MAIN LANDING GEAR (MLG) MAIN DOOR ACTUATOR PROXIMITY SWITCH 248022750	MOS					27-FEB-1990			
32.350	SN-UNKNOWN REF: AMM 32-61-45-900-801	HRS/MSC AFL	O/C	TSN:0			0 0			
32-61-45-900-801-02	RH MAIN LANDING GEAR (MLG) MAIN DOOR ACTUATOR PROXIMITY SWITCH 248022750	MOS					27-FEB-1990			
32.350	SN-UNKNOWN REF: AMM 32-61-45-900-801	HRS/MSC AFL	O/C	TSN:0			0 0			
32-61-49-900-801-01	LH MLG LEG OUTBOARD PROXIMITY SWITCH PN	MOS					27-FEB-1990			
	SN-UNKNOWN REF: AMM 32-61-49-900-801	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0			
32-61-49-900-801-02	LH MLG LEG INBOARD PROXIMITY SWITCH PN	MOS					27-FEB-1990			
	SN-UNKNOWN REF: AMM 32-61-49-900-801	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0			
32-61-49-900-801-03	RH MLG LEG INBOARD PROXIMITY SWITCH PN	MOS					27-FEB-1990			
	SN-UNKNOWN REF: AMM 32-61-49-900-801	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0			
32-61-49-900-801-04	RH MLG LEG OUTBOARD PROXIMITY SWITCH PN	MOS					27-FEB-1990			
	SN-UNKNOWN REF: AMM 32-61-49-900-801	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0			
32-61-49-900-801-05	NLG LEG LH PROXIMITY SWITCH PN	MOS					27-FEB-1990			
	SN-UNKNOWN REF: AMM 32-61-49-900-801	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0			
32-61-49-900-801-06	NLG LEG RH PROXIMITY SWITCH PN	MOS					27-FEB-1990			
	SN-UNKNOWN REF: AMM 32-61-49-900-801	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0			
32-61-49-900-801-07	NOSE LANDING GEAR LEFT MAIN DOOR PROXIMITY SWITCH 84738-702	MOS					27-FEB-1990			
32.390	SN-UNKNOWN REF: AMM 32-61-49-900-801	HRS/MSC AFL	O/C	TSN:0			0 0			
32-61-49-900-801-08	NOSE LANDING GEAR RIGHT MAIN DOOR PROXIMITY SWITCH 84738-702	MOS					27-FEB-1990			
32.390	SN-UNKNOWN REF: AMM 32-61-49-900-801	HRS/MSC AFL	O/C	TSN:0			0 0			
32-61-49-900-802-01	NLG DRAG BRACE LH PROXIMITY SWITCH PN	MOS					27-FEB-1990			
	SN-UNKNOWN REF: AMM 32-61-49-900-802	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-61-49-900-802-02	NLG DRAG BRACE RH PROXIMITY SWITCH PN SN-UNKNOWN REF: AMM 32-61-49-900-802	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0			
32-61-49-900-802-03	LH MLG BRACE ACTUATOR PROXIMITY NO. 1 SWITCH 84738702 2372 REF: AMM 32-61-49-900-802	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
32-61-49-900-802-04	LH MLG BRACE ACTUATOR PROXIMITY NO. 2 SWITCH PN SN-UNKNOWN REF: AMM 32-61-49-900-802	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0			
32-61-49-900-802-05	RH MLG BRACE ACTUATOR PROXIMITY NO. 1 SWITCH 84738702 2372 REF: AMM 32-61-49-900-802	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
32-61-49-900-802-06	RH MLG BRACE ACTUATOR PROXIMITY NO. 2 SWITCH PN SN-UNKNOWN REF: AMM 32-61-49-900-802	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0			
32-61-49-900-803-01	NLG UPLOCK BOX PROXIMITY NO. 1 SWITCH PN SN-UNKNOWN REF: AMM 32-61-49-900-803	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0			
32-61-49-900-803-02	NLG UPLOCK BOX PROXIMITY NO. 2 SWITCH PN SN-UNKNOWN REF: AMM 32-61-49-900-803	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0			
32-61-49-900-803-03	LH MLG UPLOCK BOX PROXIMITY SWITCH PN SN-UNKNOWN REF: AMM 32-61-49-900-803	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0			
32-61-49-900-803-04	RH MLG UPLOCK BOX PROXIMITY SWITCH PN SN-UNKNOWN REF: AMM 32-61-49-900-803	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0			
32-61-49-900-803-05	LH UPLOCK BOX PROXIMITY NO. 1 SWITCH PN SN-UNKNOWN REF: AMM 32-61-49-900-803	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0			
32-61-49-900-803-06	LH UPLOCK BOX PROXIMITY NO. 2 SWITCH PN SN-UNKNOWN REF: AMM 32-61-49-900-803	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-61-49-900-803-07	RH UPLOCK BOX PROXIMITY NO. 1 SWITCH PN SN-UNKNOWN REF: AMM 32-61-49-900-803	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0			
32-61-49-900-803-08	RH UPLOCK BOX PROXIMITY NO. 2 SWITCH PN SN-UNKNOWN REF: AMM 32-61-49-900-803	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0			
321111	LH MAIN LANDING GEAR (MLG) STRUT ASSEMBLY D22803100 SN-UNKNOWN REF: AMM 32-11-00-900-801	MOS HRS/MSC AFL	O/C	TSN:291 TSO:140 TSN:9515 TSO:4197.4 TSN:5634 TSO:2414			05-MAY-2014 9515 5634			
321161	RH MAIN LANDING GEAR (MLG) STRUT ASSEMBLY D22804100 SN-UNKNOWN REF: AMM 32-11-00-900-801	MOS HRS/MSC AFL	O/C	TSN:291 TSO:140 TSN:9515 TSO:4197.4 TSN:5634 TSO:2414			05-MAY-2014 9515 5634			
321241	LH MAIN LANDING GEAR STRUT DOOR FGFB191 87 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
321251	RH MAIN LANDING GEAR STRUT DOOR FGFB192 87 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
321261	LH MAIN LANDING GEAR DOOR FGFB293100 94BZ REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
321271	RH MAIN LANDING GEAR DOOR FGFB293200 94BZ REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
321301	LH MAIN LANDING GEAR DOOR UPLOCK UNIT C24257002 U677 REF: AMM 32-12-29-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
321311	RH MAIN LANDING GEAR DOOR UPLOCK UNIT C24257002 U678 REF: AMM 32-12-29-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
322111	NOSE LANDING GEAR (NLG) CYLINDER D22812100 SN-UNKNOWN REF: AMM 32-21-00-900-801	MOS HRS/MSC AFL	O/C	TSN:151 TSO:0 TSN:5317.6 TSO:0 TSN:3220 TSO:0			18-SEP-2002 5317.6 3220			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
322121	NOSE LANDING GEAR (NLG) SHOCK ABSORBER									
32.110	D22813200 SN-UNKNOWN REF: AMM 32-21-01-900-801	MOS HRS/MSC AFL	O/C	TSN:151 TSO:0 TSN:5317.6 TSO:0 TSN:3220 TSO:0			18-SEP-2002 5317.6 3220			
322155	NOSE LANDING GEAR TELESCOPIC TUBE YOKE ASSEMBLY									
32.120	GA62269 449MNR REF:	MOS HRS/MSC AFL	H/T	TSO:2 TSO:0 TSO:0			05-MAY-2014 9515 5634			
322171	NOSE LANDING GEAR ACTUATOR									
32.130	D22795001 U80 REF: AMM 32-22-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
322211	NOSE LANDING GEAR STRUT MAIN DOOR									
32.140	FGFB291300 83BZ REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
322221	NOSE LANDING GEAR STRUT SECONDARY DOOR									
32.140	FGFB291400 82AG REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
322231	LH NOSE LANDING GEAR DOOR									
32.150	FGFB291100 92BZ REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
322241	RH NOSE LANDING GEAR DOOR									
32.150	FGFB291200 92BZ REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
322A25	PROX NLG TELESCOPIC TUBE (11GA-A) SWITCH									
	D22073300-1 U1276 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			30-MAY-2003 5502.6 3324			
322A26	PROX NLG TELESCOPIC TUBE (11GA-B) SWITCH									
	D22073300 SN-UNKNOWN REF:	MOS HRS/MSC AFL APH	O/C				27-FEB-1990 0 0 0			
323101	GEAR/DOOR CONTROL									
32.200	BHC1031-1 105 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323121	GEAR EXTENSION CONTROL ELECTRIC VALVE									
32.210	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
323131	GEAR RETRACTION CONTROL ELECTRIC VALVE									
32.210	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323141	DOOR OPENING CONTROL ELECTRIC VALVE									
32.220	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323151	DOOR CLOSING CONTROL ELECTRIC VALVE									
32.220	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323161	GEAR ELECTRO DISTRIBUTOR									
32.230	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323181	DOOR ELECTRO DISTRIBUTOR									
32.230	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323201	MAIN LANDING GEAR DOOR ACTUATOR RESTRICTOR VALVE									
32.230	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323231	SHUTTLE VALVE PROTECTION CHECK VALVE									
32.240	C24816000 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323241	LH MAIN LANDING GEAR ACTUATOR EXTENSION RESTRICTOR VALVE									
32.250	A24508-5220 B12581 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323251	RH MAIN LANDING GEAR ACTUATOR EXTENSION RESTRICTOR VALVE									
32.250	A24508-5220 B12592 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323261	LH MAIN LANDING GEAR ACTUATOR RETRACTION RESTRICTOR VALVE									
32.260	A24510-5220 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323271	RH MAIN LANDING GEAR ACTUATOR RETRACTION RESTRICTOR VALVE									
32.260	A24510-5220 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
323281	LH MAIN LANDING GEAR ACTUATOR DOOR OPENING RESTRICTOR VALVE									
32.270	A24506-5200 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323291	RH MAIN LANDING GEAR ACTUATOR DOOR OPENING RESTRICTOR VALVE									
32.270	A24506-5200 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323331	NOSE LANDING GEAR UNLOCKING RESTRICTOR VALVE									
32.290	A24508-5090 B12463 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323341	NOSE LANDING GEAR TELESCOPIC STRUT UNLOCKING RESTRICTOR VALVE									
32.290	A24508-5180 B12570 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323551	NOSE LANDING GEAR SWIVEL COUPLING									
32.320	C24266-1 U954 REF:	MOS HRS/MSC AFL	O/C	TSR:4 TSR:6022.6 TSR:3607			17-SEP-2004 6022.6 3607			
323721	LH MAIN LANDING GEAR WHEEL WELL PROXIMITY DETECTOR									
32.380	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
323731	RH MAIN LANDING GEAR WHEEL WELL PROXIMITY DETECTOR									
32.380	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
324451	NORMAL/EMERGENCY BRAKE DISTRIBUTOR									
32.530	57530-21 20R REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
324461	NORMAL BRAKE ELECTRIC DISTRIBUTOR									
32.530	65660-1 229A REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
324471	NORMAL BRAKE DISTRIBUTOR RETURN CHECK VALVE									
32.540	A24516 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
324501	LH SERVO-VALVE RETURN CHECK VALVE									
32.560	A24516 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
324511	RH SERVO-VALVE RETURN CHECK VALVE A24516	MOS					27-FEB-1990			
32.560	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
324521	LH BRAKE NORMAL RESTRICTOR VALVE C24758140	MOS					27-FEB-1990			
32.570	B168 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
324531	RH BRAKE NORMAL RESTRICTOR VALVE C24758140	MOS					27-FEB-1990			
32.570	B170 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
324541	LH BRAKE NORMAL PRESSURE SWITCH 7G663-1	MOS					27-FEB-1990			
32.580	560 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
324551	RH BRAKE NORMAL PRESSURE SWITCH 7G1090	MOS					18-MAR-2001			
32.580	210 REF:	HRS/MSC AFL	O/C	TSN:0			4795 2900			
324561	LH BRAKING SYSTEM FILTER ADB295-4	MOS					27-FEB-1990			
32.590	290 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
324571	RH BRAKING SYSTEM FILTER ADB295-4	MOS					27-FEB-1990			
32.590	291 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
324577	PARKING BRAKE SELECTOR VALVE UPSTREAM FILTER PN	MOS					27-FEB-1990			
32.595	SN-UNKNOWN REF:	HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0			0 0 0			
324578	PARKING BRAKE SELECTOR VALVE DOWNSTREAM FILTER PN	DAYS								
32.595	SN-UNKNOWN REF:	HRS/MSC AFL	O/C				0 0			
324581	LH BRAKING SYSTEM SWIVEL COUPLING A100-24660	MOS					27-FEB-1990			
32.600	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
324591	RH BRAKING SYSTEM SWIVEL COUPLING A101-24660	MOS					27-FEB-1990			
32.600	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
324701	EMERGENCY BRAKE ELECTRIC DISTRIBUTOR									
32.650	65670-1 1070A REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
324711	EMERGENCY BRAKE DISTRIBUTOR RETURN CHECK VALVE									
32.650	A24515 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
324721	LH MAIN GEAR EMERGENCY SYSTEM PRESSURE SWITCH									
32.660	7G862 245 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
324731	RH MAIN GEAR EMERGENCY SYSTEM PRESSURE SWITCH									
32.660	7G1108 457 REF:	MOS HRS/MSC AFL	O/C				26-APR-2001 4861 2945			
324741	LH EMERGENCY/PARKING BRAKE SHUTTLE VALVE									
32.670	CN100 69 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
324751	RH EMERGENCY/PARKING BRAKE SHUTTLE VALVE									
32.670	CN100 70 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
324821	PARKING BRAKE ACCUMULATOR PRESSURE GAUGE									
32.690	18040100 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
324831	PARKING BRAKE ACCUMULATOR CHECK VALVE									
32.700	L95H07-204 H83085 REF:	MOS HRS/MSC AFL	O/C	TSN:9 TSN:0 TSN:0			02-SEP-2016 10230 5939			
324841	PARKING BRAKE ACCUMULATOR OVERPRESSURE VALVE									
32.700	D25AB1310 101 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
324851	PARKING BRAKE PRESSURE SWITCH									
32.700	90G198-1 098 REF: AMM 32-42-17-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
325111	STEERING AMPLIFIER									
32.710	C24242010 H0866 REF:	MOS HRS/MSC AFL	O/C				16-FEB-2016 10171.4 5911			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
325121	NOSE LANDING GEAR STEERING ACTUATOR									
32.710	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
325171	STEERING ACCUMULATOR									
32.730	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
325191	STEERING SYSTEM FILTERING ELEMENT									
32.740	ADB295-4 0237 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
325201	LH NOSE LANDING GEAR STEERING SWIVEL COUPLING									
32.750	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
325211	RH NOSE LANDING GEAR STEERING SWIVEL COUPLING									
32.750	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
325251	STEERING SLIDING DISTRIBUTOR VALVE									
32.760	C24166-1 U346 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
325271	STEERING SUPPLY ELECTRODISTRIBUTOR									
32.760	65670-1 1165A REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
CHAPTER 33 LIGHTS										
33-10-17-900-801-01	LH CIRCUIT BREAKER PANEL SPOTLIGHT									
33.030	4X650 SN-UNKNOWN REF: AMM 33-10-17-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
33-10-17-900-801-02	RH CIRCUIT BREAKER PANEL SPOTLIGHT									
33.030	4X650 SN-UNKNOWN REF: AMM 33-10-17-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
+ 33-20-00-200-801-01	INSPECTION OF "ALC" LIGHTING TUBES									
33.085		MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
33-20-00-200-802-01 (s)	CHECK OF THE CONNECTION OF "SELA" LIGHTING TUBES									
33.290	PKG 1 REF: AMM 33-20-00-200-802	MOS HRS/MSC AFL	8 400	+1m +40			20-SEP-2017 10758.2 6172			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-40-01-900-801-01	LH WING NAVIGATION LIGHT									
33.120	30-1205-1 SN-UNKNOWN REF: AMM 33-40-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
33-40-01-900-801-02	RH WING NAVIGATION LIGHT									
33.120	30-1205-2 SN-UNKNOWN REF: AMM 33-40-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
33-40-09-900-802-01	UPPER ANTI-COLLISION LIGHT									
33.190	30-1136-9 DFJ1 REF: AMM 33-40-09-900-802	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			25-OCT-2001 5011 3041			
33-40-37-900-801-01	LH LANDING LIGHT									
33.170	4240531 49210 REF: AMM 33-40-37-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
33-40-37-900-801-02	RH LANDING LIGHT									
33.170	4240531 49213 REF: AMM 33-40-37-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
33-40-53-960-801-01	REAR WHITE ANTI-COLLISION LIGHT BOX POWER SUPPLY									
33.210	39-44-31 799 REF: AMM 33-40-53-960-801	MOS HRS/MSC AFL	O/C				06-DEC-2011 8516.3 5072			
+ 33-50-00-720-801-01	FUNCTIONAL TEST NO. 1 EMERGENCY (EPS 1) POWER SUPPLY									
33.240	D734-02-001 1402 REF: See Workcard	MOS HRS/MSC AFL	17	+3%			03-FEB-2017 10425.7 6021	03-JUL-2018	18-JUL-2018	258 d (+15)
+ 33-50-00-720-801-02	FUNCTIONAL TEST NO. 2 EMERGENCY (EPS 2) POWER SUPPLY									
33.240	D734-02-001 3076 REF: See Workcard	MOS HRS/MSC AFL	17	+3%			03-FEB-2017 10425.7 6021	03-JUL-2018	18-JUL-2018	258 d (+15)
+ 33-50-00-720-801-03	FUNCTIONAL TEST NO. 3 EMERGENCY (EPS 3) POWER SUPPLY									
33.250	D734-02-001 3325179 REF: See Workcard	MOS HRS/MSC AFL	17	+3%			03-FEB-2017 10425.7 6021	03-JUL-2018	18-JUL-2018	258 d (+15)
33-50-00-720-801-04	FUNCTIONAL TEST NO. 4 EMERGENCY (EPS 4) POWER SUPPLY									
33.130	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	N/A							
33-50-05-350-801-01	RESTORATION PILOT FLASHLIGHT (DEEP CYCLE) (DME ONLY)									
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL APH	O/C				27-FEB-1990 0 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-50-05-350-803-01	RESTORATION OF THE RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASHLIGHT (2LT) PN SN-UNKNOWN REF: AMM 33-50-05-350-803	MOS HRS/MSC AFL	N/A				27-FEB-1990 0 0			
33-50-05-350-803-02	RESTORATION OF THE RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASHLIGHT (3LT) PN SN-UNKNOWN REF: AMM 33-50-05-350-803	MOS HRS/MSC AFL	N/A				27-FEB-1990 0 0			
33-50-05-350-820-01	RESTORATION OF THE RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASHLIGHT (2LT) PN SN-UNKNOWN REF: AMM 33-50-05-350-820	MOS HRS/MSC AFL	N/A				27-FEB-1990 0 0			
33-50-05-350-820-02	RESTORATION OF THE RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASHLIGHT (3LT) PN SN-UNKNOWN REF: AMM 33-50-05-350-820	MOS HRS/MSC AFL	N/A				27-FEB-1990 0 0			
33-50-05-900-801-01	PILOT FLASHLIGHT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0 0			
33-50-05-900-801-02	COPILOT FLASHLIGHT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0 0			
33-50-05-960-801-02	RESTORATION COPILOT FLASHLIGHT (BATTERY REPLACEMENT) (DME ONLY) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				27-FEB-1990 0 0			
33-50-33-610-801-01	SERVICING NO. 1 EMERGENCY (EPS 1) POWER SUPPLY D734-02-001 1402 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-JAN-2016			
33-50-33-610-801-02	SERVICING NO. 2 EMERGENCY (EPS 2) POWER SUPPLY D734-02-001 3076 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-JAN-2016			
33-50-33-610-801-03	SERVICING NO. 3 EMERGENCY (EPS 3) POWER SUPPLY D734-02-001 3325179 REF: See Workcard	MOS HRS/MSC AFL	O/C				05-APR-2016			
33-50-33-610-801-04	SERVICING NO. 4 EMERGENCY (EPS 4) POWER SUPPLY PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	N/A							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-50-33-900-801-01	NO. 1 EMERGENCY (EPS 1) POWER SUPPLY									
33.240	D734-02-001 1402 REF: AMM 33-50-33-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			03-FEB-2017 10425.7 6021			
33-50-33-900-801-02	NO. 2 EMERGENCY (EPS 2) POWER SUPPLY									
33.240	D734-02-001 3076 REF: AMM 33-50-33-900-801	MOS HRS/MSC AFL	O/C				03-FEB-2017 10425.7 6021			
33-50-33-900-801-03	NO. 3 EMERGENCY (EPS 3) POWER SUPPLY									
33.250	D734-02-001 3325179 REF: AMM 33-50-33-900-801	MOS HRS/MSC AFL	O/C	TSN:15 TSR:0 TSN:107.3 TSR:0 TSN:48 TSR:0			03-FEB-2017 10425.7 6021			
33-50-33-900-801-04	NO. 4 EMERGENCY (EPS 4) POWER SUPPLY									
33.130	PN NOT INSTALLED REF: AMM 33-50-37-900-801	MOS HRS/MSC AFL	O/C				0 0			
33-50-37-960-802-01	DISCARD NO. 1 EMERGENCY (EPS 1) POWER SUPPLY BATTERY PACK									
33.240 LIFE LIMIT	D734-02-001 1402 REF: AMM 33-50-37-960-802	MOS HRS/MSC AFL	25				03-FEB-2017 10425.7 6021	03-MAR-2019		501 d
33-50-37-960-802-02	DISCARD NO. 2 EMERGENCY (EPS 2) POWER SUPPLY BATTERY PACK									
33.240 LIFE LIMIT	D734-02-001 3076 REF: AMM 33-50-37-960-802	MOS HRS/MSC AFL	25				03-FEB-2017 10425.7 6021	03-MAR-2019		501 d
33-50-37-960-802-03	DISCARD NO. 3 EMERGENCY (EPS 3) POWER SUPPLY BATTERY PACK									
33.250 LIFE LIMIT	D734-02-001 3325179 REF: AMM 33-50-37-960-802	MOS HRS/MSC AFL	25				03-FEB-2017 10425.7 6021	03-MAR-2019		501 d
33-50-37-960-802-04	DISCARD NO. 4 EMERGENCY (EPS 4) POWER SUPPLY BATTERY PACK									
33.130	PN NOT INSTALLED REF: AMM 33-50-37-960-802	MOS HRS/MSC AFL	N/A							
331101	PILOT LIGHTING BOX									
33.010	24-01 1480 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
331111	COPILOT LIGHTING BOX									
33.010	24-01 1485 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
331121	PILOT DOME LIGHT									
33.020	35-43-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
331131	COPILOT DOME LIGHT									
33.020	35-43-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
331161	PILOT READING LIGHT									
33.040	34150-13-305 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
331171	COPILOT READING LIGHT									
33.040	34150-13-305 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
331181	PILOT FLUORESCENT GLARESHIELD TUBE									
33.050	6845-510C44 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				09-MAR-2001 4783 2894			
331191	COPILOT FLUORESCENT GLARESHIELD TUBE									
33.050	6845-510C44 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				09-MAR-2001 4783 2894			
331201	GLARESHIELD POWER SUPPLY BOX									
33.060	55-0520-4-3 95 REF:	MOS HRS/MSC AFL	O/C	TSN:661			24-JUN-1991 486 247			
331211	PILOT LIGHTING INSTRUMENT TRANSFORMER									
33.070	24-54 919 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
331221	COPILOT LIGHTING INSTRUMENT TRANSFORMER									
33.070	24-54 910 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
331231	LIGHTING PEDESTAL TRANSFORMER									
33.080	24-54 914 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
331241	OVERHEAD PANEL LIGHTING TRANSFORMER									
33.080	24-014 231 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
331251	CENTER INSTRUMENT PANEL LIGHTING TRANSFORMER									
33.070	24-54 32 REF:	MOS HRS/MSC AFL	O/C				11-OCT-2010 8024.9 4795			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
331A01	GLARE SHIELD RHEOSTAT 424-22K-22K 213 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-JUN-1991 489 249			
333101	LH REAR COMPARTMENT DOME LIGHT 15-0254-3 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
333111	RH REAR COMPARTMENT DOME LIGHT 15-0254-3 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
333121	BAGGAGE COMPARTMENT DOME LIGHT 15-0254-3 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
333131	BAGGAGE COMPARTMENT SPOT LIGHT 32-24 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
333141	NOSE CONE INSPECTION LIGHT B8550-1-1385 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
334131	LH WING STROBE POWER SUPPLY 39-42-1 959 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-APR-2010 7706.6 4620			
334141	RH WING STROBE POWER SUPPLY 39-42-3 981 REF:	MOS HRS/MSC AFL	O/C			02/04/2001	04-FEB-2000 4333 2618			
334151	LH WING STROBE LIGHT 39-28-21 403 REF: AMM 33-40-31-960-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
334161	RH WING STROBE LIGHT 39-28-21 2604 REF: AMM 33-40-31-960-801	MOS HRS/MSC AFL	O/C				13-JUL-2015 9949.4 5827			
334171	LH ICE DETECTION SPOT LIGHT 30-1361-9 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
334181	RH ICE DETECTION SPOT LIGHT									
33.160	30-1361-10 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
334221	TAXI LIGHT									
33.180	01-0790589-00 00544 REF: AMM 33-40-41-900-801	MOS HRS/MSC AFL	O/C	TSN:23 TSN:0 TSN:0			21-JUN-2017 10663 6123			
334231	TAXI LIGHT PROXIMITY DETECTOR									
33.180	84739702 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
334251	VERTICAL STABILIZER ANTI-COLLISION POWER SUPPLY									
33.190	60-2667-3 1398 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
334271	FUSELAGE ANTI-COLLISION POWER SUPPLY									
33.200	39-44-31 248 REF:	MOS HRS/MSC AFL	O/C				24-MAR-2007 6587.2			
334281	FUSELAGE ANTI-COLLISION LIGHT									
33.200	39-59-2 171 REF: AMM 33-40-09-960-803	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
334301	REAR STROBE LIGHT									
33.210	39-54-21 1029 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-JAN-2002 5134.8 3122			
334A01	LIGHT NAV LEFT FAIRING									
	SPSF900--12-1-0 0272-04 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			18-SEP-2002 5317.6 3220			
334A02	LIGHT NAV RIGHT FAIRING									
	SPSF900-11-1-0 0272-03 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			18-SEP-2002 5317.6 3220			
334A06	PWR SPLY,PULSE LNDG-LIGHT									
	2400-25-4-4 K00118 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
335151	FORWARD PASSENGER DOOR LIGHT									
33.260	306-03 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
335161	AFT PASSENGER DOOR LIGHT									
33.260	306-03 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
335171	EMERGENCY EXIT EXTERIOR LIGHT									
33.270	32-515M8 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
335181	RH WING EVACUATION LIGHT									
33.270	30-1358-17 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
CHAPTER 34		NAVIGATION								
+ 34-01-00-720-801-01 (s)	FUNCTIONAL TEST OF THE EFIS SYSTEM						PKG			
34.032	PKG 6,18,204 REF: AMM 34-01-00-720-801	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
+ 34-01-25-710-801-01 (s)	OPERATIONAL TEST OF THE EFIS FANS						PKG			
34.020	PKG 21 REF: AMM 34-01-25-710-801	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
+ 34-10-00-720-801-01 (s)	FUNCTIONAL TEST OF THE AIR DATA SYSTEM						PKG			
34.045	PKG 16,18,203 REF: AMM 34-10-00-720-801	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
RVSM										
+ 34-10-11-720-801-01 (s)	CHECK OF THE LH ANGLE-OF-ATTACK (AOA) SENSOR ELECTRICAL ZERO SETTING						PKG			
27.480	PKG 31 REF: AMM 34-10-11-720-801	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
+ 34-10-11-720-801-02 (s)	CHECK OF THE RH ANGLE-OF-ATTACK (AOA) SENSOR ELECTRICAL ZERO SETTING						PKG			
27.480	PKG 31 REF: AMM 34-10-11-720-801	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
34-10-11-900-801-01	LH ANGLE-OF-ATTACK (AOA) SENSOR									
27.480	861CAU2 0251A REF: AMM 34-10-11-900-801	MOS HRS/MSC AFL	O/C				14-NOV-2016 10318.4 5973			
34-10-11-900-801-02	RH ANGLE-OF-ATTACK (AOA) SENSOR									
27.480	861CAU2 0473A REF: AMM 34-10-11-900-801	MOS HRS/MSC AFL	O/C	TSR:8 TSR:0 TSR:0			22-JUN-2017 10663 6123			
34-11-00-680-802-01 (s)	DRAINING OF THE STAND-BY PITOT / STATIC PRESSURE SYSTEM						PKG			
	PKG 16,18,203 REF: AMM 34-11-00-680-802	MOS HRS/MSC AFL	24				30-AUG-2016 10212.9 5929			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-11-00-790-801-01	LEAK TEST OF THE PILOT STATIC AIR PRESSURE SYSTEM	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
	REF: See Workcard									
34-11-00-790-801-02	LEAK TEST OF THE PILOT TOTAL AIR PRESSURE SYSTEM	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
	REF: AMM 34-11-00-790-801									
34-11-00-790-801-03	LEAK TEST OF THE COPILOT STATIC AIR PRESSURE SYSTEM	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
	REF: See Workcard									
34-11-00-790-801-04	LEAK TEST OF THE COPILOT TOTAL AIR PRESSURE SYSTEM	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
	REF: AMM 34-11-00-790-801									
34-11-00-790-801-05	LEAK TEST OF THE STAND-BY STATIC AIR PRESSURE SYSTEMS	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
	REF: See Workcard									
34-11-00-790-801-06	LEAK TEST OF THE STAND-BY TOTAL AIR PRESSURE SYSTEMS	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
	REF: AMM 34-11-00-790-801									
34-11-01-200-801-01 (s)	CHECK OF THE LH TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING	MOS HRS/MSC AFL	8	+1m			PKG 20-SEP-2017 10758.2 6172			
	PKG 11									
	REF: See Workcard									
34-11-01-200-801-02 (s)	CHECK OF THE RH TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING	MOS HRS/MSC AFL	8	+1m			PKG 20-SEP-2017 10758.2 6172			
	PKG 11									
	REF: See Workcard									
34-11-01-200-801-03 (s)	CHECK OF THE STAND-BY TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING	MOS HRS/MSC AFL	8	+1m			PKG 20-SEP-2017 10758.2 6172			
	PKG 11									
	REF: See Workcard									
34-11-01-900-801-01	LH TOTAL PRESSURE PROBE	MOS HRS/MSC AFL	O/C				05-JUN-2001 4881 2958			
34.080	50520 2507				TSN:0 TSN:0					
	REF: AMM 34-11-01-900-801									
34-11-01-900-801-02	RH TOTAL PRESSURE PROBE	MOS HRS/MSC AFL	O/C				20-JUL-1990 27 14			
34.080	50520 646				TSN:0 TSN:0 TSN:0					
	REF: AMM 34-11-01-900-801									



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 34-14-01-700-881-01	TEST NO. 1 AIR DATA (ADC1) COMPUTER (FAR 91.411) 7000700-647 34.050 MANDATORY 87082236 REF: FAR 91.411	MOS HRS/MSC AFL	24				05-AUG-2016	05-AUG-2018		291 d
+ 34-14-01-700-881-02	TEST NO. 2 AIR DATA (ADC 2) COMPUTER (FAR 91.411) 7000700-647 34.055 MANDATORY 89073474 REF: FAR 91.411	MOS HRS/MSC AFL	24				05-AUG-2016	05-AUG-2018		291 d
34-14-01-900-801-01	NO. 1 AIR DATA (ADC1) COMPUTER 7000700-647 34.050 87082236 REF: AMM 34-14-01-900-801	MOS HRS/MSC AFL	O/C			10/27/2001	27-OCT-2000 4653 2813			
34-14-01-900-801-02	NO. 2 AIR DATA (ADC 2) COMPUTER 7000700-647 34.055 89073474 REF: AMM 34-14-01-900-801	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
+ 34-15-01-700-881-01	TEST PILOT ALTIMETER (FAR 91.411) 4016341-904 34.100 MANDATORY 91036463 REF: FAR 91.411	MOS HRS/MSC AFL	24				05-AUG-2016	05-AUG-2018		291 d
+ 34-15-01-700-881-02	TEST COPILOT ALTIMETER (FAR 91.411) 4016341-904 34.100 MANDATORY 89055486 REF: FAR 91.411	MOS HRS/MSC AFL	24				05-AUG-2016	05-AUG-2018		291 d
+ 34-15-02-700-881-01	TEST PILOT STAND-BY ALTIMETER (FAR 91.411) 64141-530-1 34.110 MANDATORY 4254 (M) REF: FAR 91.411	MOS HRS/MSC AFL	24				05-AUG-2016	05-AUG-2018		291 d
+ 34-16-00-720-801-01	FUNCTIONAL TEST NO. 1 AIR DATA (ADC1) COMPUTER INDICATOR 7000700-647 34.050 87082236 REF: AMM 34-16-00-720-801	MOS HRS/MSC AFL	24	+3%			05-AUG-2016	05-AUG-2018	27-AUG-2018	291 d (+22)
+ 34-16-00-720-801-02	FUNCTIONAL TEST NO. 2 AIR DATA (ADC 2) COMPUTER INDICATOR 7000700-647 34.055 89073474 REF: AMM 34-16-00-720-801	MOS HRS/MSC AFL	24	+3%			05-AUG-2016	05-AUG-2018	27-AUG-2018	291 d (+22)
+ 34-16-00-720-801-03	FUNCTIONAL TEST PILOT STAND-BY ALTIMETER 64141-530-1 34.110 4254 (M) REF: AMM 34-16-00-720-801	MOS HRS/MSC AFL	24	+3%			05-AUG-2016	05-AUG-2018	27-AUG-2018	291 d (+22)
+ 34-16-00-720-801-04	FUNCTIONAL TEST STAND-BY MACH-AIRSPEED INDICATOR 64032-229-1 34.140 1378 REF: AMM 34-16-00-720-801	MOS HRS/MSC AFL	24	+3%			30-AUG-2016 10212.9 5929	30-AUG-2018	21-SEP-2018	316 d (+22)

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 34-21-00-700-801-01 (s)	CHECK OF THE ARINC 429 LINES TO THE INERTIAL REFERENCE SYSTEM (IRS)						PKG			
34.150	PKG 31 REF: AMM 34-21-00-700-801	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
+ 34-21-00-710-801-01 (s)	OPERATIONAL TEST OF THE NO. 1 INERTIAL (IRU1) REFERENCE SYSTEM						PKG			
34.310	PKG 21 REF: AMM 34-21-00-710-801	MOS HRS/MSC AFL	1600				20-SEP-2017 10758.2 6172			
+ 34-21-00-710-801-02 (s)	OPERATIONAL TEST OF THE NO. 2 INERTIAL (IRU2) REFERENCE SYSTEM						PKG			
34.310	PKG 21 REF: AMM 34-21-00-710-801	MOS HRS/MSC AFL	1600				20-SEP-2017 10758.2 6172			
+ 34-21-00-710-801-03 (s)	OPERATIONAL TEST OF THE NO. 3 INERTIAL (IRU3) REFERENCE SYSTEM						PKG			
34.312	PKG 21 REF: AMM 34-21-00-710-801	MOS HRS/MSC AFL	1600				20-SEP-2017 10758.2 6172			
34-21-01-900-801-01	NO. 1 INERTIAL (IRU1) REFERENCE UNIT									
34.310	HG1075AE03 326 REF: AMM 34-21-01-900-801	MOS HRS/MSC AFL	O/C				19-OCT-2016 10281.2 5959			
34-21-01-900-801-02	NO. 2 INERTIAL (IRU2) REFERENCE UNIT									
34.310	HG1075AE03 821 REF: AMM 34-21-01-900-801	MOS HRS/MSC AFL	O/C				19-OCT-2016 10281.2 5959			
34-21-01-900-801-03	NO. 3 INERTIAL (IRU3) REFERENCE UNIT									
34.312	HG1075AE03 688 REF: AMM 34-21-01-900-801	MOS HRS/MSC AFL	O/C				04-NOV-2016 10318.4 5973			
34-21-13-100-801-01 (s)	CLEANING/REPLACEMENT NO. 1 IRU BLOWER VENTILATION FILTERS						PKG			
34.380	011215 PKG 14 PN7283 REF: AMM 34-21-13-100-801	MOS HRS/MSC AFL	32	+1m			08-FEB-2017 10425.7 6021			
34-21-13-100-801-02 (s)	CLEANING/REPLACEMENT NO. 2 IRU BLOWER VENTILATION FILTERS						PKG			
34.380	10089782-105 PKG 14 PY4736 REF: AMM 34-21-13-100-801	MOS HRS/MSC AFL	32	+1m			08-FEB-2017 10425.7 6021			
34-21-13-100-801-03 (s)	CLEANING/REPLACEMENT NO. 3 IRU BLOWER VENTILATION FILTERS						PKG			
34.385	10089782-105 PKG 14 SN-UNKNOWN REF: AMM 34-21-13-100-801	MOS HRS/MSC AFL	32	+1m			08-FEB-2017 10425.7 6021			
34-41-01-900-801-01	WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA ASSEMBLY									
34.290	7021450-801 UFP040C3029 REF: AMM 34-41-01-900-801	MOS HRS/MSC AFL	O/C				04-APR-2003 5450.5			



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-42-01-820-801-01	CALIBRATION NO. 1 RADIO-ALTIMETER TRANSCEIVER									
34.340	7001840-922 88122867 REF: AMM 34-42-01-820-801	MOS HRS/MSC AFL	O/C							
34-42-01-820-801-02	CALIBRATION NO. 2 RADIO-ALTIMETER TRANSCEIVER									
34.340	7001840-922 86102075 REF: AMM 34-42-01-820-801	MOS HRS/MSC AFL	O/C							
34-51-00-710-801-01	OPERATIONAL TEST OF THE VOR NAVIGATION SYSTEM							27-FEB-1990		
		MOS HRS/MSC AFL	O/C					0		0
REF: AMM 34-51-00-710-801								0		
+ 34-51-01-820-801-01	CALIBRATION NO. 1 VOR/ILS/MARKER RECEIVER									
34.430	622-6137-201 20GF REF: AMM 34-51-01-820-801	MOS HRS/MSC AFL	O/C					02-FEB-2017		
+ 34-51-01-820-801-02	CALIBRATION NO. 2 VOR/ILS/MARKER RECEIVER									
34.430	622-6137-201 16780 REF: AMM 34-51-01-820-801	MOS HRS/MSC AFL	O/C							
34-51-05-900-801-01	LH VOR/LOC ANTENNA									
34.440	DMN4-45-3 12540 REF: AMM 34-51-05-900-801	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0		05-MAY-2014 9515 5634		
34-51-05-900-801-02	RH VOR/LOC ANTENNA									
34.440	DMN4-45-3 12539 REF: AMM 34-51-05-900-801	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0		05-MAY-2014 9515 5634		
34-51-20-710-801-01	OPERATIONAL TEST OF THE INSTRUMENT LANDING SYSTEM (ILS)									
		MOS HRS/MSC AFL	O/C					27-FEB-1990 0 0		
REF: AMM 34-51-20-710-801										
34-51-40-710-801-01	OPERATIONAL TEST OF THE MARKER SYSTEM - MARKER 1 SYSTEM									
		MOS HRS/MSC AFL	O/C					27-FEB-1990 0 0		
REF: AMM 34-51-40-710-801										
34-51-40-710-801-02	OPERATIONAL TEST OF THE MARKER SYSTEM - MARKER 2 SYSTEM									
		MOS HRS/MSC AFL	O/C					27-FEB-1990 0 0		
REF: AMM 34-51-40-710-801										
34-52-00-710-801-01	OPERATIONAL TEST OF THE DISTANCE MEASURING EQUIPMENT (DME) SYSTEM									
		MOS HRS/MSC AFL	O/C					27-FEB-1990 0 0		
REF: AMM 34-52-00-710-801										

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-53-00-710-801-01	OPERATIONAL TEST OF THE AUTOMATIC DIRECTION FINDER (ADF) SYSTEM - ADF 1 SYSTEM	MOS HRS/MSC O/C AFL					27-FEB-1990 0 0			
	REF: AMM 34-53-00-710-801									
34-53-00-710-801-02	OPERATIONAL TEST OF THE AUTOMATIC DIRECTION FINDER (ADF) SYSTEM - ADF 2 SYSTEM	MOS HRS/MSC O/C AFL					27-FEB-1990 0 0			
	REF: AMM 34-53-00-710-801									
+ 34-54-00-700-881-01	TEST NO. 1 ATC TRANSPONDER (FAR 91.413)	MOS HRS/MSC AFL	24				05-AUG-2016	05-AUG-2018		291 d
34.480	066-01143-2101 M151203 REF: FAR 91.413									
	MANDATORY									
+ 34-54-00-700-881-02	TEST NO. 2 ATC TRANSPONDER (FAR 91.413)	MOS HRS/MSC AFL	24				05-AUG-2016	05-AUG-2018		291 d
34.490	066-01143-2101 M184603 REF: FAR 91.413									
	MANDATORY									
34-54-00-720-802-01	FUNCTIONAL TEST NO. 1 ATC TRANSPONDER	MOS HRS/MSC AFL	24	+3%			05-AUG-2016	05-AUG-2018	27-AUG-2018	291 d (+22)
34.480	066-01143-2101 M151203 REF: See Workcard									
34-54-00-720-802-02	FUNCTIONAL TEST NO. 2 ATC TRANSPONDER	MOS HRS/MSC AFL	24	+3%			05-AUG-2016	05-AUG-2018	27-AUG-2018	291 d (+22)
34.490	066-01143-2101 M184603 REF: See Workcard									
+ 34-58-01-710-881-01 (s)	CHECK VOR EQUIPMENT FOR IFR OPERATIONS (FAR 91.171)	DAYS HRS/MSC AFL	30				01-SEP-2012 8914.1 5280			
34.445	REF: FAR 91.171									
	TRACKED IN-HOUSE									
+ 34-61-00-710-801-01 (s)	OPERATIONAL TEST OF THE PILOT FLIGHT MANAGEMENT SYSTEM	MOS HRS/MSC AFL	32	+1m			PKG 08-FEB-2017 10425.7 6021			
34.240	PKG 14 REF: AMM 34-61-00-710-801									
+ 34-61-00-710-801-02 (s)	OPERATIONAL TEST OF THE COPILOT FLIGHT MANAGEMENT SYSTEM	MOS HRS/MSC AFL	32	+1m			PKG 08-FEB-2017 10425.7 6021			
34.240	PKG 14 REF: AMM 34-61-00-710-801									
34-61-01-900-803-01	REMOVAL / INSTALLATION OF THE DATA MANAGEMENT UNIT (DMU) - DMU COMPUTER (22RJ).	PN SN-UNKNOWN AFL	O/C			TSN:0 TSN:0 TSN:0	27-FEB-1990 0 0			
34-61-07-900-801-01	NO. 1 FMS CONTROL DISPLAY UNIT (CDU)	PN SN-UNKNOWN AFL	O/C			TSN:0 TSN:0 TSN:0	27-FEB-1990 0 0			
	REF: AMM 34-61-07-900-801									

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-61-07-900-801-02	NO. 2 FMS CONTROL DISPLAY UNIT (CDU) PN SN-UNKNOWN REF: AMM 34-61-07-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0			
34-61-09-960-801-01	REPLACEMENT NO. 1 FMS CONTROL DISPLAY UNIT (CDU) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
34-61-09-960-801-02	REPLACEMENT OF THE CONTROL DISPLAY UNIT BATTERY - CDU 2 PN SN-UNKNOWN REF: AMM 34-61-09-960-801	MOS HRS/MSC AFL	N/A				27-FEB-1990 0 0			
34-90-10-900-801-01	CONTROL DISPLY UNIT (CDU) (GNS-XLS BATTERY ONLY) BATTERY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0 0			
341021	ANGLE OF ATTACK METER COMPUTER SLZ7729 FH1041C REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
341026	ANGLE OF ATTACK METER PROBE SLZ7319 AJ1048B REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
341031	ANGLE OF ATTACK METER INDICATOR SLZ7728 RG1057B REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
341036	ANGLE OF ATTACK METER CONTROL 911001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
341201	LH PRESSURE STATIC PORT 49800-01 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
341211	RH PRESSURE STATIC PORT 49800-01 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
341221	LH STANDBY PRESSURE STATIC PORT 49800-01 2314 REF:	MOS HRS/MSC AFL	O/C				26-MAY-2012 8750.4 5198			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
341231	RH STANDBY PRESSURE STATIC PORT 49800-01	MOS					26-MAY-2012			
34.070	2362 REF:	HRS/MSC AFL	O/C				8750.4 5198			
341261	STAND-BY PITOT PRESSURE PROBE 50520	MOS		TSN:0			20-JUL-1990			
34.080	648 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			27 14			
341271	TOTAL TEMPERATURE PROBE 102AU1CK	MOS					13-FEB-2011			
34.090	71092 REF:	HRS/MSC AFL	O/C				8167.8 4889			
341301	PILOT ALTIMETER 4016341-904	MOS					16-JUN-1999			
34.100	91036463 REF:	HRS/MSC AFL	O/C				4088 2448			
341321	COPILOT ALTIMETER 4016341-904	MOS					16-JUN-1999			
34.100	89055486 REF:	HRS/MSC AFL	O/C				4088 2448			
341341	PILOT STAND-BY ALTIMETER 64141-530-1	MOS		TSR:0			30-AUG-2016			
34.110	4254 (M) REF:	HRS/MSC AFL	O/C	TSR:0 TSR:0			10212.9 5929			
341401	PILOT VERTICAL SPEED INDICATOR 066-50001-1804	MOS					02-DEC-2008			
34.120	6121 REF:	HRS/MSC AFL	O/C				7241.5			
341421	COPILOT VERTICAL SPEED INDICATOR 066-50001-1804	MOS					12-OCT-2000			
34.120	6121 REF:	HRS/MSC AFL	O/C				4636			
341441	PILOT MACH-AIRSPPEED INDICATOR 4018366-902	MOS					12-OCT-2007			
34.130	98041867 REF:	HRS/MSC AFL	O/C				6810.4			
341461	COPILOT MACH-AIRSPPEED INDICATOR 4018366-902	MOS					12-OCT-2007			
34.130	91030730 REF:	HRS/MSC AFL	O/C				6810.4			
341481	STAND-BY MACH-AIRSPPEED INDICATOR 64032-229-1	MOS					29-MAY-2014			
34.140	1378 REF:	HRS/MSC AFL	O/C	TSN:9533.3 TSN:5641			9533.3 5641			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
341A15	LIGHTNING SNSR PROCESSOR 7011822-903 88010137 REF:	MOS HRS/MSC AFL	O/C				04-OCT-2004 6022.6			
341A16	LIGHTNING SNSR ANTENNA 7014062-901 89120175 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
342101 34.160	PILOT DDRMI INDICATOR 63540-250-2 111 REF:	MOS HRS/MSC AFL	O/C				12-OCT-2003 5619 3397			
342121 34.160	COPILOT DDRMI INDICATOR 63540-250-2 825 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			26-FEB-2004 5778.1 3498			
342201 34.170	PILOT UPPER SCREEN DISPLAY 7003110-901 96029682 REF:	MOS HRS/MSC AFL	O/C				19-AUG-2011 8360.3			
342221 34.170	PILOT LOWER SCREEN DISPLAY 7003110-901 87092328 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
342241 34.180	COPILOT UPPER SCREEN DISPLAY 7003110-901 95119402 REF:	MOS HRS/MSC AFL	O/C				08-JUN-2010 7799.3			
342261 34.180	COPILOT LOWER SCREEN DISPLAY 7003110-901 89023303 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
342281 34.190	MULTIFUNCTION SCREEN DISPLAY 7003110-901 98101451 REF:	MOS HRS/MSC AFL	O/C				04-NOV-2016 10318.4 5973			
342301 34.200	PILOT PROCESSOR DISPLAY UNIT 7007356-906 91060400 REF:	MOS HRS/MSC AFL	O/C				08-FEB-2017 10425.7 6021			
342321 34.200	COPILOT PROCESSOR DISPLAY UNIT 7007356-906 90110380 REF:	MOS HRS/MSC AFL	O/C				08-FEB-2017 10425.7 6021			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
342341	PILOT CONTROL DISPLAY PANEL 7007277-901	MOS		TSN:0			20-JUL-1990			
34.210	88100261 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			27 14			
342361	COPILOT CONTROL DISPLAY PANEL 7007277-901	MOS		TSR:0			20-SEP-2017			
34.210	92070409 REF:	HRS/MSC AFL	O/C	TSR:0 TSR:0			10758.2 6172			
342381	PILOT SWITCH REVERSION PANEL 7007280-901	MOS		TSN:0			27-FEB-1990			
34.220	89040281 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
342391	COPILOT SWITCH REVERSION PANEL 7007280-901	MOS		TSN:0			27-FEB-1990			
34.220	89020276 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
342451	REMOTE CONTROL DISPLAY PANEL 7008703-903	MOS					08-APR-1991			
34.245	86070112 REF:	HRS/MSC AFL	O/C				381 195			
342501	STAND-BY HORIZON H200AKM	MOS					19-OCT-2016			
34.250	5619 REF: AMM 34-23-00-900-801	HRS/MSC AFL	O/C				10281.2 5959			
342541	STAND-BY COMPASS WL1001KCA1	MOS		TSN:0			18-JUL-2006			
34.270	AP4221201 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			6403.3 3826			
342601	EFIS 1 BLOWER 030002	MOS				06/13/2001	13-JUN-2000			
34.275	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			4508 2731			
342611	EFIS 2 BLOWER 030002	MOS				06/13/2001	13-JUN-2000			
34.275	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			4508 2731			
343101	GLIDE NO. 1/ NO. 2 ANTENNA DMN25-2	MOS					27-FEB-1990			
34.280	2611 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
343151	MARKER ANTENNA S35-1000-1	MOS					29-AUG-2002			
34.280	4562 REF:	HRS/MSC AFL	O/C				5317.6 3220			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
344051	MULTIFUNCTION DISPLAY PROCESSOR UNIT 7009289-805 94010275 REF:	MOS HRS/MSC AFL	O/C				27-MAY-2011 8267			
344061	MULTIFUNCTION DISPLAY CONTROL 7007062-803 91081007 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			14-OCT-2004 6024.4 3609			
344141	PILOT RADAR CONTROL 7008471-405 88090482 REF:	MOS HRS/MSC AFL	O/C				06-JUL-2000 4535 2750			
344151	COPILOT RADAR CONTROL 7008471-405 90010858 REF:	MOS HRS/MSC AFL	O/C	TSN:3642 TSN:2120			23-JUL-1998 3669 2134			
344156	MLS ANTENNA 810001-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
344241	INERTIAL SYSTEM DISPLAY UNIT CG1230AC10 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
344261	NO. 1 MODE SELECTOR UNIT CG1042AB03 689 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
344281	NO. 2 MODE SELECTOR UNIT CG1042AB03 694 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
344301	NO. 3 MODE SELECTOR UNIT CG1042AB03 861 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
344356	NO. 1 RADIO-ALTIMETER TRANSCEIVER 7001840-922 88122867 REF: AMM 34-42-01-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-JUN-2013 9234.8 5467			
344361	NO. 2 RADIO-ALTIMETER TRANSCEIVER 7001840-922 86102075 REF: AMM 34-42-01-900-801	MOS HRS/MSC AFL	O/C				11-MAY-2017 10553.3 6091			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
344371	NO. 1 RADIO-ALTIMETER TRANSMISSION ANTENNA S67-2002-13 545-3855 REF:	MOS HRS/MSC AFL	O/C				07-JUN-2010 7798.6			
344381	NO. 1 RADIO-ALTIMETER RECEPTION ANTENNA S67-2002-13 1314 REF:	MOS HRS/MSC AFL	O/C				28-APR-1999 4029 2411			
344386	NO. 2 RADIO-ALTIMETER TRANSMISSION ANTENNA S67-2002 543-56328 REF:	MOS HRS/MSC AFL	O/C				30-APR-2011 8225 4913			
344391	NO. 2 RADIO-ALTIMETER RECEPTION ANTENNA S67-2002-13 368 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
344441	NO. 1 IRU BLOWER 011215 PN7283 REF:	MOS HRS/MSC AFL	O/C			07/10/2000	10-JUL-1999 4111 2461			
344461	NO. 2 IRU BLOWER 10089782-105 PY4736 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
344481	NO. 3 IRU BLOWER 10089782-105 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
344A01	CDI CONVERTER 702100-300 179 REF:	MOS HRS/MSC AFL	O/C				12-AUG-1991 524 272			
344A16	CHECKLIST MODULE 7008266-903 91090983 REF:	MOS HRS/MSC AFL	O/C				23-APR-2009 7355.7			
344A21	STORMSCOPE PROCESSOR 78-8060-6086-5 UXP08902193 REF:	MOS HRS/MSC AFL	O/C				04-APR-2003 5450.5 3289			
344A22	STORMSCOPE DISPLAY 78-8051-9170-3 UXD11902395 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
344A23	STORMSCOPE ANTENNA 78-8051-9200-8 UXA11902395 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
345101 34.390	NO. 1 ADF CONTROL G6862-01 87 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5996 TSR:0 TSN:3593 TSR:0			12-OCT-2004 6022.6 3607			
345111 34.390	NO. 2 ADF CONTROL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				20-JUL-1990 27 14			
345121 34.400	NO. 1 ADF RECEIVER 622-2362-001 13878 REF:	MOS HRS/MSC AFL	O/C				02-AUG-2013			
345131 34.400	NO. 2 ADF RECEIVER 622-2873-001 691 REF:	MOS HRS/MSC AFL	O/C				23-JUL-1998 3669 2134			
345141 34.410	NO. 1 ADF LOOP ANTENNA 622-2363-001 24406 REF:	MOS HRS/MSC AFL	O/C	TSN:0			04-APR-2003 5450.5 3289			
345151 34.410	NO. 2 ADF LOOP ANTENNA 622-2363-001 21835 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			04-APR-2003 5450.5 3289			
345201 34.420	NO. 1 VOR/DME CONTROL 622-6521-013 17AW REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-AUG-1999 4139.6 2477			
345211 34.420	NO. 2 VOR/DME CONTROL 622-6521-013 15971 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			09-OCT-2005 6221.6 3737			
345221 34.430	NO. 1 VOR/ILS/MARKER RECEIVER 622-6137-201 20GF REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			11-FEB-2017 10425.7 6021			
345231 34.430	NO. 2 VOR/ILS/MARKER RECEIVER 622-6137-201 16780 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			19-OCT-2016 10281.2 5959			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
345301	NO. 1 DME TRANSCEIVER									
34.450	622-6263-003 3162 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			11-MAY-2017 10553.3 6091			
345311	NO. 2 DME TRANSCEIVER									
34.450	622-6263-003 7072 REF:	MOS HRS/MSC AFL	O/C	TSR:3 TSR:0 TSR:0			05-MAY-2014 9515 5634			
345321	NO. 1 DME ANTENNA									
34.460	DMNI50-2-2 137793 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
345331	NO. 2 DME ANTENNA									
34.460	DMNI50-2-2 137796 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
345401	NO. 1 ATC CONTROL									
34.470	071-01618-0125 654 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-DEC-2004 6059.6 3629			
345411	NO. 2 ATC CONTROL									
34.470	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				20-JUL-1990 27 14			
345421	NO. 1 ATC TRANSPONDER									
34.480	066-01143-2101 M151203 REF:	MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			
345431	NO. 2 ATC TRANSPONDER									
34.490	066-01143-2101 M184603 REF:	MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			
345441	NO. 1 UPPER ATC ANTENNA									
34.500	DMNI50-2-2 134026 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-MAY-2014 9515 5634			
345451	NO. 2 UPPER ATC ANTENNA									
34.500	DMNI50-2-2 134629 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-MAY-2014 9515 5634			
345481	NO. 1 LOWER ATC ANTENNA									
	DMNI50-2-2 137218 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
345491	NO. 2 LOWER ATC ANTENNA DMNI50-2-2 137789 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
345501	VLF/OMEGA RECEIVER/ PROCESSOR UNIT 87272054V06 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
345511	VLF/OMEGA ANTENNA 87232276V00 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
345A03	GPS SENSOR HG2021GD03 286 REF:	MOS HRS/MSC AFL	O/C				17-OCT-2001 5006 3037			
345A04	GPS ANTENNA S67-1575-20 10463 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
345A05	GPS #2 SENSOR HG2021GD02 99114812 REF:	MOS HRS/MSC AFL	O/C				10-MAY-2013 9181.5 5437			
345A07	GPS #2 ANTENNA S67-1575-20 6778 REF:	MOS HRS/MSC AFL	O/C				17-OCT-2001 5006 3037			
345A30	TCAS PROCESSOR 066-01146-2121 TPU67B-C10397 REF:	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
345A31	TCAS #1 ANTENNA 071-01548-0100 6528 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-AUG-1996 2691 1526			
345A32	TCAS #2 ANTENNA 071-01548-0100 583-12946 REF:	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
345A33	TCAS CONTROL 071-01618-0125 654 REF:	MOS HRS/MSC AFL	O/C				21-DEC-2004 6059.6 3629			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
346101	PILOT FMS CONTROL DISPLAY 2888-03-1 139 REF:	MOS HRS/MSC AFL	O/C				18-JUL-2013 9287.7 5499			
346121	COPILOT FMS CONTROL DISPLAY 2888-03-1 065 REF:	MOS HRS/MSC AFL	O/C				04-DEC-2009 7587.6 4550			
346141	PILOT FMS COMPUTER 7018879-03022 96010757 REF:	MOS HRS/MSC AFL	O/C				12-OCT-2004 6022.6			
346161	COPILOT FMS COMPUTER 7018879-03022 95090432 REF:	MOS HRS/MSC AFL	O/C				12-OCT-2004 6022.6			
346181	FMS DATA LOADER G7226-01 266 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		07/29/2006	29-JUL-2005 6189.68 3713			
346211	NO. 1 FMS CONFIGURATION MODULE 7014940-903 95111079 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-AUG-1996 2691 1526			
346221	NO. 2 FMS CONFIGURATION MODULE 7014940-903 95121089 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-AUG-1996 2691 1526			
346A01	CONT FMS #3 DISPLAY UNIT 2888-03-1 578 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-OCT-2004 6022.6 3607			
346A06	FMS #3 COMPUTER 7018879-03022 04084151 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-OCT-2004 6022.6 3607			
346A11	DATA AFIS MANAGEMENT UNIT 400-045500-0003 M282 REF:	MOS HRS/MSC AFL	O/C				26-OCT-2007 6820.7			
346A15	CONFIG AFIS MODULE 31990-1 1996 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
346A29	DATA NMS TRANSFER UNIT 43000-01-01-3 474 REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1990 27 14			
346A48	NO. 3 FMS CONFIGURATION MODULE 7014940-903 02025739 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-OCT-2004 6022.6 3607			
CHAPTER 35 OXYGEN										
35-10-05-350-801-01	RESTORATION LH PILOT OXYGEN MASK (OVERHAUL) MC10-12-151 105777 REF: AMM 35-10-05-350-801	MOS HRS/MSC AFL	72	+3%			23-JUN-2016	23-JUN-2022	27-AUG-2022	1709 d (+65)
35.060 OVERHAUL										
35-10-05-350-801-02	RESTORATION RH PILOT OXYGEN MASK (OVERHAUL) MC10-12-152 SE12183 REF: AMM 35-10-05-350-801	MOS HRS/MSC AFL	72	+3%			20-JUL-2016	20-JUL-2022	24-SEP-2022	1736 d (+66)
35.060 OVERHAUL										
35-10-05-350-801-03	RESTORATION THIRD CREW MEMBER OXYGEN MASK (OVERHAUL) 289-601-228 SN-UNKNOWN REF: AMM 35-10-05-350-801	MOS HRS/MSC AFL	O/C				03-DEC-2010 8089.7			
35-10-05-710-801-01	OPERATIONAL TEST LH PILOT OXYGEN MASK PKG 15 REF: AMM 35-10-05-710-801	MOS HRS/MSC AFL	12	+3%			15-JUN-2017 10663 6123	15-JUN-2018	25-JUN-2018	240 d (+10)
35-10-05-710-801-02	OPERATIONAL TEST RH PILOT OXYGEN MASK PKG 15 REF: AMM 35-10-05-710-801	MOS HRS/MSC AFL	12	+3%			15-JUN-2017 10663 6123	15-JUN-2018	25-JUN-2018	240 d (+10)
35-10-05-710-801-03	OPERATIONAL TEST THIRD CREW MEMBER OXYGEN MASK PKG 15 REF: AMM 35-10-05-710-801	MOS HRS/MSC AFL	O/C				03-DEC-2010 8089.7 4843			
35-10-05-900-801-01	LH PILOT OXYGEN MASK MC10-12-151 105777 REF: AMM 35-10-05-900-801	MOS HRS/MSC AFL	H/T				30-AUG-2016 10212.9 5929			
35-10-05-900-801-02	RH PILOT OXYGEN MASK MC10-12-152 SE12183 REF: AMM 35-10-05-900-801	MOS HRS/MSC AFL	H/T				30-AUG-2016 10212.9 5929			
35-10-05-900-801-03	THIRD CREW MEMBER OXYGEN MASK 289-601-228 SN-UNKNOWN REF: AMM 35-10-05-900-801	MOS HRS/MSC AFL	O/C	TSN:72 TSO:0 TSN:2030.1 TSO:0 TSN:1214 TSO:0			03-DEC-2010 8089.7 4843			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
35-10-60-200-801-01S	INSPECTION LH PILOT OXYGEN MASK (BE AEROSPACE) MC10-12-151 105777 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
35-10-60-200-801-02S	INSPECTION RH PILOT OXYGEN MASK (BE AEROSPACE) MC10-12-152 SE12183 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C							
35-10-60-200-801-03S	INSPECTION THIRD CREW MEMBER OXYGEN MASK (BE AEROSPACE) 289-601-228 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
35-10-60-350-801-01S	OVERHAUL LH PILOT OXYGEN MASK (BE AEROSPACE) MC10-12-151 105777 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
35-10-60-350-801-02S	OVERHAUL RH PILOT OXYGEN MASK (BE AEROSPACE) MC10-12-152 SE12183 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C							
35-10-60-350-801-03S	OVERHAUL THIRD CREW MEMBER OXYGEN MASK (BE AEROSPACE) 289-601-228 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
35-13-60-350-801-01S	OVERHAUL LH PILOT OXYGEN MASK FULL FACE QUICK DONNING (ZODIAC AEROTECHNICS) MC10-12-151 105777 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
35-13-60-350-801-02S	OVERHAUL RH PILOT OXYGEN MASK FULL FACE QUICK DONNING (ZODIAC AEROTECHNICS) MC10-12-152 SE12183 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C							
35-13-60-350-801-03S	OVERHAUL THIRD CREW MEMBER OXYGEN MASK FULL FACE QUICK DONNING (ZODIAC AEROTECHNICS) 289-601-228 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
35-20-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE PASSENGER OXYGEN MASKS PKG 12,16 35.250 REF: AMM 35-20-00-210-801	MOS HRS/MSC AFL	16	+1m			PKG 08-FEB-2017 10425.7 6021			
+ 35-20-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM PKG 21 35.090 REF: AMM 35-20-00-720-801	MOS HRS/MSC AFL	1600	+40			PKG 20-SEP-2017 10758.2 6172			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
35-20-01-350-801-01	RESTORATION PASSENGER OXYGEN CONTROLLER (OVERHAUL)									
35.110	RCA74-03	MOS	72	+3%			29-APR-2016	29-APR-2022	03-JUL-2022	1654 d (+65)
OVERHAUL	1279 REF: AMM 35-20-01-350-801	HRS/MSC AFL								
35-20-01-900-801-01	PASSENGER OXYGEN CONTROLLER									
35.110	RCA74-03	MOS				TSO:4	30-AUG-2016			
	1279	HRS/MSC	H/T			TSO:0	10212.9			
	REF: AMM 35-20-01-900-801	AFL				TSO:0	5929			
35-21-05-210-801-01	INSPECTION OF THE RILSAN OXYGEN TUBE									
		MOS								
		HRS/MSC	N/A							
	REF: See Workcard	AFL								
35-21-20-350-801-01S	OVERHAUL FIRST AID OXYGEN CYLINDER									
	PN	MOS					27-FEB-1990			
	SN-UNKNOWN	HRS/MSC	N/A				0			
	REF: GENERIC CMM	AFL					0			
		APH					0			
35-21-20-900-801-01	FIRST AID OXYGEN CYLINDER									
	PN	MOS				TSN:0	27-FEB-1990			
	SN-UNKNOWN	HRS/MSC	O/C			TSN:0	0			
	REF: GENERIC NO REF	AFL				TSN:0	0			
		APH				TSN:0	0			
35-21-20-960-801-01S	REPLACE FIRST AID OXYGEN CYLINDER									
	PN	MOS					27-FEB-1990			
	SN-UNKNOWN	HRS/MSC	N/A				0			
	REF: GENERIC CMM	AFL					0			
		APH					0			
35-30-01-960-801-01	DISCARD PROTECTIVE BREATHING EQUIPMENT HOOD									
35.230	802300-14	MOS	120				18-NOV-2008	18-NOV-2018		396 d
LIFE LIMIT	E08110512	HRS/MSC								
	REF: AMM 35-30-01-960-801	AFL								
+ 35-30-05-210-801-01	GENERAL VISUAL INSPECTION PORTABLE OXYGEN BOTTLE (AND MASKS)									
35.240	89420330	MOS	12	+3%			20-SEP-2017	20-SEP-2018	30-SEP-2018	337 d (+10)
	125102	HRS/MSC					10758.2			
	REF: AMM 35-30-05-210-801	AFL					6172			
+ 35-30-05-350-801-01	RESTORATION PORTABLE OXYGEN BOTTLE (OVERHAUL) AND MASKS									
35.050	89420330	MOS	60	+3%			04-MAR-2014	04-MAR-2019	28-APR-2019	502 d (+55)
OVERHAUL	125102	HRS/MSC								
	REF: AMM 35-30-05-350-801	AFL								
35-30-05-960-801-01	DISCARD PORTABLE OXYGEN BOTTLE									
	89420330	MOS					05-MAY-2014			
	125102	HRS/MSC	O/C				9515			
	REF: AMM 35-30-05-960-801	AFL					5634			



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 35-30-09-100-801-01	CLEANING PORTABLE OXYGEN BOTTLE (AND MASKS)									
35.050	89420330 125102 REF: AMM 35-30-09-100-801	MOS HRS/MSC AFL	12	+3%			20-SEP-2017 10758.2 6172	30-AUG-2018	10-SEP-2018	316 d (+11)
+ 35-40-01-790-801-01	HYDROSTATIC TEST OXYGEN CYLINDER									
35.010	176219-115 1975-20983 REF: AMM 35-40-01-790-801	MOS HRS/MSC AFL	60				01-JUL-2015	01-JUL-2020		987 d
MANDATORY										
35-40-01-900-801-01	OXYGEN CYLINDER									
35.010	176219-115 1975-20983 REF: AMM 35-40-01-900-801	MOS HRS/MSC AFL	H/T			TSN:79 TSO:0 TSO:0 TSO:0	22-JUL-2015 9953.6 5829			
35-40-01-960-801-01	DISCARD OXYGEN CYLINDER									
35.010	176219-115 1975-20983 REF: AMM 35-40-01-960-801	MOS HRS/MSC AFL	180				01-DEC-2008	01-DEC-2023		2235 d
LIFE LIMIT										
+ 35-40-05-720-801-01	FUNCTIONAL TEST OXYGEN PRESSURE REDUCER VALVE									
35.010	172200-01 1975 REF: AMM 35-40-05-720-801	MOS HRS/MSC AFL	60				22-JUL-2015 9953.6 5829	22-JUL-2020		1008 d
350121	OXYGEN PRESSURE REDUCER VALVE									
35.010	172200-01 1975 REF:	MOS HRS/MSC AFL	O/C			TSO:0 TSO:0 TSO:0	22-JUL-2015 9953.6 5829			
350141	HP OXYGEN PRESSURE BOTTLE GAGE									
35.030	CMT150 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C			TSN:0	27-FEB-1990 0 0			
350161	OXYGEN FILLER VALVE									
35.040	DKR131 SO283866-01 REF:	MOS HRS/MSC AFL	O/C				24-APR-2010 7715.1 4627			
350201	PORTABLE OXYGEN BOTTLE									
35.050	89420330 125102 REF:	MOS HRS/MSC AFL	O/C			TSO:2 TSO:0 TSO:0	05-MAY-2014 9515 5634			
350A13	OXYGEN NEBULIZER KIT									
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C			TSN:0	01-OCT-2004			
351121	PILOT OXYGEN MASK HOSE									
35.070	DTF44A435 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C			TSN:11	27-FEB-1990 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
351131	PILOT OXYGEN CONNECTOR									
35.080	DPB179 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
351171	COPILOT OXYGEN MASK HOSE									
35.070	DTF55A350 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:11			27-FEB-1990 0 0			
351181	COPILOT OXYGEN CONNECTOR									
35.080	DPB179 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
352111	NO. 1 PASSENGER OXYGEN MASK									
35.120	289-601-228 N/A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
352121	NO. 2 PASSENGER OXYGEN MASK									
35.120	289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				07-SEP-2013 9353.3 5528			
352131	NO. 3 PASSENGER OXYGEN MASK									
35.120	289-601-228 N/A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
352141	NO. 4 PASSENGER OXYGEN MASK									
35.130	289-601-228 N/A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
352151	NO. 5 PASSENGER OXYGEN MASK									
35.130	289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:8 TSN:0 TSN:0			19-APR-2013 9161.3 5420			
352161	NO. 6 PASSENGER OXYGEN MASK									
35.130	289-601-228 N/A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
352171	NO. 7 PASSENGER OXYGEN MASK									
35.140	289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:72 TSN:2030.1 TSN:1214			03-DEC-2010 8089.7 4843			
352181	NO. 8 PASSENGER OXYGEN MASK									
35.140	289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:8 TSN:0 TSN:0			19-APR-2013 9161.3 5420			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
352191	NO. 9 PASSENGER OXYGEN MASK									
35.140	289-601-228 N/A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
352201	NO. 10 PASSENGER OXYGEN MASK									
35.150	289-601-228 N/A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
352211	NO. 11 PASSENGER OXYGEN MASK									
35.150	289-601-228 N/A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
352221	NO. 12 PASSENGER OXYGEN MASK									
35.150	289-601-228 N/A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
352261	NO. 1 FIRST AID MASK									
35.170	289-601-211 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:72 TSN:2030.1 TSN:1214			03-DEC-2010 8089.7 4843			
352271	NO. 2 FIRST AID MASK									
35.170	289-601-211 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				03-DEC-2010 8089.7 4843			
352281	NO. 1 LAVATORY OXYGEN MASK									
35.180	289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				03-DEC-2010 8089.7 4843			
352291	NO. 2 LAVATORY OXYGEN MASK									
35.180	289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:72 TSN:2030.1 TSN:1214			03-DEC-2010 8089.7 4843			
353101	PROTECTIVE BREATHING EQUIPMENT HOOD									
35.230	802300-14 E08110512 REF:	MOS HRS/MSC AFL	H/T				18-NOV-2008 7255.2 4345			
353A01	NO. 2 PROTECTIVE BREATHING EQUIPMENT HOOD									
LIFE LIMIT	802300-14 E14030106 REF:	MOS HRS/MSC AFL	H/T	TSN:5 TSN:0 TSN:0			14-NOV-2014 9738 5733			
353A53	NO. 3 PROTECTIVE BREATHING EQUIPMENT HOOD									
LIFE LIMIT	802300-14 E08110511 REF:	MOS HRS/MSC AFL	H/T							

CHAPTER 36 PNEUMATIC

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
36-10-10-200-801-01S	INSPECTION OF THE WAVE GUIDE PRESSURIZATION	MOS					27-FEB-1990			
	REF: GENERIC CMM	HRS/MSC	N/A				0			
		AFL					0			
		APH					0			
36-10-10-960-801-01S	REPLACEMENT OF THE WINDSHIELD WASHER SYSTEM FILTER	MOS					27-FEB-1990			
	REF: GENERIC CMM	HRS/MSC	N/A				0			
		AFL					0			
		APH					0			
36-10-10-960-802-01S	REPLACEMENT OF THE WAVE GUIDE PRESSURIZATION FILTERS	MOS					27-FEB-1990			
	REF: GENERIC CMM	HRS/MSC	N/A				0			
		AFL					0			
		APH					0			
36-10-29-280-801-01	SPECIAL DETAILED INSPECTION OF THE NO. 2 ENGINE BLEED AIR HP PIPE	MOS					13-JUL-2013			
36.010	REF: AMM 36-10-29-280-801	HRS/MSC	O/C				9281.9			
		AFL					5494			
36-10-33-350-801-01	RESTORATION NO. 1 ENGINE ARTICULATED PIPE (OVERHAUL)	MOS					30-SEP-2013			
36.040	B45CB1120	HRS/MSC	5000/E/C	+150			9385	14385	14535	3609.3 (+150)
OVERHAUL	0620131466	AFL					5543			
	REF: AMM 36-10-33-350-801									
36-10-33-350-801-02	RESTORATION NO. 3 ENGINE ARTICULATED PIPE (OVERHAUL)	MOS					05-MAY-2014			
36.040	B45CB1120	HRS/MSC	5000/E/C	+150			9515	14515	14665	3739.3 (+150)
OVERHAUL	01213	AFL					5634			
	REF: AMM 36-10-33-350-801									
361101	NO. 1 ENGINE LOW PRESSURE BLEED CHECK VALVE	MOS					27-FEB-1990			
36.020	CYLB51161-1	HRS/MSC	O/C		TSN:0		0			
	SN-UNKNOWN	AFL					0			
	REF:									
361111	NO. 2 ENGINE LOW PRESSURE BLEED CHECK VALVE	MOS					27-FEB-1990			
36.020	CYLB51161-1	HRS/MSC	O/C		TSN:0		0			
	SN-UNKNOWN	AFL					0			
	REF:									
361121	NO. 3 ENGINE LOW PRESSURE BLEED CHECK VALVE	MOS					27-FEB-1990			
36.020	CYLB51161-1	HRS/MSC	O/C		TSN:0		0			
	SN-UNKNOWN	AFL					0			
	REF:									
361171	NO. 1 ENGINE ARTICULATED PIPE	MOS					30-SEP-2013			
36.040	B45CB1120	HRS/MSC	H/T		TSO:0		9385			
	0620131466	AFL			TSO:0		5543			
	REF:				TSO:0					

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
361181	NO. 3 ENGINE ARTICULATED PIPE B45CB1120	MOS		TSO:4			05-MAY-2014			
36.040	01213 REF:	HRS/MSC AFL	H/T	TSO:0 TSO:0			9515 5634			
361191	NO. 1 ENGINE LOW PRESSURE INTERCOMMUNICATION CHECK VALVE CYLB51161-1	MOS					27-FEB-1990			
36.050	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
361201	NO. 3 ENGINE LOW PRESSURE INTERCOMMUNICATION CHECK VALVE CYLB51161-1	MOS					27-FEB-1990			
36.050	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
361211	NO. 2 ENGINE HIGH PRESSURE CHECK VALVE CYLB50713-1	MOS					27-FEB-1990			
36.060	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
361221	APU BLEED AIR CHECK VALVE CYLB50713-1	MOS					27-FEB-1990			
36.070	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
361241	NO. 2 ENGINE PRESSURE REGULATING (PRV2) VALVE 617C	MOS					05-FEB-2009			
36.080	SN-UNKNOWN REF:	HRS/MSC AFL	O/C				7282			
361251	NO. 3 ENGINE PRESSURE REGULATING (PRV3) VALVE 3215632-1	MOS					06-NOV-2004			
36.080	311C REF:	HRS/MSC AFL	O/C				6034.3 3617			
361261	NO. 2 ENGINE PRV2 3 WAYS ELECTRIC VALVE L92A07-502	MOS				04/02/2002	02-APR-2001			
36.090	20591 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			4816 2913			
361271	NO. 3 PRV2 3 WAYS ELECTRIC VALVE L92A07-501	MOS					27-FEB-1990			
36.090	20207 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
361281	NO. 1 HIGH PRESSURE AIR BLEED VALVE B48CB1042	MOS		TSO:0			27-JUN-2006			
36.100	T503 REF:	HRS/MSC AFL	O/C	TSO:0 TSO:0						
361291	BLEED AIR ISOLATION ELECTRIC VALVE BYLB51908	MOS					15-DEC-2011			
36.110	458 REF:	HRS/MSC AFL	O/C				8522.3			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
362101	AIR BLEED INDICATING CONTROL									
36.120	EL125-02 190 REF:	MOS HRS/MSC AFL	O/C				24-APR-2010 7715.1 4627			
362111	OVERHEAT DETECTION BOX									
36.120	EL137-00 263 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			21-JUL-2006 6403.3 3826			
362151	NO. 1 ENGINE THERMOCOUPLE SENSOR									
36.130	RP493-00 DAAB00810 REF:	MOS HRS/MSC AFL	O/C				15-DEC-2009 7592.9 4554			
362161	NO. 2 ENGINE THERMOCOUPLE SENSOR									
36.130	RP161-00 814 REF:	MOS HRS/MSC AFL	O/C				30-APR-2009 7362 4416			
362171	NO. 3 ENGINE THERMOCOUPLE SENSOR									
36.130	RP161-00 288 REF:	MOS HRS/MSC AFL	O/C				15-DEC-2009 7592.9 4554			
362181	NO. 1 ENGINE THERMOCOUPLE SENSOR									
36.140	RP129-02 5571 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JUN-2006 6382.5 3819			
362191	NO. 2 THERMOCOUPLE SENSOR									
36.140	RP129-02 5191 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-SEP-2005 6211.5 3731			
362201	NO. 3 ENGINE THERMOCOUPLE SENSOR									
36.140	RP129-02 5256 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-JAN-2006 6305.1 3772			
367100	NO. 1 OZONE CONVERTER									
36.030	20425-1 6128 REF: AMM 21-71-01-900-801	MOS HRS/MSC AFL	O/C	TSO:2 TSO:0 TSO:0			05-MAY-2014 9515 5634			
367120	NO. 2 OZONE CONVERTER									
36.030	20425-1 6164 REF: AMM 21-71-01-900-801	MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			
CHAPTER 38 WATER/WASTE										
38-00-00-610-801-01 (s)	SERVICING OF THE WATER SYSTEM						PKG			
38.080	PKG 12,16 REF: See Workcard	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
38-10-00-210-801-01 (s)	CHECK OF COMPONENTS AND FITTINGS OF THE WATER SYSTEM AND PRESSURIZATION SYSTEMS FOR CORROSION AND DAMAGE						PKG			
	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: See Workcard	HRS/MSC AFL	3750				9515 5634			
38-10-00-670-801-01 (s)	STERILIZATION OF POTABLE WATER SYSTEM						PKG			
38.010	PKG 11	MOS	8	+1m			20-SEP-2017			
	REF: AMM 38-10-00-670-801	HRS/MSC AFL					10758.2 6172			
38-13-01-960-801-01 (s)	REPLACEMENT OF THE MAIN FILTER CARTRIDGE						PKG			
38.020	PKG 12	MOS	16	+1m			20-SEP-2017			
	REF: AMM 38-13-01-960-801	HRS/MSC AFL					10758.2 6172			
38-13-09-710-801-01	OPERATIONAL TEST OF THE WATER HEATING MONITORING SYSTEM							27-FEB-1990		
38.070		MOS	O/C				0	0		
	REF: AMM 38-13-09-710-801	HRS/MSC AFL								
38-13-09-900-801-01	FORWARD WATER HEATER									
	8921082G6	MOS				TSN:0	30-AUG-2016			
	N1523219	HRS/MSC	O/C			TSN:0	10212.9			
	REF: AMM 38-13-09-900-802	AFL				TSN:0	5929			
38-13-09-900-801-02	AFT WATER HEATER									
	8921082G6	MOS				TSN:0	30-AUG-2016			
	N1523220	HRS/MSC	O/C			TSN:0	10212.9			
	REF:	AFL				TSN:0	5929			
38-15-01-710-801-01	OPERATIONAL TEST OF THE ULTRA-VIOLET (UV) WATER PURIFIER							27-FEB-1990		
		MOS	N/A				0	0		
	REF: AMM 38-15-01-710-801	HRS/MSC AFL APH					0 0 0			
38-15-09-960-801-01	REPLACEMENT OF THE UV LAMP							27-FEB-1990		
		MOS	N/A				0	0		
	REF: AMM 38-15-09-960-801	HRS/MSC AFL APH					0 0 0			
38-15-17-100-801-01	CLEANING OF THE ULTRA-VIOLET (UV) WATER STERILIZATION QUARTZ LENS						PKG			
	PKG 5,201	MOS	N/A				27-FEB-1990			
	REF: AMM 38-15-17-100-801	HRS/MSC AFL APH					0 0 0			
38-30-00-100-801-01	CLEANING OF THE WATER TRAP FILTER IN WASH HANDBASIN DRAINAGE SYSTEM							27-FEB-1990		
38.060		MOS	O/C				0	0		
	REF: AMM 38-30-00-100-801	HRS/MSC AFL					0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
38-31-17-200-801-01	INSPECTION OF THE DRAIN BOX									
38.090	REF: AMM 38-31-17-200-801	MOS HRS/MSC AFL APH	O/C				27-FEB-1990 0 0 0			
38-34-17-210-801-01	GENERAL VISUAL INSPECTION OF THE FORWARD TOILET DRAIN CONTROL						PKG			
	PKG 17	MOS HRS/MSC AFL	N/A				27-FEB-1990 0 0			
38-34-21-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE AFT TOILET DRAIN CONTROL						PKG			
	PKG 14,17	MOS HRS/MSC AFL	32	+1m			08-FEB-2017 10425.7 6021			
38-90-13-100-801-01S	CLEANING OF THE MINI-DEMAND DRAIN TANK									
	REF: SMM 38-90-13	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
381151	POTABLE WATER PRESSURE REGULATOR									
38.030	B07-235A1KA SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				07-SEP-2013 9353.3 5528			
381171	POTABLE WATER TWO WAYS VALVE									
38.040	879B14-13 67 REF:	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
381201	POTABLE WATER FILLING PLUG									
38.040	FGFB838001210A1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
381A02	DRAIN WATER FWD MAST									
	MAT-302706-A 1273 REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		09-FEB-2017 10425.7 6021			
CHAPTER 39	ELECTRICAL PANELS, PARTS AND INSTRUMENTS									
393A02	(29HN) PCB									
	24-241-1 12005 REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0	09/19/2001	19-SEP-2000 4819 2788			
CHAPTER 46	INFORMATION SYSTEMS									
46-20-02-720-801-01	FUNCTIONAL TEST PILOT ELECTRONIC FLIGHT BAG (EFB) UNIT BATTERY									
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
46-20-02-720-801-02	FUNCTIONAL TEST COPILOT ELECTRONIC FLIGHT BAG (EFB) UNIT BATTERY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
46-90-03-900-801-01	PILOT ELECTRONIC FLIGHT BAG (EFB) UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0 0			
46-90-03-900-801-02	COPILOT ELECTRONIC FLIGHT BAG (EFB) UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0 0			
CHAPTER 49 AIRBORNE AUXILIARY POWER										
496101	APU T5 INDICATOR 2396-507-00-10 49.155 232 REF:	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0 0			
496201	APU TACHOMETER 2396-506-00-10 49.155 228 REF:	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0 0			
49APU1	APU 3800188-2 P192 REF:	MOS HRS/MSC AFL	E/C							
APU Model : GTCP36-150(F) Serial # P192 Part # 3800188-2										
491010	APU - TURBINE ROTOR 3615880-1 5-01345-9441 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC APUS	10000	TSN:803.1			31-JUL-1996 803.1	10000		4822.4
491020	APU - COMPRESSOR ROTOR 3822101-1 0-03501-6238 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC APUS	100000	TSR:0 TSN:803.1 TSR:0			31-JUL-1996 803.1	100000		94822.4
491025	APU - VISUAL CHECK COMPRESSOR ROTOR REF: MM 49-20-00	MOS HRS/MSC APUS	4500				21-MAY-2012 4104.7	8604.7		3427.1

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 491030	APU - HOT SECTION INSPECTION	MOS					21-MAY-2012			
	REF: MM 49-20-00	HRS/MSC APUS	4500				4104.7		8604.7	3427.1
493010	APU - FUEL CONTROL	MOS								
49.030	3882730-2 A512 REF:	HRS/MSC APUS	O/C							
493030	APU - ORIFICE FITTING	MOS					13-JUN-1990			
	3606721-1 SN-UNKNOWN REF: MM 49-30-56	HRS/MSC APUS	O/C	TSN:10			10 0			
493040	APU - FUEL SHUTOFF VALVE	MOS					27-FEB-1990			
	692545-17 SN-UNKNOWN REF: MM 49-30-54	HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			0 0 0			
+ 493050	APU - CHECK FUEL NOZZLE FLOW RATE	MOS					21-MAY-2012			
	REF: MM 49-20-00	HRS/MSC APUS	4500				4104.7		8604.7	3427.1
493060	APU - CONTROLLER	MOS					29-NOV-1991			
	2118306-3 118-246 REF: MM 49-60-46	HRS/MSC APUS	O/C	TSN:0			325 0			
493070	APU - LOAD CONTROL VALVE	MOS					13-JUN-1990			
	109812-3-1 864 REF: MM 49-50-33	HRS/MSC APUS	O/C	TSN:10			10 0			
494010	APU - IGNITION UNIT	MOS					05-MAY-2006			
	3888000-2 89258482 REF: MM 49-40-32	HRS/MSC APUS	O/C							
494020	APU - IGNITOR PLUG	MOS					07-SEP-2013			
	3888-002-2 SN-UNKNOWN REF: MM 49-40-33	HRS/MSC APUS	O/C	TSN:128 TSN:2452			4437			
+ 494030	APU - INSPECT/CLEAN IGNITOR PLUG	MOS					17-JAN-2015			
	3888-002-2 SN-UNKNOWN REF: MM 49-40-33	HRS/MSC APUS	750				4673.8		5423.8	246.2
497010	APU - MOTION PICK UP TRANSDUCER	MOS					13-JUN-1990			
	3876104-1 SN-UNKNOWN REF: MM 49-60-43	HRS/MSC APUS	O/C	TSN:10			10 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING	
497020	APU - IMMERSION THERMOCOUPLE 3876003-3 5-20219-949 REF: MM 49-60-45	MOS HRS/MSC APUS	O/C	TSN:0			31-JUL-1996 803 0				
497030	APU - HOURMETER 3888126-1 SN-UNKNOWN REF: MM 49-70-41	MOS HRS/MSC APUS	O/C	TSN:10			13-JUN-1990 10 0				
499010	APU - ROTARY OIL PUMP 3880225-2 SN-UNKNOWN REF: MM 49-90-51	MOS HRS/MSC APUS	O/C	TSN:10			13-JUN-1990 10 0				
+ 499020	APU - REMOVE AND INSPECT REF: MM 49-90-46	MAGNETIC DRAIN PLUG MOS HRS/MSC APUS	17 750				30-AUG-2016 4887.8	30-JAN-2018 5637.8		104 d 460.2	
499030	APU - DRAIN AND REFILL OIL REF: MM 49-20-00	MOS HRS/MSC APUS	17 750				30-AUG-2016 4887.8	30-JAN-2018 5637.8		104 d 460.2	
499040	APU - REMOVE AND REPLACE REF: MM 49-90-47	OIL FILTER ELEMENT MOS HRS/MSC APUS	17 750				30-AUG-2016 4887.8	30-JAN-2018 5637.8		104 d 460.2	
499050	APU - PRESSURE REGULATING VALVE 3880021-17 SN-UNKNOWN REF: MM 49-90-52	MOS HRS/MSC APUS	O/C	TSN:0			31-JUL-1996 803 0				
499060	APU - HIGH OIL TEMPERATURE SWITCH 3888030-1 SN-UNKNOWN REF: MM 49-60-46	MOS HRS/MSC APUS	O/C	TSN:10			13-JUN-1990 10 0				
499070	APU - LOW OIL PRESSURE SWITCH 3876001-8 857 REF: MM 49-60-43	MOS HRS/MSC APUS	O/C	TSN:0			31-JUL-1996 803 0				
499110	APU - SOAP CHECK OIL REF: SIL SIL APU-49	MOS HRS/MSC APUS	O/C				21-MAY-2012 4104.7				
CHAPTER 51 STD PRACTICES AND STRUCT-GENRL											
+ 51-30-00-220-802-01 (s)	DETAILED INSPECTION OF THE INTERNAL COMPOSITE MATERIAL COMPONENTS						PKG				
51.040	PKG 31	MOS	72	+2m			05-MAY-2014 9515 5634				
	REF: AMM 51-30-00-220-802	AFL	3750								



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
CHAPTER 52 DOORS										
+ 52-00-00-200-802-01 (s)	INSPECTION/CHECK OF THE MAIN ENTRANCE BAGGAGE COMPARTMENT AND REAR COMPARTMENT DOOR FRAME SEALS						PKG			
53.100	PKG 31	MOS	72	+2m			05-MAY-2014	9515		
	REF: AMM 52-00-00-200-802	HRS/MSC AFL	3750				5634			
52-00-00-640-801-01 (s)	LUBRICATION OF THE VISIBLE DOOR HINGES AND LOCKS						PKG			
52.010	PKG 1,15	MOS	8	+1m			20-SEP-2017	10758.2		
	REF: AMM 52-00-00-640-801	HRS/MSC AFL	400	+40			6172			
+ 52-10-00-220-801-01 (s)	DETAILED INSPECTION						PKG			
52.040	PKG 31	MOS	72	+2m			05-MAY-2014	9515		
	REF: AMM 52-10-00-220-801	HRS/MSC AFL	3750				5634			
52-10-00-610-801-01 (s)	SERVICING OF THE PASSENGER DOOR						PKG			
52.030	PKG 14,17	MOS	32	+1m			08-FEB-2017	10425.7		
	REF: AMM 52-10-00-610-801	HRS/MSC AFL					6021			
52-10-00-610-802-01 (s)	SERVICING OF THE PASSENGER DOOR SAFETY CATCH						PKG			
	PKG 1,17	MOS	8				20-SEP-2017	10758.2		
	REF: AMM 52-10-00-610-802	HRS/MSC AFL	400				6172			
52-10-00-640-801-01 (s)	LUBRICATION OF THE ROLLERS OF THE PASSENGER DOOR LOWER MECHANISM						PKG			
52.120	PKG 32	MOS	144	+2m			05-MAY-2014	9515		
	REF: AMM 52-10-00-640-801	HRS/MSC AFL	7500				5634			
+ 52-10-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PASSENGER DOOR						PKG			
52.020	PKG 31	MOS	72	+2m			05-MAY-2014	9515		
	REF: AMM 52-10-00-720-801	HRS/MSC AFL	3750				5634			
52-10-01-900-801-01	PASSENGER DOOR									
52.030	FGFB295 84HP	MOS				TSN:0	27-FEB-1990	0		
	REF: AMM 52-10-01-900-801	HRS/MSC AFL	O/C				0			
52-10-03-900-801-01	PASSENGER DOOR PNEUMATIC ACTUATOR									
52.045	222900M02 SN-UNKNOWN	MOS					27-FEB-1990	0		
	REF: AMM 52-10-03-900-801	HRS/MSC AFL	H/T				0			
52-10-03-960-801-01	DISCARD PASSENGER DOOR PNEUMATIC ACTUATOR									
52.045	222900M02 SN-UNKNOWN	MOS					27-FEB-1990	0		
	REF: AMM 52-10-03-960-801	HRS/MSC AFL	N/A				0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-10-11-900-801-01	PASSENGER DOOR COUNTERBALANCING ACTUATOR									
52.040	AE4014Z006 2246282 REF: AMM 52-10-11-900-801	MOS HRS/MSC AFL	O/C				02-MAY-2008 6968.3 4165			
52-10-11-960-801-01	DISCARD PASSENGER DOOR COUNTERBALANCING ACTUATOR									
52.040	AE4014Z006 2246282 REF: AMM 52-10-11-960-801	MOS HRS/MSC AFL	O/C							
52-20-00-610-801-01 (s)	SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN						PKG			
52.050	PKG 12,16 REF: AMM 52-20-00-610-801	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
52-20-00-610-801-01A	SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN (MANDATORY 5-40)									
52.050 MANDATORY 5-40	REF: AMM 52-20-00-610-801	MOS HRS/MSC AFL	24				08-FEB-2017 10425.7 6021	08-FEB-2019		478 d
52-20-00-610-801-02 (s)	SERVICING OF THE EMERGENCY EXIT						PKG			
	PKG 12,16 REF: AMM 52-20-00-610-801	MOS HRS/MSC AFL	16				08-FEB-2017 10425.7 6021			
+ 52-20-00-710-801-01 (s)	OPERATIONAL TEST OF THE EMERGENCY EXIT UNLOCKING FROM OUTSIDE						PKG			
52.050	PKG 21 REF: AMM 52-20-00-710-801	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172			
52-30-00-270-801-01	ULTRASONIC TEST BAGGAGE COMPARTMENT DOOR OUTER SKIN									
52.060	FGFB299 77BZ REF: AMM 52-30-00-270-801	MOS HRS/MSC AFL	O/C				27-FEB-1990 0 0			
52-30-00-610-801-01 (s)	SERVICING OF THE BAGGAGE COMPARTMENT DOOR						PKG			
52.060	PKG 12 REF: AMM 52-30-00-610-801	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
+ 52-30-00-710-801-01 (s)	TEST BAGGAGE COMPARTMENT DOOR MECHANISM						PKG			
52.060	FGFB299 PKG 31 77BZ REF: AMM 52-30-00-710-801	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
+ 52-30-00-710-801-02 (s)	TEST BAGGAGE COMPARTMENT DOOR SLIDING BOLTS						PKG			
52.060	FGFB299 PKG 31 77BZ REF: AMM 52-30-00-710-801	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
+ 52-30-00-710-801-02A	OPERATIONAL TEST BAGGAGE COMPARTMENT DOOR SLIDING BOLTS (MANDATORY 5-40)									
52.060 MANDATORY 5-40	FGFB299 77BZ REF: AMM 52-30-00-710-801	MOS HRS/MSC AFL	8000				05-MAY-2014 9515 5634	17515		6739.3

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-30-01-900-801-01	BAGGAGE COMPARTMENT DOOR									
52.060	FGFB299 77BZ REF: AMM 52-30-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
52-30-19-900-801-01	BAGGAGE COMPARTMENT DOOR REDUCING GEAR MOTOR									
52.060	4220-5 279 REF: AMM 52-30-19-900-801	MOS HRS/MSC AFL	O/C				20-APR-2009 7350.2			
52-40-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE SERVICE DOORS						PKG			
52.090	PKG 16,18,203 REF: AMM 52-40-00-210-801	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
52-41-07-610-801-01 (s)	SERVICING OF THE NOSE LANDING GEAR (NLG) WELL CEILING DOOR						PKG			
52.110	PKG 16,18,203 REF: AMM 52-41-07-610-801	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
52-50-00-710-801-01 (s)	INSPECTION/TEST OF THE BLOWOUT DOOR/PANELS						PKG			
	PKG 31 REF: AMM 52-50-00-710-801	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
52-53-00-610-801-01 (s)	SERVICING OF THE CABIN / BAGGAGE COMPARTMENT DOOR						PKG			
52.100	PKG 12,17 REF: AMM 52-53-00-610-801	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
52-54-00-210-801-01 (s)	INSPECTION OF ALL CABIN DOORS, DIVIDERS AND BULKHEADS						PKG			
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			27-FEB-1990 0 0			
52-54-05-210-801-02 (s)	INSPECTION OF THE GALLEY POCKET DOOR MOUNTING LOCATIONS, LAMINATE AND MECHANISM FOR CORROSION, WEAR, CRACKS OR DAMAGE						PKG			
	PKG 31 REF: SMM 52-90-07	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
52-54-05-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE GALLEY POCKET SLIDING DOOR CABLES AND CABLE SILENCER						PKG			
	PKG 2,6 REF: AMM 52-54-05-210-802	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
52-55-00-610-801-01 (s)	SERVICING S-DUCT DOOR						PKG			
52.080	FGFB241025500 PKG 16,18,203 85BZ REF: AMM 52-55-00-610-801	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
52-60-09-610-801-01 (s)	SERVICING OF THE REAR COMPARTMENT DOOR						PKG			
52.070	PKG 14,17 REF: AMM 52-60-09-610-801	MOS HRS/MSC AFL	32	+1m			08-FEB-2017 10425.7 6021			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-90-01-200-801-01S (s)	INSPECTION OF THE MID CABIN DIVIDER/DOOR/BULKHEAD, ALL MOUNTING LOCATIONS FOR CORROSION, CRACKS, OR DAMAGE PKG 31 REF: SMM 52-90-01	MOS HRS/MSC AFL	72 3750	+2m			PKG 05-MAY-2014 9515 5634			
52-90-03-210-801-01S (s)	GENERAL VISUAL INSPECTION OF MID-CABIN POP UP DIVIDER AND CURTAIN PKG 31 REF: SMM 52-90-03	MOS HRS/MSC AFL	72 3750	+2m			PKG 27-FEB-1990 0 0			
522101 52.050	EMERGENCY EXIT FGFB296001 87HP REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
523A01	PRX BAG DR(12MW) DETECTOR 84738702 7350 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-JUN-1991 489 249			
523A02	PRX BAG DR(9MW) DETECTOR 84738702 7303 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-JUN-1991 486 247			
523A14	BAGGAGE DOOR CONTROL FGFB641840A2 145 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			21-JUN-2000 4517 2740			
524101 52.070	REAR COMPARTMENT DOOR FGFB297 81HP REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
525301 52.080	S-DUCT DOOR FGFB241025500 85BZ REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
CHAPTER 53 FUSELAGE										
+ 53-00-00-200-803-01 53.140	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 30 REF: AMM 53-00-00-200-803	MOS HRS/MSC AFL	11250				18-SEP-2002 5317.6 3220	11250		5068
+ 53-00-00-200-803-01A 53.140 MANDATORY 5-40	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 30 (MANDATORY 5-40) REF: AMM 53-00-00-200-803	MOS HRS/MSC AFL	11250				18-SEP-2002 5317.6 3220	11250		5068

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-00-00-200-803-02	DETAILED INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 30	MOS HRS/MSC AFL APH	11250				27-FEB-1990 0 0 0	11250	5068	
53-00-00-200-803-02A	DETAILED INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 30 (MANDATORY 5-40)	MOS HRS/MSC AFL APH	11250				27-FEB-1990 0 0 0	11250	5068	
53-00-00-200-810-01	INSPECTION SPECIFIC TO A/C 1	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
53.305	REF: AMM 53-00-00-200-810									
53-00-00-200-811-01	SPECIFIC INSPECTION OF THE REPAIRED AREAS (S/N 155)	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
53.300	REF: AMM 53-00-00-200-811									
53-00-00-200-812-01	SPECIFIC INSPECTION OF THE REPAIRED AREAS (S/N 67)	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
53.0502	REF: AMM 53-00-00-200-812									
+ 53-00-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR	MOS HRS/MSC AFL	24	+1m			PKG 30-AUG-2016 10212.9 5929			
53.010	PKG 16,18,203 REF: AMM 53-00-00-210-801									
53-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR (CPCP)	MOS HRS/MSC AFL	25				30-AUG-2016 10212.9 5929	30-SEP-2018	347 d	
CPCP	REF: AMM 53-00-00-210-801									
53-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE FUSELAGE EXTERIOR	MOS HRS/MSC AFL	72	+2m			PKG 05-MAY-2014 9515 5634			
53.010	PKG 31 REF: AMM 53-00-00-220-801									
53-00-00-220-801-01C	DETAILED INSPECTION OF THE FUSELAGE EXTERIOR (CPCP)	MOS HRS/MSC AFL	74				05-MAY-2014 9515 5634	05-JUL-2020	991 d	
CPCP	REF: AMM 53-00-00-220-801									
53-00-00-220-810-01	SPECIFIC DETAILED INSPECTION OF THE REPAIRED AREAS (S/N 67)	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
53.0501	REF: AMM 53-00-00-220-810									

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-00-00-220-811-01	SPECIFIC DETAILED INSPECTION OF THE REPAIRED AREAS (S/N 155)									
53.300	REF: AMM 53-00-00-220-811	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
53-00-00-220-812-01	DETAILED INSPECTION OF THE RIVETS AT FRAMES 05 AND 07 (S/N 2)						PKG			
53.315	PKG 203 REF: AMM 53-00-00-220-812	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			
+ 53-10-00-200-808-01 (s)	INSPECTION OF THE NOSE LANDING GEAR (NLG) BAY						PKG			
53.095	PKG 11,15 REF: AMM 53-10-00-200-808	MOS HRS/MSC AFL	8	+1m			20-SEP-2017 10758.2 6172			
53-10-00-200-808-01C	INSPECTION OF THE NOSE LANDING GEAR (NLG) BAY (CPCP)									
CPCP	REF: AMM 53-10-00-200-808	MOS HRS/MSC AFL	9				20-SEP-2017 10758.2 6172	20-JUN-2018		245 d
+ 53-10-00-200-810-01	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4									
53.120	REF: AMM 53-10-00-200-810	MOS HRS/MSC AFL	3750				18-SEP-2002 5317.6 3220	6970		788
+ 53-10-00-200-810-01A	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 (MANDATORY 5-40)									
53.120 MANDATORY 5-40	REF: AMM 53-10-00-200-810	MOS HRS/MSC AFL	3750				18-SEP-2002 5317.6 3220	6970		788
53-10-00-200-810-02	DETAILED INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4									
	REF: AMM 53-10-00-200-810	MOS HRS/MSC AFL APH	11250				27-FEB-1990 0 0 0	11250		5068
53-10-00-200-810-02A	DETAILED INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 (MANDATORY 5-40)									
MANDATORY 5-40	REF: AMM 53-10-00-200-810	MOS HRS/MSC AFL APH	11250				27-FEB-1990 0 0 0	11250		5068
+ 53-10-00-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT						PKG			
53.0301	PKG 16,18,203 REF: AMM 53-10-00-210-802	MOS HRS/MSC AFL	24	+3%			30-AUG-2016 10212.9 5929			
+ 53-10-00-220-801-01 (s)	DETAILED INSPECTION OF THE STATIC PRESSURE PROBES AND OF THE FUSELAGE SKIN IN PROBE AREAS						PKG			
53.260 RVSM	PKG 16,18,203 REF: AMM 53-10-00-220-801	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 53-10-00-220-802-01 (s)	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT						PKG			
53.0302	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 53-10-00-220-802	HRS/MSC					9515			
		AFL	3750				5634			
53-10-00-220-802-01C	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT (CPCP)									
		MOS	74				05-MAY-2014		05-JUL-2020	991 d
		HRS/MSC					9515			
CPCP	REF: AMM 53-10-00-220-802	AFL					5634			
+ 53-10-01-250-801-01 (s)	EDDY CURRENT INSPECTION OF THE FRAME 0 STIFFENER TIP						PKG			
53.170	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 53-10-01-250-801	HRS/MSC					9515			
		AFL	3750				5634			
53-10-03-220-801-03 (s)	DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS						PKG			
	PKG 32	MOS	144				05-MAY-2014			
	REF: AMM 53-10-03-220-801	HRS/MSC					9515			
		AFL	7500				5634			
53-10-03-220-801-03C	DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS (CPCP)									
		MOS	148				05-MAY-2014		05-SEP-2026	3244 d
		HRS/MSC					9515			
CPCP	REF: AMM 53-10-03-220-801	AFL					5634			
+ 53-10-03-250-801-01 (s)	SPECIAL DETAILED INSPECTION OF THE UPPER PASSENGER DOOR FRAME EDGING						PKG			
53.130	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 53-10-03-250-801	HRS/MSC					9515			
		AFL	3750				5634			
+ 53-10-03-250-801-01A	SPECIAL DETAILED INSPECTION OF THE UPPER PASSENGER DOOR FRAME EDGING (MANDATORY 5-40)									
53.130		MOS					05-MAY-2014			
MANDATORY 5-40	REF: AMM 53-10-03-250-801	HRS/MSC					9515		9384	3202
		AFL	3750				5634			
53-10-33-220-802-01	INSPECTION OF THE THE COCKPIT WINDSHIELD / WINDOW FRAMES / RETAINERS AND ATTACHMENTS									
53.230		MOS					27-FEB-1990			
	REF: AMM 53-10-33-220-802	HRS/MSC	O/C				0			
		AFL					0			
53-10-33-220-802-01C	INSPECTION OF THE THE COCKPIT WINDSHIELD / WINDOW FRAMES / RETAINERS AND ATTACHMENTS (CPCP)									
		MOS					27-FEB-1990			
	REF: AMM 53-10-33-220-802	HRS/MSC	O/C				0			
CPCP		AFL					0			
+ 53-10-39-220-801-01 (s)	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES						PKG			
53.220	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 53-10-39-220-801	HRS/MSC					9515			
		AFL	3750				5634			
53-10-39-220-801-01C	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)									
		MOS	74				05-MAY-2014		05-JUL-2020	991 d
		HRS/MSC					9515			
CPCP	REF: AMM 53-10-39-220-801	AFL					5634			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 53-10-39-220-802-01 (s)	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES						PKG			
53.240	PKG 32	MOS	144	+2m			05-MAY-2014			
	REF: AMM 53-10-39-220-802	HRS/MSC	7500				9515			
		AFL					5634			
53-10-39-220-802-01C	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)									
		MOS	148				05-MAY-2014		05-SEP-2026	3244 d
	REF: AMM 53-10-39-220-802	HRS/MSC					9515			
		AFL					5634			
+ 53-10-41-220-801-01	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NLG ACTUATOR									
53.200		MOS					05-MAY-2014			
	REF: AMM 53-10-41-220-801	HRS/MSC	O/C				9515			
		AFL					5634			
+ 53-10-41-220-801-01A	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NLG ACTUATOR (MANDATORY 5-40)									
53.200		MOS					05-MAY-2014			
	REF: AMM 53-10-41-220-801	HRS/MSC	O/C				9515			
		AFL					5634			
+ 53-10-43-220-801-01 (s)	DETAILED INSPECTION OF THE STIFFENERS AT THE BOTTOM OF THE NOSE LANDING GEAR (NLG) WELL LH WALL						PKG			
53.097	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 53-10-43-220-801	HRS/MSC					9515			
		AFL	3750				5634			
+ 53-10-43-220-801-01A	DETAILED INSPECTION OF THE STIFFENERS AT THE BOTTOM OF THE NOSE LANDING GEAR (NLG) WELL LH WALL (MANDATORY 5-40)									
53.097		MOS					05-MAY-2014			
	REF: AMM 53-10-43-220-801	HRS/MSC					9515		9384	3202
		AFL	3750				5634			
+ 53-11-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA						PKG			
53.0201	PKG 16,18,203	MOS	24	+1m			30-AUG-2016			
	REF: AMM 53-11-00-210-801	HRS/MSC					10212.9			
		AFL					5929			
53-11-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA (CPCP)									
		MOS	25				30-AUG-2016		30-SEP-2018	347 d
	REF: AMM 53-11-00-210-801	HRS/MSC					10212.9			
		AFL					5929			
+ 53-11-00-760-801-01 (s)	CHECK OF THE NOSE CONE ELECTRICAL BONDING						PKG			
53.250	PKG 12,16	MOS	16	+1m			08-FEB-2017			
	REF: AMM 53-11-00-760-801	HRS/MSC					10425.7			
		AFL					6021			
53-11-21-960-801-01	REPLACEMENT OF THE NOSE CONE SEAL									
53.270	PKG 31	MOS					01-MAY-2008			
	REF: AMM 53-11-21-960-801	HRS/MSC	7500				6968.3		11665	5483
		AFL					4165			
+ 53-30-00-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE PASSENGER CABIN						PKG			
53.0401	PKG 16,18,203	MOS	24	+1m			30-AUG-2016			
	REF: AMM 53-30-00-210-802	HRS/MSC					10212.9			
		AFL					5929			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 53-30-00-220-801-01 (s)	DETAILED INSPECTION OF THE PASSENGER CABIN UNDER THE FLOOR						PKG			
53.0402	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 53-30-00-220-801	HRS/MSC					9515			
		AFL	3750				5634			
53-30-00-220-801-01C	DETAILED INSPECTION OF THE PASSENGER CABIN - UNDER THE FLOOR (CPCP)									
		MOS	74				05-MAY-2014	05-JUL-2020		991 d
CPCP	REF: AMM 53-30-00-220-801	HRS/MSC					9515			
		AFL					5634			
53-30-00-220-807-01 (s)	DETAILED INSPECTION OF THE PASSENGER CABIN ABOVE THE FLOOR						PKG			
53.0402	PKG 32	MOS	144	+2m			05-MAY-2014			
	REF: See Workcard	HRS/MSC					9515			
		AFL	7500				5634			
+ 53-30-00-250-801-01 (s)	EDDY CURRENT INSPECTION OF THE PASSENGER CABIN SKIN PANEL AROUND EMERGENCY EXIT DOOR ROUNDED ANGLES						PKG			
53.160	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 53-30-00-250-801	HRS/MSC					9515			
		AFL	3750				5634			
+ 53-30-00-250-801-01A	EDDY CURRENT INSPECTION OF THE PASSENGER CABIN SKIN PANEL AROUND EMERGENCY EXIT DOOR ROUNDED ANGLES (MANDATORY 5-40)									
53.160		MOS					05-MAY-2014			
MANDATORY 5-40	REF: AMM 53-30-00-250-801	HRS/MSC					9515	9384		3202
		AFL	3750				5634			
+ 53-30-00-250-802-01 (s)	EDDY CURRENT INSPECTION OF THE SKIN PANELS AROUND CABIN WINDOW CUT-OUTS						PKG			
53.150	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 53-30-00-250-802	HRS/MSC					9515			
		AFL	3750				5634			
+ 53-30-00-250-802-01A	EDDY CURRENT INSPECTION OF THE SKIN PANELS AROUND CABIN WINDOW CUT-OUTS (MANDATORY 5-40)									
53.150		MOS					05-MAY-2014			
MANDATORY 5-40	REF: AMM 53-30-00-250-802	HRS/MSC					9515	9384		3202
		AFL	3750				5634			
53-30-03-960-801-01	REPLACEMENT OF THE ALUMINUM LIGHTNING DIVERTER STRIPS ON REAR TANK									
53.290		MOS					27-FEB-1990			
	REF: AMM 53-30-03-960-801	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
+ 53-40-00-200-804-01 (s)	INSPECTION OF THE LH MLG BAY						PKG			
53.090	PKG 11,15	MOS	8	+1m			20-SEP-2017			
	REF: AMM 53-40-00-200-804	HRS/MSC					10758.2			
		AFL					6172			
53-40-00-200-804-01C	INSPECTION OF THE LH MLG BAY (CPCP)									
		MOS	9				20-SEP-2017	20-JUN-2018		245 d
CPCP	REF: AMM 53-40-00-200-804	HRS/MSC					10758.2			
		AFL					6172			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 53-40-00-200-804-02 (s)	INSPECTION OF THE RH MLG BAY						PKG			
53.090	PKG 11,15 REF: AMM 53-40-00-200-804	MOS HRS/MSC AFL	8	+1m			20-SEP-2017 10758.2 6172			
53-40-00-200-804-02C	INSPECTION OF THE RH MLG BAY (CPCP)									
CPCP	REF: AMM 53-40-00-200-804	MOS HRS/MSC AFL	9				20-SEP-2017 10758.2 6172	20-JUN-2018		245 d
+ 53-40-00-210-802-01	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS						PKG			
53.0601	PKG 16,203 REF: AMM 53-40-00-210-802	MOS HRS/MSC AFL	O/C				30-AUG-2016 10212.9 5929			
+ 53-40-00-220-801-01	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS									
53.0602	PKG 16,203 REF: AMM 53-40-00-220-801	MOS HRS/MSC AFL	72 3750				30-AUG-2016 10212.9 5929	30-AUG-2022 9679		1777 d 3497
53-40-00-220-801-01C	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS (CPCP)									
CPCP	REF: AMM 53-40-00-220-801	MOS HRS/MSC AFL	74				30-AUG-2016 10212.9 5929	30-OCT-2022		1838 d
+ 53-40-00-220-802-01 (s)	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS						PKG			
53.050	PKG 31 REF: AMM 53-40-00-220-802	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
53-40-00-220-802-01C	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (CPCP)									
CPCP	REF: AMM 53-40-00-220-802	MOS HRS/MSC AFL	74				05-MAY-2014 9515 5634	05-JUL-2020		991 d
+ 53-40-00-270-801-01 (s)	ULTRASONIC INSPECTION FOR CORROSION AROUND THE FASTENERS OF THE FRONT CENTER PANEL AHEAD OF FRAME 10						PKG			
53.280	PKG 31 REF: AMM 53-40-00-270-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
53-40-00-270-801-01C	ULTRASONIC INSPECTION FOR CORROSION AROUND THE FASTENERS OF THE FRONT CENTER PANEL AHEAD OF FRAME 10 (CPCP)									
CPCP	REF: AMM 53-40-00-270-801	MOS HRS/MSC AFL	74				05-MAY-2014 9515 5634	05-JUL-2020		991 d
53-40-06-220-801-01	DETAILED INSPECTION OF THE CORROSION ON CENTERWING REAR SPAR						PKG			
53.310	PKG 203 REF: AMM 53-40-06-220-801	MOS HRS/MSC AFL APH	N/A				27-FEB-1990 0 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-40-07-280-802-01	SPECIFIC DETAILED INSPECTION (SDI) OF THE REPAIRED AREA ON CENTER WING LOWER PANEL	MOS HRS/MSC N/A AFL					27-FEB-1990 0 0			
	REF: AMM 53-40-07-280-802									
53-40-07-280-803-01A	SPECIAL DETAILED INSPECTION OF THE REPAIRED AREAS ON CENTERWING LOWER PANEL	MOS HRS/MSC N/A AFL					27-FEB-1990 0 0			
	REF:									
53-41-00-220-801-01 (s)	DETAILED INSPECTION OF THE UPPER LH WING ROOT BOLT RECESSES	MOS HRS/MSC AFL	72	+2m			PKG 05-MAY-2014 9515 5634			
	PKG 16,31,203									
	REF: See Workcard		3750							
53-41-00-220-801-01C	DETAILED INSPECTION OF THE UPPER LH WING ROOT BOLT RECESSES (CPCP)	MOS HRS/MSC AFL	74				05-MAY-2014 9515 5634	05-JUL-2020		991 d
	CPCP									
	REF: See Workcard									
53-41-00-220-801-02 (s)	DETAILED INSPECTION OF THE UPPER RH WING ROOT BOLT RECESSES	MOS HRS/MSC AFL	24	+1m			PKG 30-AUG-2016 10212.9 5929			
	PKG 16,18,203									
	REF: See Workcard									
53-41-00-220-801-02C	DETAILED INSPECTION OF THE UPPER RH WING ROOT BOLT RECESSES (CPCP)	MOS HRS/MSC AFL	25				30-AUG-2016 10212.9 5929	30-SEP-2018		347 d
	CPCP									
	REF: See Workcard									
+ 53-41-00-220-802-01 (s)	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES -LH WING	MOS HRS/MSC AFL	72	+2m			PKG 05-MAY-2014 9515 5634			
	PKG 31									
	REF: AMM 53-41-00-220-802		3750							
	53.110									
+ 53-41-00-220-802-01A	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - LH WING (MANDATORY 5-40)	MOS HRS/MSC AFL	7500				05-MAY-2014 9515 5634	13134		6952
	MANDATORY 5-40									
	REF: AMM 53-41-00-220-802									
	53.110									
+ 53-41-00-220-802-02 (s)	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - RH WING	MOS HRS/MSC AFL	72				05-MAY-2014 9515 5634			
	PKG 31									
	REF: AMM 53-41-00-220-802		3750							
+ 53-41-00-220-802-02A	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - RH WING (MANDATORY 5-40)	MOS HRS/MSC AFL	7500				05-MAY-2014 9515 5634	13134		6952
	MANDATORY 5-40									
	REF: AMM 53-41-00-220-802									
	53.240									
53-41-00-620-802-01	RENEWAL OF THE TEMPORARY PROTECTION OF THE LH WING ROOT UPPER BOLT RECESSES	MOS HRS/MSC O/C AFL					05-MAY-2014 9515 5634			
	REF: AMM 53-41-00-620-802									
	57.240									

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-41-00-620-802-01C	RENEWAL OF THE TEMPORARY PROTECTION OF THE LH WING ROOT UPPER BOLT RECESSES (CPCP)	MOS HRS/MSC AFL	O/C				05-MAY-2014 9515 5634			
CPCP	REF: AMM 53-41-00-620-802									
53-41-00-620-802-02 (s)	RENEWAL OF THE TEMPORARY PROTECTION OF THE RH WING ROOT UPPER BOLT RECESSES	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
57.250	PKG 31									
	REF: AMM 53-41-00-620-802		3750							
53-41-00-620-802-02C	RENEWAL OF THE TEMPORARY PROTECTION OF THE RH WING ROOT UPPER BOLT RECESSES (CPCP)	MOS HRS/MSC AFL	74				05-MAY-2014 9515 5634	05-JUL-2020		991 d
CPCP	REF: AMM 53-41-00-620-802									
53-41-01-640-801-01 (s)	LUBRICATION OF THE LH WING/FUSELAGE CONNECTING ROD	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
57.030	PKG 31									
	REF: AMM 53-41-01-640-801		3750							
53-41-01-640-801-02 (s)	LUBRICATION OF THE RH WING/FUSELAGE CONNECTING ROD	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
57.030	PKG 31									
	REF: AMM 53-41-01-640-801		3750							
+ 53-50-00-210-804-01 (s)	GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT	MOS HRS/MSC AFL	8	+1m			20-SEP-2017 10758.2 6172			
53.080	PKG 11,15									
	REF: AMM 53-50-00-210-804									
53-50-00-210-804-01C	GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT (CPCP)	MOS HRS/MSC AFL	9				20-SEP-2017 10758.2 6172	20-JUN-2018		245 d
CPCP	REF: AMM 53-50-00-210-804									
+ 53-50-00-210-806-01 (s)	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
53.0701	PKG 16,18,203									
	REF: AMM 53-50-00-210-806									
53-50-00-210-806-01C	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)	MOS HRS/MSC AFL	25				30-AUG-2016 10212.9 5929	30-SEP-2018		347 d
CPCP	REF: AMM 53-50-00-210-806									
+ 53-50-00-210-807-01 (s)	GENERAL VISUAL INSPECTION APU OF THE APU AREA	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			
49.005	PKG 12,15,202									
	REF: AMM 53-50-00-210-807									
+ 53-50-00-220-803-01 (s)	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
53.0702	PKG 31									
	REF: AMM 53-50-00-220-803		3750							

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-50-00-220-803-01A	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT	MOS					05-MAY-2014			
MANDATORY 5-40	REF: AMM 53-50-00-220-803	HRS/MSC AFL	3750				9515 5634	9384		3202
53-50-00-220-803-01C	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)	MOS	74				05-MAY-2014	05-JUL-2020		991 d
CPCP	REF: AMM 53-50-00-220-803	HRS/MSC AFL					9515 5634			
+ 53-50-00-220-805-01 (s)	DETAILED INSPECTION OF THE REAR COMPARTMENT						PKG			
53.082	PKG 16,18,203	MOS	24	+1m			30-AUG-2016			
	REF: AMM 53-50-00-220-805	HRS/MSC AFL					10212.9 5929			
53-50-00-220-805-01C	DETAILED INSPECTION OF THE REAR COMPARTMENT (CPCP)	MOS	25				30-AUG-2016	30-SEP-2018		347 d
CPCP	REF: AMM 53-50-00-220-805	HRS/MSC AFL					10212.9 5929			
53-50-00-220-807-01 (s)	DETAILED INSPECTION OF THE FRAME 30 UPPER PART						PKG			
	PKG 31	MOS	72				02-FEB-2017			
	REF: AMM 53-50-00-220-807	HRS/MSC AFL	3750				10425.7 6021			
53-50-00-220-807-01A	DETAILED INSPECTION OF THE FRAME 30 UPPER PART	MOS					02-FEB-2017			
MANDATORY 5-40	REF: AMM 53-50-00-220-807	HRS/MSC AFL	3750				10425.7 6021	9771		3589
+ 53-50-30-250-802-01 (s)	EDDY-CURRENT INSPECTION OF THE REAR EDGE OF BEAMS AT FRAME 30						PKG			
53.180	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 53-50-30-250-802	HRS/MSC AFL	3750				9515 5634			
+ 53-60-00-760-801-01 (s)	CHECK OF THE FUSELAGE VENTRAL (CENER LOWER) FAIRING ELECTRICAL BONDING						PKG			
53.255	PKG 14,17	MOS	32	+1m			08-FEB-2017			
	REF: AMM 53-60-00-760-801	HRS/MSC AFL					10425.7 6021			
+ 53-80-00-200-801-01 (s)	CHECK OF THE CONDENSATION AND STREAM WATER DRAINS						PKG			
51.020	PKG 12,16	MOS	16	+1m			08-FEB-2017			
	REF: AMM 53-80-00-200-801	HRS/MSC AFL					10425.7 6021			
53-80-01-710-801-01	OPERATIONAL TEST OF THE "AFT WATER LEAK" WATER DETECTION SYSTEM PCB	MOS					27-FEB-1990			
	REF: AMM 53-80-01-710-801	HRS/MSC AFL	N/A				0 0			
53-80-01-710-801-02	OPERATIONAL TEST "AFT WATER LEAK" WATER DETECTION SYSTEM SENSOR						27-FEB-1990			
	PN	MOS					27-FEB-1990			
	SN-UNKNOWN	HRS/MSC	N/A				0			
	REF: AMM 53-80-01-710-801	AFL					0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-80-01-900-801-01	"AFT WATER LEAK" WATER DETECTION SYSTEM SENSOR PN SN-UNKNOWN REF: AMM 53-80-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1990 0 0			
+ 53-80-09-710-801-01 (s)	OPERATIONAL TEST OF THE "CIRCLE SEAL" AUTOMATIC DRAINS PKG 31 51.050 REF: AMM 53-80-09-710-801	MOS HRS/MSC AFL	72 3750	+2m			PKG 05-MAY-2014 9515 5634			
530A01	NOSE CONE 4989-901 030 REF:	MOS HRS/MSC AFL	O/C	TSR:4 TSR:0 TSR:0			05-MAY-2014 9515 5634			
530A03	NOSE CONE FAIRING 4989-901 030 REF:	MOS HRS/MSC AFL	O/C	TSR:4 TSR:0 TSR:0			05-MAY-2014 9515 5634			
534A01	LANDING LIGHT LEFT LENS SPSF900-10-4-0 0272-01 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			18-SEP-2002 5317.6 3220			
534A02	LANDING LIGHT RIGHT LENS SPSF900-9-4-0 0272-02 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			18-SEP-2002 5317.6 3220			
CHAPTER 54	NACELLES/PYLONS									
+ 54-00-00-210-810-01 (s)	GENERAL VISUAL INSPECTION NO. 1 ENGINE NACELLE AND PYLON PKG 42 54.0101 REF: AMM 54-00-00-210-810	MOS HRS/MSC AFL	300	+30			PKG 21-JUN-2017 10663 6123			
+ 54-00-00-210-810-02 (s)	GENERAL VISUAL INSPECTION NO. 3 ENGINE NACELLE AND PYLON PKG 62 54.0101 REF: AMM 54-00-00-210-810	MOS HRS/MSC AFL	300	+30			PKG 21-JUN-2017 10663 6123			
+ 54-00-00-210-811-01	GENERAL VISUAL INSPECTION OF THE NO. 2 ENGINE NACELLE PKG 52 54.0201 REF: AMM 54-00-00-210-811	MOS HRS/MSC AFL	17				16-JUN-2017 10663 6123	16-NOV-2018		394 d
54-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE NO. 1 ENGINE NACELLE AND PYLON PKG 32 54.0102 REF: AMM 54-00-00-220-801	MOS HRS/MSC AFL	144 7500	+2m			PKG 05-MAY-2014 9515 5634			
54-00-00-220-801-01C	DETAILED INSPECTION OF THE NO. 1 ENGINE NACELLE AND PYLON (CPCP) CPCP REF: AMM 54-00-00-220-801	MOS HRS/MSC AFL	148				05-MAY-2014 9515 5634	05-SEP-2026		3244 d

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
54-00-00-220-801-02 (s)	DETAILED INSPECTION OF THE NO. 3 ENGINE NACELLE AND PYLON						PKG			
54.0102	PKG 32	MOS	144	+2m			05-MAY-2014			
	REF: AMM 54-00-00-220-801	HRS/MSC					9515			
		AFL	7500				5634			
54-00-00-220-801-02C	DETAILED INSPECTION OF THE NO. 3 ENGINE NACELLE AND PYLON (CPCP)									
		MOS	148				05-MAY-2014		05-SEP-2026	3244 d
	CPCP	HRS/MSC					9515			
	REF: AMM 54-00-00-220-801	AFL					5634			
54-11-00-610-801-01 (s)	SERVICING OF THE NO. 1 ENGINE COWLINGS						PKG			
54.060	PKG 2,16	MOS	16	+1m			08-FEB-2017			
	REF: AMM 54-11-00-610-801	HRS/MSC	800	+40			10425.7			
		AFL					6021			
54-11-00-610-801-02 (s)	SERVICING OF THE NO. 2 ENGINE COWLINGS						PKG			
54.060	PKG 2,16	MOS	16	+1m			08-FEB-2017			
	REF: AMM 54-11-00-610-801	HRS/MSC	800	+40			10425.7			
		AFL					6021			
54-11-00-610-801-03 (s)	SERVICING OF THE NO. 3 ENGINE COWLINGS						PKG			
54.060	PKG 2,16	MOS	16	+1m			08-FEB-2017			
	REF: AMM 54-11-00-610-801	HRS/MSC	800	+40			10425.7			
		AFL					6021			
+ 54-11-00-760-801-01 (s)	CHECK OF THE ENGINE COWLING ELECTRICAL BONDING						PKG			
54.125	PKG 12,16	MOS	16	+1m			08-FEB-2017			
	REF: AMM 54-11-00-760-801	HRS/MSC					10425.7			
		AFL					6021			
+ 54-13-05-210-801-01 (s)	GENERAL VISUAL INSPECTION NO. 2 ENGINE OF THE NO. 2 ENGINE AFTERBODY						PKG			
78.015	PKG 1,5	MOS	8	+1m			20-SEP-2017			
	REF: AMM 54-13-05-210-801	HRS/MSC	400	+40			10758.2			
		AFL					6172			
54-13-05-220-801-01 (s)	DETAILED INSPECTION OF THE NO. 2 ENGINE AFTERBODY						PKG			
	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 54-13-05-220-801	HRS/MSC					9515			
		AFL	3750				5634			
54-14-01-280-801-01	SPECIAL DETAILED INSPECTION NO. 1 ENGINE NACELLE FAN INNER COWLINGS									
54.120		MOS					19-JUN-1990			
	REF: AMM 54-14-01-280-801	HRS/MSC	O/C				23			
		AFL					10			
54-14-01-280-801-02	SPECIAL DETAILED INSPECTION NO. 3 ENGINE NACELLE FAN INNER COWLINGS									
54.120		MOS					19-JUN-1990			
	REF: AMM 54-14-01-280-801	HRS/MSC	O/C				23			
		AFL					10			
CHAPTER 55		STABILIZERS								
+ 55-00-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF NO. 2 ENGINE AIR INTAKE AND S-DUCT						PKG			
55.0101	PKG 16,18,203	MOS	24	+3%			30-AUG-2016			
	REF: AMM 55-00-00-210-801	HRS/MSC					10212.9			
		AFL					5929			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF NO. 2 ENGINE AIR INTAKE AND S-DUCT (CPCP)	MOS HRS/MSC AFL	25				30-AUG-2016 10212.9 5929	30-SEP-2018		347 d
CPCP	REF: AMM 55-00-00-210-801									
+ 55-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF NO. 2 ENGINE AIR INTAKE AND S-DUCT						PKG			
55.0102	PKG 31	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
CPCP	REF: AMM 55-00-00-220-801									
55-00-00-220-801-01C	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF NO. 2 ENGINE AIR INTAKE AND S-DUCT (CPCP)	MOS HRS/MSC AFL	74				05-MAY-2014 9515 5634	05-JUL-2020		991 d
CPCP	REF: AMM 55-00-00-220-801									
+ 55-00-00-760-801-01 (s)	CHECK OF THE RUDDER ELECTRICAL BONDING						PKG			
55.110	PKG 16,18,203	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
CPCP	REF: AMM 55-00-00-760-801									
55-00-00-760-801-02 (s)	CHECK OF THE LH ELEVATOR ELECTRICAL BONDING						PKG			
	PKG 16,18,203	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
CPCP	REF: AMM 55-00-00-760-801									
55-00-00-760-801-03 (s)	CHECK OF THE RH ELEVATOR ELECTRICAL BONDING						PKG			
	PKG 16,18,203	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
CPCP	REF: AMM 55-00-00-760-801									
55-10-00-220-801-01 (s)	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE						PKG			
	PKG 31,32	MOS HRS/MSC AFL	144				27-FEB-1990 0 0			
CPCP	REF: AMM 55-10-00-220-801									
55-10-00-220-801-01C (s)	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE						PKG			
	PKG 31	MOS HRS/MSC AFL	148				27-FEB-1990 0 0			
CPCP	REF: AMM 55-10-00-220-801									
55-10-00-220-802-01 (s)	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS						PKG			
	PKG 31,32	MOS HRS/MSC AFL	144				27-FEB-1990 0 0			
CPCP	REF: AMM 55-10-00-220-802									
55-10-00-220-802-01C (s)	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS						PKG			
	PKG 31	MOS HRS/MSC AFL	148				27-FEB-1990 0 0			
CPCP	REF: AMM 55-10-00-220-802									

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-10-00-270-801-01	ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS									
55.030		MOS	288	+2m			05-MAY-2014	27-FEB-2038	27-APR-2038	7437 d (+59)
	REF: AMM 55-10-00-270-801	HRS/MSC					9515			
		AFL	11250				5634	16884		10702
55-10-00-270-801-01A	ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS (MANDATORY 5-40)									
55.030		MOS					05-MAY-2014			
MANDATORY 5-40	REF: AMM 55-10-00-270-801	HRS/MSC					9515			
		AFL	3750				5634	9384		3202
55-10-00-640-802-01 (s)	GREASING OF THE HORIZONTAL STABILIZER FRONT TORQUE LINK AND ACTUATOR UPPER HINGE						PKG			
27.237	PKG 18,203	MOS	24	+1m			30-AUG-2016			
	REF: AMM 55-10-00-640-802	HRS/MSC					10212.9			
		AFL					5929			
55-10-01-900-801-01	HORIZONTAL STABILIZER									
55.065	FGFB330	MOS					27-FEB-1990			
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0			
	REF: AMM 55-10-01-900-801	AFL					0			
55-10-03-640-801-01 (s)	LUBRICATION OF THE SPRING-LOADED FAIRING MECHANISM						PKG			
	PKG 16,18,203	MOS	24	+1m			30-AUG-2016			
	REF: AMM 55-10-03-640-801	HRS/MSC					10212.9			
		AFL					5929			
+ 55-10-31-220-801-01 (s)	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS						PKG			
55.090	PKG 31	MOS	72	+2m			05-MAY-2014			
	REF: AMM 55-10-31-220-801	HRS/MSC					9515			
		AFL	3750				5634			
+ 55-10-31-220-801-01A	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS (MANDATORY 5-40)									
55.090		MOS					05-MAY-2014			
MANDATORY 5-40	REF: AMM 55-10-31-220-801	HRS/MSC					9515			
		AFL	3750				5634	9384		3202
55-10-33-640-801-01 (s)	LUBRICATION OF THE HORIZONTAL STABILIZER REAR HINGE PINS						PKG			
27.235	PKG 1	MOS	8	+1m			20-SEP-2017			
	REF: AMM 55-10-33-640-801	HRS/MSC	400	+40			10758.2			
		AFL					6172			
55-10-39-220-801-01	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS									
55.040		MOS					27-FEB-1990			
	REF: AMM 55-10-39-220-801	HRS/MSC					0			
		AFL	11250				0	11250		5068
55-10-39-220-801-01A	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS (MANDATORY 5-40)									
55.040		MOS					27-FEB-1990			
MANDATORY 5-40	REF: AMM 55-10-39-220-801	HRS/MSC					0			
		AFL	11250				0	11250		5068
55-20-01-900-801-01	LH ELEVATOR									
55.070	FGFB341	MOS					27-FEB-1990			
	107-285HD	HRS/MSC	O/C		TSN:0		0			
	REF: AMM 55-20-01-900-801	AFL					0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-20-01-900-801-02	RH ELEVATOR FGFB342 108-287HD REF: AMM 55-20-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
55-20-03-640-801-01 (s)	LUBRICATION OF THE LH ELEVATOR BEARING PKG 32 REF: AMM 55-20-03-640-801	MOS HRS/MSC AFL	144 7500	+2m			PKG 05-MAY-2014 9515 5634			
55-20-03-640-801-02 (s)	LUBRICATION OF THE RH ELEVATOR BEARING PKG 32 REF: AMM 55-20-03-640-801	MOS HRS/MSC AFL	144 7500	+2m			PKG 05-MAY-2014 9515 5634			
55-20-03-640-802-01 (s)	LUBRICATION OF THE ELEVATOR CONTROL SURFACE HINGES PKG 1,15 REF: AMM 55-20-03-640-802	MOS HRS/MSC AFL	8 400	+1m +40			PKG 20-SEP-2017 10758.2 6172			
55-20-05-640-801-01 (s)	LUBRICATION OF THE ELEVATOR CONTROL BEARINGS AND U-JOINTS PKG 2,5,201 REF: AMM 55-20-05-640-801	MOS HRS/MSC AFL	16 800	+1m +40			PKG 08-FEB-2017 10425.7 6021			
55-30-00-270-801-01	ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS 55.050 REF: AMM 55-30-00-270-801	MOS HRS/MSC AFL	288 11250	+2m	-67		05-MAY-2014 9515 5634	27-FEB-2038 16884	27-APR-2038	7437 d (+59) 10702
55-30-00-270-801-01A	ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS (MANDATORY 5-40) 55.050 MANDATORY 5-40 REF: AMM 55-30-00-270-801	MOS HRS/MSC AFL	3750				05-MAY-2014 9515 5634	9384		3202
55-30-01-900-801-01	VERTICAL STABILIZER FGFB310 SN-UNKNOWN REF: AMM 55-30-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
55-40-01-900-801-01	RUDDER FGFB321 81-284 REF: AMM 55-40-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
55-40-05-640-801-01 (s)	LUBRICATION OF THE RUDDER BEARING PKG 32 REF: AMM 55-40-05-640-801	MOS HRS/MSC AFL	144 7500	+2m			PKG 05-MAY-2014 9515 5634			
55-40-05-640-802-01 (s)	LUBRICATION OF THE RUDDER CONTROL SURFACE HINGES PKG 1,15 REF: AMM 55-40-05-640-802	MOS HRS/MSC AFL	8 400	+1m +40			PKG 20-SEP-2017 10758.2 6172			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
551101	LH SPRING LOADED RIB									
55.060	PN SN-UNKNOWN REF: AMM 55-10-03-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
551121	RH SPRING LOADED RIB									
55.060	PN SN-UNKNOWN REF: AMM 55-10-03-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
CHAPTER 56 WINDOWS										
56-10-01-900-801-01	PILOT WINDSHIELD									
56.010	SPSF900-2-5-2 295 REF: AMM 56-10-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
56-10-01-900-801-02	COPILOT WINDSHIELD									
56.010	SPSF900-3-7-2 1746 REF: AMM 56-10-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-AUG-1996 2691 1526			
56-10-01-900-801-03	FRONT WINDSHIELD									
56.010	SPSF900-1-7-3 713 REF: AMM 56-10-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0		04/05/2003	05-APR-2002 5204.5 3170			
56-10-07-900-801-01	RH SIDE WINDOW									
56.035	SPSF900-5-8-2 1199 REF: AMM 56-10-07-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0		04/05/2003	05-APR-2002 5204.5 3170			
+ 56-10-09-640-801-01 (s)	LUBRICATION OF THE OPENING WINDOW MECHANISM									
56.020	PKG 12,16 REF: AMM 56-10-09-640-801	MOS HRS/MSC AFL	16	+1m			PKG 08-FEB-2017 10425.7 6021			
56-10-09-900-801-01	OPENING WINDOW									
56.020	SPSF900-4-6-1 1337 REF: AMM 56-10-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-MAR-2004 5790.8 3503			
56-10-11-900-801-01	LH REAR WINDOW									
56.030	SPSF900-6-9-3 5007 REF: AMM 56-10-11-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2016 10212.9 5929			
56-10-11-900-801-02	RH REAR WINDOW									
56.030	SPSF900-7-5-2 1726 REF: AMM 56-10-11-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-AUG-1996 2691 1526			
56-20-05-900-801-01	NO. 1 LEFT CABIN WINDOW									
56.040	SPSF900-8-6-0 3620 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
56-20-05-900-801-02	NO. 2 LEFT CABIN WINDOW SPSF900-8-6-0 3624 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-03	NO. 3 LEFT CABIN WINDOW SPSF900-8-6-0 3627 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-04	NO. 4 LEFT CABIN WINDOW SPSF900-8-6-0 3632 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-05	NO. 5 LEFT CABIN WINDOW SPSF900-8-6-0 3630 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-06	NO. 6 LEFT CABIN WINDOW SPSF900-8-6-0 3498 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-07	NO. 7 LEFT CABIN WINDOW SPSF900-8-6-0 3626 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-08	NO. 8 LEFT CABIN WINDOW SPSF900-8-6-0 3497 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-09	NO. 9 LEFT CABIN WINDOW SPSF900-8-6-0 3494 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-10	NO. 10 LEFT CABIN WINDOW SPSF900-8-6-0 3495 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-11	NO. 11 LEFT CABIN WINDOW SPSF900-8-6-0 3496 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-12	NO. 12 LEFT CABIN WINDOW SPSF900-8-6-0 3628 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
56-20-05-900-801-13	NO. 1 RIGHT CABIN WINDOW SPSF900-8-6-0 3621 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-14	NO. 2 RIGHT CABIN WINDOW SPSF900-8-6-0 3629 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-15	NO. 3 RIGHT CABIN WINDOW SPSF900-8-6-0 3631 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-16	NO. 4 RIGHT CABIN WINDOW SPSF900-8-6-0 3619 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-17	NO. 5 RIGHT CABIN WINDOW SPSF900-8-6-0 3625 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-18	NO. 6 RIGHT CABIN WINDOW SPSF900-8-6-0 3623 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-19	NO. 7 RIGHT CABIN WINDOW SPSF900-8-6-0 3622 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-20	NO. 8 RIGHT CABIN WINDOW SPSF900-8-6-0 3490 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-21	NO. 9 RIGHT CABIN WINDOW SPSF900-8-6-0 3491 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-22	NO. 10 RIGHT CABIN WINDOW SPSF900-8-6-0 3492 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			
56-20-05-900-801-23	NO. 11 RIGHT CABIN WINDOW SPSF900-8-6-0 3633 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220 TSR:0			18-SEP-2002 5317.6 3220			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
56-20-05-900-801-24	NO. 12 RIGHT CABIN WINDOW									
56.110	SPSF900-8-6-0 3493 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5317.6 TSR:0 TSN:3220			18-SEP-2002 5317.6 3220			
CHAPTER 57 WINGS										
+ 57-00-00-210-801-01 (s)	GENERAL VISUAL INSPECTION LH WING (AREA W1)						PKG			
57.0101	FGFB101 PKG 16,18,203 82-286 REF: AMM 57-00-00-210-801	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
57-00-00-210-801-01C	GENERAL VISUAL INSPECTION LH WING (AREA W1) (CPCP)						30-AUG-2016 10212.9 5929	30-SEP-2018		347 d
CPCP										
+ 57-00-00-210-801-02 (s)	GENERAL VISUAL INSPECTION RH WING (AREA W2)						PKG			
57.0101	FGFB102 PKG 16,18,203 82-286 REF: AMM 57-00-00-210-801	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
57-00-00-210-801-02C	GENERAL VISUAL INSPECTION RH WING (AREA W2) (CPCP)						30-AUG-2016 10212.9 5929	30-SEP-2018		347 d
CPCP										
+ 57-00-00-220-802-01 (s)	DETAILED INSPECTION LH WING (AREA W1)						PKG			
57.0102	FGFB101 PKG 31 82-286 REF: AMM 57-00-00-220-802	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
57-00-00-220-802-01C	DETAILED INSPECTION LH WING (AREA W1) (CPCP)						05-MAY-2014 9515 5634	05-JUL-2020		991 d
CPCP										
+ 57-00-00-220-802-02 (s)	DETAILED INSPECTION RH WING (AREA W2)						PKG			
57.0102	FGFB102 PKG 31 82-286 REF: AMM 57-00-00-220-802	MOS HRS/MSC AFL	72	+2m			05-MAY-2014 9515 5634			
57-00-00-220-802-02C	DETAILED INSPECTION RH WING (AREA W2) (CPCP)						05-MAY-2014 9515 5634	05-JUL-2020		991 d
CPCP										
+ 57-00-00-760-801-01 (s)	CHECK ELECTRICAL BONDING OF THE LH AILERON						PKG			
57.265	PKG 16,18,203 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
+ 57-00-00-760-801-02 (s)	CHECK ELECTRICAL BONDING OF THE RH AILERON						PKG			
57.265	PKG 16,18,203 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 57-00-00-760-801-03 (s)	CHECK ELECTRICAL BONDING OF THE LH FLAPS PKG 16,18,203 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			PKG 30-AUG-2016 10212.9 5929			
57.270										
+ 57-00-00-760-801-04 (s)	CHECK ELECTRICAL BONDING OF THE RH FLAPS PKG 16,18,203 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			PKG 30-AUG-2016 10212.9 5929			
57.270										
+ 57-00-00-760-801-05 (s)	CHECK ELECTRICAL BONDING OF THE LH SLATS PKG 16,18,203 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			PKG 30-AUG-2016 10212.9 5929			
57.280										
+ 57-00-00-760-801-06 (s)	CHECK ELECTRICAL BONDING OF THE RH SLATS PKG 16,18,203 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			PKG 30-AUG-2016 10212.9 5929			
57.280										
+ 57-00-00-760-801-07 (s)	CHECK ELECTRICAL BONDING OF THE LH AIRBRAKES PKG 16,18,203 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			PKG 30-AUG-2016 10212.9 5929			
57.275										
+ 57-00-00-760-801-08 (s)	CHECK ELECTRICAL BONDING OF THE RH AIRBRAKES PKG 16,18,203 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			PKG 30-AUG-2016 10212.9 5929			
57.275										
57-00-01-900-800-01	LH WING FGFB101 82-286 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSN:0	27-FEB-1990 0 0			
57.145										
57-00-01-900-800-02	RH WING FGFB102 82-286 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSN:0	27-FEB-1990 0 0			
57.145										
+ 57-10-00-290-801-01 (s)	BORESCOPE INSPECTION OF THE WING TANKS PKG 31 REF: AMM 57-10-00-290-801	MOS HRS/MSC AFL	72	+2m			PKG 05-MAY-2014 9515 5634			
57.130										
57-10-00-290-801-01C	BORESCOPE INSPECTION OF THE WING TANKS (CPCP) REF: AMM 57-10-00-290-801	MOS HRS/MSC AFL	74				05-MAY-2014 9515 5634	05-JUL-2020		991 d
CPCP										
57-10-01-210-801-01	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS REF: AMM 57-10-01-210-801	MOS HRS/MSC AFL APH	11250				27-FEB-1990 0 0 0	11250		5068

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-10-01-210-801-01A	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS (MANDATORY 5-40)	MOS					27-FEB-1990			
MANDATORY 5-40	REF: AMM 57-10-01-210-801	HRS/MSC	11250				0		11250	5068
		AFL					0			
		APH					0			
57-10-14-220-801-01	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9	MOS					27-FEB-1990			
	REF: AMM 57-10-14-220-801	HRS/MSC	11250				0		11250	5068
		AFL					0			
		APH					0			
57-10-14-220-801-01A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9 (MANDATORY 5-40)	MOS					27-FEB-1990			
MANDATORY 5-40	REF: AMM 57-10-14-220-801	HRS/MSC	11250				0		11250	5068
		AFL					0			
		APH					0			
57-10-14-220-802-01	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9	MOS					27-FEB-1990			
	REF: AMM 57-10-14-220-802	HRS/MSC	11250				0		11250	5068
		AFL					0			
		APH					0			
57-10-14-220-802-01A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 (MANDATORY 5-40)	MOS					27-FEB-1990			
MANDATORY 5-40	REF: AMM 57-10-14-220-802	HRS/MSC	11250				0		11250	5068
		AFL					0			
		APH					0			
57-10-15-220-801-01	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3	MOS					27-FEB-1990			
	REF: AMM 57-10-15-220-801	HRS/MSC	11250				0		11250	5068
		AFL					0			
		APH					0			
57-10-15-220-801-01A	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 (MANDATORY 5-40)	MOS					27-FEB-1990			
MANDATORY 5-40	REF: AMM 57-10-15-220-801	HRS/MSC	11250				0		11250	5068
		AFL					0			
		APH					0			
57-10-15-220-802-01	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17	MOS					27-FEB-1990			
	REF: AMM 57-10-15-220-802	HRS/MSC	11250				0		11250	5068
		AFL					0			
		APH					0			
57-10-15-220-802-01A	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 (MANDATORY 5-40)	MOS					27-FEB-1990			
MANDATORY 5-40	REF: AMM 57-10-15-220-802	HRS/MSC	11250				0		11250	5068
		AFL					0			
		APH					0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 57-10-15-250-801-01	EDDY-CURRENT INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE									
57.120		MOS HRS/MSC AFL					27-FEB-1990 0 0			5068
	REF: AMM 57-10-15-250-801		11250					11250		
+ 57-10-15-250-801-01A	EDDY-CURRENT INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE (MANDATORY 5-40)									
57.120		MOS HRS/MSC AFL					27-FEB-1990 0 0			5068
	MANDATORY 5-40		11250					11250		
REF: AMM 57-10-15-250-801										
57-45-01-900-801-01	LH INBOARD MOVABLE SLAT									
57.160	FGFB133 102-325RA	MOS HRS/MSC AFL	O/C		TSN:18		31-JUL-1990 37			
	REF: AMM 57-45-01-900-801									
57-45-01-900-801-02	RH INBOARD MOVABLE SLAT									
57.170	FGFB143A7 14/200RA	MOS HRS/MSC AFL	O/C				05-AUG-2008 7092.3			
	REF: AMM 57-45-01-900-801									
57-45-13-900-801-01	LH OUTBOARD MOVABLE SLAT									
57.160	FGFB134A1 97-317RA	MOS HRS/MSC AFL	O/C				05-AUG-2008 7092.3			
	REF: AMM 57-45-13-900-801									
57-45-13-900-801-02	RH OUTBOARD MOVABLE SLAT									
57.170	FGFB144A1 86-299RA	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
	REF: AMM 57-45-13-900-801									
+ 57-45-25-250-801-01 (s)	EDDY CURRENT INSPECTION OF SLAT TRACKS 5 AND 10									
57.300	PKG 32	MOS HRS/MSC AFL	144	+2m			PKG 05-MAY-2014 9515 5634			
	REF: AMM 57-45-25-250-801		7500							
+ 57-45-25-250-801-02 (s)	EDDY CURRENT INSPECTION OF SLAT TRACKS 1 AND 4									
	PKG 32	MOS HRS/MSC AFL	144				PKG 27-FEB-1990 0 0			
	REF: AMM 57-45-25-250-801		7500							
+ 57-55-00-700-801-01 (s)	CHECK OF THE LH WING FLAP LATERAL CLEARANCE									
57.285	PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 05-MAY-2014 9515 5634			
	REF: AMM 57-55-00-700-801		3750							
+ 57-55-00-700-801-02 (s)	CHECK OF THE RH WING FLAP LATERAL CLEARANCE									
57.290	PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 05-MAY-2014 9515 5634			
	REF: AMM 57-55-00-700-801		3750							
57-55-01-900-801-01	LH INBOARD FLAP									
57.180	FGFB161 82-287	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
	REF: AMM 57-55-01-900-801									

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-55-01-900-801-02	RH INBOARD FLAP									
57.180	FGFB162 82-289 REF: AMM 57-55-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
57-55-05-900-801-01	LH OUTBOARD FLAP									
57.190	FGFB163 82-288 REF: AMM 57-55-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
57-55-05-900-801-02	RH OUTBOARD FLAP									
57.190	FGFB164 82-289 REF: AMM 57-55-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
+ 57-55-07-220-801-01 (s)	DETAILED INSPECTION OF THE PROTECTION ON LH WING INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS						PKG			
57.150	PKG 31 REF: AMM 57-55-07-220-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
+ 57-55-07-220-801-02 (s)	DETAILED INSPECTION OF THE PROTECTION ON RH WING INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS						PKG			
57.150	PKG 31 REF: AMM 57-55-07-220-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
+ 57-55-11-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE FOREFLAP BRACKETS						PKG			
57.210	PKG 31 REF: AMM 57-55-11-210-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
57-55-13-640-801-01 (s)	GREASING/LUBRICATION OF LH WING FLAP ROLLERS AND TRACKS						PKG			
	PKG 2,5,201 REF: AMM 57-55-13-640-801	MOS HRS/MSC AFL	16 800	+1m +40			08-FEB-2017 10425.7 6021			
57-55-13-640-801-02 (s)	GREASING/LUBRICATION OF RH WING FLAP ROLLERS AND TRACKS						PKG			
	PKG 2,5,201 REF: AMM 57-55-13-640-801	MOS HRS/MSC AFL	16 800	+1m +40			08-FEB-2017 10425.7 6021			
+ 57-55-21-250-801-01 (s)	EDDY-CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5						PKG			
57.200	PKG 31 REF: AMM 57-55-21-250-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
57-60-01-900-801-01	LH AILERON									
57.140	F50B153 119-290 REF: AMM 57-60-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
57-60-01-900-801-02	RH AILERON									
57.140	F50B154 106-277 REF: AMM 57-60-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-60-05-640-801-01 (s)	PRESSURE LUBRICATION OF THE LH AILERON BEARINGS						PKG			
57.140	PKG 31 REF: AMM 57-60-05-640-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
57-60-05-640-801-02 (s)	PRESSURE LUBRICATION OF THE RH AILERON BEARINGS						PKG			
57.140	PKG 31 REF: AMM 57-60-05-640-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
57-60-05-640-802-01 (s)	LUBRICATION OF THE OF THE LH AILERON CONTROL SURFACE HINGES						PKG			
	PKG 1,15 REF: AMM 57-60-05-640-802	MOS HRS/MSC AFL	8 400	+1m +40			20-SEP-2017 10758.2 6172			
57-60-05-640-802-02 (s)	LUBRICATION OF THE OF THE RH AILERON CONTROL SURFACE HINGES						PKG			
	PKG 1,15 REF: AMM 57-60-05-640-802	MOS HRS/MSC AFL	8 400	+1m +40			20-SEP-2017 10758.2 6172			
57-70-01-900-801-01	LH OUTBOARD AIRBRAKE									
57.220	FGFB165 103-294 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
57-70-01-900-801-02	LH MIDDLE AIRBRAKE									
57.220	FGFB169 103-577 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
57-70-01-900-801-03	LH INBOARD AIRBRAKE									
57.220	FGFB167 103-286 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
57-70-01-900-801-04	RH INBOARD AIRBRAKE									
57.230	FGFB168 102-289 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
57-70-01-900-801-05	RH MIDDLE AIRBRAKE									
57.230	FGFB169 103-578 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
57-70-01-900-801-06	RH OUTBOARD AIRBRAKE									
57.230	FGFB166 102-286 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
57-70-03-640-801-01 (s)	LUBRICATION OF THE AIRBRAKE HINGES						PKG			
	PKG 12,15,202 REF: AMM 57-70-03-640-801	MOS HRS/MSC AFL	16	+1m			08-FEB-2017 10425.7 6021			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
570201	LH WING/FUSELAGE CONNECTING ROD									
57.030	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
570221	RH WING/FUSELAGE CONNECTING ROD									
57.030	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
CHAPTER 71 POWER PLANT										
71-00-00-910-802-01	PERFORM NO. 1 ENGINE NO. 1 ENGINE INSPECTION RUN-UP									
71.050		MOS HRS/MSC AFL	O/C				02-SEP-2014 9662.4 5699			
71-00-00-910-802-02	PERFORM NO. 2 ENGINE NO. 2 ENGINE INSPECTION RUN-UP									
71.050		MOS HRS/MSC AFL	O/C				02-SEP-2014 9662.4 5699			
71-00-00-910-802-03	PERFORM NO. 3 ENGINE NO. 3 ENGINE INSPECTION RUN-UP									
71.050		MOS HRS/MSC AFL	O/C				02-SEP-2014 9662.4 5699			
+ 71-20-02-250-801-01	SPECIAL DETAILED INSPECTION (EDDY CURENT) OF THE NO. 1 ENGINE FRONT MOUNT									
54.030		MOS HRS/MSC AFL		2500			05-NOV-2007 6820.7 4090	6590		408
71-20-02-250-801-01A	SPECIAL DETAILED INSPECTION (EDDY CURENT) OF THE NO. 1 ENGINE FRONT MOUNT (MANDATORY 5-40)									
MANDATORY 5-40		MOS HRS/MSC AFL		10000			05-NOV-2007 6820.7 4090	10000		3818
+ 71-20-02-250-801-02	SPECIAL DETAILED INSPECTION (EDDY CURENT) OF THE NO. 3 ENGINE FRONT MOUNT									
54.030		MOS HRS/MSC AFL		2500			05-NOV-2007 6820.7 4090	6590		408
71-20-02-250-801-02A	SPECIAL DETAILED INSPECTION (EDDY CURENT) OF THE NO. 3 ENGINE FRONT MOUNT (MANDATORY 5-40)									
MANDATORY 5-40		MOS HRS/MSC AFL		10000			05-NOV-2007 6820.7 4090	10000		3818
+ 71-20-02-250-802-01	SPECIAL DETAILED INSPECTION NO. 1 ENGINE FRONT MOUNT SHACKLE									
54.050		MOS HRS/MSC AFL		2500			05-NOV-2007 6820.7 4090	6590		408
+ 71-20-02-250-802-02	SPECIAL DETAILED INSPECTION NO. 3 ENGINE FRONT MOUNT SHACKLE									
54.050		MOS HRS/MSC AFL		2500			05-NOV-2007 6820.7 4090	6590		408

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 71-20-07-250-801-01	SPECIAL DETAILED INSPECTION	NO. 1 ENGINE REAR MOUNT								
54.040		MOS					05-NOV-2007			
	REF: AMM 71-20-07-250-801	HRS/MSC					6820.7			
		AFL	2500				4090	6590		408
71-20-07-250-801-01A	SPECIAL DETAILED INSPECTION	NO. 1 ENGINE REAR MOUNT (MANDATORY 5-40)								
		MOS					05-NOV-2007			
	REF: AMM 71-20-07-250-801	HRS/MSC					6820.7			
MANDATORY 5-40		AFL	10000				4090	10000		3818
+ 71-20-07-250-801-02	SPECIAL DETAILED INSPECTION	NO. 3 ENGINE REAR MOUNT								
54.040		MOS					05-NOV-2007			
	REF: AMM 71-20-07-250-801	HRS/MSC					6820.7			
		AFL	2500				4090	6590		408
71-20-07-250-801-02A	SPECIAL DETAILED INSPECTION	NO. 3 ENGINE REAR MOUNT (MANDATORY 5-40)								
		MOS					05-NOV-2007			
	REF: AMM 71-20-07-250-801	HRS/MSC					6820.7			
MANDATORY 5-40		AFL	10000				4090	10000		3818
71-20-17-230-801-01	SPECIAL DETAILED INSPECTION	NO. 2 ENGINE LH FRONT SHOCK MOUNT VIBRATION ISOLATORS / REPLACEMENT OF RUBBER CORES								
71.070	LM833SA13	MOS					13-JUL-2013			
	NSN	HRS/MSC	5000	+3%			9281.9	14281.9	14431.9	3506.2 (+150)
	REF: AMM 71-20-17-230-801	AFL					5494			
71-20-17-230-801-02	SPECIAL DETAILED INSPECTION	NO. 2 ENGINE RH FRONT SHOCK MOUNT VIBRATION ISOLATORS / REPLACEMENT OF RUBBER CORES								
71.070	LM833SA13	MOS					13-JUL-2013			
	NSN	HRS/MSC	5000	+3%			9281.9	14281.9	14431.9	3506.2 (+150)
	REF: AMM 71-20-17-230-801	AFL					5494			
712001	NO. 1 ENGINE FRONT UPPER SHOCK MOUNT									
71.075	3071071-3	MOS					05-MAY-2014			
	08361-014	HRS/MSC	O/C				9515			
	REF:	AFL					5634			
712002	NO. 1 ENGINE FRONT LOWER SHOCK MOUNT									
71.075	3071071-3	MOS					05-MAY-2014			
	08361-016	HRS/MSC	O/C				9515			
	REF:	AFL					5634			
712003	NO. 2 ENGINE LH FRONT SHOCK MOUNT									
71.070	LM833SA13	MOS					13-JUL-2013			
	NSN	HRS/MSC	O/C				9281.9			
	REF: AMM 71-20-17-230-801	AFL					5494			
712004	NO. 2 ENGINE RH FRONT SHOCK MOUNT									
71.070	LM833SA13	MOS					13-JUL-2013			
	NSN	HRS/MSC	O/C				9281.9			
	REF: AMM 71-20-17-230-801	AFL					5494			
712005	NO. 3 ENGINE FRONT UPPER SHOCK MOUNT									
71.080	3071071-3	MOS					14-JAN-2014			
	08361-014	HRS/MSC	O/C				9479.8			
	REF:	AFL					5608			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
712006	NO. 3 ENGINE FRONT LOWER SHOCK MOUNT 3071071-3 08361-016 REF:	MOS HRS/MSC AFL	O/C				14-JAN-2014 9479.8 5608			
712251	NO. 2 ENGINE HOIST 4219-1 189 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
71EN1	NO. 1 ENGINE 3075330-2 P97304C REF:	MOS HRS/MSC AFL	E/C	TSN:6206.8			17-JAN-2015 9764.1 5742			
71EN2	NO. 2 ENGINE 3075330-2 P97301C REF:	MOS HRS/MSC AFL APH	E/C	TSN:9222.2 TSN:5450			22-AUG-2013 9350.9 5527			
71EN3	NO. 3 ENGINE 3075330-2 P97305C REF:	MOS HRS/MSC AFL APH	E/C				22-AUG-2013 9350.9 5644			
ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P97304C Part # 3075330-2										
+ 710120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI)	MOS HRS/MSC ENC	2500	+100			11-NOV-2013 8983.8 5317	(11483.8) 12041.1	11583.8	1265.4 (+100)
71.010	REF: LMM 72-00-00									
+ 710130 (s)	NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES	MOS HRS/MSC ENC	800				30-AUG-2016 9655.6 5603			
71.020	PKG 4 REF: LMM 72-00-00									
+ 714010 (s)	NO. 1 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS	MOS HRS/MSC ENC	800				30-AUG-2016 9655.6 5603			
71.030	PKG 4 REF: GENERIC NO REF									
+ 715010 (s)	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS	MOS HRS/MSC ENC	800				30-AUG-2016 9655.6 5603			
71.040	PKG 4 REF: GENERIC NO REF									
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P97301C Part # 3075330-2										
+ 710120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI)	MOS HRS/MSC ENC	2500	+100			07-JUN-2013 9127.1 5393	(11627.1) 11781.9	11727.1	1006.2 (+100)
71.010	REF: LMM 72-00-00									

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 710130 (s)	NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES						PKG			
71.020	PKG 4	MOS					30-AUG-2016			
	REF: LMM 72-00-00	HRS/MSC	800				10058.1			
		ENC					5828			
+ 714010 (s)	NO. 2 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS						PKG			
71.030	PKG 4	MOS					30-AUG-2016			
	REF: GENERIC NO REF	HRS/MSC	800				10058.1			
		ENC					5828			
+ 715010 (s)	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS						PKG			
71.040	PKG 4	MOS					30-AUG-2016			
	REF: GENERIC NO REF	HRS/MSC	800				10058.1			
		ENC					5828			
ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P97305C Part # 3075330-2										
+ 710120	NO. 3 ENGINE - MAJOR PERIODIC INSPECTION (MPI)									
71.010		MOS					22-AUG-2013			
	REF: LMM 72-00-00	HRS/MSC	2500	+100	-15		9222.2	(11707.2)	11900.2	11807.2 1124.5 (+100)
		ENC					5450			
+ 710130 (s)	NO. 3 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES						PKG			
71.020	PKG 4	MOS					30-AUG-2016			
	REF: LMM 72-00-00	HRS/MSC	800				10019.9			
		ENC					5816			
+ 714010 (s)	NO. 3 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS						PKG			
71.030	PKG 4	MOS					30-AUG-2016			
	REF: GENERIC NO REF	HRS/MSC	800				10019.9			
		ENC					5816			
+ 715010 (s)	NO. 3 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS						PKG			
71.040	PKG 4	MOS					30-AUG-2016			
	REF: GENERIC NO REF	HRS/MSC	800				10019.9			
		ENC					5816			
CHAPTER 72 ENGINE										
ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P97304C Part # 3075330-2										
721001	NO. 1 ENGINE - PRESERVATION OF ENGINE									
72.001		MOS					29-DEC-1988			
	REF: LMM 72-00-00	HRS/MSC	O/C				0			
		ENC					0			
721002	NO. 1 ENGINE - PERFORM ENGINE PRESERVATION CHECK									
72.001		MOS					29-DEC-1988			
	REF: LMM 72-00-00	HRS/MSC	O/C				0			
		ENC					0			
721003	NO. 1 ENGINE - DE-PRESERVATION OF ENGINE									
72.001		MOS					29-DEC-1988			
	REF: LMM 72-00-00	HRS/MSC	O/C				0			
		ENC					0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 723110	NO. 1 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)									
72.010	REF: LMM 72-00-00	MOS HRS/MSC ENC	5000	+200			15-APR-2014 8983.8 5317	(13983.8) 14541.1	14183.8	3765.4 (+200)
724110	NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE									
72.020	3072443-5 3P-34857 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C			TSN:5555 TSN:3025	08-MAR-2001 4631.1 2798			
+ 724120	NO. 1 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE									
725010	3072443-5 3P-34857 REF: LMM 72-40-04	MOS HRS/MSC ENC	2500	+100			15-APR-2014 8983.8 5317	(11483.8) 12041.1	11583.8	1265.4 (+100)
72.040	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC									
LIFE LIMIT	3075713-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	10000			TSN:5174	21-APR-2011 4687	9513		3477
725020	NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC									
72.050	3075425-1 1-01345-486 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000			TSN:4047 TSN:2475	08-MAR-2001 4631.1 2798	10323		4287
LIFE LIMIT										
725030	NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC									
72.060	3075437-3 0-12172-1232 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000			TSN:4047 TSN:2475	08-MAR-2001 4631.1 2798	10323		4287
LIFE LIMIT										
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC									
72.070	3075227-1 0-03501-7156 REF: LMM 72-50-06	MOS HRS/MSC ENC	10000			TSN:4047 TSN:2475	08-MAR-2001 4631.1 2798	10323		4287
LIFE LIMIT										
725050	NO. 1 ENGINE - FAN DISC									
72.080	3074621 5-12172-113 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000			TSN:2880 TSN:1472	08-MAR-2001 4631.1 2798	11326		5290
LIFE LIMIT										
725060	NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC									
72.090	3072395-2 000316002356 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000			TSN:25 TSN:19	08-MAR-2001 4631.1 2798	12779		6743
LIFE LIMIT										
725070	NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC									
72.100	3072396-3 000316001919 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000			TSN:25 TSN:19	08-MAR-2001 4631.1 2798	12779		6743
LIFE LIMIT										
725080	NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC									
72.110	3072397-3 000316000108 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000			TSN:25 TSN:19	08-MAR-2001 4631.1 2798	12779		6743
LIFE LIMIT										

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725090	NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3075326-3	MOS					08-MAR-2001			
72.120	001365105691	HRS/MSC		TSN:25			4631.1			
LIFE LIMIT	REF: GENERIC NO REF	ENC	20000	TSN:19			2798	22779		16743
725091	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1	MOS					08-MAR-2001			
72.130	991119500759	HRS/MSC	O/C	TSN:25			4631.1			
	REF: LMM 72-30-10	ENC		TSN:19			2798			
725110	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3073398-1	MOS					26-JUL-1989			
72.140	8-12172-723	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:0			0	10000		3964
725130	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3072545-1	MOS					29-DEC-1988			
72.150	8P-21810	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	12000	TSN:0			0	12000		5964
725140	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE 3077065-1	MOS					29-DEC-1988			
72.160	6-18040-5106	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	30000	TSN:0			0	30000		23964
725150	NO. 1 ENGINE - FAN DRIVE SHAFT 3074641-3	MOS					29-DEC-1988			
72.170	8P-020335	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	ENC		TSN:27980			0			
725160	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3075292-4	MOS					09-JAN-2008			
72.180	3P173	HRS/MSC	O/C				6611.4			
	REF: LMM 72-50-05	ENC								
725180	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE 3075715-4	MOS					21-APR-2011			
72.190	07P04801	HRS/MSC	O/C				7823.8			
	REF: GENERIC NO REF	ENC								
725190	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL 3073765-9	MOS					23-OCT-2007			
72.200	061756502347	HRS/MSC	O/C				6611.4			
	REF: GENERIC NO REF	ENC								
725191	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT 3074052-12	MOS					23-OCT-2007			
72.210	061756502149	HRS/MSC	O/C				6611.4			
	REF: GENERIC NO REF	ENC								
725230	NO. 1 ENGINE - FAN SPINNER 3074623-3	MOS					08-MAR-2001			
72.220	002428000148	HRS/MSC	O/C	TSN:25			4631.1			
	REF: GENERIC NO REF	ENC		TSN:19			2798			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
726110	NO. 1 ENGINE - ACCESSORY GEARBOX 3070003-31	MOS					24-FEB-2001 4631.1			
72.230	P-5048 REF: LMM 72-60-02	HRS/MSC ENC	O/C							
+ 726120	NO. 1 ENGINE - INSPECT ACCESSORY GEARBOX 3070003-31	MOS					15-APR-2014 8983.8 5317	(13983.8) 14541.1	14183.8	3765.4 (+200)
72.240	P-5048 REF: LMM 72-60-02	HRS/MSC ENC	5000	+200						
726130	NO. 1 ENGINE - TRANSFER GEARBOX 3070093-12	MOS					24-FEB-2001 4631.1			
72.250	P6299 REF: LMM 72-60-01	HRS/MSC ENC	O/C		TSN:4631.1					
726140	NO. 1 ENGINE - INSPECT TRANSFER GEARBOX 3070093-12	MOS					29-DEC-1988 0 0			
72.250	P6299 REF: LMM 72-00-00	HRS/MSC ENC	O/C		TSI:0 TSI:0					
+ 727110	NO. 1 ENGINE - INSPECT FAN SUPPORT ASSEMBLY 3070093-12	MOS					11-NOV-2013 8983.8 5317	(13983.8) 14541.1	14183.8	3765.4 (+200)
72.270	REF: LMM 72-70-06	HRS/MSC ENC	5000	+200						
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P97301C Part # 3075330-2										
721001	NO. 2 ENGINE - PRESERVATION OF ENGINE 3072443-5	MOS					05-MAY-2014 9360.2 5533			
72.001	REF: LMM 72-00-00	HRS/MSC ENC	O/C							
721002	NO. 2 ENGINE - PERFORM ENGINE PRESERVATION CHECK 3072443-5	MOS					12-DEC-1988 0 0			
72.001	REF: LMM 72-00-00	HRS/MSC ENC	O/C							
721003	NO. 2 ENGINE - DE-PRESERVATION OF ENGINE 3072443-5	MOS					12-DEC-1988 0 0			
72.001	REF: LMM 72-00-00	HRS/MSC ENC	O/C							
+ 723110	NO. 2 ENGINE - COMPRESSOR ZONE INSPECTION (CZI) 3072443-5	MOS					07-JUN-2013 9127.1 5393	(14127.1) 14281.9	14327.1	3506.2 (+200)
72.010	REF: LMM 72-00-00	HRS/MSC ENC	5000	+200						
724110	NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE 3072443-5	MOS					12-DEC-1988 0 0			
72.020	8-22151-2400 REF: GENERIC NO REF	HRS/MSC ENC	O/C		TSN:0 TSN:0					
+ 724120	NO. 2 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE 3072443-5	MOS					07-JUN-2013 9127.1 5393	(11627.1) 11781.9	11727.1	1006.2 (+100)
72.020	8-22151-2400 REF: LMM 72-40-04	HRS/MSC ENC	2500	+100						

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725010	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC 70080025-1	MOS		TSN:0			07-JUN-2013			
72.040	11-156103-01016	HRS/MSC		TSN:0			9127.1			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:0			5393		15393	9312
725020	NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC 3075714-1	MOS		TSR:0			07-JUN-2013			
72.050	1-01345-490	HRS/MSC		TSN:8543.2	TSR:0		9127.1			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:5070	TSR:0		5393		10323	4242
725030	NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC 3075437-3	MOS					21-OCT-2000			
72.060	0-12172-1281	HRS/MSC		TSN:4022			4606.6			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:2456			2779		10323	4242
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC 3075227-1	MOS					12-DEC-1988			
72.070	6-12172-2204	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: LMM 72-50-06	ENC	10000	TSN:0			0		10000	3919
725050	NO. 2 ENGINE - FAN DISC 3074621	MOS					12-DEC-1988			
72.080	6-12172-952	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:0			0		10000	3919
725060	NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3072395-2	MOS					12-DEC-1988			
72.090	7-12112-238	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:0			0		10000	3919
725070	NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3072396-3	MOS		TSR:0			07-JUN-2013			
72.100	6-12112-968	HRS/MSC		TSN:9127.1	TSR:0		9127.1			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:5393	TSR:0		5393		10000	3919
725080	NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3072397-3	MOS					12-DEC-1988			
72.110	7-12112-765	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:0			0		10000	3919
725090	NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3075326-3	MOS					21-OCT-2000			
72.120	0-03501-7152	HRS/MSC		TSN:4022			4606.6			
LIFE LIMIT	REF: GENERIC NO REF	ENC	20000	TSN:2456			2779		20323	14242
725091	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1	MOS		TSR:0			07-JUN-2013			
72.130	8P-13905	HRS/MSC	O/C	TSN:9127.1	TSR:0		9127.1			
	REF: LMM 72-30-10	ENC		TSN:5393	TSR:0		5393			
725110	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3073398-1	MOS					12-DEC-1988			
72.140	6-23365-1593	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:0			0		10000	3919

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725130	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3072545-1	MOS					12-DEC-1988			
72.150	8P-156362	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	12000	TSN:0			0	12000		5919
725140	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE 3077065-1	MOS					12-DEC-1988			
72.160	6-18040-5138	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	30000	TSN:0			0	30000		23919
725150	NO. 2 ENGINE - FAN DRIVE SHAFT 3074641-3	MOS					12-DEC-1988			
72.170	8P-19356	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	ENC		TSN:0			0			
725160	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3077036-1	MOS					21-OCT-2000			
72.180	9P-8520	HRS/MSC	O/C	TSN:5485			4606.6			
	REF: LMM 72-50-05	ENC		TSN:2639			2779			
725180	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE 3075715-4	MOS					07-JUN-2013			
72.190	05P05111	HRS/MSC	O/C	TSR:0			9127.1			
	REF: GENERIC NO REF	ENC		TSR:0			5393			
725190	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL 3073765-9	MOS					12-JUL-1996			
72.200	96P04280	HRS/MSC	O/C							
	REF: GENERIC NO REF	ENC								
725191	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT 3074052-1	MOS					21-OCT-2000			
72.210	960740404929	HRS/MSC	O/C	TSN:1915			4606.6			
	REF: GENERIC NO REF	ENC		TSN:1253			2779			
725230	NO. 2 ENGINE - FAN SPINNER 3074623-3	MOS					07-JUN-2013			
72.220	13-5060-00021	HRS/MSC	O/C	TSN:0			9127.1			
	REF: GENERIC NO REF	ENC		TSN:0			5393			
726110	NO. 2 ENGINE - ACCESSORY GEARBOX 3070003-31	MOS					12-DEC-1988			
72.230	P-5027	HRS/MSC	O/C	TSN:0			0			
	REF: LMM 72-60-02	ENC		TSN:0			0			
+ 726120	NO. 2 ENGINE - INSPECT ACCESSORY GEARBOX 3070003-31	MOS					07-JUN-2013			
72.240	P-5027	HRS/MSC	5000	+200			9127.1	(14127.1) 14281.9	14327.1	3506.2 (+200)
	REF: LMM 72-60-02	ENC					5393			
726130	NO. 2 ENGINE - TRANSFER GEARBOX 3070093-12	MOS					21-SEP-2000			
72.250	P-6283	HRS/MSC	O/C	TSN:4606.6			4606.6			
	REF: LMM 72-60-01	ENC								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
726140	NO. 2 ENGINE - INSPECT TRANSFER GEARBOX									
72.250	3070093-12 P-6283 REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				12-DEC-1988 0 0			
+ 727110	NO. 2 ENGINE - INSPECT FAN SUPPORT ASSEMBLY									
72.270	REF: LMM 72-70-06	MOS HRS/MSC ENC	5000	+200			07-JUN-2013 9127.1 5393	(14127.1) 14281.9	14327.1	3506.2 (+200)
ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P97305C Part # 3075330-2										
721001	NO. 3 ENGINE - PRESERVATION OF ENGINE									
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				29-DEC-1988 0 0			
721002	NO. 3 ENGINE - PERFORM ENGINE PRESERVATION CHECK									
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				29-DEC-1988 0 0			
721003	NO. 3 ENGINE - DE-PRESERVATION OF ENGINE									
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				29-DEC-1988 0 0			
+ 723110	NO. 3 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)									
72.010	REF: LMM 72-00-00	MOS HRS/MSC ENC	5000	+200			18-SEP-2013 9222.2 5450	(14222.2) 14415.2	14422.2	3639.5 (+200)
724110	NO. 3 ENGINE - COMBUSTION CHAMBER PLENUM CASE									
72.020	3072443-5 5P-36839 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				18-SEP-2013 9222.2 5450			
+ 724120	NO. 3 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE									
72.050	3072443-5 5P-36839 REF: LMM 72-40-04	MOS HRS/MSC ENC	2500	+100			18-SEP-2013 9222.2 5450	(11722.2) 11915.2	11822.2	1139.5 (+100)
725010	NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC									
72.040	3074747-2 6-23315-1125 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000				29-DEC-1988 0 0	10000		3869
725020	NO. 3 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC									
72.050	3075425-1 1-01345-484 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000				20-NOV-2000 4607.2 2780	10324		4193
725030	NO. 3 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC									
72.060	3075437-1 0-12172-1287 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000				20-NOV-2000 4607.2 2780	10324		4193

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725040	NO. 3 ENGINE - HIGH PRESSURE TURBINE DISC 3075227-1	MOS					29-DEC-1988			
72.070	6-12172-2197	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: LMM 72-50-06	ENC	10000	TSN:0			0	10000		3869
725050	NO. 3 ENGINE - FAN DISC 3074621	MOS					29-DEC-1988			
72.080	6-12172-1847	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:0			0	10000		3869
725060	NO. 3 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3072395-2	MOS					29-DEC-1988			
72.090	7-12112-261	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:0			0	10000		3869
725070	NO. 3 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3072396-3	MOS					29-DEC-1988			
72.100	6-12112-1005	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:0			0	10000		3869
725080	NO. 3 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3072397-3	MOS					29-DEC-1988			
72.110	7-12112-639	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:0			0	10000		3869
725090	NO. 3 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3075326-3	MOS					20-NOV-2000			
72.120	0-03501-7172	HRS/MSC		TSN:4022			4607.2			
LIFE LIMIT	REF: GENERIC NO REF	ENC	20000	TSN:2456			2780	20324		14193
725091	NO. 3 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1	MOS					29-DEC-1988			
72.130	8P-13918	HRS/MSC	O/C	TSN:0			0			
	REF: LMM 72-30-10	ENC		TSN:0			0			
725110	NO. 3 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3073398-1	MOS					29-DEC-1988			
72.140	6-23365-1486	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:0			0	10000		3869
725130	NO. 3 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3072545-1	MOS					29-DEC-1988			
72.150	8P-21804	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	12000	TSN:0			0	12000		5869
725140	NO. 3 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE 3077065-1	MOS					29-DEC-1988			
72.160	6-18040-5132	HRS/MSC		TSN:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	30000	TSN:0			0	30000		23869
725150	NO. 3 ENGINE - FAN DRIVE SHAFT 3074641-3	MOS					29-DEC-1988			
72.170	8P-020337	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	ENC		TSN:0			0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING	
725160	NO. 3 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3075292-4 99P01366 REF: LMM 72-50-05	MOS HRS/MSC ENC	O/C				23-OCT-2007 6761				
725180	NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE 3075406-6 4P-13294 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:1915 TSN:1253			20-NOV-2000 4607.2 2780				
725190	NO. 3 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL 3074741 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			29-DEC-1988 0 0				
725191	NO. 3 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT 3074052-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				20-NOV-2000 4607.2 2780				
725230	NO. 3 ENGINE - FAN SPINNER 3074623-3 00242800013 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			20-NOV-2000 4607.2 2780				
726110	NO. 3 ENGINE - ACCESSORY GEARBOX 3070003-31 P-5049 REF: LMM 72-60-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			29-DEC-1988 0 0				
+ 726120	NO. 3 ENGINE - INSPECT ACCESSORY GEARBOX 3070003-31 P-5049 REF: LMM 72-60-02	MOS HRS/MSC ENC	5000	+200			18-SEP-2013 9222.2 5450	(14222.2)	14415.2	14422.2 3639.5 (+200)	
726130	NO. 3 ENGINE - TRANSFER GEARBOX 3070093-12 P-6305 REF: LMM 72-60-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			29-DEC-1988 0 0				
726140	NO. 3 ENGINE - INSPECT TRANSFER GEARBOX 3070093-12 P-6305 REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				29-DEC-1988 0 0				
+ 727110	NO. 3 ENGINE - INSPECT FAN SUPPORT ASSEMBLY REF: LMM 72-70-06	MOS HRS/MSC ENC	5000	+200			22-AUG-2013 9222.2 5450	(14222.2)	14415.2	14422.2 3639.5 (+200)	
CHAPTER 73 ENGINE FUEL AND CONTROL											
+ 73-20-01-710-802-01 (s)	OPERATIONAL TEST OF THE NO. 1 ENGINE COMPUTER STAND-BY POWER SUPPLY						PKG				
73.075	PKG 21 REF: AMM 73-20-01-710-802	MOS HRS/MSC AFL	1600	+40			20-SEP-2017 10758.2 6172				



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 73-20-01-710-802-01A	OPERATIONAL TEST OF THE NO. 1 ENGINE COMPUTER STAND-BY POWER SUPPLY (MANDATORY 5-40)									
73.075 MANDATORY 5-40	REF: AMM 73-20-01-710-802	MOS HRS/MSC AFL	1640				20-SEP-2017 10758.2 6172		12398.2	1622.5
732101	NO. 1 ENGINE FUEL COMPUTER									
73.070	2119010-900 52-BA0064 REF:	MOS HRS/MSC AFL	O/C				27-AUG-2003 5583.9 3363			
732102	NO. 2 ENGINE FUEL COMPUTER									
73.070	2119010-9000 52-BA0064 REF:	MOS HRS/MSC AFL	O/C				31-JUL-2009			
732103	NO. 3 ENGINE FUEL COMPUTER									
73.070	2119010-9000 42-BA0055 REF:	MOS HRS/MSC AFL	O/C				31-JUL-2009			
733101	NO. 1 ENGINE FUEL FLOW INDICATOR									
73.080	9-464-30 1542 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
733102	NO. 2 ENGINE FUEL FLOW INDICATOR									
73.080	9-464-30 515 REF:	MOS HRS/MSC AFL	O/C				15-JUN-2011 8296 4954			
733103	NO. 3 ENGINE FUEL FLOW INDICATOR									
73.080	9-464-30 1599 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
733151	NO. 1 ENGINE FUEL FLOW TRANSMITTER									
73.090	9-231-14 2437 REF:	MOS HRS/MSC AFL	O/C	TSN:584 TSN:318			11-NOV-1991 584 318			
733152	NO. 2 ENGINE FUEL FLOW TRANSMITTER									
73.090	9-231-14 2531 REF:	MOS HRS/MSC AFL	O/C	TSN:584 TSN:318			11-NOV-1991 584 318			
733153	NO. 3 ENGINE FUEL FLOW TRANSMITTER									
73.090	9-231-14 1110 REF:	MOS HRS/MSC AFL	O/C				23-AUG-2007			
ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P97304C Part # 3075330-2										
731110	NO. 1 ENGINE - FUEL PUMP									
73.010	3070850-57 MX480130 REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	TSN:4631.1			24-FEB-2001 4631.1			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
731120 (s)	NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2	MOS					PKG			
73.010	REF: LMM 73-21-02 TR 73-5	HRS/MSC ENC	300	+100			16-JUN-2017 10105.7 5977			
731130	NO. 1 ENGINE - FLOW DIVIDER/DRAIN VALVE 394396-2-1	MOS					24-FEB-2001			
73.030	7249 REF: GENERIC NO REF	HRS/MSC ENC	O/C				4631.1			
731140	NO. 1 ENGINE - FUEL HEATER 158670-5	MOS					21-APR-2011			
73.040	71-5915 REF: LMM 73-10-04	HRS/MSC ENC	O/C				7823.8 4687			
+ 731150 (s)	NO. 1 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE) PKG 4	MOS					PKG			
73.050	REF: LMM 79-20-06	HRS/MSC ENC	800				30-AUG-2016 9655.6 5603			
731160	NO. 1 ENGINE - FUEL HEATER CHECK VALVE 3073932-4	MOS					21-JAN-2008			
73.060	1-20404-464 REF: LMM 73-10-04	HRS/MSC ENC	O/C				6611.4			
732110	NO. 1 ENGINE - FUEL CONTROL UNIT 3070800-45	MOS					15-SEP-2017			
73.070	17610 REF: LMM 73-20-01	HRS/MSC ENC	O/C		TSR:0 TSR:0 TSR:0		10200.9 6026			
732120	NO. 1 ENGINE - PRESSURE LIMITER VALVE 3070685-6	MOS					24-FEB-2001			
73.080	A9471 REF: GENERIC NO REF	HRS/MSC ENC	O/C				4631.1			
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P97301C Part # 3075330-2										
731110	NO. 2 ENGINE - FUEL PUMP 3070850-26	MOS					01-FEB-2008			
73.010	A10316CV REF: LMM 73-20-01	HRS/MSC ENC	O/C				6876.1			
731120 (s)	NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2	MOS					PKG			
73.010	REF: LMM 73-21-02 TR 73-5	HRS/MSC ENC	300	+100			16-JUN-2017 10508.2 6022			
731130	NO. 2 ENGINE - FLOW DIVIDER/DRAIN VALVE 394396-2-1	MOS					12-DEC-1988			
73.030	7235 REF: GENERIC NO REF	HRS/MSC ENC	O/C		TSN:0 TSN:0		0 0			
731140	NO. 2 ENGINE - FUEL HEATER 158670-5	MOS					12-DEC-1988			
73.040	48-4876 REF: LMM 73-10-04	HRS/MSC ENC	O/C		TSN:0 TSN:0		0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 731150 (s)	NO. 2 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE) PKG 4	MOS					PKG			
73.050	REF: LMM 79-20-06	HRS/MSC ENC	800				30-AUG-2016 10058.1 5828			
731160	NO. 2 ENGINE - FUEL HEATER CHECK VALVE 3073932-6	MOS					23-OCT-2007			
73.060	061142600259 REF: LMM 73-10-04	HRS/MSC ENC	O/C				6786.5			
732110	NO. 2 ENGINE - FUEL CONTROL UNIT 3070800-35	MOS					30-AUG-2016			
73.070	15370 REF: LMM 73-20-01	HRS/MSC ENC	O/C	TSR:0 TSR:0 TSR:0			10058.1 5828			
732120	NO. 2 ENGINE - PRESSURE LIMITER VALVE 3070685-6	MOS					12-DEC-1988			
73.080	A9431 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0			
ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P97305C Part # 3075330-2										
731110	NO. 3 ENGINE - FUEL PUMP 3070850-57	MOS					29-DEC-1988			
73.010	MX480136 REF: LMM 73-20-01	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0			
731120 (s)	NO. 3 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2	MOS					PKG			
73.010	REF: LMM 73-21-02 TR 73-5	HRS/MSC ENC	300	+100			16-JUN-2017 10470 6072			
731130	NO. 3 ENGINE - FLOW DIVIDER/DRAIN VALVE 394396-2-1	MOS					29-DEC-1988			
73.030	7264 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0			
731140	NO. 3 ENGINE - FUEL HEATER 158670-3	MOS					20-NOV-2000			
73.040	15-4004 REF: LMM 73-10-04	HRS/MSC ENC	O/C	TSN:4022 TSN:2456			4607.2 2780			
+ 731150 (s)	NO. 3 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE) PKG 4	MOS					PKG			
73.050	REF: LMM 79-20-06	HRS/MSC ENC	800				30-AUG-2016 10019.9 5816			
731160	NO. 3 ENGINE - FUEL HEATER CHECK VALVE 3073932-4	MOS					23-OCT-2007			
73.060	061142600259 REF: LMM 73-10-04	HRS/MSC ENC	O/C				6761			
732110	NO. 3 ENGINE - FUEL CONTROL UNIT 3070800-26	MOS					02-JUL-2009			
73.070	A7879C REF: LMM 73-20-01	HRS/MSC ENC	O/C				7397.8			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
732120	NO. 3 ENGINE - PRESSURE LIMITER VALVE									
73.080	3070685-6 A4341 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				20-NOV-2000 4607.2 2780			
CHAPTER 74 IGNITION										
ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P97304C Part # 3075330-2										
741110	NO. 1 ENGINE - IGNITION UNIT									
74.010	3073914 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			29-DEC-1988 0 0			
+ 741120 (s)	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM						PKG			
74.010	PKG 0 REF: LMM 74-00-01	MOS HRS/MSC ENC	1200	+200			08-SEP-2017 10200.9 6026			
742110	NO. 1 ENGINE - 6 O'CLOCK IGNITOR PLUG									
74.030	3074541-1 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				23-OCT-2007 6611.4			
+ 742120 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE						PKG			
74.030	PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600				11-NOV-2013 8983.8 5317			
742130	NO. 1 ENGINE - 7 O'CLOCK IGNITOR PLUG									
74.050	3074541-1 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				23-OCT-2007 6611.4			
+ 742140 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE						PKG			
74.050	PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600				11-NOV-2013 8983.8 5317			
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P97301C Part # 3075330-2										
741110	NO. 2 ENGINE - IGNITION UNIT									
74.010	3073914-4 9603R001 REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				21-OCT-2000 4606.6 2779			
+ 741120 (s)	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM						PKG			
74.010	PKG 0 REF: LMM 74-00-01	MOS HRS/MSC ENC	1200	+200			16-JUN-2017 10508.2 6022			
742110	NO. 2 ENGINE - 6 O'CLOCK IGNITOR PLUG									
74.030	3074541-4 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-JUN-2013 9127.1 5393			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 742120 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE PKG 5	MOS					PKG			
74.030	REF: LMM 74-00-01	HRS/MSC ENC	1600				07-JUN-2013 9127.1 5393			
742130	NO. 2 ENGINE - 7 O'CLOCK IGNITOR PLUG 3074541-4	MOS		TSN:0			07-JUN-2013			
74.050	SN-UNKNOWN REF: LMM 74-00-01	HRS/MSC ENC	O/C	TSN:0 TSN:0			9127.1 5393			
+ 742140 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE PKG 5	MOS					PKG			
74.050	REF: LMM 74-00-01	HRS/MSC ENC	1600				07-JUN-2013 9127.1 5393			
ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P97305C Part # 3075330-2										
741110	NO. 3 ENGINE - IGNITION UNIT 3073914-4	MOS					20-NOV-2000			
74.010	465972 REF: LMM 74-00-01	HRS/MSC ENC	O/C	TSO:937 TSO:645			4607.2 2780			
+ 741120 (s)	NO. 3 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM PKG 0	MOS					PKG			
74.010	REF: LMM 74-00-01	HRS/MSC ENC	1200	+200			16-JUN-2017 10470 6072			
742110	NO. 3 ENGINE - 6 O'CLOCK IGNITOR PLUG 3074541-1	MOS					23-OCT-2007			
74.030	SN-UNKNOWN REF: LMM 74-00-01	HRS/MSC ENC	O/C				6761			
+ 742120 (s)	NO. 3 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE PKG 5	MOS					PKG			
74.030	REF: LMM 74-00-01	HRS/MSC ENC	1600				22-AUG-2013 9222.2 5450			
742130	NO. 3 ENGINE - 7 O'CLOCK IGNITOR PLUG 3074541-1	MOS					23-OCT-2007			
74.050	SN-UNKNOWN REF: LMM 74-00-01	HRS/MSC ENC	O/C				6761			
+ 742140 (s)	NO. 3 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE PKG 5	MOS					PKG			
74.050	REF: LMM 74-00-01	HRS/MSC ENC	1600				22-AUG-2013 9222.2 5450			
CHAPTER 75 AIR										
ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P97304C Part # 3075330-2										
750130	NO. 1 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR 3070816-4-N	MOS					27-SEP-2006			
75.010	26111 REF: LMM 75-40-01	HRS/MSC ENC	O/C				6210.1			
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P97301C Part # 3075330-2										

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
750130	NO. 2 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR									
75.010	3070816-12 1316901765257 REF: LMM 75-40-01	MOS HRS/MSC ENC	O/C				17-NOV-2016 10163.6 5872			
ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P97305C Part # 3075330-2										
750130	NO. 3 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR									
75.010	3070816-12 1516901765798 REF: LMM 75-40-01	MOS HRS/MSC ENC	O/C				17-NOV-2016 10125.4 5860			
CHAPTER 76 ENGINE CONTROLS										
+ 76-10-00-220-801-01 (s)	CHECK OF THE OF THE NO. 1 ENGINE THROTTLE LEVERS FOR FRICTION POINTS						PKG			
76.030	PKG 2 REF: AMM 76-10-00-220-801	MOS HRS/MSC AFL	16 800	+1m +40			08-FEB-2017 10425.7 6021			
+ 76-10-00-220-801-02 (s)	CHECK OF THE OF THE NO. 2 ENGINE THROTTLE LEVERS FOR FRICTION POINTS						PKG			
76.030	PKG 2 REF: AMM 76-10-00-220-801	MOS HRS/MSC AFL	16 800	+1m +40			08-FEB-2017 10425.7 6021			
+ 76-10-00-220-801-03 (s)	CHECK OF THE OF THE NO. 3 ENGINE THROTTLE LEVERS FOR FRICTION POINTS						PKG			
76.030	PKG 2 REF: AMM 76-10-00-220-801	MOS HRS/MSC AFL	16 800	+1m +40			08-FEB-2017 10425.7 6021			
76-10-00-220-802-01	MEASUREMENT OF THE NO. 1 ENGINE THROTTLE LEVER OPERATING FORCES									
76.060	REF: AMM 76-10-00-220-802	MOS HRS/MSC AFL	O/C				16-NOV-2013 9449.6 5588			
76-10-00-220-802-02	MEASUREMENT OF THE NO. 2 ENGINE THROTTLE LEVER OPERATING FORCES									
76.060	REF: AMM 76-10-00-220-802	MOS HRS/MSC AFL	O/C				13-JUL-2013 9281.9 5494			
76-10-00-220-802-03	MEASUREMENT OF THE NO. 3 ENGINE THROTTLE LEVER OPERATING FORCES									
76.060	REF: AMM 76-10-00-220-802	MOS HRS/MSC AFL	O/C				14-JAN-2014 9479.8 5608			
76-10-01-900-801-01	THROTTLE CONTROL UNIT									
76.070	FGFB771100A4 89 REF: AMM 76-10-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
76-10-21-640-802-01 (s)	LUBRICATION OF THE NO. 1 ENGINE TELEFLEX CONTROL CABLE BALL-JOINTS						PKG			
76.050	PKG 31 REF: AMM 76-10-21-640-802	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
76-10-21-640-802-02 (s)	LUBRICATION OF THE NO. 2 ENGINE TELEFLEX CONTROL CABLE BALL-JOINTS						PKG			
76.050	PKG 31 REF: AMM 76-10-21-640-802	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
76-10-21-640-802-03 (s)	LUBRICATION OF THE NO. 3 ENGINE TELEFLEX CONTROL CABLE BALL-JOINTS						PKG			
76.050	PKG 31 REF: AMM 76-10-21-640-802	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
76-10-21-900-801-01	NO. 1 ENGINE TELEFLEX CONTROL CABLE									
76.090	4803854 15034 REF: AMM 76-10-21-900-801	MOS HRS/MSC AFL	O/C				12-OCT-2004 6022.6			
76-10-21-900-801-02	NO. 3 ENGINE TELEFLEX CONTROL CABLE									
76.090	4234499 3059 REF: AMM 76-10-21-900-801	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
76-10-21-900-802-01	NO. 2 ENGINE TELEFLEX CONTROL CABLE									
76.095	4234483 3056 REF: AMM 76-10-21-900-802	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
76-10-25-640-801-01 (s)	GREASING OF THE NO. 1 ENGINE TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARINGS						PKG			
76.040	PKG 32 REF: AMM 76-10-25-640-801	MOS HRS/MSC AFL	144 7500	+2m			05-MAY-2014 9515 5634			
76-10-25-640-801-02 (s)	GREASING OF THE NO. 2 ENGINE TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARINGS						PKG			
76.040	PKG 32 REF: AMM 76-10-25-640-801	MOS HRS/MSC AFL	144 7500	+2m			05-MAY-2014 9515 5634			
76-10-25-640-801-03 (s)	GREASING OF THE NO. 3 ENGINE TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARINGS						PKG			
76.040	PKG 32 REF: AMM 76-10-25-640-801	MOS HRS/MSC AFL	144 7500	+2m			05-MAY-2014 9515 5634			
+ 76-10-33-820-801-01 (s)	CHECK OF THE OF THE NO. 1 ENGINE THROTTLE CONTROL CABLE TENSION						PKG			
76.065	PKG 31 REF: AMM 76-10-33-820-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
+ 76-10-33-820-801-02 (s)	CHECK OF THE OF THE NO. 2 ENGINE THROTTLE CONTROL CABLE TENSION						PKG			
76.065	PKG 31 REF: AMM 76-10-33-820-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			
+ 76-10-33-820-801-03 (s)	CHECK OF THE OF THE NO. 3 ENGINE THROTTLE CONTROL CABLE TENSION						PKG			
76.065	PKG 31 REF: AMM 76-10-33-820-801	MOS HRS/MSC AFL	72 3750	+2m			05-MAY-2014 9515 5634			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
76-10-33-900-801-01	NO. 1 ENGINE THROTTLE CONTROL CABLE FGFB771000040	MOS					27-FEB-1990			
76.080	SN-UNKNOWN REF: AMM 76-10-33-900-801	HRS/MSC AFL	O/C	TSN:0			0 0			
76-10-33-900-801-02	NO. 2 ENGINE THROTTLE CONTROL CABLE FGFB771000050	MOS					27-FEB-1990			
76.080	SN-UNKNOWN REF: AMM 76-10-33-900-801	HRS/MSC AFL	O/C	TSN:0			0 0			
76-10-33-900-801-03	NO. 3 ENGINE THROTTLE CONTROL CABLE FGFB771000060	MOS					27-FEB-1990			
76.080	SN-UNKNOWN REF: AMM 76-10-33-900-801	HRS/MSC AFL	O/C	TSN:0			0 0			
761A04	DEEC ENGINE #1 HARNESS 3074225-4E	MOS					27-FEB-1990			
	0006092 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
761A05	DEEC ENGINE #2 HARNESS 3074225-4E	MOS					27-FEB-1990			
	0002101 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
761A06	DEEC ENGINE #3 HARNESS 3074225-4E	MOS					27-FEB-1990			
	0006084 REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
762111	NO. 1 ENGINE FUEL SHUTOFF VALVE L88A31662	MOS					27-FEB-1990			
76.100	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
762112	NO. 2 ENGINE FUEL SHUTOFF VALVE L88A31663	MOS					27-FEB-1990			
76.110	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
762113	NO. 3 ENGINE FUEL SHUTOFF VALVE L88A31664	MOS					27-FEB-1990			
76.120	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0			
ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P97304C Part # 3075330-2										
+ 760120	NO. 1 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL									
76.020		MOS					11-NOV-2013			
	REF: See Workcard	HRS/MSC ENC	N/A				8983.8 5317			
760130	NO. 1 ENGINE - DOWNLOAD ECTM									
76.050		MOS					21-JUN-2017			
	REF: See Workcard	HRS/MSC ENC	O/C				10105.7 5977			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
761310	NO. 1 ENGINE - SURGE BLEED VALVE									
76.030	978812-5-1 5418 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C				23-OCT-2007 6611.4			
761320	NO. 1 ENGINE - SOLENOID CONTROLLER VALVE									
76.040	109696-4-1 6237 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C	TSN:5509.5			08-AUG-2003 5359.5 3233			
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P97301C Part # 3075330-2										
+ 760120	NO. 2 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL									
76.020	REF: See Workcard	MOS HRS/MSC ENC	N/A				13-JUL-2013 9127.1 5393			
760130	NO. 2 ENGINE - DOWNLOAD ECTM									
76.050	REF: See Workcard	MOS HRS/MSC ENC	O/C				21-JUN-2017 10508.2 6022			
761310	NO. 2 ENGINE - SURGE BLEED VALVE									
76.030	978812-5-1 7281 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C				23-OCT-2007 6786.5			
761320	NO. 2 ENGINE - SOLENOID CONTROLLER VALVE									
76.040	109696-4-1 6001 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			12-DEC-1988 0 0			
ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P97305C Part # 3075330-2										
+ 760120	NO. 3 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL									
76.020	REF: See Workcard	MOS HRS/MSC ENC	N/A				30-SEP-2013 9222.2 5450			
760130	NO. 3 ENGINE - DOWNLOAD ECTM									
76.050	REF: See Workcard	MOS HRS/MSC ENC	O/C				15-JUN-2017 10470 6072			
761310	NO. 3 ENGINE - SURGE BLEED VALVE									
76.030	978812-5-1 6169 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C				23-OCT-2007 6761			
761320	NO. 3 ENGINE - SOLENOID CONTROLLER VALVE									
76.040	109696-4-1 6136 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C	TSN:5359.5			08-AUG-2003 5509.5 3233			
CHAPTER 77 ENGINE INDICATING										

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
771119	NO. 1 ENGINE N1 INDICATOR 5428-701-80-10 715 REF:	MOS HRS/MSC AFL	O/C				21-JUN-2017 10663 6123			
771120	NO. 2 ENGINE N1 INDICATOR 5428-701-80-10 280 REF:	MOS HRS/MSC AFL	O/C				26-SEP-2007 6775.5			
771121	NO. 3 ENGINE N1 INDICATOR 5428-701-80-10 453 REF:	MOS HRS/MSC AFL	O/C	TSR:152 TSR:4638.6 TSR:2514			21-JUN-2017 10663 6123			
771155	NO. 1 ENGINE N2 INDICATOR 5423-713-80-10 319 REF:	MOS HRS/MSC AFL	O/C				13-DEC-2016 10339.7 5990			
771156	NO. 2 ENGINE N2 INDICATOR 5423-713-80-10 248A REF:	MOS HRS/MSC AFL	O/C				13-DEC-2016 10339.7 5990			
771157	NO. 3 ENGINE N2 INDICATOR 5423-713-80-10 140 REF:	MOS HRS/MSC AFL	O/C				17-JUN-2008 7027.8			
771173	NO. 1 ENGINE ITT INDICATOR 5428-559-80-10 150 REF:	MOS HRS/MSC AFL	O/C				27-AUG-2003 5583.9 3363			
771174	NO. 2 ENGINE ITT INDICATOR 5428-559-80-10 110A REF:	MOS HRS/MSC AFL	O/C				27-AUG-2003 5583.9 3363			
771175	NO. 3 ENGINE ITT INDICATOR 5428-559-80-10 165 REF:	MOS HRS/MSC AFL	O/C				12-OCT-2003 5619 3397			
ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P97304C Part # 3075330-2										
771110	NO. 1 ENGINE - LOW PRESSURE (N1) TRANSDUCER 3075388-2 N/A REF: LMM 77-10-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			17-JAN-2015 9206.8 5416			
771120	NO. 1 ENGINE - HIGH PRESSURE (N2) TRANSDUCER 30707223-3 061936048214 REF: LMM 77-10-05	MOS HRS/MSC ENC	O/C				21-OCT-2006 6212.9			



Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
772110	NO. 1 ENGINE - ITT THERMOCOUPLE HARNESS									
77.030	3073605-1 072021904553 REF: LMM 77-20-01	MOS HRS/MSC ENC	O/C				23-OCT-2007 6611.4			
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P97301C Part # 3075330-2										
771110	NO. 2 ENGINE - LOW PRESSURE (N1) TRANSDUCER									
77.010	3075388-1 SN-UNKNOWN REF: LMM 77-10-03	MOS HRS/MSC ENC	O/C				23-OCT-2007 6786.5			
771120	NO. 2 ENGINE - HIGH PRESSURE (N2) TRANSDUCER									
77.020	3070722-10 14910300059 REF: LMM 77-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			03-APR-2015 9687.6 5675			
772110	NO. 2 ENGINE - ITT THERMOCOUPLE HARNESS									
77.030	3073605-1 1215027700335 REF: LMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-JUN-2013 9127.1 5393			
ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P97305C Part # 3075330-2										
771110	NO. 3 ENGINE - LOW PRESSURE (N1) TRANSDUCER									
77.010	3075388-1 221 REF: LMM 77-10-03	MOS HRS/MSC ENC	O/C				20-NOV-2000 4607.2 2780			
771120	NO. 3 ENGINE - HIGH PRESSURE (N2) TRANSDUCER									
77.020	3070722-3 031936035173 REF: LMM 77-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0		10/06/2004	06-OCT-2003 5554.4			
772110	NO. 3 ENGINE - ITT THERMOCOUPLE HARNESS									
77.030	3073605-1 072021903566 REF: LMM 77-20-01	MOS HRS/MSC ENC	O/C				23-OCT-2007 6761			
CHAPTER 78 EXHAUST										
78-30-00-210-801-01	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER									
78.010		MOS HRS/MSC AFL	E/C				13-JUL-2013 9281.9 5494			
+ 78-30-00-720-801-01 (s)	FUNCTIONAL TEST OF THE THRUST REVERSER SYSTEM WITH ENGINE SHUT DOWN						PKG			
78.020	PKG 31	MOS HRS/MSC AFL		72 3750	+2m		05-MAY-2014 9515 5634			
78-30-00-910-807-01	PERFORM INHIBITION OF THE THRUST REVERSER									
78.170		MOS HRS/MSC AFL APH	O/C				27-FEB-1990 0 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
78-31-00-640-802-01 (s)	GREASING OF THE THRUST REVERSER HINGES						PKG			
78.145	PKG 1 REF: AMM 78-31-00-640-802	MOS HRS/MSC AFL	8 400	+1m +40			20-SEP-2017 10758.2 6172			
78-31-00-640-804-01 (s)	GREASING OF THE THRUST REVERSER CONTROL AND UNLOCKING LINKAGE						PKG			
78.100	PKG 16,18,203 REF: AMM 78-31-00-640-804	MOS HRS/MSC AFL	24	+1m			30-AUG-2016 10212.9 5929			
78-31-15-960-801-01	REPLACEMENT THRUST REVERSER HYDRAULIC CONTROL ACTUATOR OF THE BALL-JOINT END-FITTING OF THE THRUST REVERSER DOOR ACTUATOR									
78.100	106124-01 93 REF: AMM 78-31-15-960-801	MOS HRS/MSC AFL	O/C				30-AUG-2000 4606 2779			
78-32-09-900-801-01	THRUST REVERSER HYDRAULIC ACCUMULATOR									
78.050	60909-1 7915 REF: AMM 78-32-09-900-801	MOS HRS/MSC AFL	O/C				02-MAY-2008 6968.3 4165			
783101	THRUST REVERSER SYSTEM PRESSURE GAGE									
78.030	18040100 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
783106	THRUST REVERSER SYSTEM CHARGING VALVE									
78.040	MS26889-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
783221	THRUST REVERSER ELECTRODISTRIBUTION CONTROL									
78.060	108131-02 100 REF:	MOS HRS/MSC AFL	O/C		TSN:32		20-JUL-1990 27 14			
783301	THRUST REVERSER SYSTEM CHECK SUPPLY VALVE									
78.070	A24515 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
783311	THRUST REVERSER SYSTEM CHECK RETURN VALVE									
78.070	C24816000 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
783321	THRUST REVERSER RETRACTION JACK ISOLATION VALVE									
78.080	AE99113E SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			
783331	THRUST REVERSER EXTENSION JACK ISOLATION VALVE									
78.080	AE99113E SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0		27-FEB-1990 0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
783341	THRUST REVERSER JACK LOCKING ISOLATION VALVE									
78.090	AE99113G SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
783401	THRUST REVERSER HYDRAULIC CONTROL ACTUATOR									
78.100	106124-01 93 REF:	MOS HRS/MSC AFL	O/C	TSN:3669 TSN:2134			23-JUL-1998 3669 2134			
783411	THRUST REVERSER SYNCHRONIZING BELLCRANK									
78.110	F900HD3200240A5 117 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			11-NOV-1991 583 316			
783421	THRUST REVERSER LEFT CONTROL DOOR ADJUSTMENT ROD									
78.120	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
783431	THRUST REVERSER RIGHT CONTROL DOOR ADJUSTMENT ROD									
78.120	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
783441	THRUST REVERSER UPPER CATCH UNLOCK JACK									
78.130	106125-01 197 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
783451	THRUST REVERSER LOWER CATCH UNLOCK JACK									
78.130	106125-01 196 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
783461	THRUST REVERSER UPPER LOCKING CATCH									
78.140	A861TS4RF900 874 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
783471	THRUST REVERSER LOWER LOCKING CATCH									
78.140	A861TS4RF50 881 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
783501	LH THRUST REVERSER DOOR INDICATING MICROSWITCH									
78.150	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
783506	RH THRUST REVERSER DOOR INDICATING MICROSWITCH									
78.150	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			0 0			

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
783511	THRUST REVERSER SYNCHRONIZING BELLCRANK MICROSWITCH									
78.160	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
783A01	THRUST REVERSER LH DOOR									
	F900HD310000A3 43HD40 REF:	MOS HRS/MSC AFL	O/C				23-JUL-1998 3669 2134			
783A02	THRUST REVERSER RH DOOR									
	F900HD310000A3 12HD8 REF:	MOS HRS/MSC AFL	O/C				28-JAN-1999 3871 2312			
CHAPTER 79 OIL										
793083	NO. 1 ENGINE LOW OIL PRESSURE SWITCH									
79.075	8G1126-2 1966 REF:	MOS HRS/MSC AFL	O/C				21-JUN-2017 10663 6123			
793084	NO. 2 ENGINE LOW OIL PRESSURE SWITCH									
79.075	8G1126-2 551 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
793085	NO. 3 ENGINE LOW OIL PRESSURE SWITCH									
79.075	8G1126-2 2612 REF:	MOS HRS/MSC AFL	O/C				21-JUN-2017 10663 6123			
793101	NO. 1 ENGINE OIL PRESSURE TRANSMITTER									
79.080	64251-417-2 2853 REF:	MOS HRS/MSC AFL	O/C				11-MAY-2017 10553.3 6091			
793102	NO. 2 ENGINE OIL PRESSURE TRANSMITTER									
79.080	64251-417-2 7373 REF:	MOS HRS/MSC AFL	O/C				11-MAY-2017 10553.3 6091			
793103	NO. 3 ENGINE OIL PRESSURE TRANSMITTER									
79.080	64251-417-2 7373 REF:	MOS HRS/MSC AFL	O/C				20-MAY-2009			
793119	NO. 1 ENGINE OIL TEMPERATURE PROBE									
79.090	158465-3 33-3928 REF:	MOS HRS/MSC AFL	O/C				21-APR-2011			
793120	NO. 2 ENGINE OIL TEMPERATURE PROBE									
79.090	56B17 11477 REF:	MOS HRS/MSC AFL	O/C	TSN:584 TSN:318			11-NOV-1991 584 318			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
793121	NO. 3 ENGINE OIL TEMPERATURE PROBE									
79.090	56B17 11678 REF:	MOS HRS/MSC AFL	O/C	TSN:584 TSN:318			11-NOV-1991 584 318			
793137	NO. 1 ENGINE DUAL OIL INDICATOR									
79.100	64857-418-1 464 REF:	MOS HRS/MSC AFL	O/C				22-JAN-2010 7656.8 4584			
793138	NO. 2 ENGINE DUAL OIL INDICATOR									
79.100	64857-418-1 415 REF:	MOS HRS/MSC AFL	O/C				11-MAY-2017 10553.3 6091			
793139	NO. 3 ENGINE DUAL OIL INDICATOR									
79.100	64857-418-1 464 REF:	MOS HRS/MSC AFL	O/C				11-MAY-2017 10553.3 6091			
793155	ENGINE OIL LEVEL INDICATOR									
79.110	267-968-004 133 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
793161	ENGINE OIL LEVEL AMPLIFIER									
79.120	360-967-004 217 REF:	MOS HRS/MSC AFL	O/C	TSN:0			27-FEB-1990 0 0			
793167	NO. 1 ENGINE OIL LEVEL GAGE									
79.130	029-907-004 428 REF:	MOS HRS/MSC AFL	O/C	TSN:584 TSN:319			11-NOV-1991 584 318			
793168	NO. 2 ENGINE OIL LEVEL GAGE									
79.130	029-907-004 427 REF:	MOS HRS/MSC AFL	O/C	TSN:584 TSN:318			11-NOV-1991 584 318			
793169	NO. 3 ENGINE OIL LEVEL GAGE									
79.130	029-907-004 424 REF:	MOS HRS/MSC AFL	O/C	TSN:584 TSN:318			11-NOV-1991 584 318			
ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P97304C Part # 3075330-2										
790110 (s)	NO. 1 ENGINE - ANALYZE OIL AND FILTER						PKG			
79.010	PKG 1 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			15-SEP-2017 10200.9 6026			
790120	NO. 1 ENGINE - CHANGE OIL									
79.020	REF: See Workcard	MOS HRS/MSC ENC	1200	+100			21-JUN-2017 10105.7 5977	(11305.7) 11863	11405.7	1087.3 (+100)

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 790130 (s)	NO. 1 ENGINE - INSPECT OIL CHIP DETECTOR PKG 1	MOS					PKG			
79.030	REF: LMM 79-20-03	HRS/MSC ENC	150	+100			15-SEP-2017 10200.9 6026			
792110	NO. 1 ENGINE - OIL PUMP 3060785-2	MOS					21-APR-2011			
79.040	041405700234 REF: LMM 79-20-03	HRS/MSC ENC	O/C				7823.8 4687			
792120	NO. 1 ENGINE - BY-PASS INDICATOR VALVE 3002780-3	MOS					29-DEC-1988			
79.050	SN-UNKNOWN REF: LMM 79-30-01	HRS/MSC ENC	O/C		TSN:0 TSN:0		0 0			
792130	NO. 1 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY 3075323-3	MOS					18-AUG-2006			
79.060	SN-UNKNOWN REF: LMM 79-20-02	HRS/MSC ENC	O/C				6200.5			
792140	NO. 1 ENGINE - UPPER OIL COOLER 158600-7	MOS					21-APR-2011			
79.070	64-7774 REF: LMM 79-20-09	HRS/MSC ENC	O/C				7823.8 4687			
792150	NO. 1 ENGINE - LOWER LEFT OIL COOLER 159900-3	MOS					21-APR-2011			
79.080	46-8912 REF: LMM 79-20-09	HRS/MSC ENC	O/C				7823.8 4687			
792160	NO. 1 ENGINE - LOWER RIGHT OIL COOLER 159910-3	MOS					21-APR-2011			
79.090	102-4874 REF: LMM 79-20-09	HRS/MSC ENC	O/C				7823.8 4687			
792170	NO. 1 ENGINE - OIL TEMPERATURE REGULATOR 158610-8	MOS					21-APR-2011			
79.100	56-900 REF: LMM 79-20-07	HRS/MSC ENC	O/C							
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P97301C Part # 3075330-2										
790110 (s)	NO. 2 ENGINE - ANALYZE OIL AND FILTER PKG 1	MOS					PKG			
79.010	REF: LMM 72-00-00	HRS/MSC ENC	150	+100			15-SEP-2017 10603.4 6071			
790120	NO. 2 ENGINE - CHANGE OIL	MOS					08-SEP-2017			
79.020	REF: See Workcard	HRS/MSC ENC	1200	+100			10603.4 6071	(11803.4) 11958.2	11903.4	1182.5 (+100)
+ 790130 (s)	NO. 2 ENGINE - INSPECT OIL CHIP DETECTOR PKG 1	MOS					PKG			
79.030	REF: LMM 79-20-03	HRS/MSC ENC	150	+100			15-SEP-2017 10603.4 6071			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
792110	NO. 2 ENGINE - OIL PUMP 3071949-11	MOS					21-OCT-2000			
79.040	7728 REF: LMM 79-20-03	HRS/MSC ENC	O/C	TSO:0 TSO:0			4606.6 2779			
792120	NO. 2 ENGINE - BY-PASS INDICATOR VALVE 3002780-4	MOS					07-JUN-2013			
79.050	12-150233-00603 REF: LMM 79-30-01	HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			9127.1 5393			
792130	NO. 2 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY 3075323-3	MOS					10-AUG-2011			
79.060	5510C REF: LMM 79-20-02	HRS/MSC ENC	O/C				8326.1 4972			
792140	NO. 2 ENGINE - UPPER OIL COOLER 158600-7	MOS					12-DEC-1988			
79.070	28-9176 REF: LMM 79-20-09	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0			
792150	NO. 2 ENGINE - LOWER LEFT OIL COOLER 159900-3	MOS					12-DEC-1988			
79.080	88-6820 REF: LMM 79-20-09	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0			
792160	NO. 2 ENGINE - LOWER RIGHT OIL COOLER 159910-3	MOS					12-DEC-1988			
79.090	68-6738 REF: LMM 79-20-09	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0			
792170	NO. 2 ENGINE - OIL TEMPERATURE REGULATOR 158610-8	MOS					12-DEC-1988			
79.100	117-6852 REF: LMM 79-20-07	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0			
ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P97305C Part # 3075330-2										
790110 (s)	NO. 3 ENGINE - ANALYZE OIL AND FILTER PKG 1	MOS					PKG			
79.010	REF: LMM 72-00-00	HRS/MSC ENC	150	+100			15-SEP-2017 10565.2 6121			
790120	NO. 3 ENGINE - CHANGE OIL 158610-8	MOS					19-JUN-2017			
79.020	REF: See Workcard	HRS/MSC ENC	1200	+100			10470 6072	(11670) 11863	11770	1087.3 (+100)
+ 790130 (s)	NO. 3 ENGINE - INSPECT OIL CHIP DETECTOR PKG 1	MOS					PKG			
79.030	REF: LMM 79-20-03	HRS/MSC ENC	150	+100			15-SEP-2017 10565.2 6121			
792110	NO. 3 ENGINE - OIL PUMP 3071949-12	MOS					06-FEB-2017			
79.040	7263C REF: LMM 79-20-03	HRS/MSC ENC	O/C	TSR:0 TSR:0 TSR:0			10232.7 5907			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900B S/N 083 (N361K): 10775.7 HRS, 6182 AFL as of 11-Oct-2017

Owner/Operator: MCGRAW INSURANCE SERVICES

Report Date: 18-OCT-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
792120	NO. 3 ENGINE - BY-PASS INDICATOR VALVE 3002780-4	MOS		TSN:0			24-MAR-2017			
79.050	16-122000-00741 REF: LMM 79-30-01	HRS/MSC ENC	O/C	TSN:0 TSN:0			10267.1 5933			
792130	NO. 3 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY 3071564-8	MOS		TSN:0			29-DEC-1988			
79.060	SN-UNKNOWN REF: LMM 79-20-02	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0			
792140	NO. 3 ENGINE - UPPER OIL COOLER 158600-7	MOS		TSN:0			29-DEC-1988			
79.070	48-9206 REF: LMM 79-20-09	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0			
792150	NO. 3 ENGINE - LOWER LEFT OIL COOLER 159900-3	MOS		TSN:0			29-DEC-1988			
79.080	88-6827 REF: LMM 79-20-09	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0			
792160	NO. 3 ENGINE - LOWER RIGHT OIL COOLER 159910-3	MOS		TSN:0			23-OCT-2007			
79.090	65-5899 REF: LMM 79-20-09	HRS/MSC ENC	O/C	TSN:0			6761			
792170	NO. 3 ENGINE - OIL TEMPERATURE REGULATOR 158610-8	MOS		TSN:0			29-DEC-1988			
79.100	107-6828 REF: LMM 79-20-07	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0			