

Production Marks on the outside of the cabinet


You may notice some marks on the outside of the fridge cabinet when you take it out of the shipping box. These are from our production process.

The small holes are vent holes which allow air to escape and be replaced with the insulation foam we inject into the cabinet. The silver tape covers the larger holes where the foam machine enters the cabinet.

The Scratches which may be noticed are from the foaming process also. When the cabinet is foamed the cabinet is placed in a strong metal mold to hold the shape during the foaming process. When the mold is opened under pressure some marks may be left on the cabinet.

The cabinet is designed to be mounted in an enclosure and is not visible after the unit is mounted.

The front of the refrigerator which is exposed after installation should not have any of these production marks



The reliability and performance of the unit is not compromised with these marks.

Thanks for purchasing a Nova Kool Product.