

Landscaping



The bigger the plant buffer,
the better.

1 Haul material offsite.



Include material hauling in your landscaping contract.

2 Revegetate bare areas.



Add loam and reseed.

3 Mow high.




Ditches, swales, and BMPs should be mowed 6" or higher.

4 Plant natives.



They require less maintenance, watering, and fertilizer.

5 Keep a buffer.



Minimize mowing near water bodies and wetlands.



Long Creek Watershed Management District

Implemented with Assistance from:
Cumberland County Soil & Water Conservation District
35 Main Street, Suite 3, Windham, ME 04062
(207) 892-4700 | www.restorelongcreek.org