

Winter Maintenance



Pretreat and maintain snow removal.

1 Use mechanical removal.



Remove snow with plows, snowblowers, and shovels before using sand & salt.

For parcel specific winter maintenance tips, sign up for the SWiM program provided by the Long Creek Watershed Management District.

2 Use the right products.



Use product for current conditions and forecasted weather.

3 Timing is everything.



Pretreat with brine or wet sodium chloride before the storm.

4 Use the right amount.



Calibrate equipment for current conditions to apply just enough.

5 Store snow correctly.



Use your parcel map for appropriate snow storage locations.



Long Creek Watershed Management District

Implemented with Assistance from:
Cumberland County Soil & Water Conservation District
35 Main Street, Suite 3, Windham, ME 04062
(207) 892-4700 | www.restorelongcreek.org