

Manufacturer	Model	240p Compatibility Test	240p Processing Test	Note/Comments
Dynex	E198MZNKWBBDNN	FAIL	-	
Element	ELEFW195	FAIL	-	
Emerson	LF461EM4	FAIL	-	
Hisense	32K20DW	PASS	FAIL	
Hisense	40H5	PASS	FAIL	
Insignia	E196MZNK3WBYN	FAIL	-	
JVC	EM48FTR	FAIL	-	
JVC	EM39FT	FAIL	-	
JVC	EM32T	PASS	FAIL	
LG	39LB5600	FAIL	-	
LG	47LB5900	FAIL	-	
LG	47LB6300	PASS	FAIL	
LG	55LB7200	PASS	FAIL	
LG	60PB6650	FAIL*	-	TV can be tricked into not rejecting 240p by rapidly swiching from 480i (e.g. PS1 game booting on a PS2, Wii Virtual Console)
LG	60LB7100	PASS	FAIL	
LG	32LB5600	FAIL	-	
LG	42LB5800	FAIL	-	
LG	32LB560B	FAIL	-	
LG	24LB451B	FAIL	-	
LG	24MA31D-PU	FAIL	-	
LG	M2262DL	FAIL*	-	TV can be tricked into not rejecting 240p by rapidly swiching from 480i (e.g. PS1 game booting on a PS2, Wii Virtual Console)
Mitsubishi	WD-65C9	PASS	PASS	Composite video fails processing test.
Panasonic	TC-42PX24	PASS	FAIL	
Panasonic	TH-42PX80U	FAIL	-	
Proscan	PLDV321300	FAIL	-	
Proscan	PLDED3231ARK	FAIL	-	
RCA	F38310	PASS	PASS*	Proper processing, but causes an abrupt jump in the video every few seconds.
Samsung	UN40H5003AFXZA	PASS	PASS	
Samsung	UN24H4500	PASS	PASS	Had ground loop issue with both Component & Composite. Could just be a defective unit.
Samsung	UN55HU3620	PASS	PASS	
Samsung	UN55HU8700	PASS	PASS	
Samsung	UN60H7150	PASS	PASS*	Drop shadow looks minimally strange but only on non-black&white backgrounds.
Samsung	PN60F5300	PASS	PASS	
Samsung	PN60F5500	PASS	PASS	
Samsung	UN40HU6950	PASS	PASS	
Samsung	UN32EH4003	PASS	PASS	
Samsung	LT24D310	PASS	PASS	
Samsung	T28D310NH	PASS	PASS	
Samsung	UN32EH5300	PASS	PASS	
Sanyo	DP39E23	FAIL	-	
Sceptre	E240BC-FHD	PASS	PASS	
Seiki	SE29HY34	FAIL*	-	240p Composite also doesn't work. 480i Component and 480i Composite both work.
Seiki	SE32HY10	FAIL*	-	240p Composite also doesn't work. 480i Component and 480i Composite both work.
Sharp	LC60LE660U	PASS	PASS*	Has too much of a smoothing filter. Affects striped backgrounds in drop shadow test.
Sharp	LC70SQ15U	PASS	FAIL	
Sharp	LC60SQ15U	PASS	FAIL	
Sony	KDL40W600B	PASS	FAIL	

Sony	KDL55W800B	PASS	FAIL	
Sony	KDL60W630B	PASS	FAIL	
Sony	KDL-48W590B	PASS	FAIL	
Sony	KD-34XBR960	PASS	PASS*	Proper 240p processing only when DRC mode is set to "interlaced".
Sony	KDL-48W580B	PASS	FAIL	
Toshiba	40L1400U	FAIL	-	Using composite over Y jack requires change in setup menu.
Toshiba	32L1400U	FAIL	-	Using composite over Y jack requires change in setup menu.
Toshiba	40L3400U	FAIL	-	Using composite over Y jack requires change in setup menu.
Toshiba	58L5400U	PASS	FAIL*	Drop shadow looks very strange only on non-black&white backgrounds. Input lag is atrocious.
Vizio	E390-B0	FAIL*	-	Couldn't get Composite to work with 240p either.
Vizio	E420-B1	PASS	FAIL	
Vizio	E390-A1	PASS	FAIL	
Vizio	M422I-B1	PASS	FAIL	
Vizio	E480I-B2	PASS	FAIL	
Vizio	E390-B1E	PASS	FAIL	
Vizio	M522I-B2	PASS	FAIL	Noticably bad input lag.
Vizio	P552UI-B2	FAIL	-	
Vizio	E280-B1	PASS	FAIL	
Vizio	E320-B2	PASS	FAIL	
Vizio	VX20L	FAIL	-	
↓↓↓ --- COMMUNITY SUBMITTED MODELS --- ↓↓↓				
Westinghouse	LTV-32W6	PASS	FAIL	Has an ATI Xilleon image processor. 480i is poorly processed too. TV introduces about 60-70ms of lag even when using 480p.
LG	47LD450	FAIL	-	
LG	32LH20-UA	FAIL	-	
Samsung	UN55D8000	PASS	???	Processing was not tested.
Sony	CECH-ZED1U	PASS	PASS	
LG	65LW6500-UA	FAIL	-	
Panasonic	TH-P42V20S	PASS	FAIL	
↑↑↑ --- COMMUNITY SUBMITTED MODELS --- ↑↑↑				