

les basic

whitsunday — care & maintenance

timber — solid, veneer

wipe surface with a soft, moist cloth. If you must use detergent, use a neutral diluted detergent. Dry the surface with a clean, soft cloth after washing. Avoid bleaches, acids, or abrasive materials.

upholstery — fabric, leather

please refer to the manufacturer of your chosen textile for care and maintenance instructions.

metal — powdercoated, polished

wipe surface with a soft, moist cloth. If you must use detergent, use a neutral diluted detergent. Dry the surface with a clean, soft cloth after washing. Avoid bleaches, acids, or abrasive materials.