

PCT Notes from Discussion with Martin Anaya

Phone call – 1/4/2012 & Additional Activity

Two procedural issues (PCT responsible)

- Meeting not broadcast live (failure to shut down Adcock properly)
- Delayed start due to junction box construction (Dec. 14) 15 minutes late

Continuing Issues with Sound

MCC Equipment

- 7 microphones & Harness
- 1 Wireless Microphone
- 2 Mixers

Issues

- Hard to set up (time requirement)
- Dual Mixer / One volume readout display
- Experience needed to become expert at adjustment
- Note: PCT has worked with MCC equipment at their place

Going Forward:

Seton Site Notes

Spoke with Pat Green – 1/9/12

Her input from Becky Clark – on 1/16 PCT will return to stabilize box

Painting box will be done at that time or later (question for Marty / Jason)

Immediate Actions

Continue operator procedure improvement

- PCT omnidirectional mike

- Jan. 11 Meeting will test this option
- Arrive at 6:30 for setup, discussion
- Test wireless / mixer for speaker if there is time before hand

Recommend: Establish MCC Committee to Consider Options

- Review/ monitor audio performance
- Review requirements for amplifier (public meeting)
- Review other equipment options
- Review experience / methods of other agencies (many have fixed in place setup)
- Bring recommendations to council