

Dumpster Management



Keep solid waste contained.

1 Keep it covered.



Always keep dumpster lids closed.

2 Use drain plugs.



Contact LCWMD if your dumpster needs drain plugs.

3 Empty regularly.



Schedule dumpsters to be emptied before they become full.

4 Pick the right spot.



Place dumpsters on level surface away from storm drains.

5 Keep area tidy.



Maintain the area around the dumpster daily.



Long Creek Watershed Management District

Implemented with Assistance from:
Cumberland County Soil & Water Conservation District
35 Main Street, Suite 3, Windham, ME 04062
(207) 892-4700 | www.restorelongcreek.org