

PROJECT: CHS

DATE Thursday, February 19, 2015

REPORT BY: Rick Buhl

MANPOWER DETAIL		
SUB-CONTRACTOR: Ranor Drywall	# OF WORKERS:	4
ACTIVITIES:		
They continued framing metal stud walls and ceilings. They completed the off	ices on north side began	i
the enterance area.		
SUB-CONTRACTOR: Brite eletric	# OF WORKERS:	3
ACTIVITIES:	•	
They Continued working on electrical and data rough in on walls and ceilings.		
SUB-CONTRACTOR: Dehart Plumbing	# OF WORKERS:	3
ACTIVITIES:		
They began rough in on the first floor restrooms, drinking fountains, and conf	erence room.	
SUB-CONTRACTOR: Dehart HVAC	# OF WORKERS:	1
ACTIVITIES:		

He vented the restroom fans through the roof and completed rough in on the south side of building.