

PROJECT: CHS	DATE: Friday, March 20, 2020
REPORT BY: Rick Buhl	
REPORT DT. NICK BUILL	
MANPOWER DETAIL	
SUB-CONTRACTOR: Ranor Drywall	# OF WORKERS:
ACTIVITIES:	
They had 2 guys wokring on tape and texture and 2 guys finis	shed all the metal stud framing except
a few spots where we have to move fire sprinklers.	
SUB-CONTRACTOR: Dehart HVAC	# OF WORKERS:
ACTIVITIES:	
They started rough in on the wood framed walls.	
SUB-CONTRACTOR: Dehart Plumbing	# OF WORKERS: 2
ACTIVITIES:	
They completed rough in on the wood framed walls.	
SUB-CONTRACTOR: Brite Electric	# OF WORKERS: 3
ACTIVITIES:	<u> </u>
They continued working on the electrical rough in and overhood	ead conduit runs.
SUB-CONTRACTOR:	# OF WORKERS:
ACTIVITIES:	•
SUB-CONTRACTOR:	# OF WORKERS:
ACTIVITIES:	
SUB-CONTRACTOR:	# OF WORKERS:
ACTIVITIES:	

<u>NOTES</u>
Contractors scheduled - who & when (upcoming schedule)
Inspection scheduled - when & what
Important conversation/phone call notes
Project/material delays
FIELD ISSUES
What is it? What is being/has been done? Expected resolution date?
INSPECTION REPORT
What inspection - corrections needed & when they are scheduled to be complete. Re-inspect date.