

PROJECT: CHS DATE:	Tuesday, May 12, 2015
REPORT BY: Rick Buhl	
MANPOWER DETAIL  SUB-CONTRACTOR: Brite Electric	# OF WORKERS: 2
ACTIVITIES: They continued working on power for lighting.	
SUB-CONTRACTOR: Ranor Drywall # OF WORKERS: 1  ACTIVITIES: He taped and skimmed the patch areas in the hall for can lighting and the existing part of the second floor for electrical.	
SUB-CONTRACTOR: Commercial Specialties  ACTIVITIES: They continued working on the T-bar Tiles.	# OF WORKERS: 2
SUB-CONTRACTOR: Step Above Flooring Tile  ACTIVITIES: One guy finished the tile on the second floor and the other too worked on ground the second floor and the other too worked on ground the second floor and the other too worked on ground the second floor and the other too worked on ground the second floor and the other too worked on ground the second floor and the other too worked on ground the second floor and the other too worked on ground the second floor and the other too worked on ground the second floor and the other too worked on ground the second floor and the second floor and the other too worked on ground the second floor and the other too worked on ground the second floor and the other too worked on ground the second floor and the second floor	# OF WORKERS: 3
SUB-CONTRACTOR: Step above flooring Carpet  ACTIVITIES: They continued working on carpet mainly counseling rooms.	# OF WORKERS: 4
SUB-CONTRACTOR: Advanced Security Technologies  ACTIVITIES:  He worked on the elevator fire alarm system.	# OF WORKERS: 1
SUB-CONTRACTOR: Dons Mobile Glass  ACTIVITIES: He took measurements for the glass.	# OF WORKERS: 1