

PROJECT: Keystone Pacific Warehouse

DATE: Tuesday, February 9, 2016

REPORT BY: Rick Buhl

MANPOWER DETAIL

SUB-CONTRACTOR: Phase 1 Construction

OF WORKERS:

ACTIVITIES:

They finished up the rebar and cleaned up the footings for inspection.

SUB-CONTRACTOR: layman Electric

OF WORKERS:

ACTIVITIES:

He installed the ufer groung in the footing.

NOTES

We are ready for concrete but the supplier is booked tomorrow morning so we will pooring concrete Thursday and Friday.

INSPECTION REPORT

foundation inspection which includes footings, piers, rebar, anchor bolts, and ufer ground - Passed