



SJI PART # 20187
TLC27L4ACN

SJI PART # 20185
CA3046 OR LM3086N



Note notch end for correct chip position



SJI PART # 20186
LT1079ACN

SJI PART NUMBER

CHIP PICTURE

20185

Most common chip to fail, we pack three of this chip inside CMT-3 for spares

Existing chip may look like either picture



20186



20187

