

CMS Contracting & Plant Hire Pty Ltd

ABN 73 143 852 411

10-12 Churchill Street, SILVERWATER NSW 2128

Ph 02 9647 1929

Email accounts@cmscontracting.com.au

www.cmscontracting.com.au



SERVICE & MAINTENANCE REPORT

Docket # 0041

DATE: 12-08-23 MAKE: Yanmar
 LOCATION OF JOB: Silverwater MODEL: Vio 17-1
 PLANT NO: X54 SERIAL NO: 12017
 REGO NO: _____ HOURS/KMS: 504

WORK REQUIRED: 500 HOUR SERVICE

WORK PERFORMED:
Change Engine oil & filter
" fuel filter
" hydraulic return filter
" outer air filter element
Top up hydraulic tank
check coolant, fan belt, water separator, radiator
grease
safety inspection

OUTSTANDING WORK REQUIRED:

CONSUMABLES: _____ HYDRAULIC OIL: 3 GREASE: 1
 ENGINE OIL: 3 GEAR OIL: _____ COOLANT: _____
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>3.5</u>	TOTAL KILOMETERS	
-------------	----------	--------------	------------	------------------	--

PLANT SAFETY CHECK	
Machine Hours	✓
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF
 Serviceperson: Trenton Van Loon
 Licence No.: _____
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.
 Signature: _____

NO: 18046

TUTT BRYANT EQUIPMENT



A Member of the Tutt Bryant Group

SYDNEY
TUTT BRYANT EQUIPMENT
6 FERRINGROVE PLACE,
SOUTH GRANVILLE NSW 2142
TEL: (02) 9780 7200
FAX: (02) 9780 7290

MELBOURNE
TUTT BRYANT EQUIPMENT
80-86 FRANKSTON -
DANDENONG ROAD
DANDENONG VIC 3175
TEL: (03) 9554 0300
FAX: (03) 9554 0398

BRISBANE
TUTT BRYANT EQUIPMENT
10-14 ASHOVER ROAD
ROCKLEA QLD 4106
TEL: (07) 3277 5422
FAX: (07) 3875 1680

PERTH
TUTT BRYANT EQUIPMENT
50 GREAT EASTERN HWY
SOUTH GUILDFORD WA 6055
TEL: (08) 9478 0600
FAX: (08) 9478 0688

ADELAIDE
TUTT BRYANT EQUIPMENT
908 MAIN NORTH ROAD
MAWSON LAKES SA 5095
TEL: (08) 8262 8292
FAX: (08) 8262 8320

Field Service Time Sheet and Report

DATE: 19-11-22 CUSTOMER O/NO: SALES TAX NO:

CLIENT: cms MACHINE: V3017-1 HOURS: 15.8

ADDRESS: SERIAL NO.: 12017 PLANT No.: X54

LOCATION OF JOB: Silverwater ENGINE NO: JOB NO:

DAY & DATE	TRAVELLING TIME						WORKING TIME						TRAVELLING		
	Start AM	Finish AM	Start PM	Finish PM	ORD	O/T	Start AM	Finish AM	Start AM	Finish PM	ORD	O/T	From	To	Km
	6:30	7					7	8:30							
	8:30	9													

WORK REQUIRED OR FAULT REPORTED: 150 hr Service

CAUSE OF FAILURE:

REPAIRS & TESTS:
Change Eng oil & filter
Fuel filter - a clean water separator
Hyd oil filter
Blew out radiator
Grease
Caring out safety inspection

CONTINGENCIES & TIMES LOST:

CONSUMABLES: \$	DIFF OIL: LTRS	COOLANT: LTRS						
ENGINE OIL: 5 LTRS	HYD OIL: 5 LTRS	GREASE: 1 CARTS						
TRANS OIL: LTRS	GEAR OIL: LTRS	ENVIRO COSTS: LTRS						
Date	Motor Expenses	Amount	Date	Accom/Meals	Amount	Date	Phone Calls/Misc	Amount
	Total \$		Total \$			Total \$		

Is job completed: All parts returned for credit: Approved:

Serviceperson: [Signature]
Signature:

I/We accept that the service and/or inspection has been completed, and Repairs and times indicated above are to my/our satisfaction. Client (or agent).

Signature: Not on site