CMS Contracting & Plant Hire Pty Ltd

ABN 73 143 852 411

10-12 Churchill Street, SILVERWATER NSW 2128

Ph 02 9647 1929 Email accounts@cmscontractir

Email accounts@cmscontracting.com.au www.cmscontracting.com.au CON



SERVICE & MAINTENANCE REPORT

Docket # 0039

w.cmscontracting.com.a	u	CONT	TRACTING	Docket # 0005
DATE:	12 -08	- 23	MAKE:	Sumitomo
OCATION OF JOB:		Cieen	MODEL:	SH145 X 6
	X58			145N6 - 1708
LANT NO:			SERIAL NO:	
EGO NO:			HOURS/KMS:	1024
WORK REQUIRED:	1000	Hour	SERVICE	
WORK PERFORMED:	change	4 x	oucket teet	h
	.1	engine o	il & filte	d .
	71	primary 8	Secondary	Avel filters
	11	•		pilot filters
	t00 110			
		hydraulic		
			rive & swit	
	11	air Alters	and cabi	n Rites
	Safety	inspection		
	grease	-		
	3 30.30			
OUTSTANDING WORK RE	QUIRED:	nge coolo	nt & hy	odraulic breather
element	next s	ervice		
CONSUMABLES:		HYDRAULIC OIL:	20	GREASE:
ENGINE OIL:	17	GEAR OIL:	8	COOLANT:
	<u>· </u>			
TRANS OIL:		DIFF OIL:	E	ENVIRO COSTS:
TRAVEL TIME	1	FIELD LABOUR	6	TOTAL KILOMETERS
PLANT SAFETY CHECK		√	(1)	
Machine Hours			SIGN OFF	
Lights, Warning Devices, Signs et Hydraulics – leaks, damage, conn				Tracks Vac Loss
Components – damage, broken	ections		Serviceperson:	Trenton Van Loon
Wheel/Tracks/Tyres – loose, nut			Licence No.:	
Pins – pivots, rams, lift arms, buc Guards – in place, secure, warnin			I goodh that the	nuice and for increastion has been associated all
Condition of hoods, sheaves, cha	ins		·	vice and/or inspection has been completed. All et a satisfactory standard. The times/quantities
Cabin – controls, loose objects, s	eat belts, windscreen visib	ility	indicated above are	
Warning lights/Gauges Operation of brakes, steering, co	ntrols, wipers, levers, buc	kets	Signature:	
Other – e.g. Fire Extinguisher, ele	ctrical connections, wires		Jignaturei	
Environmental spill kit complete Plant Security	& available			
	R TO COMPLETION			

CMS Contracting & Plant Hire Pty Ltd

ABN 73 143 852 411

LOCATION OF JOB:

10-12 Churchill Street, SILVERWATER NSW 21

Ph 02 9647 1929

PLANT NO:

DATE:

Email accounts@cmscontracting.com.au www.cmscontracting.com.au



SERVICE & RT

ERWATER NSW 2128		MAINTENANCE REPO	
cting.com.au u	CONTRACTING	Docket # 0027	
23 - 3 - 23	MAKE:	Sumitomo	
Oakville	MODEL:	SH145-6	
X58	SERIAL NO:	1708	

REGO NO:			HOURS/KMS:	571		
WORK REQUIRED:		500 HOUR	2 SERVICE			
WORK PERFORMED:	Change	engine oil	& filter			
			1			
		imary air f				
	check s	wing reducti	on hydrauli	c 1 coclant	levels	
	Chech	fan belt t	£ tension			
	grease					
	9					
	Satiety	in spection				
CONSUMABLES:	18		6		1	
TRANS OIL:		DIFF OIL:		ENVIRO COSTS:		
TRAVEL TIME	1	FIELD LABOUR	4	TOTAL KILOMETERS		
PLANT SAFETY CHECK						
Machine Hours	-		SIGN OFF			
Lights, Warning Devices, Sign	ns etc		SIGN OFF			
Hydraulics – leaks, damage,	connections		Serviceperson:	Trenton Vo	an Loon	
Components – damage, broken			Bei videpersoni			
Wheel/Tracks/Tyres – loose, nuts, wear			Licence No.:			
Pins – pivots, rams, lift arms			1			
Guards – in place, secure, warnings			I accept that the service and/or inspection has been completed. All			
Condition of hoods, sheaves Cabin – controls, loose object		visibility		repairs are complete to a satisfactory standard. The times/quantities		
Warning lights/Gauges	.is, seat peits, willustreen	VISIDITEY	indicated above are	correct.		
Operation of brakes, steerin	g. controls, wipers, levers	buckets	Signature			
Other – e.g. Fire Extinguishe			Signature:			
Environmental spill kit comp			1 <u></u>			
Plant Security						
VIP CHECK AROUND PLANT	PRIOR TO COMPLETION					