

CMS Contracting & Plant Hire Pty Ltd

ABN 73 143 852 411

10-12 Churchill Street, SILVERWATER NSW 2128

Ph 02 9647 1929

Email accounts@cmscontracting.com.au

www.cmscontracting.com.au



SERVICE & MAINTENANCE REPORT

Docket # 0042

DATE: 19-08-23 MAKE: Bobcat
 LOCATION OF JOB: Como MODEL: T76
 PLANT NO: PO9 SERIAL NO: B4CE16312
 REGO NO: _____ HOURS/KMS: 514

WORK REQUIRED: 500 HOUR SERVICE

WORK PERFORMED:
change engine oil & filter
" 3 hydraulic filters
" inner & outer air filters
top up hydraulic oil, coolant
check belt tension
clean water trap
tension loose tracks
test BICS, emergency arm, battery
clean HVAC plenum
grease & safety inspection

OUTSTANDING WORK REQUIRED:
final drives to be changed
coolant leak, broken bucket tilt angle sensor

CONSUMABLES: _____ HYDRAULIC OIL: 2 GREASE: 1
 ENGINE OIL: 7 GEAR OIL: _____ COOLANT: 3
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>4.75</u>	TOTAL KILOMETERS	
-------------	----------	--------------	-------------	------------------	--

PLANT SAFETY CHECK	
Machine Hours	
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF
 Serviceperson: Trenton Van Loan
 Licence No.: _____
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.
 Signature: _____



Sydney's Earthmoving Services

Plant Maintenance

0416 126 604 • PO Box 1147 Epping 1710 • ABN 46 945 841 584

Field Service Time Sheet and Report

2457

DATE: 17-12-22 CUSTOMER O/No: HOURS: 2.66
 CLIENT: cms MACHINE: T76 PLANT No: P09
 ADDRESS: SERIAL No: B4CE16312 REGO No: 27238-E
 LOCATION OF JOB: House Hill ENGINE No: JOB No: 3657

WORK REQUIRED
 2.50 hr Service

WORK PERFORMED
 change Eng oil & filter
 Fuel Filters
 Air cleaner
 Blow out radiator
 A/C Filters
 Grease
 Carry out safety inspection

OUTSTANDING WORK REQUIRED

CONSUMABLES \$ HYD OIL 5 LITRES GREASE 1
 ENGINE OIL 7 LITRES GEAR OIL LITRES COOLANT LITRES
 TRANS OIL LITRES DIFF OIL LITRES ENVIRO COSTS LITRES

TRAVEL TIME	FIELD LABOUR	W/SHOP LABOUR	TOTAL KLMS
1	1.5		

Serviceperson: Scott Mangan

Licence No.: 212 101 703 097 171

Signature: 

I / We accept that the service and / or inspection has been completed, and repairs and times indicated above are to my/our satisfaction. Client (or agent).

Signature:  Not on site

DESIGNATION: WHITE CUSTOMER - PINK OFFICE - YELLOW SERVICE PERSON