

CMS Contracting & Plant Hire Pty Ltd

ABN 73 143 852 411

10-12 Churchill Street, SILVERWATER NSW 2128

Ph 02 9647 1929

Email accounts@cmscontracting.com.au

www.cmscontracting.com.au



CONTRACTING

SERVICE & MAINTENANCE REPORT

Docket # 0046

DATE: 10 - 9 - 2023 MAKE: Kubota
 LOCATION OF JOB: Silverwater MODEL: U48-4
 PLANT NO: X47 SERIAL NO: 20167
 REGO NO: _____ HOURS/KMS: 3020

WORK REQUIRED: 3000 HOUR SERVICE

WORK PERFORMED:
Change engine oil & filter
" fuel filter & drain water separator
" hydraulic oil & 3 filters
" final drive oil
clean hydraulic breather & air precleaner
top up coolant
change air filters
check belts, tracks & track rollers
clean radiator
grease & safety inspection

OUTSTANDING WORK REQUIRED:
change hydraulic tank drain plug
next service.

CONSUMABLES: _____ HYDRAULIC OIL: 45 GREASE: 1
 ENGINE OIL: 10 GEAR OIL: 3 COOLANT: 1
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>5</u>	TOTAL KILOMETERS	
--------------------	----------	---------------------	----------	-------------------------	--

PLANT SAFETY CHECK	✓
Machine Hours	
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF

Serviceperson: Trenton Van Loon

Licence No.: _____

I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Signature: _____



Sydney's Earthmoving Services

Plant Maintenance

0416 126 604 • PO Box 1147 Epping 1710 • ABN 46 945 841 584

Field Service Time Sheet and Report

2492

DATE: 16-2-23 CUSTOMER O/No: HOURS: 2760
 CLIENT: CMS Group MACHINE: UH3-4 PLANT No: X47
 ADDRESS: SERIAL No: 20167 REGO No:
 LOCATION OF JOB: Camm ENGINE No: JOB No: 3692

WORK REQUIRED

2750 hr Service

WORK PERFORMED

change Eng. oil & filter
 " Fuel filter & clean water separator
 " L.R. Travel oils
 " Air cleaner
 " Hyd. oil filters
 Blow out radiator
 Adjust main fan belt
 Grease
 Carry out safety inspection.

OUTSTANDING WORK REQUIRED

CONSUMABLES \$ HYD OIL 10 LITRES GREASE 1
 ENGINE OIL 10 LITRES GEAR OIL 3 LITRES COOLANT LITRES
 TRANS OIL LITRES DIFF OIL LITRES ENVIRO COSTS LITRES

TRAVEL TIME	FIELD LABOUR	W/SHOP LABOUR	TOTAL KLMS
1.5	2		

Serviceperson: Scott Mangan

Licence No.: 212 101 703 097 171

Signature: 

I / We accept that the service and / or inspection has been completed, and repairs and times indicated above are to my/our satisfaction. Client (or agent).

Signature: 

DESIGNATION: WHITE CUSTOMER - PINK OFFICE - YELLOW SERVICE PERSON