

CMS Contracting & Plant Hire Pty Ltd
 ABN 73 143 852 411
 10-12 Churchill Street, SILVERWATER NSW 2128
 Ph 02 9647 1929
 Email accounts@cmscontracting.com.au
 www.cmscontracting.com.au



SERVICE & MAINTENANCE REPORT

Docket # 0044

DATE: 9-9-2023 MAKE: Yanmar
 LOCATION OF JOB: Kemps Creek MODEL: Vic 82
 PLANT NO: X48 SERIAL NO: 524
 REGO NO: _____ HOURS/KMS: 3558

WORK REQUIRED: 3500 HOUR SERVICE

WORK PERFORMED:
change engine oil & filter
" fuel filter & drain water separator
tighten engine belts
change final drives
replace air filter
check coolant & radiator
change hydraulic return filter
grease
safety inspection

OUTSTANDING WORK REQUIRED:

CONSUMABLES: _____ HYDRAULIC OIL: _____ GREASE: 1
 ENGINE OIL: 10.5 GEAR OIL: 3 COOLANT: 1
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

| | | | | | |
|--------------------|----------|---------------------|-------------|-------------------------|--|
| TRAVEL TIME | <u>1</u> | FIELD LABOUR | <u>3.25</u> | TOTAL KILOMETERS | |
|--------------------|----------|---------------------|-------------|-------------------------|--|

| | |
|--|---|
| PLANT SAFETY CHECK | ✓ |
| Machine Hours | |
| Lights, Warning Devices, Signs etc | |
| Hydraulics – leaks, damage, connections | |
| Components – damage, broken | |
| Wheel/Tracks/Tyres – loose, nuts, wear | |
| Pins – pivots, rams, lift arms, bucket pins | |
| Guards – in place, secure, warnings | |
| Condition of hoods, sheaves, chains | |
| Cabin – controls, loose objects, seat belts, windscreen visibility | |
| Warning lights/Gauges | |
| Operation of brakes, steering, controls, wipers, levers, buckets | |
| Other – e.g. Fire Extinguisher, electrical connections, wires etc | |
| Environmental spill kit complete & available | |
| Plant Security | |
| VIP CHECK AROUND PLANT PRIOR TO COMPLETION | |

SIGN OFF
 Serviceperson: Trenton Van Loan
 Licence No.: _____
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.
 Signature: _____



Sydney's Earthmoving Services

Plant Maintenance

0416 126 604 • PO Box 1147 Epping 1710 • ABN 46 945 841 584

Field Service Time Sheet and Report

2496

DATE: 21-2-23 CUSTOMER O/No: HOURS: 3090
 CLIENT: cms MACHINE: 12082 PLANT No: X48
 ADDRESS: SERIAL No: 00524 REGO No:
 LOCATION OF JOB: Kareek ENGINE No: JOB No: 3696

WORK REQUIRED

3000hr Service

WORK PERFORMED

change Eng oil & filters

Fuel filters

I.O air cleaner

A/C Filter

A/C Belt

Main fan belt

Coolant

Hyd oil & filters

Leak Taps out

Cutting edge

Re-shim C.U area

Grease

Blow out radiator

carry out safety inspection

R.R. L.H Rubber Track

OUTSTANDING WORK REQUIRED

CONSUMABLES \$ HYD OIL 65 LITRES GREASE 1
 ENGINE OIL 10 LITRES GEAR OIL 3 LITRES COOLANT 1 LITRES
 TRANS OIL LITRES DIFF OIL LITRES ENVIRO COSTS LITRES

| TRAVEL TIME | FIELD LABOUR | W/SHOP LABOUR | TOTAL KLMS |
|-------------|--------------|---------------|------------|
| 1.5 | 3.5 | | |

Serviceperson: Scott Mangan

Licence No.: 212 101 703 097 171

Signature: 

I / We accept that the service and / or inspection has been completed, and repairs and times indicated above are to my/our satisfaction. Client (or agent).

Signature: 

DESIGNATION: WHITE CUSTOMER - PINK OFFICE - YELLOW SERVICE PERSON