

CMS Contracting & Plant Hire Pty Ltd
 ABN 73 143 852 411
 10-12 Churchill Street, SILVERWATER NSW 2128
 Ph 02 9647 1929
 Email accounts@cmscontracting.com.au
 www.cmscontracting.com.au



SERVICE & MAINTENANCE REPORT
Docket # 0056

DATE: 10-11-23 MAKE: Yanmar
 LOCATION OF JOB: Silverwater MODEL: Vic82
 PLANT NO: X50 SERIAL NO: 532
 REGO NO: _____ HOURS/KMS: 3000

WORK REQUIRED: 3000 HOUR SERVICE

WORK PERFORMED:
Change engine oil + filter
" fuel filter + water separator changed
" both air filters
" hydraulic return filter + clean suction filter
" hydraulic pilot filter + oil
Tension fan belts
Fill up washer bottle + repair windscreen wiper
Clean cab filters
Grease + safety inspection
+ change gear oil

OUTSTANDING WORK REQUIRED: Isolator not isolating correctly

CONSUMABLES: _____ HYDRAULIC OIL: 50 GREASE: 1
 ENGINE OIL: 10 GEAR OIL: 4 COOLANT: 1
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>5.25</u>	TOTAL KILOMETERS	
-------------	----------	--------------	-------------	------------------	--

PLANT SAFETY CHECK	<input checked="" type="checkbox"/>
Machine Hours	
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF
 Serviceperson: Trenton van Loon
 Licence No.: _____
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.
 Signature: _____



Sydney's Earthmoving Services

Plant Maintenance

0416 126 604 • PO Box 1147 Epping 1710 • ABN 46 945 841 584

Field Service Time Sheet and Report

2452

DATE: 3-11-22 CUSTOMER O/No: HOURS: 2462
 CLIENT: CMS MACHINE: 150 82 PLANT No: X50
 ADDRESS: SERIAL No: 00532 REGO No:
 LOCATION OF JOB: Mosman ENGINE No: JOB No: 3652

WORK REQUIRED

2500hr Service

WORK PERFORMED

change Eng oil & filter
 " Fuel filters
 " Hyd oil filters
 " Air cleaner
 " L.R Travel oils
 Blow out radiator
 " A/C Filter
 Grease
 carry out safety inspection

OUTSTANDING WORK REQUIRED

CONSUMABLES \$ HYD OIL 10 LITRES GREASE 1
 ENGINE OIL 10 LITRES GEAR OIL 4 LITRES COOLANT LITRES
 TRANS OIL LITRES DIFF OIL LITRES ENVIRO COSTS LITRES

TRAVEL TIME	FIELD LABOUR	W/SHOP LABOUR	TOTAL KLMS
1.5	2		

Serviceperson: Scott Mangan

Licence No.: 212 101 703 097 171

Signature:

I / We accept that the service and / or inspection has been completed, and repairs and times indicated above are to my/our satisfaction. Client (or agent).

Signature: Not on site

DESIGNATION: WHITE CUSTOMER - PINK OFFICE - YELLOW SERVICE PERSON