

CMS Contracting & Plant Hire Pty Ltd
 ABN 73 143 852 411
 10-12 Churchill Street, SILVERWATER NSW 2128
 Ph 02 9647 1929
 Email accounts@cmscontracting.com.au
 www.cmscontracting.com.au



SERVICE & MAINTENANCE REPORT

Docket # 0055

DATE: 26-10-23 MAKE: Kubota
 LOCATION OF JOB: Silverwater MODEL: U35-4
 PLANT NO: X46 SERIAL NO: 14564
 REGO NO: _____ HOURS/KMS: 3022

WORK REQUIRED: 3000 HOUR SERVICE

WORK PERFORMED:
Change engine oil & filter
" fuel filter & clean water separator
" hydraulic oil / suction & return filters
Top up cooling system
Adjust fan belt & track tension
Change air cleaners
" pit filter.
" final drive oil
Grease & safety inspection

OUTSTANDING WORK REQUIRED:

CONSUMABLES: _____ HYDRAULIC OIL: 35 GREASE: _____
 ENGINE OIL: 7 GEAR OIL: 2 COOLANT: 1
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>4.5</u>	TOTAL KILOMETERS	
-------------	----------	--------------	------------	------------------	--

PLANT SAFETY CHECK	
Machine Hours	✓
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF

Serviceperson: Trenton Van Loon

Licence No.: _____

I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Signature: _____

CMS Contracting & Plant Hire Pty Ltd

ABN 73 143 852 411

10-12 Churchill Street, SILVERWATER NSW 2128

Ph 02 9647 1929

Email accounts@cmscontracting.com.au

www.cmscontracting.com.au



SERVICE & MAINTENANCE REPORT

Docket # 0031

DATE: 28-5-23 MAKE: Kubota
 LOCATION OF JOB: Silverwater MODEL: U35-4
 PLANT NO: X46 SERIAL NO: 14564
 REGO NO: _____ HOURS/KMS: 2789

WORK REQUIRED: 2750 HOUR SERVICE

WORK PERFORMED: change engine oil + filter
drain water separator
clean air filters
top up hydraulic oil
check fan belt, coolant etc
clean radiator
grease
safety inspection

OUTSTANDING WORK REQUIRED: _____

CONSUMABLES: _____ HYDRAULIC OIL: 5 GREASE: 1
 ENGINE OIL: 7 GEAR OIL: _____ COOLANT: _____
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u>/</u>	FIELD LABOUR	<u>2</u>	TOTAL KILOMETERS	
-------------	----------	--------------	----------	------------------	--

PLANT SAFETY CHECK	<input checked="" type="checkbox"/>
Machine Hours	
Lights, Warning Devices, Signs etc	
Hydraulics - leaks, damage, connections	
Components - damage, broken	
Wheel/Tracks/Tyres - loose, nuts, wear	
Pins - pivots, rams, lift arms, bucket pins	
Guards - in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin - controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other - e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF
 Serviceperson: Trenton Van Loon
 Licence No.: _____
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.
 Signature: _____