

CMS Contracting & Plant Hire Pty Ltd
 ABN 73 143 852 411
 10-12 Churchill Street, SILVERWATER NSW 2128
 Ph 02 9647 1929
 Email accounts@cmscontracting.com.au
 www.cmscontracting.com.au



SERVICE & MAINTENANCE REPORT

Docket # 0053

DATE: 30-10-2023 MAKE: AVSA
 LOCATION OF JOB: Silverwater MODEL: 0600 APG
 PLANT NO: D109 SERIAL NO: 64075270
 REGO NO: _____ HOURS/KMS: 2040

WORK REQUIRED: 2000 HOUR SERVICE

WORK PERFORMED:
Change engine oil & filters
" air filters
Tension fan belt
Top up coolant
Install new hoseclamps on suction line from tank
Change hydraulic oil (filter wrong not replaced)
Check final drive oil (change next service)
Top up transmission oil
Change brake fluid
Grease + safety inspection

OUTSTANDING WORK REQUIRED:
New master cylinder, New hydraulic tank,
New hydraulic suction filter (wrong), new fuel filter (wrong), Trans filter

CONSUMABLES: BRAKE FLUID HYDRAULIC OIL: 50 GREASE: 1
 ENGINE OIL: 12 GEAR OIL: _____ COOLANT: 1
 TRANS OIL: 2 DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>10</u>	TOTAL KILOMETERS	
--------------------	----------	---------------------	-----------	-------------------------	--

PLANT SAFETY CHECK	
Machine Hours	✓
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF
 Serviceperson: Trenton Van Loon
 Licence No.: _____
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.
 Signature: _____

CMS Contracting & Plant Hire Pty Ltd

ABN 73 143 852 411

10-12 Churchill Street, SILVERWATER NSW 2128

Ph 02 9647 1929

Email accounts@cmscontracting.com.au

www.cmscontracting.com.au



SERVICE & MAINTENANCE REPORT

Docket # 0035

DATE: 20.07.2023 MAKE: AUSA
 LOCATION OF JOB: SILVERWATER MODEL: D600
 PLANT NO: D109 SERIAL NO: 64075270
 REGO NO: _____ HOURS/KMS: 1859

WORK REQUIRED: 1850 HR SERVICE

WORK PERFORMED:
CHANGE ENGINE OIL + FILTER
CHANGE FUEL FILTERS
CHECK ALL LEVELS
GREASE
SAFETY INSPECTION

OUTSTANDING WORK REQUIRED:

CONSUMABLES: _____ HYDRAULIC OIL: _____ GREASE: 1
 ENGINE OIL: 8 GEAR OIL: _____ COOLANT: _____
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u> </u>	FIELD LABOUR	<u>2.5</u>	TOTAL KILOMETERS	<u> </u>
--------------------	-----------------------------	---------------------	------------	-------------------------	-----------------------------

PLANT SAFETY CHECK	
Machine Hours	<u>1859</u> ✓
Lights, Warning Devices, Signs etc	✓
Hydraulics – leaks, damage, connections	✓
Components – damage, broken	✓
Wheel/Tracks/Tyres – loose, nuts, wear	✓
Pins – pivots, rams, lift arms, bucket pins	✓
Guards – in place, secure, warnings	✓
Condition of hoods, sheaves, chains	✓
Cabin – controls, loose objects, seat belts, windscreen visibility	✓
Warning lights/Gauges	✓
Operation of brakes, steering, controls, wipers, levers, buckets	✓
Other – e.g. Fire Extinguisher, electrical connections, wires etc	✓
Environmental spill kit complete & available	✓
Plant Security	✓
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF
 Serviceperson: TRENTON VAN LOON
 Licence No.: _____
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.
 Signature: _____