

CMS Contracting & Plant Hire Pty Ltd

ABN 73 143 852 411
 10-12 Churchill Street, SILVERWATER NSW 2128
 Ph 02 9647 1929
 Email accounts@cmscontracting.com.au
 www.cmscontracting.com.au



CONTRACTING

SERVICE & MAINTENANCE REPORT

Docket # 0061

DATE: 23 / 11 / 23 MAKE: Yanmar
 LOCATION OF JOB: Silverwater MODEL: Vio 55-6
 PLANT NO: X56 SERIAL NO: BH676
 REGO NO: _____ HOURS/KMS: 1005

WORK REQUIRED: 1000 HOUR SERVICE

WORK PERFORMED: Change engine oil & filter
" fuel filter & water separator + clean bowl
check belts , top up overflow bottle
inspect radiator , fill washer bottle
change both air filters
" hydraulic oil & return filter + clean suction filter
clean cab filters
change final drive oil
safety inspection + grease

OUTSTANDING WORK REQUIRED: _____

CONSUMABLES: _____ HYDRAULIC OIL: 36 GREASE: 1
 ENGINE OIL: 7.4 GEAR OIL: 1 COOLANT: _____
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>3.75</u>	TOTAL KILOMETERS	
-------------	----------	--------------	-------------	------------------	--

PLANT SAFETY CHECK	✓	SIGN OFF Serviceperson: <u>Trenton Van Loon</u> Licence No.: _____ I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct. Signature: _____
Machine Hours		
Lights, Warning Devices, Signs etc		
Hydraulics – leaks, damage, connections		
Components – damage, broken		
Wheel/Tracks/Tyres – loose, nuts, wear		
Pins – pivots, rams, lift arms, bucket pins		
Guards – in place, secure, warnings		
Condition of hoods, sheaves, chains		
Cabin – controls, loose objects, seat belts, windscreen visibility		
Warning lights/Gauges		
Operation of brakes, steering, controls, wipers, levers, buckets		
Other – e.g. Fire Extinguisher, electrical connections, wires etc		
Environmental spill kit complete & available		
Plant Security		
VIP CHECK AROUND PLANT PRIOR TO COMPLETION		

CMS Contracting & Plant Hire Pty Ltd

ABN 73 143 852 411

10-12 Churchill Street, SILVERWATER NSW 2128

Ph 02 9647 1929

Email accounts@cmscontracting.com.au

www.cmscontracting.com.au

**CONTRACTING****SERVICE & MAINTENANCE REPORT****Docket # 0036**

DATE: 26 - 07 - 23 MAKE: Yanmar
 LOCATION OF JOB: Como MODEL: VIO55-6B
 PLANT NO: X56 SERIAL NO: BH676
 REGO NO: _____ HOURS/KMS: 765

WORK REQUIRED: 750 HOUR SERVICE

WORK PERFORMED: change engine oil & filter
top up hydraulic oil
check coolant, final drives, radiator, fan belt
grease
drain water separator
safety inspection

OUTSTANDING WORK REQUIRED: _____

CONSUMABLES: _____ HYDRAULIC OIL: 8 GREASE: 1
 ENGINE OIL: 8 GEAR OIL: _____ COOLANT: _____
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>2</u>	TOTAL KILOMETERS	
-------------	----------	--------------	----------	------------------	--

PLANT SAFETY CHECK	
Machine Hours	✓
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF
 Serviceperson: Trenton Van Loon
 Licence No.: _____
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.
 Signature: _____