

**CMS Contracting & Plant Hire Pty Ltd**  
 ABN 73 143 852 411  
 10-12 Churchill Street, SILVERWATER NSW 2128  
 Ph 02 9647 1929  
 Email accounts@cmscontracting.com.au  
 www.cmscontracting.com.au



**SERVICE & MAINTENANCE REPORT**

**Docket # 0063**

DATE: 16-12-23 MAKE: Sumitomo  
 LOCATION OF JOB: manly vale MODEL: SH145-6  
 PLANT NO: X53 SERIAL NO: 1485  
 REGO NO: \_\_\_\_\_ HOURS/KMS: 3043

**WORK REQUIRED:** 3000 HOUR SERVICE

---

**WORK PERFORMED:**  
change engine oil & filter  
" primary & secondary fuel filters  
Top up hydraulic oil  
Change final drive oil + swing drive oil  
Clean fuel pump + change filter  
change primary + secondary air filter  
Top up coolant  
change cab filters  
change hydraulic breather element  
Safety inspection + grease

**OUTSTANDING WORK REQUIRED:**

---

CONSUMABLES: \_\_\_\_\_ HYDRAULIC OIL: 25 GREASE: 1  
 ENGINE OIL: 17 GEAR OIL: 5 COOLANT: 1  
 TRANS OIL: \_\_\_\_\_ DIFF OIL: \_\_\_\_\_ ENVIRO COSTS: \_\_\_\_\_

<b>TRAVEL TIME</b>	<u>1</u>	<b>FIELD LABOUR</b>	<u>6</u>	<b>TOTAL KILOMETERS</b>	
--------------------	----------	---------------------	----------	-------------------------	--

PLANT SAFETY CHECK	
Machine Hours	✓
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

**SIGN OFF**  
 Serviceperson: Trenton Van Loon  
 Licence No.: \_\_\_\_\_  
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.  
 Signature: \_\_\_\_\_

**CMS Contracting & Plant Hire Pty Ltd**

ABN 73 143 852 411  
 10-12 Churchill Street, SILVERWATER NSW 2128  
 Ph 02 9647 1929  
 Email accounts@cmscontracting.com.au  
 www.cmscontracting.com.au



**SERVICE & MAINTENANCE REPORT**

**Docket # 0028**

DATE: 5-4-23 MAKE: Sumitomo  
 LOCATION OF JOB: Minchinbury MODEL: SH145-6  
 PLANT NO: X53 SERIAL NO: 1485  
 REGO NO: \_\_\_\_\_ HOURS/KMS: 2546

WORK REQUIRED: 2500 HOUR SERVICE

WORK PERFORMED:  
Change engine oil & filter  
" fuel filters  
" final drive oil  
" air filters  
" air con / cabin filter  
check swing reduction, hydraulic & coolant levels  
check belt tension  
inspect radiator hoses, cleaned radiator  
drained water separator (rust evident)  
grease + safety inspection.

OUTSTANDING WORK REQUIRED:  
 \_\_\_\_\_  
 \_\_\_\_\_

CONSUMABLES: \_\_\_\_\_ HYDRAULIC OIL: 10 GREASE: 1  
 ENGINE OIL: 18 GEAR OIL: 6 COOLANT: \_\_\_\_\_  
 TRANS OIL: \_\_\_\_\_ DIFF OIL: \_\_\_\_\_ ENVIRO COSTS: \_\_\_\_\_

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>4</u>	TOTAL KILOMETERS	
-------------	----------	--------------	----------	------------------	--

PLANT SAFETY CHECK	<input checked="" type="checkbox"/>
Machine Hours	
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

**SIGN OFF**  
 Serviceperson: Trenton Van Leen  
 Licence No.: \_\_\_\_\_  
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.  
 Signature: \_\_\_\_\_