

CMS Contracting & Plant Hire Pty Ltd
 ABN 73 143 852 411
 10-12 Churchill Street, SILVERWATER NSW 2128
 Ph 02 9647 1929
 Email accounts@cmscontracting.com.au
 www.cmscontracting.com.au



SERVICE & MAINTENANCE REPORT

Docket # 0064

DATE: 5-1-24 MAKE: Takeuchi
 LOCATION OF JOB: Silverwater MODEL: TB215R
 PLANT NO: X60 SERIAL NO: 215002024
 REGO NO: _____ HOURS/KMS: 530

WORK REQUIRED: 500 HOUR SERVICE

WORK PERFORMED:
Change engine oil & filter
" fuel filter & water separator filter
" hydraulic oil return filter
check hydraulics, coolant, belt, radiator
grease
safety inspection
clean air cleaner

OUTSTANDING WORK REQUIRED:

CONSUMABLES: _____ HYDRAULIC OIL: 1 GREASE: 1
 ENGINE OIL: 4.3 GEAR OIL: _____ COOLANT: _____
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME		FIELD LABOUR	<u>2</u>	TOTAL KILOMETERS	
-------------	--	--------------	----------	------------------	--

PLANT SAFETY CHECK	✓
Machine Hours	
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF
 Serviceperson: Les Nicholas
 Licence No.: _____
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.
 Signature: _____

CMS Contracting & Plant Hire Pty Ltd

ABN 73 143 852 411

10-12 Churchill Street, SILVERWATER NSW 2128

Ph 02 9647 1929

Email accounts@cmscontracting.com.au

www.cmscontracting.com.au



SERVICE & MAINTENANCE REPORT

Docket # 0047

DATE: 10-9-23 MAKE: Takeuchi
 LOCATION OF JOB: Silverwater MODEL: TB215R
 PLANT NO: X60 SERIAL NO: 215002024
 REGO NO: _____ HOURS/KMS: 355

WORK REQUIRED: 250 HOUR SERVICE

WORK PERFORMED:
Change engine oil & filter
Top up hydraulic oil
Change final drive oil
Grease
Safety inspection
Clean water separator
Cleaned air cleaner - replace next service.

OUTSTANDING WORK REQUIRED:

CONSUMABLES: _____ HYDRAULIC OIL: 2.5 GREASE: 1
 ENGINE OIL: 4.3 GEAR OIL: 2 COOLANT: _____
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>2</u>	TOTAL KILOMETERS	
-------------	----------	--------------	----------	------------------	--

PLANT SAFETY CHECK	
Machine Hours	✓
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF
 Serviceperson: Trenton Van Loon
 Licence No.: _____
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.
 Signature: _____