

CMS Contracting & Plant Hire Pty Ltd
 ABN 73 143 852 411
 10-12 Churchill Street, SILVERWATER NSW 2128
 Ph 02 9647 1929
 Email accounts@cmscontracting.com.au
 www.cmscontracting.com.au



Docket No. 1310

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date	8:27 PM, 18th Feb, 2024	Make	
Asset	X52	Model	
Rego Nbr		Serial Number	
Location of job	Yard	Hours/Odometer	2356
Completed by	Trenton Van Loon	Licence Number	Trenton van Loon

Work Required	250 hour service
---------------	------------------

Work Performed	Engine oil and filter changed Fuel filter changed Check fan belt - ok Check coolant level in radiator and bottle - ok Check radiator for leaks and cleanliness- ok Change outer airfilter Check track tension Check cab - ROPS/seatbelt/extinguisher - ok One light not working on boom Reset service meter Grease machine Also repaired plate compactor pull cord
----------------	--

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease			
Consumables	Rags, gloves, brake cleaner	Hydraulic Oil	Grease 1
Engine Oil	7	Gear Oil	Coolant
Trans Oil		Diff Oil	Enviro Costs

Additional Job Notes	Starter cord replaced on plate compactor
----------------------	--

Plant Safety Check - Please tick all that have been checked:	
<ul style="list-style-type: none"> ✓ Lights, Warning Devices, Signs etc ✓ Hydraulics - leaks damage connections ✓ Components - damage, broken ✓ Wheel/Tracks/Tyres - loose, nuts, wear ✓ Pins - pivots, rams, lift arms, bucket pins ✓ Guards - in place, secure, warnings 	<ul style="list-style-type: none"> ✓ Condition of hoods, sheaves, chains ✓ Cabin - controls, loose objects, seat belts, windscreen visibility ✓ Warning lights / gauges ✓ Operation of brakes, steering, controls, wipers, levers, buckets ✓ Other - eg: fire extinguisher, electrical connections, wires etc ✓ Environmental Spill Kit complete & available ✓ Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time	Field Labour	2.1	Total Kilometers
-------------	--------------	------------	------------------

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Trenton Van Loon
Licence No:	Trenton van Loon
Signature:	



CONTRACTING

SERVICE & MAINTENANCE REPORT

Docket # 0043

DATE: 31 - 07 - 2023 MAKE: Yanmar
 LOCATION OF JOB: Silverwater MODEL: Vio 55-6
 PLANT NO: XS2 SERIAL NO: BG214
 REGO NO: _____ HOURS/KMS: 2009

WORK REQUIRED: 2000 HOUR SERVICE

- WORK PERFORMED:
- Change engine oil & filter
 - " fuel filter & clean water separator
 - top up coolant
 - tension belts & tracks
 - drain & refill hydraulic oil - change suction
 - change air filters & return filters
 - " cabin filter & cleaned gauze filter
 - grease
 - wash out radiator
 - change gear oil (final drives)

OUTSTANDING WORK REQUIRED: - Safety inspection

CONSUMABLES: _____ HYDRAULIC OIL: 36 GREASE: 1
 ENGINE OIL: 8 GEAR OIL: 3 COOLANT: 1
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>6</u>	TOTAL KILOMETERS	
-------------	----------	--------------	----------	------------------	--

PLANT SAFETY CHECK	
Machine Hours	<u>2009</u>
Lights, Warning Devices, Signs etc	✓
Hydraulics – leaks, damage, connections	✓
Components – damage, broken	✓
Wheel/Tracks/Tyres – loose, nuts, wear	✓
Pins – pivots, rams, lift arms, bucket pins	✓
Guards – in place, secure, warnings	✓
Condition of hoods, sheaves, chains	✓
Cabin – controls, loose objects, seat belts, windscreen visibility	✓
Warning lights/Gauges	✓
Operation of brakes, steering, controls, wipers, levers, buckets	✓
Other – e.g. Fire Extinguisher, electrical connections, wires etc	✓
Environmental spill kit complete & available	✓
Plant Security	✓
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	✓

SIGN OFF
 Serviceperson: Trenton Van Loon
 Licence No.: _____
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.
 Signature: _____