

CMS Contracting & Plant Hire Pty Ltd
 ABN 73 143 852 411
 10-12 Churchill Street, SILVERWATER NSW 2128
 Ph 02 9647 1929
 Email accounts@cmscontracting.com.au
 www.cmscontracting.com.au



Docket No. 2584

SERVICE & MAINTENANCE REPORT

To be completed by a licensed servicer.

Date	2:16 PM, 4th Feb, 2024	Make	
Asset	X55 - 6T Excavator	Model	
Rego Nbr		Serial Number	
Location of job	Queens Park	Hours/Odometer	1049
Completed by	Trenton Van Loon	Licence Number	Trenton van Loon

Work Required	1000 hour service
---------------	-------------------

Work Performed	Engine oil and filter changed Fuel filter changes Clean water separator and replace element Hydraulic return filter changed Hydraulic oil changed - was vmbelow site glass level on arrival Change air filters inner and outer - very clogged Top up washer bottle Top up coolant check level in radiator - ok Drain deposits from fuel tank Check radiatir - ok Check fan belt tension Check wipers and top up wahser Check track tension - ok Check track rollers - ok Change final drive oil Change AC filters - both clogged Test lights/seatbelt/AC - OK Check extinguisher - ok ROPS - ok Grease machine Reset service meter
----------------	--

Outstanding Work Required	Conduct Prestarts to ensure Hydraulic oil level is ok
---------------------------	---

Consumables/Oils/Grease					
Consumables	Gloves rags, brake cleaner,	Hydraulic Oil	38	Grease	1
Engine Oil	8	Gear Oil	2	Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	Went to yard - Empty oil and restock spare oil that was used from Sumitomo service last year Fill up oil for this service and next service Collect fuel card Fill brake cleaner
----------------------	---

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time	0.5	Field Labour	5.5	Total Kilometers	24
-------------	------------	--------------	------------	------------------	-----------

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Trent van Loon
Licence No:	Trenton van Loon
Signature:	



CMS Contracting & Plant Hire Pty Ltd
 ABN 73 143 852 411
 10-12 Churchill Street, SILVERWATER NSW 2128
 Ph 02 9647 1929
 Email accounts@cmscontracting.com.au
 www.cmscontracting.com.au



SERVICE & MAINTENANCE REPORT

Docket # 0057

DATE: 11 - 11 - 23 MAKE: Yanmar
 LOCATION OF JOB: Kemps Creek MODEL: VO 55-6
 PLANT NO: X55 SERIAL NO: BH675
 REGO NO: _____ HOURS/KMS: 817

WORK REQUIRED: 750 HOUR SERVICE

WORK PERFORMED:
Change engine oil + filter
" fuel filter + clean water separator
replaced outer air filter
top up hydraulic oil
check belts.
grease + safety inspection
Fixed wiring on work light.

OUTSTANDING WORK REQUIRED:

CONSUMABLES: _____ HYDRAULIC OIL: 4 GREASE: 1
 ENGINE OIL: 8 GEAR OIL: _____ COOLANT: _____
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>2</u>	TOTAL KILOMETERS	
-------------	----------	--------------	----------	------------------	--

PLANT SAFETY CHECK	✓
Machine Hours	
Lights, Warning Devices, Signs etc	
Hydraulics - leaks, damage, connections	
Components - damage, broken	
Wheel/Tracks/Tyres - loose, nuts, wear	
Pins - pivots, rams, lift arms, bucket pins	
Guards - in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin - controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other - e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF

Serviceperson: Trenton Van Loon

Licence No.: _____

I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Signature: _____