## CMS Contracting & Plant Hire Pty Ltd

ABN 73 143 852 411

10-12 Churchill Street, SILVERWATER NSW 2128

Ph 02 9647 1929

Email accounts@cmscontracting.com.au

www.cmscontracting.com.au



Docket No. 1305

## **SERVICE & MAINTENANCE REPORT**

Work to be completed by a licensed mechanic

Date	10:57 AM, 18th Feb, 2024	Make	
Asset	D112	Model	
Rego Nbr		Serial Number	
Location of job	Yard	Hours/Odometer	105
Completed by	Trenton Van Loon	Licence Number	Trenton van Loon

Work Required	100 hour service
Work Performed	Engine oil and filter changed Check hydraulic oil level Air filter Clean prefilter Tension
	tracks Check park brake - ok Grease machine

## Outstanding Work Required

Additional Job Notes

Consumables/Oils/Grease					
Consumables	Rags, gloves, brake cleaner	Hydraulic Oil	Grease	1	
Engine Oil	1	Gear Oil	Coolant		
Trans Oil		Diff Oil	Enviro Costs	1	

[	Plant Safety Check - Please tick all that have been checked:				
		Lights, Warning Devices, Signs etc		Condition of hoods, sheaves, chains	
-		Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility	
	✓	Components - damage, broken	✓	Warning lights / gauges	

Fuel filter and hydraulic filter not required to change until 300 hours

✓ Components - damage, broken
✓ Wheel/Tracks/Tyres - loose, nuts, wear
✓ Pins - pivots, rams, lift arms, bucket pins
✓ Guards - in place, secure, warnings

✓ Operation of brakes, steering, controls, wipers, levers, buckets
✓ Other - eg: fire extinguisher, electrical connections, wires etc
Environmental Spill Kit complete & available

✓ Plant Security

## ✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time	Fi	ield Labour	2.4	Total Kilometers

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Trenton Van Loon
Licence No:	Trenton van Loon
Signature:	

