



**Docket No. 1306**

**SERVICE & MAINTENANCE REPORT**

Work to be completed by a licensed mechanic

Date	12:02 PM, 18th Feb, 2024	Make	
Asset	<b>D110</b>	Model	
Rego Nbr		Serial Number	
Location of job	Yard	Hours/Odometer	<b>650</b>
Completed by	Trenton Van Loon	Licence Number	Trent van Loon

Work Required	100 hour service
---------------	------------------

Work Performed	Engine oil and filter changed Check and top up hydraulic oil Change fuel filter Inspect ignition barrel and key - replacement barrel and key required ad loose - secured with cable tie for now. Machine was not tracking straight Inspect engine mounts - found front engine mount cracked almost all the way thru on one side and completely snapped in the other. Engine mount removed and welded for temporary repair - replace ASAP Change both air filters Segreagated rubbing hoses Check track tension Grease machine Horn is missing
----------------	---

Outstanding Work Required	Horn missing, Bash Plates and bolts all missing - new bracket will need welding on. Front engine mount needs replacing ASAP. Ignition barrel needs replacing
---------------------------	--

Consumables/Oils/Grease			
Consumables	<b>Rags, gloves, brake cleaner, welding supplies, cable ties</b>	Hydraulic Oil	<b>1</b>
Engine Oil	<b>1</b>	Gear Oil	
Trans Oil		Diff Oil	
		Grease	<b>1</b>
		Coolant	
		Enviro Costs	

Additional Job Notes	Prioritise replacing engine mount
----------------------	-----------------------------------

Plant Safety Check - Please tick all that have been checked:	
<ul style="list-style-type: none"> <li>✓ Lights, Warning Devices, Signs etc</li> <li>✓ Hydraulics - leaks damage connections</li> <li>✓ Components - damage, broken</li> <li>✓ Wheel/Tracks/Tyres - loose, nuts, wear</li> <li>✓ Pins - pivots, rams, lift arms, bucket pins</li> <li>✓ Guards - in place, secure, warnings</li> </ul>	<ul style="list-style-type: none"> <li>✓ Condition of hoods, sheaves, chains</li> <li>✓ Cabin - controls, loose objects, seat belts, windscreen visibility</li> <li>✓ Warning lights / gauges</li> <li>✓ Operation of brakes, steering, controls, wipers, levers, buckets</li> <li>✓ Other - eg: fire extinguisher, electrical connections, wires etc</li> <li>✓ Environmental Spill Kit complete &amp; available</li> <li>✓ Plant Security</li> </ul>

✓ **VIP CHECK AROUND PLANT PRIOR TO COMPLETION**

Travel Time		Field Labour	<b>5.5</b>	Total Kilometers	
-------------	--	--------------	------------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Trenton Van Loon
Licence No:	Trent van Loon
Signature:	

**CMS Contracting & Plant Hire Pty Ltd**  
 ABN 73 143 852 411  
 10-12 Churchill Street, SILVERWATER NSW 2128  
 Ph 02 9647 1929  
 Email accounts@cmscontracting.com.au  
 www.cmscontracting.com.au



**SERVICE & MAINTENANCE REPORT**

**Docket # 0060**

DATE: 18-11-23 MAKE: Cormidi  
 LOCATION OF JOB: Silverwater MODEL: C85  
 PLANT NO: 0110 SERIAL NO: CRM1085PAJOP40425  
 REGO NO: \_\_\_\_\_ HOURS/KMS: 556

**WORK REQUIRED:**

500 HOUR SERVICE

**WORK PERFORMED:**

change engine oil & filter  
" hydraulic oil filter  
" fuel filter  
repair track tension  
replace air filters  
" battery  
" bash plate  
grease + safety inspection

**OUTSTANDING WORK REQUIRED:**

CONSUMABLES: \_\_\_\_\_ HYDRAULIC OIL: 1 GREASE: 1  
 ENGINE OIL: 1 GEAR OIL: \_\_\_\_\_ COOLANT: \_\_\_\_\_  
 TRANS OIL: \_\_\_\_\_ DIFF OIL: \_\_\_\_\_ ENVIRO COSTS: \_\_\_\_\_

<b>TRAVEL TIME</b>	<u>1</u>	<b>FIELD LABOUR</b>	<u>3.5</u>	<b>TOTAL KILOMETERS</b>	
--------------------	----------	---------------------	------------	-------------------------	--

<b>PLANT SAFETY CHECK</b>	✓
Machine Hours	
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

**SIGN OFF**

Serviceperson: Trenton Van Loon

Licence No.: \_\_\_\_\_

I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Signature: \_\_\_\_\_