

**CMS Contracting & Plant Hire Pty Ltd**  
 ABN 73 143 852 411  
 10-12 Churchill Street, SILVERWATER NSW 2128  
 Ph 02 9647 1929  
 Email accounts@cmscontracting.com.au  
 www.cmscontracting.com.au



**Form No. 1593**

**SERVICE & MAINTENANCE REPORT**

Work to be completed by a licensed mechanic

Date	3:38 PM, 4th Apr, 2024	Make	
Asset	X57	Model	
Rego Nbr		Serial Number	
Location of job	Silverwater	Hours/Odometer	732
Completed by	Connor Snell	Licence Number	Hayden Rust

Work Required	250 hour service
---------------	------------------

Work Performed	Carry out 250 hour service, replace engine oil, engine oil filter, outer air filter and check all fluid levels, grease and safety inspection
----------------	--

Outstanding Work Required	
---------------------------	--

Consumables/Oils/Grease			
Consumables		Hydraulic Oil	4
Engine Oil	3.4	Gear Oil	
Trans Oil		Diff Oil	
		Grease	1
		Coolant	
		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:	
<ul style="list-style-type: none"> <li>✓ Lights, Warning Devices, Signs etc</li> <li>✓ Hydraulics - leaks damage connections</li> <li>✓ Components - damage, broken</li> <li>✓ Wheel/Tracks/Tyres - loose, nuts, wear</li> <li>✓ Pins - pivots, rams, lift arms, bucket pins</li> <li>✓ Guards - in place, secure, warnings</li> </ul>	<ul style="list-style-type: none"> <li>✓ Condition of hoods, sheaves, chains</li> <li>✓ Cabin - controls, loose objects, seat belts, windscreen visibility</li> <li>✓ Warning lights / gauges</li> <li>✓ Operation of brakes, steering, controls, wipers, levers, buckets</li> <li>✓ Other - eg: fire extinguisher, electrical connections, wires etc</li> <li>✓ Environmental Spill Kit complete &amp; available</li> <li>✓ Plant Security</li> </ul>

**✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION**

Travel Time		Field Labour	1.5	Total Kilometers	
-------------	--	--------------	-----	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Hayden Rust
Licence No:	Hayden Rust
Signature:	

**CMS Contracting & Plant Hire Pty Ltd**  
 ABN 73 143 852 411  
 10-12 Churchill Street, SILVERWATER NSW 2128  
 Ph 02 9647 1929  
 Email accounts@cmscontracting.com.au  
 www.cmscontracting.com.au



**CONTRACTING**

**SERVICE & MAINTENANCE REPORT**

**Docket # 0054**

DATE: 28-10-23 MAKE: Yanmar  
 LOCATION OF JOB: Silverwater MODEL: vic 25-6A  
 PLANT NO: X57 SERIAL NO: AG732  
 REGO NO: \_\_\_\_\_ HOURS/KMS: 585

**WORK REQUIRED:** 500 HOUR SERVICE

---

**WORK PERFORMED:** Change engine oil & filter  
" fuel filter & clean water separator  
Tension fan belt  
Change catal air cleaner  
Top up hydraulic oil / change return filter  
Change final drive oil  
check + adjust track tension  
Repair beacon  
Safety inspection & grease.

**OUTSTANDING WORK REQUIRED:** Flip cutting edge next service

---

CONSUMABLES: \_\_\_\_\_ HYDRAULIC OIL: 5 GREASE: 1  
 ENGINE OIL: 4 GEAR OIL: 1 COOLANT: \_\_\_\_\_  
 TRANS OIL: \_\_\_\_\_ DIFF OIL: \_\_\_\_\_ ENVIRO COSTS: \_\_\_\_\_

<b>TRAVEL TIME</b>	<u>1</u>	<b>FIELD LABOUR</b>	<u>5.25</u>	<b>TOTAL KILOMETERS</b>	
--------------------	----------	---------------------	-------------	-------------------------	--

<b>PLANT SAFETY CHECK</b>	✓
Machine Hours	
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
<b>VIP CHECK AROUND PLANT PRIOR TO COMPLETION</b>	

**SIGN OFF**

Serviceperson: Trenton Van Loan

Licence No.: \_\_\_\_\_

I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Signature: \_\_\_\_\_