CMS Contracting & Plant Hire Pty Ltd

ABN 73 143 852 411 10-12 Churchill Street, SILVERWATER NSW 2128

Email accounts@cmscontracting.com.au www.cmscontracting.com.au

Ph 02 9647 1929



Form No. 1607

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date	4:25 PM, 10th Apr, 2024	Make	Yanmar
Asset	X61	Model	Vio55-6
Rego Nbr		Serial Number	16209
Location of job	Silverwater	Hours/Odometer	326
Completed by	Connor Snell	Licence Number	Hayden Rust

completed by	Completed by Common Shell Electrice Hamber Indyach Rase					
Work Required		250 hour service				
Work Performed		Change engine oil, change engine oil filter, top up hydraulic oil, clean our air cleaner				
		(outer and inner), grease and safety inspection, check all fluid levels				
_			•			
Outstanding Work Required		N/A				
Consumables/0	Dils/Grease					
Consumables		F	lydraulic Oil	3	Grease	1
Engine Oil	2.8		Gear Oil		Coolant	
Trans Oil			Diff Oil		Enviro Costs	
•			•		•	

Additional Job Notes

Plar	Plant Safety Check - Please tick all that have been checked:			
√ √	Lights, Warning Devices, Signs etc Hydraulics - leaks damage connections	√	Condition of hoods, sheaves, chains Cabin - controls, loose objects, seat belts, windscreen visibility	
√ √ √	Components - damage, broken Wheel/Tracks/Tyres - loose, nuts, wear Pins - pivots, rams, lift arms, bucket pins Guards - in place, secure, warnings	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Warning lights / gauges Operation of brakes, steering, controls, wipers, levers, buckets Other - eg: fire extinguisher, electrical connections, wires etc Environmental Spill Kit complete & available Plant Security	

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time	Field Labour	2	Total Kilometers	

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Hayden Rust
Licence No:	Hayden Rust
Signature:	H.C