

**CMS Contracting & Plant Hire Pty Ltd**  
 ABN 73 143 852 411  
 10-12 Churchill Street, SILVERWATER NSW 2128  
 Ph 02 9647 1929  
 Email accounts@cmscontracting.com.au  
 www.cmscontracting.com.au



**Form No. 1675**

**SERVICE & MAINTENANCE REPORT**

Work to be completed by a licensed mechanic

Date	7:24 AM, 19th Apr, 2024	Make	
Asset	<b>X54</b>	Model	
Rego Nbr		Serial Number	
Location of job	Silverwater	Hours/Odometer	<b>910</b>
Completed by	Andrew McCredden	Licence Number	Andrew McCredden

Work Required	250 hour service
---------------	------------------

Work Performed	Oil filter air outer filter oil 3.5 grease jointsHydraulic fluid 2l
----------------	---

Outstanding Work Required	Fix cab electrical connection.
---------------------------	--------------------------------

Consumables/Oils/Grease			
Consumables		Hydraulic Oil	<b>2</b>
Engine Oil	<b>3.5</b>	Gear Oil	
Trans Oil		Diff Oil	
			Grease <b>1</b>
			Coolant
			Enviro Costs

Additional Job Notes	
----------------------	--

<b>Plant Safety Check - Please tick all that have been checked:</b>			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

**✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION**

Travel Time		Field Labour	<b>2</b>	Total Kilometers	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Andrew McCredden
Licence No:	Andrew McCredden
Signature:	

**CMS Contracting & Plant Hire Pty Ltd**

ABN 73 143 852 411

10-12 Churchill Street, SILVERWATER NSW 2128

Ph 02 9647 1929

Email accounts@cmscontracting.com.au

www.cmscontracting.com.au



**SERVICE & MAINTENANCE REPORT**

**Docket # 0041**

DATE: 12-08-23 MAKE: Yanmar  
 LOCATION OF JOB: Silverwater MODEL: Vio 17-1  
 PLANT NO: X54 SERIAL NO: 12017  
 REGO NO: \_\_\_\_\_ HOURS/KMS: 504

WORK REQUIRED: 500 HOUR SERVICE

WORK PERFORMED:  
Change Engine oil & filter  
" fuel filter  
" hydraulic return filter  
" outer air filter element  
Top up hydraulic tank  
check coolant, fan belt, water separator, radiator  
grease  
safety inspection

OUTSTANDING WORK REQUIRED:  
 \_\_\_\_\_  
 \_\_\_\_\_

CONSUMABLES: \_\_\_\_\_ HYDRAULIC OIL: 3 GREASE: 1  
 ENGINE OIL: 3 GEAR OIL: \_\_\_\_\_ COOLANT: \_\_\_\_\_  
 TRANS OIL: \_\_\_\_\_ DIFF OIL: \_\_\_\_\_ ENVIRO COSTS: \_\_\_\_\_

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>3.5</u>	TOTAL KILOMETERS	
-------------	----------	--------------	------------	------------------	--

PLANT SAFETY CHECK	
Machine Hours	
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF  
 Serviceperson: Trenton Van Loon  
 Licence No.: \_\_\_\_\_  
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.  
 Signature: \_\_\_\_\_