

CMS Contracting & Plant Hire Pty Ltd
 ABN 73 143 852 411
 10-12 Churchill Street, SILVERWATER NSW 2128
 Ph 02 9647 1929
 Email accounts@cmscontracting.com.au
 www.cmscontracting.com.au



Form No. 1642

SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date	10:19 AM, 16th Apr, 2024	Make	
Asset	X50	Model	
Rego Nbr		Serial Number	
Location of job	KEMPS CREEK	Hours/Odometer	3531
Completed by	Trenton Van Loon	Licence Number	Trenton van Loon

Work Required	500 hour service
---------------	------------------

Work Performed	Engine oil and filter changed Fuel filter changed Fuel water separator element changed Outer air filter changed Inner is ok Check hydraulic oil - ok Hydraulic return filter changed Fan belts inspected -ok Inspect radiator for leaks and coolant level - ok Check track tension - ok Check track rollers - ok Changed final drive oil Grease whole machine Check AC - ok Check accumulator- ok Check lights and horn Clean cab filter - should replace paper one at next service Check fire extinguisher, seat belt and rops - ok Plug in beacon - working check lights - ok Reset service meter
----------------	---

Outstanding Work Required	Reverse camera not working correctly, cab filter needs changing (paper one)
---------------------------	---

Consumables/Oils/Grease				
Consumables	Gloves, brake cleaner, rags, sticker	Hydraulic Oil	Grease	1
Engine Oil	12L	Gear Oil	Coolant	
Trans Oil		Diff Oil	Enviro Costs	1

Additional Job Notes	Change cab filter next service
----------------------	--------------------------------

Plant Safety Check - Please tick all that have been checked:	
<ul style="list-style-type: none"> ✓ Lights, Warning Devices, Signs etc ✓ Hydraulics - leaks damage connections ✓ Components - damage, broken ✓ Wheel/Tracks/Tyres - loose, nuts, wear ✓ Pins - pivots, rams, lift arms, bucket pins ✓ Guards - in place, secure, warnings 	<ul style="list-style-type: none"> ✓ Condition of hoods, sheaves, chains ✓ Cabin - controls, loose objects, seat belts, windscreen visibility ✓ Warning lights / gauges ✓ Operation of brakes, steering, controls, wipers, levers, buckets ✓ Other - eg: fire extinguisher, electrical connections, wires etc ✓ Environmental Spill Kit complete & available ✓ Plant Security

✓ VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time	Field Labour	2.25	Total Kilometers
-------------	--------------	------	------------------

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Trenton Van Loon
Licence No:	Trenton van Loon
Signature:	

CMS Contracting & Plant Hire Pty Ltd
 ABN 73 143 852 411
 10-12 Churchill Street, SILVERWATER NSW 2128
 Ph 02 9647 1929
 Email accounts@cmscontracting.com.au
 www.cmscontracting.com.au



SERVICE & MAINTENANCE REPORT

Docket # 0056

DATE: 10-11-23 MAKE: Yanmar
 LOCATION OF JOB: Silverwater MODEL: Vic 82
 PLANT NO: X50 SERIAL NO: 532
 REGO NO: _____ HOURS/KMS: 3000

WORK REQUIRED: 3000 HOUR SERVICE

WORK PERFORMED:
Change engine oil + filter
" fuel filter + water separator changed
" both air filters
" hydraulic return filter + clean suction filter
" hydraulic pilot filter + oil
Tension fan belts
Fill up washer bottle + repair windscreen wiper
Clean cab filters
Grease + safety inspection
+ change gear oil

OUTSTANDING WORK REQUIRED: Isolator not isolating correctly

CONSUMABLES: _____ HYDRAULIC OIL: 50 GREASE: 1
 ENGINE OIL: 10 GEAR OIL: 4 COOLANT: 1
 TRANS OIL: _____ DIFF OIL: _____ ENVIRO COSTS: _____

TRAVEL TIME	<u>1</u>	FIELD LABOUR	<u>5.25</u>	TOTAL KILOMETERS	
-------------	----------	--------------	-------------	------------------	--

PLANT SAFETY CHECK	✓
Machine Hours	
Lights, Warning Devices, Signs etc	
Hydraulics – leaks, damage, connections	
Components – damage, broken	
Wheel/Tracks/Tyres – loose, nuts, wear	
Pins – pivots, rams, lift arms, bucket pins	
Guards – in place, secure, warnings	
Condition of hoods, sheaves, chains	
Cabin – controls, loose objects, seat belts, windscreen visibility	
Warning lights/Gauges	
Operation of brakes, steering, controls, wipers, levers, buckets	
Other – e.g. Fire Extinguisher, electrical connections, wires etc	
Environmental spill kit complete & available	
Plant Security	
VIP CHECK AROUND PLANT PRIOR TO COMPLETION	

SIGN OFF
 Serviceperson: Trenton van Loon
 Licence No.: _____
 I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.
 Signature: _____