



Earthmoving Equipment Australia Pty Ltd
 ABN 91 146 265 983 ACN 146 265 983
 204 Power Street,
 Glendenning, NSW 2761
 AUSTRALIA

PH: 02 9671 1000
 Email: service-team@eeaustralia.com.au
 Web: www.eeaustralia.com.au

Service Tax Invoice		Page 1 of 2		Reprint# 3		Doc #: IHCSA16547	
Customer No. 14589	Customer Name & Address CMS Group (NSW) Pty Ltd 10-12 Churchill St			Advisor Grant Meyer 313	Colour	Team SERVICE	
Doc. Date 15/03/24	Silverwater NSW 2128			Year / Make / Model 22/CASE IH/MLE CX220C ACCTG TEMPLATE			Tag No.
Reg. No. FJ1326				Model No. CX220CNLCRS	Carline MLE CX220C		Eng./Trans.
Stock No. A1853	Purchase Order No.			Contract No.	Contract Name	Contract Exp. Kms	Exp. Date
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT	Home Phone	Business Phone 0298682000	Terms Cash	Selling Dealer	Delivery Kms.	Delivery Date 14/11/23	Warr. Exp. Date 13/11/26
	Vehicle ID. DCH220D6NNEFJ1326	Engine No. 4HK1-847960		Date & Time Promised 14/02/24 05:30pm	Time Received 02:00pm	Quote Price	Air Pwr Turb
Operator	Operator Mobile # 0414393245		Customer Mobile # 0414393245				

Labour	Operation	Description	Units	Amount
--------	-----------	-------------	-------	--------

Job# 1	01IHZZZZZ500	SERVICE AS REQUIRED	Tech(s): 467 500	1122.88
Carry out 100hr service and 250hr due to meter check quick hitch operation Travel to 160 Froster Rd St Marys Haden 0407638412 15.3.24 327 h Done 100 h and 250 h service Changed engine oil filter , two fuel filter , outter air filter Changed engine oil Topped up 10 l hyd oil Topped up 300 ml gear oil to each drive and 200ml to slew Greased all pins Replaced service sticker and reset service light Done all checks according to inspection sheet Cleared old fault from memory				

Parts	Qty	Number	Description	Unit Price	Amount
Job# 1	1	IH51441635	FILTER, ENGINE OIL	55.20	55.20
Job# 1	1	IH47585451	FILTER FUEL	44.01	44.01
Job# 1	1	IHMMH80990	FILTER, FUEL	174.28	174.28
Job# 1	1	IHKBH0921	FILTER AIR	117.64	117.64

Petrol, Oils, Lubricants and Supplies				Amount
Job# 1	10.0	Hydraulic Oil		128.70
Job# 1	0.5	Gear Oil		7.29

<<< Total For Job 1 >>> 1650.00



Earthmoving Equipment Australia Pty Ltd
 ABN 91 146 265 983 ACN 146 265 983
 204 Power Street,
 Glendenning, NSW 2761
 AUSTRALIA

PH: 02 9671 1000
 Email: service-team@eeaustralia.com.au
 Web: www.eeaustralia.com.au

Service Tax Invoice		Page 2 of 2		Reprint# 3		Doc #: IHCSA16547			
Customer No. 14589	Customer Name & Address CMS Group (NSW) Pty Ltd 10-12 Churchill St Silverwater NSW 2128			Advisor Grant Meyer	313	Colour	Team SERVICE		
Doc. Date 15/03/24				Year / Make / Model 22/CASE IH/MLE CX220C ACCTG TEMPLATE			Tag No.		
Reg. No. FJ1326				Model No. CX220CNLCRS		Carline MLE CX220C		Eng./Trans.	
Stock No. A1853				Chassis No. DCH220D6NNEFJ132		Kilometres 327	Prod. Date	Orig. Del. Date 14/11/23	
Purchase Order No.	Driver	Contract No.		Contract Name	Contract Exp. Kms	Exp. Date			
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT	Home Phone	Business Phone 0298682000	Terms Cash	Selling Dealer	Delivery Kms.	Delivery Date 14/11/23	Warr. Exp. Date 13/11/26		
	Vehicle ID. DCH220D6NNEFJ1326	Engine No. 4HK1-847960	Date & Time Promised 14/02/24 05:30pm	Time Received 02:00pm	Quote Price	Air	Pwr		
						Turb			

Total Labour 1122.88
 Total Parts 391.13
 Total POL 135.99
 Total Sublet 0.00
 Total Misc 0.00

Total Tax 165.00

Total Invoice 1815.00

Total Including GST

WE ARE PLEASED TO OFFER FIXED PRICE SERVICING FOR ALL OF YOUR EQUIPMENT. PLEASE CALL US IF YOU WOULD LIKE ANY FURTHER INFORMATION

Account Details: Earthmoving Equipment Australia Pty Ltd **BSB:** 062 000 **Account Number:** 20175947 **Bank:** CBA
Condition of Invoice: This invoice is issued under the Security Payments Act of 1999. Title of goods remain with Earthmoving Equipment Australia Pty Ltd until clear funds have been paid.
Warranty: Used Equipment- No warranty given or implied, goods are sold as is, where is, with any faults if any. You have 5 working days from receiving this invoice to raise any concerns you may have with the outstanding amount. If you have not replied to this invoice in writing then payment needs to be made within credit terms.



**EARTHMOVING
EQUIPMENT
AUSTRALIA**

Work Order Number A15733

Model CX220C

Hours 410

Technician Signature [Signature]

Date 8/11/23

Serial No: FJ1326

Dealer EEA

Customer CMS Group

Address 10-12 Churchill St

Silverwater NSW 2128

Customer Signature [Signature]

Ensure this service is entered into the Service Logbook

PDI Inspection

Maintenance Repairs

Sales Inspection

Service Inspection

SAFETY EQUIPMENT	CHECK	SERVICE	OTHER	CHECK	SERVICE	OTHER	CHECK	SERVICE	OTHER	CHECK	SERVICE	OTHER	CHECK	SERVICE
1. Seat belt	✓													
2. ROPS	✓													
3. Door catches	✓													
4. Back-up alarms	✓													
5. Screens & window cracks & chips	✓													
6. Exh. Smoke	✓													
7. Strange noises	✓													
8. Vibrations	✓													
9. Turbo charger	✓													
10. Intake system	✓													
11. Muffler/Exh. System	✓													
12. Fuel pumps	✓													
13. Fuel lines/clamps	✓													
14. Fuel shut off system	✓													
15. Fuel throttle linkage	✓													
16. Fuel tanks and caps	✓													
17. Belts/tensioners	✓													
COOLING SYSTEM														
18. Radiator hoses/clamps/cap	✓													
19. Radiator core	✓													
20. Water pump	✓													
21. Fan blades & assembly	✓													
22. Anti freeze/Anti boil	✓													
ELECTRICAL														
23. Starting switch	✓													
24. Connections	✓													
25. Battery straps	✓													
26. Battery condition	✓													
27. Starter	✓													
28. Alternator	✓													
29. Wipers	✓													
30. Defrost/ac fan	✓													
31. Indicators	✓													
32. Lights interior and exterior	✓													
33. Control functions	✓													
34. All instruments	✓													
35. Other	✓													
STEERING SYSTEMS														
36. Hoses	✓													
37. Cylinder/Valves	✓													
38. Linkage/Controls	✓													
39. Other	✓													
POWER TRAIN														
40. Trans oil cooler	✓													
41. Drive shaft	✓													
42. Wheel lugs	✓													
43. Tyres/Pressures	✓													
44. Other	✓													
UNDERCARRIAGE														
45. Track condition and tension	✓													
46. Rollers	✓													
47. Idlers	✓													
48. Sprockets	✓													
49. Pads	✓													
50. Pins/Brushings	✓													
51. Other	✓													
BRAKES														
52. Air compressor	✓													
53. Bleed air tank	✓													
54. Linkage/Controls	✓													
55. Lines/Hoses	✓													
56. Pads	✓													
57. Park brake	✓													
58. Others	✓													
HYDRAULICS														
59. Lines/Hoses	✓													
60. Controls/Linkages	✓													
61. Oil cooler	✓													
62. Cylinders/Valves	✓													
63. Reservoir	✓													
64. Other	✓													
LEAKS														
65. Oil	✓													
66. Fuel	✓													
67. Coolant	✓													
68. Air	✓													
GENERAL BODY & CHASSIS CONDITION														
IMMEDIATE ATTENTION	ITEM No.	COMMENTS												
		<u>PDI as per RD A15733</u>												

KEY

PASSED INSPECTION - SERVICE PERFORMED ✓

ADJUSTMENT OR ADD A

RECOMMENDED REPAIR OR REPLACEMENT R

NOT APPLICABLE N

CUSTOMER COPY WHITE WORK ORDER COPY YELLOW