



**Form No. 3900**

## SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	12/06/2025	Make	
Asset	<b>X59</b>	Model	
Rego Nbr		Serial Number	
Location of job	Northwood	Hours/Odometer	<b>1853</b>
Completed by	Trenton Van Loon	Licence Number	Trenton van Loon

Work Required	Repair
---------------	--------

Work Performed	Replace cutting edge. Inspect mixer door on AC system, not cha ging to face setting, stuck on feet/head
----------------	---

Outstanding Work Required	Further inspect AC ducting
---------------------------	----------------------------

Consumables/Oils/Grease					
Consumables		Hydraulic Oil		Grease	
Engine Oil		Gear Oil		Coolant	
Trans Oil		Diff Oil		Enviro Costs	


Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc Hydraulics - leaks damage connections Components - damage, broken Wheel/Tracks/Tyres - loose, nuts, wear Pins - pivots, rams, lift arms, bucket pins Guards - in place, secure, warnings		Condition of hoods, sheaves, chains Cabin - controls, loose objects, seat belts, windscreen visibility Warning lights / gauges Operation of brakes, steering, controls, wipers, levers, buckets Other - eg: fire extinguisher, electrical connections, wires etc Environmental Spill Kit complete & available Plant Security

### VIP CHECK AROUND PLANT PRIOR TO COMPLETION

Travel Time		Field Labour	<b>4.5</b>	Total Kilometers	
-------------	--	--------------	------------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Trenton Van Loon
Licence No:	Trenton van Loon
Signature:	



**Form No. 3432**

## SERVICE & MAINTENANCE REPORT

Work to be completed by a licensed mechanic

Date of Service	04/03/2025	Make	
Asset	<b>X59</b>	Model	
Rego Nbr		Serial Number	
Location of job	Yard	Hours/Odometer	<b>1525</b>
Completed by	Trenton Van Loon	Licence Number	Trent van loon

Work Required	500 hour service
---------------	------------------

Work Performed	Engine oil and filter. Secondary Fuel filter. Primary fuel filter. Check hydraulic oil level - ok. Change final drive oil. Check swing drive oil level - ok. Check fan belt - ok. Check ac belt - ok. Check radiator hoses - ok. Clean fuel pump. Primary air filter replaced. Check radiator and oil cooler - ok. Greased machine. Clean out cab filters. Reset service meter. Checked cab items -ok
----------------	---

Outstanding Work Required	Replace left boom cylinder grease fitting
---------------------------	---

Consumables/Oils/Grease					
Consumables	<b>Gloves rags brake cleaner</b>	Hydraulic Oil		Grease	<b>1</b>
Engine Oil	<b>17</b>	Gear Oil	<b>4</b>	Coolant	
Trans Oil		Diff Oil		Enviro Costs	

Additional Job Notes	
----------------------	--

Plant Safety Check - Please tick all that have been checked:			
✓	Lights, Warning Devices, Signs etc	✓	Condition of hoods, sheaves, chains
✓	Hydraulics - leaks damage connections	✓	Cabin - controls, loose objects, seat belts, windscreen visibility
✓	Components - damage, broken	✓	Warning lights / gauges
✓	Wheel/Tracks/Tyres - loose, nuts, wear	✓	Operation of brakes, steering, controls, wipers, levers, buckets
✓	Pins - pivots, rams, lift arms, bucket pins	✓	Other - eg: fire extinguisher, electrical connections, wires etc
✓	Guards - in place, secure, warnings	✓	Environmental Spill Kit complete & available
		✓	Plant Security

✓ **VIP CHECK AROUND PLANT PRIOR TO COMPLETION**

Travel Time		Field Labour	<b>4</b>	Total Kilometers	
-------------	--	--------------	----------	------------------	--

SIGN OFF: I accept that the service and/or inspection has been completed. All repairs are complete to a satisfactory standard. The times/quantities indicated above are correct.

Service Person Name:	Trenton Van Loon
Licence No:	Trent van loon
Signature:	