

Site Number	Location Name	GPS Coordinates	Date and Time	Temp	pH	Turbidity (NTU)	Samples
1	RB Forebay East Bank – Surface	N44 35.95 W121 16.89	6-16-15 0845	18.7C	9.5	8.2	Nutrients and Chlorophyll-a
1	RB Forebay East Bank-Depth	N44 35.95 W121 16.89	“ 0905	10.2C	7.1	0.5	Nutrients and Chlorophyll-a
2	RB Forebay Middle-Surface	N44 36.01 W121 16.90	“ 0935	18.6C	9.6	12.3	Nutrients and Chlorophyll-a
2	RB Forebay Middle-Depth	N44 36.01 W121 16.90	“ 0950	9.9C	7.3	0.8	Nutrients and Chlorophyll-a
3	RB Forebay West Bank-Surface	N44 36.099 W121 16.966	“ 1005	19.4C	9.6	10.1	Nutrients and Chlorophyll-a
3	RB Forebay West Bank-Depth	N44 36.099 W121 16.966	“ 1025	10.6C	7.0	0.8	Nutrients and Chlorophyll-a

4	Rereg Dam Tailrace + 200 m. Depth = 1 m.	N44 43.70 W121 14.68	" 1315	17.1C	8.5	1.7	Nutrients and Chlorophyll-a
---	---	-------------------------	-----------	-------	-----	-----	--------------------------------